And a second	
4447	Robert L. Johnson Company
	City of San Diego - Sewage Disposal Unit
and the second	Air Heater Furnace Brickwork
a de	
4448	Forest Lawn Memorial-Park Assn., Inc Glendale
	Repairs to Crematory Retorts
4449	Bethlehem Steel Company, Inc.
e e e e e e e e e e e e e e e e e e e	S. S. "Bald Hill" - To Rebrick Galley Range
4450-T	Kinzbach Tool Company - Houston, Texas
(See T-508)	To Reline One (1) Carburizing Pot #73
± /~~,	To Reline One (1) High Speed Furnace #71
non-tra	
4451	Bethlehem Steel Company, Inc.
	S. S. "Mojave" - To Rebrick Galley Range
(A)	S. S. "R. P. Warner" - Galley Range Brickwk. Rprs.
	and the second of the second o
4452	Bethlehem Steel Company, Inc.
g	S. S. "Marcus Daly" - To Rebrick Galley Range
(A)	S. S. "Edward D. Baker" - Galley Range Brickwork Rprs.
(B)	S. S. "Edward D. Baker" - Repairs to Boilers
4453	Andrew Brown Company - Maywood
	To Reline 4' x 4' Ball Mill
4454	Craig Shipbuilding Co.
	Brickwork Repairs - Two (2) Boiler Furnaces - USS YF-54
THE MAIN THE TAX TO SEE	
4455	C. C. Moore & Co. Engineers, Inc.

United States Potash Co. - Carlsbad, New Mexico

Stirling Boiler #6 - Brickwork Setting

4456	Federated Metals Division., Amer. Smelting & Ref. Co.
	Los Angeles - Brickwork Repairs to #1 Brass Reverb.
) (A)	Repairs to #4 Furnace
(B)	Repairs to Aluminum Reverb.
4457	Todd Shipyards Corporation
	Operating under Contract with U.S. Navy Dept.
\$ .	Plant of Los Angeles Shipbuilding & Drydock Corp.
4458-T	S. S. "OA-39" - To Repair Two (2) Boilers
4458-T	Diamond Iron Works, Inc. & the Mahr Mfg. Co. Division
(See T-509)	Hughes Tool Co., Aircraft Strut Division - Houston, Texas
/-/,	Brickwork & Insulation -
	Two (2) Mahr Air Draw Furnaces
· · · · · · · · · · · · · · · · · · ·	Two (2) Mahr Hardening Furnaces
4459	Union Oil Company of Calif Wilmington Refinery
	Cross Plant - Brick Stack Repairs
4460	Kaiser Company, Inc., Iron & Steel Division - Fontana
	Repairs to #1 Open Hearth Furnace
4461	Twentieth Century-Fox Film Corp.
	West Los Angeles - Power Plant #1
	To Renew Brickwork - Boilers Nos. 1, 3 and 4
4462	Twentieth Century-Fox Film Corp.
	West Los Angeles - Power Plant #2
Ç	To Renew Brickwork - Boilers Nos. 2 and 3
4463	General Electric Company - Los Angeles
4403	
• • • • • •	Brickwork and Insulation - One (1) Babbitt Furnace
hhZi.	
4464	Richfield Oil Corp Watson Refinery
	Provide Opening for Soot Blower in Braun Fired Heater

4465	Union Iron & Steel Company
· .	Southern California Gas Co Aliso Street Plant
	To Brick in Door Frame
	and the second s
4466	Martin Ship Service Co.
	S. S. "Pat Doheny" - Boiler Repair
4467	Shell Oil Company, Inc Dominguez
	Dubbs Unit #2 - Furnace Repairs
	Shell Oil Company, Inc Houston, Texas
(See T-510)	Refinery - Chemical Division
. ,	To Repair #3 DMK Furnace
4469	Goodyear Tire and Rubber Co. of Calif Los Angeles
	#4 Boiler Furnace Repairs
ath. '	
4470	Bethlehem Steel Company, Ind.
	S. S. "Front Royal" - Boiler Repair
4471	Martin Ship Service Co.
	S. S. "David Belasco" - Repairs to Two (2) Boilers
(A)	Brickwork Repairs to Galley Range
4472	Kaiser Company, Inc., Iron & Steel Div Fontana
	Electric Furnace Brickwork Repairs
4473	Kaiser Company, Inc., Iron & Steel Div Fontana
	To Rebuild One (1) Bulkhead in Slow Cooling Ingot
	Furnace
(A)	To Reinsulate Covers - Slow Cooling Pits #7 & #8
(B)	To Build Two Partition Walls at Slow Cooling Pits
(C)	Brickwork Repairs to Slow Cooling Ingot Pits
(D)	Repairs to Slow Cooling Pit Covers
waa aa	

1.1	
4474	The Cudahy Packing Co Los Angeles
	Brickwork Repairs to #3 Boiler
(A)	Brickwork Repairs to #4 Boiler
1.3	
4475	Howes & Whitaker
	Seaside Oil Company - Ventura
	Brickwork & Insulation Enclosure for One (1) Fired
(L.S. P.	Oil Heater; and Insulation of Header Boxes
4476	Voicen Company Tra Twon & Steel Dir Fortone
4410	Kaiser Company, Inc., Iron & Steel Div Fontana
4476	To Patch Roof and Misc. Repairs to #4 Furnace
4477	Bethlehem Steel Company, Inc.
	S. S. "Victor H. Kelly" - Repairs to Two (2) Boilers
4478	Bethlehem Steel Company
	S. S. "Gulf Port" - To Repair Two (2) Boilers
(A)	To Reline Both Fireboxes of Galley Range
4479	Tide Water Associated Oil Co., Associated Division
	Wilmington - Watson Refinery
	Repairs to Rear Wall of Boiler #3
	110 20111 00 11000 11000 01 201102 11 3
4480	Craig Shipbuilding Co.
	S. S. "Arthur Newell Talbot"
· · · · · · · · · · · · · · · · · · ·	Brickwork Repairs to Galley Range
4481	Utility Trailer Mfg. Co Los Angeles
	Brickwork Repairs to General Electric Furnace
4482	C. C. Moore & Co. Engineers, Inc.
	Pacific Coast Borax Co., Boric Acid Plant - Boron
	Brick Settings for One (1) B. & W. Boiler and
	One (1) Llewellyn Boiler

4483	Standard Shipbuilding Corp.
	S. S. Standard "FP-174" - To Repair Galley Range
***************************************	
4484	Bethlehem Steel Company, Inc.
	S. S. "Jack London" - To Renew Brickwork in
	Bottom of Furnace in Starboard Boiler
(A)	To Renew Brick in Galley Range
(B)	Patch Brickwork in Port Boiler
4485	Bethlehem Steel Company, Inc.
	S. S. "Frank G. Drum" - To Rebrick Ovens of Galley
	Range
4486	Stone & Webster Engineering Corp.
	Natural Soda Products Co., Keeler, Calif.
	Boiler House of Soda Ash Plant
	Brick Setting for One (1) 72" x 20'-0" 200 h.p.
	HRT Boiler and thought by the Late
4487	Stauffer Chemical Co Dominguez Division
	Waste Heat Boiler #2 Brickwork Repairs
4488	Todd Shipyards Corporation
	Operating under Contract with U. S. Navy Dept.
	Plant of Los Angeles Shipbuilding & Drydock Co.
	S. S. "W. C. Fairbanks" - To Repair Three (3) Blrs
1100	7
4489	Bethlehem Steel Company, Inc.
	S. S. "River Raisin" - Boiler Brickwork Repairs
(A)	Brickwork Repairs to Port Boiler
1.1.00	model Chiramata Componention
4490	Todd Shipyards Corporation
	Standard Oil Company
	S. S. "R. C. Stoney" - Repairs to Boilers

4491	C. F. Braun & Co.
	Union Oil Company - Wilmington Refinery
	To Repair Brickwork Damaged in Ceilings of Lummus
	Fired Heater
4492	Frederick O'Brien Paint & Varnish Works - Los Angeles
	To Line 4 x 5 Pebble Mill
W.S.A.	
	Shell Oil Company, Inc Wilmington
4493	Boiler #6 - Brickwork Repairs
(A)	To Repair #7 and #8 Boilers
(B)	To Repair #1 and #2 Boilers
4494	Union Oil Company of Calif Wilmington Refinery
	Brickwork Repairs - Crude Stills #42 to #56 incl.
4495	The Dicalite Company
	Repairs to Rotary Kiln Lining and Firing Hood
4496	Kaiser Company, Inc., Iron & Steel Division - Fontana
	To Repair #6 Open Hearth Furnace
4497	Bethlehem Steel Company, Inc.
	S. S. "Cape Alexander"
	Brickwork Repairs to Both Furnaces
4498	Kaiser Company, Inc., Iron & Steel Division - Fontana
	To Rebuild #5 Open Hearth Furnace
4499	Standard Oil Company of Calif El Segundo
	To Rebuild both End Walls and both Bridge Walls -
	Furnace #11, Battery #2
4500	Bethlehem Steel Company, Inc.
	U. S. S. A0-71 - To Repair Two (2) Boilers

4501.	Bethlehem Steel Company, Inc.
Signatural consistency construction of the con	S. S. AP-115 - To Repair Four (4) Boilers
(A)	Incinerator Repairs
4502	Pacific Clay Products - Los Angeles
	To Reline Two (2) Ball Mills
4503	California Portland Cement Co Colton
ender a final de la companya de la c	To Renew Detrick Arch on #12 Kiln Stack Base
(A)	To Cover Brickwork Lining of #10 A. C. Cooler
4504	Todd Shipyards Corporation
	S. S. "Chalmette" - To Repair Two (2) Boilers
3	
. 4505	Standard Shipbuilding Corp.
	LST-274 - To Repair Galley Range Firebox
4506	Bethlehem Steel Company, Inc.
	S. S. "Wm. B. Allison"
	Brickwork Repairs to Port and Starboard Boilers
(A)	To Rebrick Galley Range
ā	
4507	Todd Shipyards Corp San Pedro
	B. & W. Boiler Brickwork:
	Hull #64 - U. S. S. "Klondike"
	Hull #65 - U. S. S. "Arcadia"
	Hull #66 - U. S. S. "Everglades"
	Hull #67 - U. S. S. "Frontier"
4508	Southern California Gas Co.
- -	Aliso Street - #1 Gas Generator Plant
	Brickwork Repairs to Generators
(A)	Drilling 28 Thermocouples
•	

	4509	Wilshire Oil Company, Inc Norwalk Refinery
	, i	F-W Boilers #1 and #3 - Furnace Brickwork Repairs
	4510	Bethlehem Steel Company, Inc. S. S. "Nathan S. Davis" - To Repair Galley Range
1818 to 1818 t	4511	Bethlehem Steel Company, Inc. U. S. S. APA-10 - To Renew Brickwork in Four (4) Blrs.
	(A)	Brickwork Repairs - Galley Ranges and Bakery Ovens
	4512	Harbor Boat Building Company  LST-119 - To Repair Galley Range and Oven
	<b>451</b> 3	Shell Chemical, Div. of Shell Union Oil Corp., Agent for Reconstruction Finance Corp., Office of Rubber Reserve Los Angeles - To Re-insulate Reactors #201B & #202B
	4514	Standard Oil Company of Calif El Segundo To Repair Bryson Arch in #30 Boiler in #1 Blr. House
	4515	Todd Shipyards Corporation S. S. "Scotts Bluff" To Renew Chrome Ore on Water Walls of Starboard Blr.
	4516	C. C. Moore & Co. Engineers  City of Burbank - Steam Plant  Boiler #3 - Baffle Alterations
	4517	Todd Shipyards Corporation S. S. APA-19 - To Repair Two (2) Boilers
	(A)	To Rebrick Incinerator and to Renew Brickwork on both Boilers

4518	Morris P. Kirk & Son, Inc Los Angeles
	Brickwork Repairs to Reverb. Furnace
(A)	Brickwork Repairs to Large Incinerator
(B)	Repairs to #2 Pot Furnace
4519	Utility Electric Steel Foundry - Los Angeles
	To Repair Core Oven
	to the control of the
4520	California Metal Enameling Co Los Angeles
	To Repair Enameling Furnace
4521	Los Angeles Potteries - Los Angeles
	To Reline 4 x 4 Ball Mill
4522	State of California
	Patton State Hospital - Patton, Calif.
	To Repair One (1) 350 h.p. Type YBL-20
	Badenhausen Boiler
e e e	
4523	Tide Water Associated Oil Co., Associated Division
	San Pedro - Marine Terminal
	To Repair Firebox in Boiler
*	
4524	Rubber Reserve Company
	Shell Chemical, Div. of Shell Union Oil Corp., Agent
	Los Angeles - Torrance Plant
,	To Rebrick Lining in Boiler #B501B
4525	C. C. Moore & Co. Engineers
	Pioneer Division, The Flintkote Company
	One (1) B. & W. F-16-AD-13/42 Integral Furnace
	Boiler
(A)	Insulation of Hot Gas Duct, Air Heater and Air
•	Duct; Furnace Side Walls and Roof

4526	C. C. Moore & Co. Engineers
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Goodyear Aircraft Corp Litchfield Park, Arizona
	One (1) B. & W. Single Class FF-15 #24 Boiler
4527	Bethlehem Steel Company
	S. S. "Tillamook" - To Repair Two (2) Boilers
4528	Bethlehem Steel Company
4528 4529	S. S. "George Von L. Meyer" - To Repair Two (2) Blrs.
4529	Bethlehem Steel Company
8 2 2	S. S. "Orson B. Munn" - To Repair Two (2) Boilers
hean	Rubber Reserve Company
4530	Shell Chemical, Div. of Shell Union Oil Corp., Agent
	Los Angeles - Torrance Plant
	To Repair Insulation Lining in Lower Side Walls of
	Reactors D-201A and D-202A
	Trouble of a particular differ a month
4531	Shell Oil Company, Inc Dominguez Refinery
1,7,5	Dubbs Furnace #3 - Brickwork Repairs
(A)	#2 and #4 Dubbs Repairs
(B)	#8 Dubbs Repairs
•	
4532	Stauffer Chemical Company - Dominguez Division
·	Acid Brick Lining for One (1) Tank 10'-0" dia. x
	5'-0" Deep
head	Union Oil Company of Calif Wilmington
4533	Cracking Plant #33
1	Repairs to Lummus Heaters Bla, Blb, B2a, B3a.
:	TIO POTTED OF THUMING HOROUTO DECE DED TO DECE DO
4534	Craig Shipbuilding Company - Long Beach, Berth #19
- 1997	S. S. "Mark Twah" - To Repair Galley Range
(A)	S. S. "Marshfield Victory" - To Repair Two (2) Blrs.

4535	Kaiser Company, Inc., Iron & Steel Division - Fontana
	Installation of Silica Tile on American Arch -
	Open Hearth #4
4536	Stauffer Chemical Company, Dominguez Division
& (A) thru	Insulation Work
(N)	
4537	Bethlehem Steel Company
it. The second	S. S. AKA-54 - To Repair Two (2) Boilers
4538	Standard Shipbuilding Company
	S. S. "Joseph Bradley" - To Repair Two (2) Boilers
(A)	Galley Range
	in the state of th
4539	Lindberg Engineering Co. and Harmon & Co.
	Kaiser Industries - Fontana
	Brickwork - One (1) Cooling Conveyor
(A)	To Raise Ray-O-Tubes in Large Shell Furnace
(B)	To Insulate Piping on 155 mm and 8" Shell Furnaces
(C)	To Enlarge Shell Openings in 155 mm Nosing-in Furnaces
·	
4540	Craig Shipbuilding Company - Long Beach, Berth #46
	S. S. "Grand Mesa" - To Repair Boilers
4541	Kaiser Company, Inc., Iron & Steel Division - Fontana
*	To Construct Slag Retaining Wall at Blast Furnace
	graph of the state
4542	Byron Jackson Company - Vernon
	To Repair One (1) Large Forge Furnace
4543	Avion Inc. for
	Gaffers & Sattler - Vernon
	Repairs to #2 and #3 Gas Enameling Furnaces

4544	California Portland Cement Co Colton
* · · · · · · · · · · · · · · · · · · ·	Brick Setting for One (1) 72" x 16'-0" HRT Boiler
3	and Rear Arch
(A)	Repairs to #10 A. C. Cooler
(B)	Repairs to #11 Kiln Hood and Lower Cooler Feed Hopper
4545	Pacific States Oil Company - Wilmington
**************************************	Repairs to #4 Boiler
(A) 4546	To Replace Brickwork in Front Wall of Boiler #3
4546	Shell Oil Company, Inc Dominguez
	To Repair Insuline Pipe Lining at Catalytic Cracking Plant
4547	Hunt, Mirk and Co., Inc.
	Acme Brewing Company - Vernon
,	Brick Setting - Kidwell Boiler #1
(A)	(Acme Order) Repair Baffles in #1 Boiler
4548	The Petrol Corporation - Los Angeles - Bandini Blvd.
	Brickwork Repairs to Retort
4549	Martin Ship Service Co.
	Oil Barge "Pellican" - Repairs to Boiler
4550	Bethlehem Steel Company
	S. S. "Mary Ball" - To Repair Port and Starboard Blrs
(A)	LST-399 - To Rew Fire Brick
(B)	S. S. "Mary Ball" - To Rebrick Galley Stove
(C)	LST-399 - Brickwork Repairs to Galley Range
heer	Tindhong Engineering Co. and Hormon & Company
4551	Lindberg Engineering Co. and Harmon & Company
	Kaiser Industries - Remaco, Colorado
	Brickwork for Three (3) Cooling Conveyors

4552	Bethlehem Steel Company
	S. S. "Fort Dearborn" - To Renew Brickwork in
Manager of the Spanish of the Spanis	Port and Starboard Boilers
(A)	S. S. "Harry Leon Wilson" - Repair Galley Range
(B)	S. S. "Fort Dearborn" - Brickwork Repairs to
	Straighten Boiler Fronts
4553	L. W. Lefort Company
and the second of the second o	Lockheed Service Center - Metro. Airport - Van Nuys
a.	Acid Brickwork - Lockheed Etch Tank
4554	Rubber Reserve Company
	Bechtel-McCone Corporation
	Standard Oil Company of Calif El Segundo
	Butadiene Plant - To Reline Seven (7) Reactor
	Vessels
(A)	Repair Brickwork of 78" Pipe Line
(B)	Repair Brickwork of F2 Furnace
(C)	Repair Brickwork on Heine Boiler
*	
4555	Federated Metals Division, Amer. Smelting & Refining Co
	To Renew Two (2) Door Arches
4556	General Metals Corporation - Vernon
	To Repair Bridge Wall in H-16 Stirling Boiler
4557	U. S. Industrial Chemicals, Inc Anaheim
	Installation of Brickwork for One (1) Air Heating
	Furnace for Spray Dryer
4558	Kaiser Company, Inc., Iron & Steel Division - Fontana
	Russell Experimental Furnace Repairs at Coke Ovens

T 222	official out company of carri.
	Dominguez Absorption Plant at Compton
	Brickwork Repairs - One (1) 250 h.p. Firebox Blr.
4560	Todd Shipyards Corp San Pedro
	Brickwork Foundry FloorHulls Nos. 64 to 67 incl.
	(Cancelled)
V°S'N 577 4561.	Material Only Furnished: 1,000 Sil-O-Cel Super Brick
4561	Rubber Reserve Company
97 9 940	Shell Chemical, Division of Shell Union Oil Corp., Agent
ත ් සෙ	Los Angeles - Torrance Plant
	To Repair American Arch, Seal off Floor and Caulk
	X-Joint in Superheater B-201-A
4562	United Ship Service Company - Wilmington
· /	S. S. "Mormackdale" - To Renew Boiler Brickwork
4563	Todd Shipyards Corporation
	Operating under Contract with U.S. Navy Department,
	Plant of Los Angeles Shipbuilding & Drydock Corp.
	S. S. "Claus Spreckles"
	To Renew Floors in Two (2) Boilers
4564	Craig Shipbuilding Company
	U. S. S. LST-447 - To Renew Brickwork and Insula-
	tion on Boiler
(A)	U. S. S. LST-447 - Galley Range Firebox
4565	Rubber Reserve Company
&A-Z	Southern California Gas Company, Agent
	Boiler and Generator Repairs
4566	Standard Shipbuilding Corp.
4 )00	
	S. S. "Edward Hope" - To Rebrick Galley Range

	Oct. 191	
	4567	Kaiser Company, Iron & Steel Division - Fontana
	idiose. La de condidende e maniero	#6 Open Hearth Repairs Tearing out only
	4568	Standard Shipbuilding Corporation
	British pagara	S. S. "McKay" - To Rebuild Galley Range
in a common		
	4569	Bethlehem Steel Company
		S. S. "Tolisse" - To Rebrick Galley Range
	4570	Bethlehem Steel Company
		S. S. "Fredricksburg" - To Repairs to Boiler
i.		
	4571	Todd Shipyards Corporation
		S. S. "River Raisin" - To Repair Boiler
	(A)	To Close Doors on Boiler Repair Job
	· ·	
	4572	Craig Shipbuilding Company
		S. S. "M. V. Cerro Azul" - To Repair Boiler
	<b>€</b> · · · · ·	
	4573.	Bethlehem Steel Company - CANCELLED
		S. S. "Illinois" - To Repair Boiler
	4574	Kaiser Company, Inc., Iron & Steel Division - Fontana
		#3 Open Hearth Furnace - Repairs to Roof, Arches,
	* .	
	4575	Swift & Company - Vernon
		Incinerator Repairs
	4576	Bethlehem Steel Company
		S. S. "Otto Mears" - To Rebrick Galley Range
	4577	Luer Packing Company - Vernon
		To Repair #1 Boiler

etc.

4578	Bethlehem Steel Company
<u> </u>	S. S. "Atlantic Coast" - Repairs to Two (2) Blrs
4579	Shell Oil Company, Inc.
	Ventura - Ventura Absorption Plant
	Repairs to Eight (8) Boilers
4580	The Petrol Corporation - Los Angeles - Bandini Blvd
THE STATE OF THE S	Brickwork Repairs to Firebox in #1 and #2 Boiler
80	
4581	Bethlehem Steel Company
ਲ ਲ	AK-110 - To Repair Two (2) Boilers
(A)	S. S. "Conrad Kohrs" - Cartage only
4582	Craig Shipbuilding Company - Long Beach
1	Berth #46 - S. S. "Norway Victory"
	To Repair Port and Starboard Boilers
4583	Hercules Forge Corporation
	Refractory Linings for Two (2) Forge Furnaces
l. = Ωl.	City of Claudel Charm Direct
4584	City of Glendale - Steam Plant
	Burner Wall Repairs - #2 Boiler Furnace
4585	Bothlohom Staol Company
4797	Bethlehem Steel Company S. S. "Wm. Prouse" - To Repair Galley Range
(A)	Repairs to Boiler
(B)	Repairs to Brick and Boiler Insulation
. (2)	Rogaria do Diron and Dorror Hibara dion
4586	Bethlehem Steel Company
)	S. S. "AK-137" - Repairs to Starboard Boiler
4587	Todd Shipyards Corporation
,	S. S. "Esso Montepelier" - Repairs to Port Boile:

per syraper e e acces	4588	Hodgson-Greene-Haldeman Shipbuilders
.,,	Maria de la companya	S. S. "Astoria" - Repairs to Galley Range
	4589	Kaiser Company, Inc., Iron & Steel Div Fontana Repairs to #2 Open Hearth
	4590	Martin Ship Service Co. S. S. "Wm. S. Grimes" - To Rebrick One (1) Galley
	per menter qui approprie desserve la resultant de la constitución de l	Range
	4591	Standard Shipbuilding Corporation
	na menenengijan valu der vy negogijaji iz Sido n	S. S. "Wallowa" Necessary Repairs to Two (2) Boilers
	4592	The Dicalite Company Repairs to No. 1 and #2 Furnaces
	<b>4</b> 593	Bethlehem Steel Company S. S. "Frederick C. Howe"
	(A)	Repairs to Port and Starboard Boilers Repairs to Galley Range
	4594	Bechtel-McCone Corporation  Standard Oil Company of Calif El Segundo  Boiler House No. 2  Repairs to Smoke Stack Breeching
	4595	Todd Shipyards Corporation  S. S. "Nehalem" - Repairs to Two (2) Boilers
	4596	Federated Metals Division, Amer. Smelting & Ref. Co.
	(A)	Repairs to #2 Brass Reverberatory Furnace Reline U. S. Furnaces

	4597	Todd Shipyards Corporation
<i>(</i> -	& <b>A</b> ′	S. S. "Tonto" - Repairs to Two (2) Boilers
	4598	Averill-Morgan Company, Inc Hollywood
		Repairs to Boiler
	4599	Craig Shipbuilding Company
13.5.8		S. S. "W. B. Ayer" - To Rebrick Galley Range
A.		
Specialist	4600	Bethlehem Steel Company
		M. S. "Anders Jahre" - To Rebrick Galley Range
(15 15 30		
	4601	Old Colony Paint & Chemical Company - Los Angeles
		To Reline Ball Mill
	4602	Standard Shipbuilding Corporation
į.		Berth #76 - Fireboat ST-164
		To Rebrick Galley Stove
	(A)	LST-343 - To Reset Fire Brick on Galley Range
	4603	Twentieth Century-Fox Film Corp Hollywood Studios
		Incinerator Repairs
	4604	Bethlehem Steel Company
		S. S. "Tanamo" - To Renew Brick in Scotch Marine Blr.
	(B)	To Rebrick Galley Range
	(C)	Port Boiler Repairs
	4605	San Diego Gas & Electric Co Sta. "B"
		To Rebuild Two (2) Furnaces, #21 and #24
)		
	Nov. 19	44
	4606	Bethlehem Steel Company
		S. S. "Greenville Victory" - To Repair Two (2) Blrs.

Repairs to Galley Range

(A)

4607	West End Chemical Company - Westend
	Borax Melting Furnace - Brickwork Repairs
4608	Morris P. Kirk & Son, Inc Los Angeles
	To Line Conveyor Chutes
(A)	To Reline Combustion Chamber
(B)	Blast Furnace Fume Line
4609	Bechtel-McCone Corporation
	Standard Oil Company of Calif El Segundo
	To Install Insulation&Brickwork _ #5 Crude Battery
-	
4610	California Shipbuilding Corporation - Terminal Island
	Repairs to Arch on #1 Shape Furnace in Plate Shop
(A)	Repairs to Two (2) Arches in Shapes Furnace #2 in Plate Shop
4611	C. C. Moore & Co. Engineers
**************************************	Pacific Coast Borax Co Boron
	Pipe Insulation
4612	Bethlehem Steel Company
	S. S. "George Luks" - To Repair Two (2) Boilers
Ones de la constant d	
4613	South Pacific Canning Company - Long Beach
	To Repair One (1) Dryer
· ·	
4614	Shell Oil Company, Inc Dominguez Refinery
And the state of t	Boiler House - Brickwork Repairs to #1 Boiler
martaux Non-recess	
4615	Shell Oil Company, Inc Wilmington Refinery
la di	Repairs to #3 Trumble Heater
(A)	To Repair Front and East Walls, Boiler #5

4616	Standard Oil Company of Calif El Segundo
);	To Rebuild Two (2) 18" Side Walls - Reformer Furnace #13, Battery #2, at Cracking Plant
1. (2 m	
4617	Stauffer Chemical Company - Dominguez Division  Acid Brick Lining in 72" dia. x 30'-0" Acid Storage
	Tank
4618	Smoot Holman Company - Inglewood To Rebuild Muffle Type Enameling Furnace
4619	Sunset Oil Company - Los Angeles
-	Main Street Tank Farm
	Refractory and Insulation Enclosure for One (1) Fired Heater
4620	The Petrol Corporation - Los Angeles - Bandini Blvd. Brickwork Repairs on #2 Still
4621	Wilshire Oil Company, Inc Norwalk Repairs to #2 and #4 Foster-Wheeler Boilers
4622	Southern Service Company, Ltd.
	San Bernardino Laundry - San Bernardino Repairs to Two (2) HRT Boilers
4623	American Potash & Chemical Corporation - Trona Pyrobor Furnace #2 - Brickwork Repairs
4624	Todd Shipyards Corporation
<i>)</i>	Operating under Contract with U.S. Navy Department,
	Plant of Los Angeles Shipbuilding & Drydock Corp.  S. S. "APA-157" - Repairs to Two (2) Boilers

4625	Bethlehem Steel Company
er	S. S. "Paul N. Gregg"
	Repairs to Two (2) Boilers
4626	The Fluor Corporation, Ltd.
egge eden grade en en en	Ohio Oil Company, South Coles Levee (near Bakersfield)
	Refractory and Insulation Enclosure for Two (2) 800
	h.p. Riley Boilers
4627	Rubber Reserve Company
	Shell Chemical, Div. of Shell Union Oil Corp., Agent
	Los Angeles - Torrance Plant
	To Repair American Arch, Seal off Floor and Caulk
	"X" Joints - Superheater Unit No. B-201-B
4628	Standard Shipbuilding Corp.
å . · ·	S. S. "Mission Carmel"
	Brickwork Repairs to both Boilers
1	
4629	India Paint and Lacquer Co Los Angeles
	To Repair Lining around Door in Ball Mill
4630	Standard Shipbuilding Corp.
	S. S. "George Clark" - Repairs to Two (2) Boilers
4631	Todd Shipyards Corporation
+ F	S. S. "Joseph Lane" - To Renew Floors of #1 Boiler
4632	Bethlehem Steel Company
	S. S. "Cape Henry" - To Repair Brickwork in Furn.
. w inf w	
	Pacific Coast Borax Co Boron
	To Rebrick Beik Furnace

	4634	Rubber Reserve Company
	A - Z	Southern California Gas Company, Agent
	,	Los Angeles - Miscellaneous Brickwork Repairs
	4635	Bethlehem Steel Company
		S. S. "Antelope Hills" - Repairs to Starboard Boiler
	1.6-6	
#	4636	Standard Shipbuilding Corporation
Q <sub>inj</sub>		S. S. "Christopher Gale"
		To Repair Two (2) Boiler Furnaces
2 2 3 10 2	4637	Defense Plant Corporation
<i>*</i> *	•	Bechtel-McCone Corporation
		General Chemical Company - El Segundo
		To Install 42" Carbon Brick Lining in 4' dia. x 24'
		high Vessel
		might vesser
	4638	Bathlaham Gtaal Gammana
	4030 & (A)	Bethlehem Steel Company
	•	S. S. "Peter Sylvester"
		Repairs to Two (2) Boilers and Brick Seal
	4639	Todd Shipyards Corporation
		S. S. "Joseph A. Holmes"
		Chrome Mortar on Walls of Port Boiler
	(A)	S. S. "Mission San Luis Obispo" - Close Access Doors
شي		
	4640	Bethlehem Steel Company
		LST-40 - Galley Range and Oven Repairs
	4641	General Electric Company
· )		White Heat Treating Company - Huntington Park
		To Reline Heat Treating Furnace
	4642	West Coast Shipbuilding & Drydock Co. /Boiler
		S. S. "Antelope Hills" - Repair Furn. Floor of Port

4643	C. C. Moore & Co. Engineers Pacific Coast Borax Company - Boron
en e	Dryer Furnace Brickwork
4644	Bethlehem Steel Company S. S. APA-115 - To Renew Plastic in Boiler Front
Conference and the conference of the conference	D. D. MARLEY - TO HOHE TEMBORS IN DOLLOW PROMO
4645	Todd Shipyards Corporation
	S. S. APA-114 - To Renew Brick in Four (4) Galley
	Ranges
(A)	To Patch Brickwork in Four (4) Boilers
4646	Standard Shipbuilding Corporation
	LST-476 - To Rebrick Galley Range
(A)	Brickwork Repairs to Donkey Boiler
4647	Standard Shipbuilding Corporation
	S. S. "Kellogg" - Repairs to Two (2) Boilers
(A)	Repairs to Galley Range
4648	Southern California Edison Company - Long Beach
	Brickwork Repairs - Boiler #54 - Boiler House #2
(A)	Furnace Brickwork Repairs to Boiler #50 in
	#3 Plant - Boiler House #3
(B)	Repair Furnace Walls - Blr. #37) Blr. House #2,
(C)	Repair Furnace Walls - Blr. #49) Plant #3
(D)	Repair Furnace Walls - Blr. #51 - Boiler House #2,
(E)	Repair Furnace Walls - Blr. #53 - Plant #3
(F)	Repair Furnace Walls - Blr. #53 - Blr. House #2, Plant #3
4649	Travis Milling Company - Blythe, Calif.
	Ardrier Furnace Brickwork
4650	Federated Metals Div., Amer. Smelting & Refining Co.

Repairs to #1 Brass Reverberatory Furnace

	4651	Todd Shipyards Corporation
e e	)	S. S. "H. C. Wallace"
		To Patch up and Brick Seal Boiler
	4652	Mohawk Petroleum Corporation - Bakersfield
		To Repair Unit #4
	1.00-127-0000	
8.5.8	Dec. 194	
diam's	4653	C. C. Moore & Co. Engineers
Print ST	To the second	Sylmar Packing Company - San Fernando
		One (1) B. & W. Class H2 #14 Boiler Setting
6 6 7		
	4654	Bethlehem Steel Company
	ACCESSORY SECTION	S. S. "El Salvador Victory"
	and the same of th	To Repair Starboard Boiler
	(A)	To Repair Port Boiler
	(B)	To Repair Galley Range
	· · · ·	
	4655	Coast Fishing Company - Wilmington
	-	To Repair One (1) Boiler
	4656	Shell Oil Company, Inc Bakersfield
	1	Ten Section Absorption Plant - Brickwork around
		N. G. E. Burners on Five (5) Heine Boilers
	4657	El Rey Products Co.
		To Rebuild Burner Tunnel in #3 Retort
	-	
	4658	Standard Shipbuilding Corp.
	THEFT	S. S. "De Galleia"
	arriver and the second	To Repair Port and Starboard Boilers

4659	Todd Shipyards Corporation
· Andrews	S. S. "John H. Rosseter" - To Brick Seal Firebox
	on #1 Boiler and to Install Access Door
(A)	To Clean and Brick Seal #2 Boiler
(B)	To Patch Brickwork in #2 Boiler
4660	Oil Field Construction Co.
	Naval Ordnance Testing Station - Inyokern
	Brickwork for Five (5) 299 h.p. Union Iron Works Blrs.
4661	Bethlehem Steel Company
	S. S. "Pendleton" - To Renew Firebox in way of Work
4662	Bethlehem Steel Company
	S. S. DM-33 - Repairs to #1 and #2 Boilers
1.770	
4663	Shell Oil Company, Inc Dominguez
	To Repair Insuline Pipe Lining at Catalytic Cracking Plant
4664	Standard Shipbuilding Corporation
	FS-202 - To Repair Firebox in Galley Range
4665	Standard Oil Company of Calif El Segundo
	To Rebuild South Side Wall, Unit #47
4666	The Fluor Corporation Ltd.
	Richfield Oil Corporation
	Rio Grande-Vinvale Refinery at Los Angeles
	Brickwork Repairs to DeFlores Heater, etc.
1.66	
4667	Bethlehem Steel Company
	S. S. AP-111 - Repairs to Firebox of #3 Boiler
(A)	To Renew Brickwork in Incinerator

4668	Southwest Paint Company - Los Angeles To Reline Pebble Mill
4669 (A)	Bethlehem Steel Company U. S. S. APD-18 - To Repair #1 and #2 Boilers To Repair Galley Range
4670 (A)	Bethlehem Steel Company  S. S. LST-218 - To Rebrick Fireboxes of Galley Range and Oven
(A)	To Rebrick Bake Oven
4671	Standard Shipbuilding Corporation  S. S. "Fort Donaldson"  Repairs to Firebox of Two (2) Boilers
4672	C. C. Moore & Co. Engineers  The Exchange Orange Products Co Ontario  Insulation and Brickwork -  One (1) Class FF15 No. 32 B. & W. Boiler
4673	Stauffer Chemical Company - Vernon  To Install 4½" Acid-Brick Lining in Tank
4674	Union Oil Company of Calif Wilmington  To Repair Fire Damage in Furnace B-3A of Unit #33
4675	Utility Electric Steel Foundry - Vernon Repairs to Annealing Furnace
4676 & (A)	Bethlehem Steel Company S. S. "Fort Dearborn" - Brickwork Repairs as necessary
4677	Industrial Manufacturers, Ltd Vernon Incinerator Brickwork

4678	Los Angeles Steel Casting Co Los Angeles II
· · · · ·	Repairs to Annealing Furnaces
4679	The Fluor Corporation Ltd.
	The Petrol Corporation - Los Angeles - Bandini Blvd.
	To Install Refractories and Insulation for One (1)
	12 million B.t.u. Petro-Chem Iso-Flow Heater
4680	Craig Shipbuilding Company - Long Beach
	U. S. S. LCI-803 - To Repair Galley Range Firebox
4681	Standard Shipbuilding Corporation
	S. S. "John Hoyt" - Hi-temp Wash on Two (2) Boilers
4682 -	West Coast Shipbuilding and Drydock Co.
	S. S. "Mission Capistrano"
	Repairs to Two (2) Watertube Boilers
4683	Todd Shipyards Corporation
	S. S. "Unatilla" - To Repair Two (2) Boilers
1.601	
4684	Todd Shipyards Corporation
	S. S. "John H. Tuttle" - To Repair Two (2) Boilers
1. 70-	
4685	Bethlehem Steel Company  Benefit to Trie (2) Beileng
	S. S. "Blackstock Ford" - Repairs to Two (2) Boilers
4686	Bethlehem Steel Company
4000	S. S. "L. P. St. Claire" - To Repair Boilers
4687	Bethlehem Steel Company
	U. S. S. AP-165 - To Repair Galley Ranges in Officers
	and Crew's Galleys

4688	Bethlehem Steel Company
( No. 11 )	M. V. "Tabian"
7	To Repair European and Lascar Galleys
4689	Southwest Steel Rolling Mills - Los Angeles 2
	Repairs to Billet Furnace
k 8	
<b>4690</b>	The Texas Company - Wilmington - Los Angeles Works
Situation of the state of the s	Repairs to Kellogg Heater Furnace of Pressure
5 (1) (2) (2) (2) (3) (4) (4) (4) (4) (4) (4) (4) (4) (4) (4	Pipe Still #2
one of the second of the secon	
4691	Oliver J. Olson & Co.
	S. S. "Whitney Olson" - To Rebrick Two (2) Boilers
4692	The Petrol Corporation - Los Angeles - Bandini Blvd.
	Brickwork Repairs - #4 Still
}	
4693	Consolidated Steel Corp., Ltd Shipbuilding Division
	Newport Beach - Boiler Brickwork on A. T. & S. F.
i	Railroad Tug Boat
4694	Standard Shipbuilding Corporation
•	S. S. "Callabee"
	Necessary Repairs to Two (2) Boilers
4695	Bethlehem Steel Company
4037	S. S. "I. N. Van Nuys"
	Necessary Repairs to Two (2) Boilers
4696	Bethlehem Steel Company
)	S. S. APA-49 - To Rebrick Three (3) Bake Ovens
(A)	Brickwork Repairs
(A)	To Rebrick Bake Ovens
(B)	To Rebrick Incinerators
(1)	Renew Firebrick and Insulation on #1 and #2 Boilers

4697	Todd Shipyards Corporation
	S. S. A0-27 - Necessary Repairs to Four (4) Blrs.
obligate de la contraction de	<u>ale Kalurapasa Nandasel Makalak Nandasel</u>
4698	Howes & Whitaker
	Southern California Gas Co., Butadiene Plant
	Insulation of Piping and Turbines in #1 Steam
	Exhauster Building
A	ben din and andre rather and a contract but the
Jan. 19	
4699	Bethlehem Steel Company
	S. S. "Comfort" (AH-6)
	Repairs to Boilers #1 and #2
(A)	Additional Brickwork on Boiler #3
4700	Bethlehem Steel Company
	S. S. "Mission San Rafael"
	To Repair Two (2) Boilers
	وكالمراوي والمراوي والمراوية والمتعالم والمراوي والمعاور والمراوي والمعاور والمراوية والمستكل
4701	Craig Shipbuilding Company
	S. S. "White Oak" - To Repair Two (2) Boilers
4702	El Rey Products Company
	Brickwork Repairs to Kettle #3
(A)	Rebuild Comb. Tunnel Heater #2
	Pacific Division
4703	Bendix Aviation Corporation - North Hollywood
	Repairs to Heat Treating Furnace
(A)	Brickwork Repairs to Box Brazing Furnace
	•
4704	California Portland Cement Co Colton
e de arcare Communicación	To Repair #10 Cooler
(A)	To Apply "Insulkote" to Kiln Boiler Setting
	March Processing
4705	White Heat Treating Co Huntington Park
	Repairs to #1 Lindberg Furnace

	4706	Crescent Towel & Linen Supply Co Los Angeles
1		Collins Boiler Brickwork Repairs
. }		
	4707	Todd Shipyards Corporation
		Berth #232-B - Terminal Island
		S. S. "McKitrick Hills" - Necessary Repairs to C
		(1) Boiler and Charles and April 1997
42 93 77		
Δ.	4708	Bethlehem Steel Company
Section 1		S. S. "Stephen G. Porter"
797 A CIT 108		To Renew Brickwork in Galley Range
ű Ç	(A)	S. S. "Tjibadak" - To Remove and Renew Brickwork in
		Galley Range
		in the second of
	4709	Todd Shipyards Corporation
		S. S. "Fort George"
		Necessary Repairs to Two (2) Boilers
		and the second of the second o
	4710	City of Burbank - Steam Plant
		To Rebuild Burner Walls in #1 Boiler
	4711	Standard Oil Company of Calif El Segundo
		9th Battery Crude Stills - Brickwork Repairs
	4712	Rubber Reserve Company
		Shell Chemical, Div. of Shell Union Oil Corp., Agent
		Los Angeles - Torrance Plant
		To Repair Rear Wall in Boiler #4
,	4713	Exeter Refining Company - Hynes Refinery
		HRT Boiler Setting
	4714	Filtrol Corporation - Vernon
		To Repair Air Heating Furnace and to Replace Brick-

work on Flash Dryer Furnace

	denical experiences	
	4715	Consolidated Steel Corporation - Wilmington
		To Repair Furnace in Blacksmith Shop
	4716	Craig Shipbuilding Company
	September 1	U. S. S. AP-149 - To Repair One (1) Boiler
1945		
1.700	4717	C. C. Moore & Co. Engineers
		U. S. Potash Company - Loving, New Mexico
		Insulation Work
	4718	Bethlehem Steel Company
		S. S. "Lookout Mountain" - To Repair Two (2) Furnaces
	And the second s	
	4719	Bethlehem Steel Company
		S. S. AP-13 - To Repair #1, #2, #3, & #4 Boilers
	(A)	To Repair Trash Burner
	AUTO-LIANNELLIANNELLIANNELLIANNELLIANNELLIANNELLIANNELLIANNELLIANNELLIANNELLIANNELLIANNELLIANNELLIANNELLIANNEL	
	4720	Standard Oil Company of Calif El Segundo
		10th Battery Crude Still #72 - Brickwork Repairs
	4721	C. F. Braun & Co.
		Union Oil Company of Calif Wilmington
		To Remove and to Replace Refractories in Treater
	and the second s	Thermofor Kiln
	obbodium.	
	4722	Stauffer Chemical Co Torrance
		Burner Brickwork
	O de la companya de l	
	4723	Modd Chinyonda Company
	4(4)	Todd Shipyards Corporation  S. S. "Mission San Jose" - To Repair Two (2) Blrs.
	telement of the second of the	D. D. MISSION DON SODS - TO Webatt 140 (5) Bits.
	h-o-b	Pathlaham Staal Commons
	4724	Bethlehem Steel Company
		S. S. "Iriquois" - To Repair Galley Range

	4725	Luer Packing Company - Vernon
	A See also Manager and a	To Renew Refractories for Leahy Burners in HRT Blr.
	4726	Craig Shipbuilding Company S. S. "Edwin Booth" To Install New Floor in Starboard Boiler
	(4)	
eč.	(A)	To Rebrick Galley Stove
일 항	(B)	Repairs to Port Boiler
90 2 - 1 - 1 - 1 - 1 - 2 - 3 - 3 - 3 - 3 - 3 - 3 - 3 - 3 - 3	4727	City of Glendale - Steam Plant #1 Boiler Baffle Repairs
ii Et	4728	Stauffer Chemical Co Torrance
	7 20	Insulation on Redler Feeder
	The Bouteroom of the I	Tilburg of oil Hearer Feeder
	4729	C. C. Moore & Co. Engineers  General Petroleum Corp Torrance Refinery
		Brick Setting and Insulation
		One (1) Class F-19 BB20/48 Integral Furnace Boiler
	4730	Bethlehem Steel Company
		S. S. "Inglewood Hills" - To Repair Two (2) Boilers
	4731	Standard Oil Company of Calif El Segundo
	:	7th Battery, #51 Vacuum Unit Crude Still -
		Furnace Brickwork Repairs
	4732	Foster Wheeler Corporation
		Standard Oil Company of Calif El Segundo
		Two (2) Foster Wheeler Boiler Settings
	4733	Bethlehem Steel Company
		S. S. "Winfield Stratton" - To Rebrick Galley Range

4734	Bethlehem Steel Company
	S. S. "Noble" - To Repair Firebox of #2 Boiler
4735	Bethlehem Steel Company S. S. "Mission Loreta" - To Patch Main Boiler
4736	Bethlehem Steel Company
	S. S. "Emba" - To Repair Two (2) Boilers
4737	Bethlehem Steel Company
	S. S. AP-112 - Repairs to Four (4) Boilers
4738	Bethlehem Steel Company
	S. S. APA-220 - To Repair Plastic Cone on Boilers
4739	Standard Shipbuilding Corporation
	S. S. "Walter A. Luckenback"
	To Repair #3 and #4 Boilers
4740	Craig Shipbuilding Company
	S. S. "George Midelmas"
	To Renew Galley Range Firebox Lining
4741	Todd Shipyards Corporation
	S. S. "John Cabot" - To Repair Two (2) Boilers
4742	Philadelphia Quartz Company - South Gate
	To Rebrick Checker Chamber Sodium Silicate Furnace
4743	Bell Oil & Refining Co Santa Maria
	Brick Settings for Two (2) ll'-0" dia. x 35'-0"
	long Asphalt Stills
4744	The Texas Company - Wilmington Refinery
	Brickwork Repairs to Furnaces & Flues of #3 Crude Uni

,

~ \	Union Oil Company of Calif Wilmington
	To Repair Ignition Arches in Lummus Treater Kiln
4746	Standard Shipbuilding Corporation S. S. "Franklin Lane -
٠ ١	Brick Seal and Brickwork Repairs to Boilers
4747	Standard Oil Company of Calif San Pedro, Marine Term.
4747	To Reline Firebox in #3 Boiler
4748	Fibreboard Products, Inc Vernon - Plant #3
	To Repair Baffle in #3 Boiler
haho	Chall Other Tax David and David
4749	Shell Oil Company, Inc Dominguez Refinery  Dubbs Unit #4 - Brickwork Repairs to Furnace
)	Dabbs onic #4 - Direkwork Repairs to Farnace
4750	Federated Metals Division, Amer. Smelting & Ref. Co.
	Repairs to #2 Reverberatory Furnace
4751	American Potash & Chemical Corp Trona
,,,	Brickwork - #1 Soda Ash Dryer Furnace
(A)	To Rebrick Chemical Potash Dryer Furnace Firebox
4752	West Coast Shipbuilding & Drydock Co.
	S. S. "Mission San Fernando" - To Repair Two (2) Blrs
4753	Craig Shipbuilding Company
	S. S. "Lyman Beecher" - To Repair Two (2) Boilers
4754	Standard Shipbuilding Corporation
	APA-223 - Repairs to Boilers
<b>3</b>	
4755	Craig Shipbuilding Company /Range S. S. "Whitney Olson" - To Clean Out & Rebrick Galley

C. F. Braun & Co.

4756	Leahy Manufacturing Company
	Philadelphia Quartz Co South Gate
Section 1. Control of the section 1. Control	Firebox Alteration - Shipping Board Boiler
September 1997	
4757	Southern Service Company Ltd.
Description of the state of the	Blue Bird Laundry - Los Angeles
	To Repair Burner Arches on Heine Boiler
4758	Standard Oil Company of Calif El Segundo
Novement of the state of the st	Pressure Still #10 - To Replace South End Wall
(A)	Extra Brickwork - Pressure Still #10
-	La sumania de la compania del compania de la compania del compania de la compania del compania de la compania del compania de la compania del compania d
4759	General Chemical Company - El Segundo
	Combustion Chamber and Duct Lining
	the state of the s
4760	New York Ohio Chemical Corp.
The second secon	affiliated with Stauffer Chamical Co Dominguez
general communication of the contraction of the con	To Reline One (1) 5' x 5' Acid Tank
(A)	Acid Brick Lining in One (1) 10" - 12" C. I. Ec-
- Total spring and the spring and th	centric Reducer
Guir ingeneral de la companya de la	
4761	Craig Shipbuilding Company
	S. S. "Sacketts Harbor" - To Repair Two (2) Boilers
4762	Craig Shipbuilding Company
•	
	S. S. "Quebec" - To Repair Two (2) Boilers
4763 -	Bethlehem Steel Company
Paulitinophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophilosophiloso	S. S. "Krasnia Armia" - To Repair Two (2) Boilers
4764	W. C. Hardesty Co., Inc Los Angeles
-	Repairs to Brick Arch in Still Firebox
(A)	To Repair Arch in Fatty Acid Still

The same of the sa

.

Feb. 19	9 <mark>45</mark>
4765	Todd Shipyards Corporation
	S. S. "Crater Lake" - Boiler Repairs
4766	California Shipbuilding Corporation - Terminal Islan
	To Repair Hearth in #1 Shapes Furnace
(A)	To Repair Hearth in #2 Shapes Furnace
4767	The Texas Company - Wilmington
	Fired Heater and Regenerator Lining Repairs
4768	Federated Metals Division, Amer. Smelting & Ref. Co.
	Repairs to #1 Reverberatory Furnace
(A)	Repairs to U. S. Furnace
(B)	To Reline U. S. Furnace
4769	Shell Oil Company, Inc Dominguez
	To Install Lientz Burner Tile in Dubbs #6 and #7
4770	Vegetable Oil Products Company, Inc Wilmington
	Schultz Hydrogen Generator - Brickwork Repairs
4771	Craig Shipbuilding Company
	S. S. "Alexander Baranoff" - To Repair Boilers
(A)	Galley Range Repair
4772	Oil Field Construction Co.
	Marine Corps Air Station - El Toro, Calif.
	Brickwork - Three (3) 400 h.p. Union Iron Works
	Water Tube Boilers
(A)	To Apply Plastic Coating to Exterior of Three (3)
	400 h.p. Union Iron Works Water Tube Boilers
4773	Bethlehem Steel Company
	S. S. "Pan Aruba" - Repairs to Two (2) Boilers

4774	Standard Shipbuilding Corporation
	S. S. APA-225 - To Repair Two (2) Boilers
	and has a superior and the superior of the sup
4775	C. F. Braun & Co.
S	Union Oil Company of Calif Wilmington
	To Repair Brickwork and Insulation in Treater
	Thermofor Kiln
4776	Harbor Boat Building Co Terminal Island
·	S. S. AK-161 - To Repair Boiler Fireside
4777	Bethlehem Steel Company
	S. S. "Stepas Darius" - To Rebrick Galley Range
4778	Todd Shipyards Corporation
	U. S. S. AP-120 - To Repair Four (4) Boilers
4779	Craig Shipbuilding Company
. <b>3</b> .∰. ∰	S. S. "Horace Greeley" - To Repair Two (2) Boilers
(A)	Repair Galley Range
Market aggregation strong transp	
4780	Harbor Boat Building Co Terminal Island
	AK-111 - To Repair Galley Range
4781	Bethlehem Steel Company
	S. S. "Cathwood" - To Repair Boilers
	· · · · · · · · · · · · · · · · · · ·
4782	Consolidated Steel Corporation - Terminal Island Repai
	S. S. "Chas. H. Windham" - To Rebrick Galley Range"
4783	Bethlehem Steel Company
na gara	S. S. "River Raisin" - To Repair Two (2) Boilers
4784	Bethlehem Steel Company
	S. S. "Telde" - To Repair Fire Brick in Five (5)
17.1	v and the second of the second

	4785	Standard Shipbuilding Corporation
		S. S. "Samuel Gompers" - To Repair Boilers
	4786	Todd Shipyards Corporation
		S. S. "Robert C. Greer" - To Repair Port Boiler
	4787	Standard Shipbuilding Corp.
		S. S. AP-101 - To Rebrick Bake Oven
*.	(A)	FS-213 - Galley Stove Firebox
	4788	Standard Oil Company of Calif El Segundo
	ੇ ਜ਼ਿਲ੍ਹੇ ਹੋ	Brickwork Repairs on #5 Rerun Furnace
	4789	Kaiser Industries
	7109	Fontana Shell Division
		To Rebuild Sidewalls of #2 Forging Furnace
	(A)	#3 Forging Furnace
	(B)	#1 Forging Furnace
	(C)	#4 Forging Furnace
	(0)	# 1018118 T 111100
	4790	The Mason Manufacturing Company - Los Angeles
		Repairs to Incinerator
	4791	Todd Shipyards Corporation
		S. S. "Fort Charlotte" - To Repair Boilers
	4792	Bethlehem Steel Company
		S. S. "Laurel Hills" - To Repair Two (2) Boilers
	4793	Todd Shipyards Corporation
		S. S. "Yam Hill" - Boiler Repairs
	4794	Bethlehem Steel Company
	£	S. S. "Greenville Victory" - Port Boiler

4795	Craig Shipbuilding Company
	S. S. "Frederick Billings" - Galley Range
SEA CARROLLING	
4796	Rubber Reserve Company
Aller open Materians and the control of the control	Southern California Gas Co., Agent - Aliso Street Plant
	To Insulate Misc. Piping at #1 Engine Room
(A)	ditto #1 Boiler Plant
(B)	#3 Boiler Plant
(C)	#1 Engine Room
(D)	" #2 Exhauster House & Yard
(E)	" #1 Engine Room
4797	Stauffer Chemical Co Dominguez Plant
	Combustion Chamber Brickwork
(A)	Insulation on Sulphur Tank, Air Ducts, Preheater and
	Burner Heads
4798	Stauffer Chemical Co Dominguez Plant
	Contact Sulphuric Acid Plant
	Acid Brickwork in Cooling Tower
	an say an anna ann an an an an an an an an an
4799	Standard Shipbuilding Corporation
	S. S. "Hadley" - Repairs to Boilers
4800	Craig Shipbuilding Company
	USMSTS "Wm. S. Scott" - To Reline One (1) Boiler
4801	Rubber Reserve Company
A to Z	Southern California Gas Co., Agent - Aliso Street Plant
	Miscellaneous Insulation Work
	A section of the sect
4802	Kaiser Company, Inc., Iron & Steel Division /Foundry
	Fontana - Lining for #11 20-ton Cupola in Ingot Mold
(A)	Lining for 40-ton Mixing Ladle for #11 20-ton Cupola
• •	

4803	Harbor Boat Building Company
	S. S. YMS-301 - To Repair Blr.
(A)	S. S. YMS-195 - To Repair Blr.
4804	Harbor Boat Building Co.
	AK-225 - Repairs to Galley Range
٥	
§ 4805	Bethlehem Steel Company
	S. S. DD-643 - Repairs to Boilers $\#1$ , $\#2$ , $\#3$ and
e e	
4806	Wilmington Welding & Boiler Works
र्ज हर	To Repair Boiler Firebox on dock at Berth #198
4807	Consolidated Steel Corporation, Ltd.
	Brickwork Repairs to Two (2) Boilers
	S. S. "Amos G. Throop"
(A)	Repairs to Galley Range
4808	Salt River Valley Water Users' Association
	Tempe, Arizona
	Repairs to Class "F" - B. & W. Boiler Setting
4809	Standard Shipbuilding Corporation
	S. S. "Mission Santa Ynez"
	Necessary Repairs to Boiler
4810	Craig Shipbuilding Company
	S. S. "Makawao"
	Necessary Repairs to Two (2) Boilers
LOTA	
4811	Todd Shipyards Corporation
	S. S. "Caribbean"
	Necessary Repairs to Two (2) Boilers

	4812	Consolidated Steel Corporation, Ltd.
		Hull #746 - Repairs to Boiler
	4813	United States Gypsum Co South Gate
		To Rebuild Front Arch in #3 Boiler
4800	4814	Wilmington Welding & Boiler Works
		S. S. AK-226 - To Repair Two (2) Boilers
	The state of the s	and the same of the same and the same of t
	4815	Consolidated Steel Corporation Ltd.
	With the second	S. S. "Ranier" - To Repair Two (2) Boilers
	and the second s	
	4816	Todd Shipyards Corporation
	Service Control of the Control of th	U.S.S. DM-16 - To Repair Two (2) Boilers
	4817	Todd Shipyards Corporation
		S. S. "Mission Capistrano" - Repairs to Main Blrs.
	(A)	Repairs to Starboard Boiler
	· Authority Control of the Control o	
	March 1	945
	4818	Harbor Boat Building Co.
	And production of the control of the	S. S. K-163 - To Repair One (1) Boiler
		A contract of the contract of
	4819	Bethlehem Steel Company
		S. S. "Pan Aruba" - To Repair Two (2) Boilers
	Monancia de la composición del composición de la composición de la composición del composición del composición de la composición del composición del composición de la composición del composición del composición del composición del composición del composición del c	
	4820	Bethlehem Steel Company
		S. S. "Wideawake" - To Repair Two (2) Boilers
	4821	Bethlehem Steel Company
		S. S. "John Goode" - To Repair Two (2) Boilers
	(A)	To Repair Galley Range
		y a salah di kacamatan kacamatan kacamatan kacamatan kacamatan kacamatan kacamatan kacamatan kacamatan kacamat
	T-4822	Superior Oil Company - Conroe, Texas
	(See T-511)	Lake Creek Recycling Plant - Boiler Covering Repairs

	T-4823 (See T-512)	Dickson Gun Plant - Houston, Texas  Hughes Tool Co., Operator  To Reline Two (2) Furnace Cars on Mahr Car Type  Normalizing Furnace #5 in Casting Shop
	4824	Harbor Boat Building Co.
225 9.5.A.	(A)	S. S. AK-110 - Brickwork Repairs to #1 Boiler S. S. AK-110 - To Repair Bake Oven
VOLEGIALIE ROMANISMO BISLA	4825	Todd Shipyards Corporation U. S. S. AP-115 - To Repair Four (4) Boilers
	4826	Riverside Cement Company - Oro Grande Hood and Cooler Brickwork for #4 Kiln
***	4827	Shell Oil Company, Inc Dominguez
	(A)	Brickwork Repairs - Dubbs #1 Brickwork Repairs - Dubbs #2
	4828	Bethlehem Steel Company U. S. S. "Egg Harbor" - To Repair Two (2) Boilers
	4829	U. S. A War Department  Post Engineer, Los Angeles Port of Embarkation  Building #232, Wilmington  Camp Ross (between Wilmington & San Pedro)  Installation of Brick Setting for One (1) #584  Kewanee Boiler for Land Based Training Ship
a	4830	Federated Metals Division, Amer. Smelting & Ref. Co.  Los Angeles - To Install Dampers in Aluminum  Reverberatory Furnace #3
	4831	Bethlehem Steel Company

S. S. "Fort Bridger" - Neces. Rprs. to Two (2) Blrs.

4832	American Potash & Chemical Corp Trona Brickwork Repairs - #16 Boiler
To a company of the second	
4833	Shell Chemical, div. of Shell Union Oil Corp., Agent
- I - I - I - I - I - I - I - I - I - I	Rubber Reserve Co Los Angeles - Torrance Plant
· · ·	Yarrow Boiler #6 Brickwork Repairs
4834	Standard Shipbuilding Corporation
	S. S. "Chalmette" - To Repair Two (2) Boilers
4835	Consolidated Steel Corp. Ltd Terminal Island Repair Yd.
	Blacksmith Forging Furnace
4836	
4030	Consolidated Steel Corp. Ltd Pico Yard - Long Beach
	Galley Ranges -
	Eleven (11) Hulls, Nos. 1226 thru 1236 incl.
1.0	
4837	West End Chemical Co Westend
	To Repair Pyroborate Furnace
4838	Bethlehem Steel Company
	S. S. "Hendry L. Hoyt" - To Repair Galley Range
	and the second of the second o
4839	Bethlehem Steel Company
	S. S. "Frenchtown" - Boiler Repairs
4840	Bechtel-McCone Corp.
	Rubber Reserve Company
	Standard Oil Co., Agent - El Segundo - Butadiene Plant
* * * .	Repairs to Houdry Reactors, Air Lines and Furnaces
4841	The Fluor Corporation Ltd.
	Wilmington Gasoline Co., Terminal Island, Wilm., Calif.
	Brick Setting for One (1) 72" x 18'-0" HRT Boiler

4842	Mohawk Petroleum Corporation - Bakersfield To Repair #2 Boiler Firebox Walls
(A)	Peephole Alterations - Navy Boiler
4843	Oil Field Construction Co.  Pacific Soap Company - San Diego  Brickwork - One (1) 260 h.p. Union Iron Works  Water Tube Boiler, Type "L"
4844	Shell Oil Company, Inc Dominguez F-W Toluene Preheater Brickwork Repairs
4845	Standard Shipbuilding Corporation  S. S. "Callabee"  To Close Access Doors and to Point up Boiler
4846	Bethlehem Steel Company S. S. "Frank H. Dodd" - Galley Range
4847	Bethlehem Steel Company S. S. "Telde" - To Repair Starboard Boiler
. 4848	Howes & Whitaker  Southern California Gas Co Ducommun Street Com-  pressor Station - Miscellaneous Piping Insulation
4849	Todd Shipyards Corporation S. S. "Coquille" - To Repair Two (2) Boilers
4850	Consolidated Steel Corp. Ltd Terminal Island S. S. "Skull Bar" - To Repair Two (2) Boilers
4851	Bethlehem Steel Company S. S. "Belle of the West" To Repair Insulation on Economizer Boxes

4852	Bethlehem Steel Company
	S. S. "Klamath Falls" -
	To Repair Two (2) Boiler Furnaces
4853	Standard Shipbuilding Corporation
	S. S. "Chapultepec" - To Repair Two (2) Boilers
4854	Oil Field Construction Co.
, 0, ,	Naval Air Station - San Diego
	Brickwork - Seven (7) 505 h.p. Type "0" Union Iron
	Works Bent Tube Water Tube Boilers
4855	Jack Leo Plumbing Co.
	Naval Convalescent Hospital - Banning
	Brick Base for Three (3) Economic Boilers
(A)	To Repair Linings in Three (3) Economic Boilers
(/	20 2102 Maria 200 (0) 2002 Maria
4856	Kaiser Industries - Fontana Shell Division
	To Replace Curb Tile in #3 Forging Furnace
(A)	To Rebuild #5 Furnace
(B)	To Rebuild #2 Forge Furnace
4857	Federated Metals Division, Amer. Smelting & Ref. Co.
900 o o o o	Repairs to Aluminum Reverberatory Furnace
(A)	To Reline U. S. Furnace with Magnesite Lining
(B)	Brass Reverberatory Furnace #1 Repairs
(C)	Slots in Bricks for Doors, #2 Furnace
4858	Craig Shipbuilding Company
	USCG "Pulaski"
	To Rebrick Furnace in Heating Boiler
4859	Rubber Reserve Company
	Shell Chemical, Div. of Shell Union Oil Corp., Agent Torrance Plant - Los Angeles - To Renew Rear Wall and Side Walls in #1 Yarrow Boiler

•

----

	4000	Shell Oll Company, Inc Dominguez
	,	To Repair Bridge Wall in #6 Boiler
	(A)	#4 Boiler - Brickwork Repairs
	4861	Bethlehem Steel Company
		S. S. "Cuba Victory" - To Repair Two (2) Boilers
2	4862	Bethlehem Steel Company
NA COL		S. S. "Cape Edmont" - To Patch up Boiler
1		
	4863	Consolidated Steel Corp. Ltd Terminal Island Repair
j		S. S. "Shabonee" - To Repair Furnace Lining
	4864	Bethlehem Steel Company
		S. S. "Clark Howell" - To Rebrick Galley Range
1		
1	4865	Richfield Oil Corp Watson Refinery, Watson
		Brickwork Repairs
	(A)	Brickwork Repairs - Vinvale Refinery
	4866	Consolidated Steel Corp Terminal Island
		DMS #3 - To Repair Two (2) Boilers
	(A)	To Rebrick Galley Range
	4867	Todd Shipyards Corporation
		U. S. S. APA-144 - To Repair Two (2) Boilers
	4868	Standard Shipbuilding Corporation
		S. S. "La Brea Hills" - To Repair Port Boiler
ì		
*	4869	Pittsberg Chemical Co Los Angeles
		Brick Lining for Glens Falls Combustion Chamber
	4870	Stauffer Chemical Co Deminguez
		Professoria Denoine - #10 Decomposer

4871	Craig Shipbuilding	Company
	USCG "Reliance"	- To Rebrick Galley Range

A Company of the Comp
1945
Wilmington Welding & Boiler Works
S. S. APA-81 - To Repair Boilers
S. S. APA-82 - Repairs
Harbor Boat Building Co.
YMS-184 - Boiler Repairs
Bethlehem Steel Company
S. S. "Schuyler Colfax" -
Brickwork Repairs to Right Oven of Galley Range
Boiler Repairs
Bethlehem Steel Company
S. S. "Jack Singer" - To Rebrick Galley Range
The Luer Packing Company - Vernon
Brickwork Repairs to #2 Boiler
Brickwork Repairs to #1 Boiler Setting
Hombon Poot Building Co
Harbor Boat Building Co.  LST-225 - To Repair Boiler
LST-1010 - To Repair Boiler
Stauffer Chemical Company - Vernon Plant
Acid Brickwork - Two (2) 72" x 24'-0" Tank Shell
• • • • • • • • • • • • • • • • • • • •
Bethlehem Steel Company
AkF-11 - Brickwork Repairs to Boiler
•
Bethlehem Steel Company
U. S. S. AK-136 - To Reline Two (2) Boilers

	4881	The Texas Company - Los Angeles Works, Wilmington
		Repairs to Stack Lining at #2 Crude Unit
,		
	4882	Hercules Forge Corp.
		To Rebrick 3'-6" Forge Slot Furnaces
3	4883	Sierra Steel Forging Company - Los Angeles
4.5.9 CENTRAL 8.5.4.		To Rebuild Brickwork 6 ft. x 9½ ft. Furnace
Salari Salari		
er 	4884	Defense Plant Corporation
		Western Electrochemical Co Henderson, Nevada
 		By: Bechtel-McCone Corporation
		Refractory Lining for Drying Machine Combustion
		Chember
)	4885	Aireon Manufacturing Corporation - Burbank
		To Reline Hard Chrome Tank
	(A) & (E	) To Reline Hard Chrome Tank
	1006	
	4886	Fluid Packed Pump Co Los Nietos
		18 ft. Cyanide Pot Furnace
	(A)	18 ft. Draw Pot Furnace
	(B)	Control Equipment
	l. 00	Garat Odla Definition Comments Trusteen Decision
	4887	Socal Oil & Refining Company - Huntington Beach
		Burner Brickwork - F. W. Heater
	4888	Can Diago Con a Electric Company Chating UDN
	4000	San Diego Gas & Electric Company - Station "B"
	(A)	Furnace Brickwork Repairs to #25 Furnace
	•	Brickwork Repairs to Furnace #26
٠	(B)	Brickwork Repairs to Furnace #27
	<b>4</b> 889	Consolidated Steel Corp Terminal Island
	4007	
		S. S. "Calibre" - Galley Range Repairs

4890	Hodgson-Greene-Haldeman Shipbuilders
	S. S. "Henry Wallace" - To Rebrick Galley Range
4891	Consolidated Steel Corp Wilmington
	Hulls 1307; 1310 to 1315, inclusive -
	Set Fire Tile and Brick in Galley Ranges
4892	Standard Shipbuilding Corporation
	S. S. "Fort Cornwallis"
	To Repair Brickwork in Two (2) Boilers
4893	Bethlehem Steel Company
	S. S. "White Swallow" - Repairs
(A)	S. S. "Neptune's Car" - To Repair Two (2) Boilers
4894	Standard Shipbuilding Corporation
	S. S. "Wm. McGuffey" - To Repair Two (2) Boilers
(A)	To Rebrick Galley Range
4895	Standard Shipbuilding Corporation
	FS-396 - To Patch Brickwork in Boiler Firebox
(A)	FS-356 - To Patch Galley Range
4896	California Portland Cement Co Colton
	To Repair #10 Kiln Stack Base
4897	The Contracting Engineers Co.
	Sunset Oil Co. Refinery - Wilmington
	Settings for Two (2) 85 h.p. Kewanee Firebox Boilers
(A)	To Brick up Skirt on Fractioning Power (for
	Sunset Oil Company direct)
<b>4</b> 898	Bethlehem Steel Company
	S. S. "Conrad Kohrs" - To Repair Two (2) Boilers

	4099	Southwestern Engineering Company
	•	The Harshaw Chemical Company - El Segundo
j		Brickwork Enclosure for One (1) Antimony Smelter
	4900	Stauffer Chemical Co., Dominguez Division - Dominguez
		Lining SO <sub>2</sub> Steel Flues and Installing Dampers
TANDE U.S.A.	4901	Stauffer Chemical Co., Dominguez Division, Dominguez Acid Brickwork for Four (4) Filter Boxes
n:	4902	Bethlehem Steel Company
동 한	,,,,,	U. S. S. AP-112 - To Repair #1, #2 and #4 Boilers
	4903	Bethlehem Steel Company
		S. S. "Mission San Antonio" -
1		To Repair Two (2) Boilers
ì		
	4904	Consolidated Steel Corporation - Terminal Island
		S. S. "John Swett" - To Repair Two (2) Boilers
	(A)	Brickwork Repairs to Galley Range and Oven Linings
	4905	Harbor Boat Building Company
		S. S. "Nancy Hanks" - Brickwork Repairs to Galley /Range
	4906	Great Lakes Carbon Corporation - Dicalite Division
		Walteria - Repairs to Rotary Kiln Lining
	U.	
	4907	English & Lauer, Inc.
		Naval Ordnance Test Station - Inyokern
)		Brick Settings for Three (3) Economic type #126 Boilers
	4908	Bethlehem Steel Company
		S. S. "John Parker" - To Patch Doors of Boiler

	4909	Howes & Whitaker
		Union Oil Company - Wilmington
	Andrew Commencer	Erection of Brick Walls for One (1) Storage Room
	4910	Standard Oil Company of Calif El Segundo
		Brickwork - Two (2) End Walls #9 Pressure Still
	(A)	To Rebuild Six (6) Openings in #9 Unit Furnace
4 ac		
	4911	Bethlehem Steel Company
	September Septem	S. S. "Wm. M. Stewart" - Galley Range Repairs
	(A)	To Repair Fireboxes of Boilers
	rio del	
	4912	Bethlehem Steel Company
	Section Control of Con	S. S. "Apsheron" - To Repair Galley Range Ovens
	4913	Bethlehem Steel Company
	· /—)	U. S. S. APA-64 - To Rebrick Ovens
	(A)	To Repair Two (2) Boilers
	Superior Control Contr	
	4914	Craig Shipbuilding Company
	guarante de la constante de la	S. S. "Mission San Diego" - To Repair Two (2) Boilers
	Printerno Artificia	o. b. iiinozoii bado io iiopaza iio (a, bolimozo
	4915	Standard Shipbuilding Corporation
		S. S. "Mission Loreto" - To Repair Two (2) Boilers
		D. D. Franklin more to tropout the (m) between
	4916	Kaiser Industries - Fontana Shell Division
	~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~	To Repair Burner Arches in #1 Forging Furnace
	(A)	To Repair Hearth in #1 Furnace
	h-07.5	Maria and a Company of the Company o
	4917	Wilson & Co., Inc Los Angeles
	/ 4 \	To Retile Burner Arch - Connelly Boiler #2
	(A)	Boiler #1 Repairs
		and the second of the second o
	4918	Bethlehem Steel Company
	A Company of the Comp	S. S. "Horseshoe" - To Repair Boiler

	4919	Todd Shipyards Corporation
		S. S. "A. C. Rubel" - To Repair Two (2) Boilers
	4920	Lohman Bros.
		Marine Corps Air Station - Miramar
		Fire-Brickwork - Prox Boiler
,		
U.S.A	4921	Lohman Bros.
		Marine Corps Air Station - Mojave
er er		Brickwork - Two (2) #124 Erie City Boilers
2 3 2 3 2 3		
é	4922	Bethlehem Steel Company
		M. B. "Roseville" - To Repair Donkey Boiler
	4923	Standard Shipbuilding Corporation
ì		S. S. "Perote" - To Repair Two (2) Boilers
	4924	Consolidated Steel Corp Terminal Island
		APA-85 - To Repair Two (2) Boilers
	1.00=	
	4925	Harbor Boat Building Co.
		LST-1108 - Brickwork Repairs to Bake Ovens
	4926	Standard Ail Co. of Colif Co. Dadre Marine Marriage
	4720	Standard Oil Co. of Calif San Pedro, Marine Terminal Brickwork Repairs - Boiler #2
		pricymory websits - poits: #5
	4927	Bethlehem Steel Company
*****	/ ţ	S. S. "Muncie Victory" - To Repair Boiler
	4928	Bethlehem Steel Company
	, ,	U. S. S. A0-75 - To Repair Two (2) Boilers
	(A)	To Repair Incinerator
	4929	Todd Shipyards Corporation
	/ -/	S. S. "Esso Buffalo" - To Repair Two (2) Boilers
		The state of the s

4930	Wilmington Welding & Boiler Works S. S. "Corinth" - To Repair Two (2) Boilers
4931	Union Oil Co. of Calif Wilmington  TCC Unit - Brickwork Repairs to Kiln
4932	Standard Shipbuilding Corporation FS-228 - To Rebrick Galley Range
4933	Bethlehem Steel Company S. S. "H. W. Wiley" - To Repair Port Boiler
4934	Mead Johnson & Co Torrance  To Replace Brick Lining in #121 Economic Boiler
(A)	To Replace Firebrick Lining and Carborundum Floor in Boiler Firebox
4935	Hodgson-Greene-Haldeman Shipbuilders S. S. "Hat Creek" - To Repair Two (2) Boilers
4936	Wilmington Welding & Boiler Works S. S. AK-178 - To Repair Boiler
4937	Anaheim Citrus Products - Anaheim To Repair Drying Furnace
May 1945	
4938	Bethlehem Steel Company
	S. S. "A. B. Hammond" - To Rebrick Galley Range
4939	Bethlehem Steel Company
(A)	S. S. "Chief Joseph" - To Repair Boilers To Rebrick Firebox of Galley Range

	4940	H. W. Loud Machine Works - Pomona
	*	Acid Brickwork in Tanks
	4941	Rubber Reserve Company
		Shell Chemical, Div. of Shell Union Oil Corp., Agent
		Torrance Plant - Los Angeles
		Butadiene Heater B-202-A Repair
	(A)	B-201-B Superheater Repairs to Roof Arch
	4942	Stauffer Chemical Company - Torrance
		Insulation Repairs on Experimental Plant
	4943	Stauffer Chemical Company - Dominguez Division
		To Remove Insulation and Reinsulate Decomposer
		Shells Nos. 1, 5, 6, 7, 8, 9, 10
i		
	4944	Federated Metals Division, Amer. Smelting & Ref. Co.
		Los Angeles - Repairs to #2 Brass Reverberatory Furn.
	4945	Southwestern Engineering Co.
		The Harshaw Chemical Co El Segundo
		To Construct One (1) 1,500,000 B.t.u. Air Heating
		Furnace
	4946	Standard Shipbuilding Corporation
		S. S. "Bunker Hill" - To Repair Two (2) Boilers
	4947	Standard Shipbuilding Corporation
	,	S. S. "Fort George" - To Repair Two (2) Boilers
	(A)	YMS-268 - To Reline Combustion Chamber
	4948	Todd Shipyards Corporation
	-	U. S. S. APA-52 - To Rebuild Two (2) Boilers

4949	Agicide Laboratories Inc Los Angeles
	Repairs to Dryer Furnace
4950	Standard Shipbuilding Corporation
+ \$1.00 mm.	S. S. "Pinnacles" - To Repair One (1) Boiler
4951	Consolidated Steel Corp.
	S. S. "Sea Snipe" - To Repair Two (2) Boilers
4952	Consolidated Steel Corp.
	APA-86 - To Repair Two (2) Boilers
4953	Wilmington Welding & Boiler Works
	APA-123 - To Repair One (1) Boiler
4954	Tide Water Associated Oil Co., Associated Division
*	Watson - Repairs to Brick Lining in Stack
4955	Standard Shipbuilding Corporation
	S. S. "Apache Canyon" - To Repair Two (2) Boilers
	The state of the s
4956	Wilmington Welding & Boiler Works
	AP-120 - To Repair Two (2) Boilers
4957	Bethlehem Steel Company
	S. S. "Champeeg" - To Repair Two (2) Boilers
4958	Bethlehem Steel Company
	S. S. "Mission San Antonio" - To Repair One (1) Boiler
4959	Craig Shipbuilding Company
	S. S. "Mission Santa Barbara" - To Repair Two (2)
	Boilers

	4960	Rubber Reserve Company
		Shell Chemical, Div. of Shell Union Oil Corp.
		Los Angeles - Torrance Plant
		Repairs to #2 Yarrow Boiler
,	4961	Consolidated Steel Corp Repair Yard
U, S. A.		S. S. "Robin Wently" - To Repair Two (2) Boilers
<u>A</u>	4962	Bethlehem Steel Company
		S. S. "John Lykes" - To Repair Starboard Boiler
6 6	4963	Union Oil Co. of Calif Wilmington Refinery
		Crude Still #45 - Brickwork Repairs
	4964	Consolidated Steel Corp Pico Repair Yard
)		S. S. APA-87 - To Repair Two (2) Boilers
	4965	Consolidated Steel Corp Pico Repair Yard
		AK-138 - To Repair Two (2) Boilers
	4966	Bethlehem Steel Company
		U. S. S. AKA-67 - To Repair Fireboxes of #1 and
		#2 Boilers
	(A)	Incinerator Repairs
	4967	Bethlehem Steel Company
		S. S. "Dolly Madison" - Galley Range
	4968	Bethlehem Steel Company
į		S. S. "Marshfield Victory"
		To Rebrick Firebox of Galley Range.
	(A)	To Repair and Patch Boilers

4969	Harbor Boat Building Co.
	LST-38 - To Repair Oven and Galley Range
(A)	To Repair Boiler
	Application of the contract of
4970	Standard Shipbuilding Corporation
	S. S. "Montezuma Castle" - Repair Two Boilers
(A)	S. S. "Henry S. Sanford" - To Rebrick Galley Range Firebox
4971	Todd Shipyards Corporation
apar na Banghari ya ki ki ki ki ki ki	U. S. S. AO-85 - Necessary Repairs to Two (2) Boilers
4972	Sterling Laundry, Inc Los Angeles
	To Repair Front Wall of HRT Boiler
4973	New York Ohio Chemical Corp Dominguez
	Affiliated with Stauffer Chemical Company
	Acid Brickwork Repairs
4974	Todd Shipyards Corporation
	S. S. "Mission Purisima"
	Necessary Repairs to Two (2) Boilers
· · · · · · · · · · · · · · · · · · ·	
4975	Reconstruction Finance Corp., Office of Rubber Reserve
(A - Z)	Southern California Gas Company, Agent - Los Angeles
	Miscellaneous Insulation Repairs
1.00	
	1 20 - 3 3 CG- f 2 C
4976	Todd Shipyards Corporation
4970	Todd Shipyards Corporation  S. S. "New London" - To Repair Two (2) Boilers
	S. S. "New London" - To Repair Two (2) Boilers
4976	S. S. "New London" - To Repair Two (2) Boilers Bethlehem Steel Company
	S. S. "New London" - To Repair Two (2) Boilers  Bethlehem Steel Company  S. S. "Northfield" - To Repair Boilers
4977	S. S. "New London" - To Repair Two (2) Boilers  Bethlehem Steel Company  S. S. "Northfield" - To Repair Boilers
	S. S. "New London" - To Repair Two (2) Boilers  Bethlehem Steel Company  S. S. "Northfield" - To Repair Boilers

	4919	Bethlenem Steel Company
}	,	APA-36 - To Repair Two (2) Boilers
	(A)	Bake Oven Repairs
	(B)	To Repair Incinerator
	•	
	4980	Wilmington Welding & Boiler Works
		APA-58 - To Repair Two (2) Boilers
, , ,	(A)	To Repair Oven Fireboxes
1000		
K.	4981	Stauffer Chemical Company - Dominguez Division
  		Waste Heat Boiler Brickwork Repairs
į		
	4982	Standard Shipbuilding Corporation
		S. S. "Sinclair Rubilene" - To Rebrick Galley Range
· control of	4983	Standard Shipbuilding Corporation
		S. S. "Celilo" - To Repair Two (2) Boilers
	(A)	YF-54 - To Repair Boiler
	4984	Consolidated Steel Corp Repair Yard
		LSM-261 - To Repair Galley Range (Work not Done)
	(A)	S. S. "Samuel Brannon" - To Repair Galley Range
	4985	Bethlehem Steel Company
		S. S. "Katrina Luckenbach" - To Repair #1 & #3 Blrs
	4986	Rubber Reserve Company
		Shell Chemical, Div. of Shell Union Oil Corp.
		Los Angeles - Torrance Plant
1		To Renew Side and Rear Walls, #5 Yarrow Boiler
	1 - 0	
	4987	Southwestern Engineering Company
		The Harshaw Chemical Company - El Segundo
		Flash Roaster - Brick Enclosure
	(A)	Eight (8) Access Doors

	·
4988	Southwestern Engineering Company
•	The Harshaw Chemical Company - El Segundo
	Two (2) Refining Furnace Linings
(A)	Converter Furnace - To Install Refractory and
	Insulation Lining
4989	Reconstruction Finance Corp., Office of Rubber Reserve
	Southern California Gas Company, Agent - Los Angeles
	No. 1 Generator Plant - Brickwork Repairs
	the state of the s
4990	Consolidated Steel Corporation
	S. S. "Fallen Timber" - To Repair Two (2) Boilers
4991	Craig Shipbuilding Company
	U. S. S. LST-486 - To Rebrick Galley Range
(A)	To Repair Bake Oven
4992	Bethlehem Steel Company
	S. S. "Mission Santa Ynez" - To Repair Two (2) Blrs.
4993	C. C. Moore & Co. Engineers
	Radio Corp. of America
	RCA Victor Division - Hollywood
	Brick Setting - One (1) Class H2 #10 Sterling Boiler
Section 1	
4994	Southern Service Company, Ltd.
	Blue Seal Linen Supply - Los Angeles
9	Renew Ignition Arch and Repair Wear Wall
4995	Bethlehem Steel Company
	U. S. A. T. "Marigold" - Galley Range Repairs
(A)	Seal around Ranges
(Al)	Seal Cover Plates around Galley Range Frame

	4996	Standard Shipbuilding Corporation
1	,	S. S. "William H. Halsted" - Repairs to Two (2) Blr
€	(A)	Repairs to Galley Range
	4997	Standard Shipbuilding Corporation
		S. S. "Edwin Abbey" - Repair Galley Range Brickwork
	4998	Wilmington Welding & Boiler Works
		To Repair Stationary Boiler on Dock
	4999	American Brazing Company - Los Angeles
		To Install Lining in G-E Brazing Furnace
T	-5000 (See T-513)	J. T. Thorpe, Inc Houston Office, Texas Office Expense
)	5001	Todd Shipyards Corporation S. S. "Mission Santa Cruz" - To Repair Two (2) Blrs
	5002	Standard Shipbuilding Corporation
		S. S. "Kingsport Victory"
		To Repair Two (2) Boilers
	5003	Hodgson-Greene-Haldeman Shipbuilders
		PCA-868 - Repair Brickwork in Cyclotherm Steam
		Generator
	5004	Consolidated Steel Corporation
		APA-88 "Presidio" - To Repair Two (2) Boilers
	5005	Consolidated Steel Corporation
		AO-76 - To Repair Two (2) Boilers
	(A)	To Repair Incinerator Brickwork

	nice production of the contract of the contrac	
	5006	Kaiser Industries - Fontana Shell Division
	and the second s	To Repair Burners - #3 Furnace
	(A)	To Repair Burners - #4 Furnace
	(B)	To Repair Burners - #5 Furnace
	(c)	To Repair Burners - #1 Furnace
	(D)	To Repair Burners - #2 Furnace
Mary and a second		
	5007	Standard Oil Company of Calif El Segundo
0(		To Repair Boiler #45 in #3 Boiler House
	American ex	
	5008	Standard Oil Company of Calif El Segundo
		Repairs to Rerun Still #5
	5009	Standard Shipbuilding Corporation
		S. S. "Schenectady" - Repairs to Two (2) Boilers
	5 <b>01</b> 0	Consolidated Steel Corporation
0	* 1. <sup>1</sup>	AVP-7 - To Renew Two (2) Boilers
of the last of the	4	
TOW CONTRACTOR COMME	5011	Federated Metals Division, Amer. Smelting & Ref. Co.
		Los Angeles - To Reline U. S. Furnace
articomethological		
1000	5012	Standard Oil Company of Calif El Segundo
Table Control of the		To Repair Boilers #11 and #12 in #1 Boiler House
00000		
and the same	5013	White Heat Treating Company - Huntington Park
	· // //	To Repair Electric Furnace
2000	(A)	To Repair Vestibule of Furnace
a de la composición dela composición de la composición de la composición dela composición dela composición dela composición de la composición dela composición de la composición dela composición del composición dela comp		
O Hill the research that shall de-	5014	Standard Shipbuilding Corporation
Antonio Godina Materia		S. S. LST-647 - To Repair Galley Stove
orio manufallo rico		
le y 1000 semble manuel	5015	Wilmington Welding & Boiler Works
refilling descentations		S. S. AP-143 - To Repair Galley Stove
·		

	Soro	perurenem Steel Company
Ý s		S. S. "Mission San Antonio" - To Repair Port Blr.
	5017	City of Glendale - Steam Plant
		Burner Wall Repairs - #1 Boiler
	5018	Travis Milling Co Blythe
52		To Install One (1) Heil Ardrier Furnace
R TREFFERD U.S.A.		
Ħ a:	5019	The Luer Packing Company - Vernon
2 2 60 50	4	#3 Boiler Furnace Brickwork Repairs
25		
	5020	Sierra Steel Forging Co Los Angeles
		Brick Setting - Forge Furnace
	(A)	Repair Brick Setting on Forge Furnace
	-	
,	5021	Rubber Reserve Company
		Shell Chemical, Div. of Shell Union Oil Corp., Agent
		Torrance Plant - Los Angeles
		To Rebrick #8 Yarrow Boiler
	5022	Bethlehem Steel Company
		S. S. "Dona Nati" - To Repair Galley Range
	<b>=000</b>	
	5023	Standard Shipbuilding Corp.
		S. S. "Darling" - To Repair Galley Range
	5024	Wilmington Welding & Boiler Works
	/ a \	S. S. A0-54 - To Repair Bake Oven and Range
)	(A)	To Repair Four (4) Boilers
	EAGE	Hodd Chimmonda Communities
	5025	Todd Shipyards Corporation
		S. S. Wm. H. Clagett" - To Repair Two (2) Boilers

5026	Bechtel-McCone (Incorporated)
. y Tamba at an a	Western Electrochemical Company - Henderson, Nevada
	Brickwork and Insulation Lining -
	Three (3) Dryer Furnaces
	Addition In the Edition of the State of
5027	Martin Ship Service Co Wilmington
	To Repair Gas Generating Boiler
June 194	<u>5</u>
5028	Oil Field Construction Co.
	Shell Oil Company, Inc Dominguez Refinery, Watson
	Enclosure for Two (2) F-W Waste Heat Boiler
(A)	Brickwork Repairs to Waste Heat Boiler
5029	Richfield Oil Corp Watson Refinery
	Brickwork Repairs to T. C. C. Unit #1, Stripper
	Tower and #4 Oxidized Asphalt Still
5030	Los Angeles Steel Casting Co Los Angeles 11
	To Repair Car Type Annealing Oven #2
5031	C. F. Braun & Co.
	Robt. S. Lytle, Operator - Coalinga, Calif.
	Fired Heater
	• • • • • • • • • • • • • • • • • • •
5032	Richfield Oil Corporation
	Tanker "Chas. S. Jones" - To Repair Galley Range
5033	Consolidated Steel Corporation - Pico Yard
	S. S. APA-104 - To Repair Two (2) Boilers
5034	California Metal Enameling Co Los Angeles
4	To Repair Burner Port - Large Enameling Furnace

....

	5035	Consolidated Steel Corporation
)	•	S. S. "Mission Capistrano" - To Repair Two (2) Blrs
	5036	Fibreboard Products Inc Vernon - Plant #2 Brickwork Repairs - Boilers #1 and #2
E USA	5037	Stauffer Chemical Company - Torrance Insulation Repairs on Experimental Plant
	5038	Todd Shipyards Corporation  S. S. "Castle Pinckney" - To Repair Two (2) Blrs.
	5039	Wilmington Welding & Boiler Works  LST-731 - To Rebrick Bake Oven and Galley Range
,,100%	5040	Bethlehem Steel Company U. S. S. DD-445 To Rebuild Boilers #1, #2, #3, and #4
	5041	Standard Shipbuilding Corporation  S. S. "Platt Park" - To Repair Two (2) Boilers
	5042	Standard Shipbuilding Corporation  S. S. "Camp Namamu" - To Repair Two (2) Boilers
	5043	Craig Shipbuilding Company U. S. S. LST-486 - To Rebrick Cleaver-Brooks Boiler
į	5044	Todd Shipyards Corporation  S. S. "Esso Buffalo" - To Repair Two (2) Boilers
	5045	Pacific Clay Products - Los Angeles To Rebuild Bag Walls in Periodic Kiln

5046	Reconstruction Finance Corp., Office of Rubber Reserve
all real back of an a first	Southern California Gas Company, Agent
The contract of the contract o	Los Angeles - Aliso Plant
	Insulate Piping for Purifiers G, H, I, J, & K
5047	Kaiser Company, Inc., Iron & Steel Division - Fontana
	Blast Furnace Stove #1 - Brickwork Repairs
(A)	Repairs to Blast Furnace Stove #3
T-5048	Jefferson Lake Sulphur Co., Inc Long Point, Texas
(See T-514	One (1) Class HIV No. 28 B. & W. Boiler Enclosure
5049	W. P. Fuller & Co. (Paint Factory) - Los Angeles
and a Program of the late of the	Repairs to Ball Mill Lining
5050	General Chemical Company - El Segundo
	Brick Lining in 10" Pipe
(A)	Acid Brick Lining in Sewer Junction Boxes
5051	Goodyear Tire and Rubber Company of California
	Los Angeles - To Repair #2 Boiler
5052	Goodyear Tire and Rubber Company of California
	Los Angeles - To Repair #3 Boiler
5053	Bethlehem Steel Company
	U. S. S. AP-147 - To Repair Three (3) Galley Ranges
5054	Standard Shipbuilding Corporation
	S. S. "Edward L. Grant" - To Repair Brickwork of
(A)	To Repair Galley Range /Boilers
	Company of the compan
5055	Reconstruction Finance Corporation, Office of Rubber Res.
	Southern California Gas Co., Agent - Aliso Street Station
(B)	Repair Generators 18A and 18B Brickwork Repairs Generators 18A and 18B

	5056	Southern Service Company, Ltd.  Valley Linen Supply - San Bernardino  To Repair B. & W. Boiler Setting
	5057	Bethlehem Steel Company
		U. S. S. DD-643 - Repairs to Brickwork on Four (4) Boilers
U.S.A	(A)	Repairs to Boilers (4), Superheater Sides and to
4		Replace Rear Wall of Superheater Side of #4 Boiler
H	(B)	Additional Repairs
1 h		
é	5058	Bethlehem Steel Company
		AP-147 - To Repair One (1) Boiler
	5059	Kaiser Company, Inc., Iron & Steel Division - Fontana
		Repairs to 800-ton Hot Metal Mixer
,		
	5060	English and Lauer, Inc.
		Ryan Aircraft Company - San Diego
		To Install Three (3) Fireboxes in Pacific Boilers
	5061	Stauffer Chemical Company, Dominguez Division -
		Dominguez - Surge Tank Acid Brick Lining
	5062	Morse Boulger Destructor Co.
		U. S. Naval Hospital - Long Beach
		Incinerator Alterations and Repairs
	5063 .	Todd Shipyards Corporation
)		S. S. "James Rolph" - To Repair Two (2) Boilers
	5064	Bethlehem Steel Company
	-	U. S. S. AP-150 - To Repair Two (2) Boilers

.

T-5065 (See T-515)	Brown Shipbuilding Company, Inc Houston, Texas Boiler Settings	
5066	Craig Shipbuilding Company	
	U. S. S. ATO-140 - To Repair Two (2) Boilers	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
(A)	To Rebrick Galley Range	
5067	Agicide Laboratories Inc Los Angeles	
And the second second second second	Repair Dryer Furnace	
5068	Swift & Company - Vernon	
,,	C-E Boiler - Brickwork Repairs	
		`
5069	Shell Chemical, Div. of Shell Union Oil Corp.	
	Dominguez - Repairs to Acid Concentrator	
	A Line State of the State of th	
5070	Consolidated Steel Corporation	
	APA-56 - To Repair Two (2) Boilers	
(A)	Galley Range Repair	
5071	Consolidated Steel Corporation	
	APA-1 - To Rebrick Two (2) Boilers	
5072	Pipe Specialty Co Newport Beach	
	LST-488 - To Rebrick Boiler	
	The second secon	
5073	Standard Shipbuilding Corporation	
	USA-7 "Octorara"	
	To Repair Port and Starboard Boilers	
(A)	To Repair Galley Range Brickwork	
5074	Hercules Forge Corporation - Los Angeles	
	4'-0" Slot Type Forge Furnace	

5075	Bethlehem Steel Company
* ***	S. S. "Henry R. Schoolcraft"
	To Rebuild Galley Range
5076	Bechtel-McCone (Incorporated)
	Shell Oil Company, Inc Martinez
	Crude Oil Heater
5077	The Exchange Orange Products Co Ontario
	To Install Refractories and Insulating Materials
	for One (1) Heil "Ardrier" Furnace
5078	Rubber Reserve Company
	Shell Chemical, Div. of Shell Union Oil Corp.
	Torrance Plant - Los Angeles
	To Rebrick #7 Yarrow Boiler
<b>5</b> 079	Consolidated Steel Corporation
	LSM-261 - To Rebrick Boiler
5080	The Texas Company - Wilmington
	Repairs to Oil Heater at Pressure Pipe Still #1
5081	Union Oil Company of California - Wilmington
	Brickwork Repairs to Treater Kiln at T. C. C. Pla
5082	Reconstruction Finance Corp., Office of Rubber Reserv
	Southern California Gas Company, Agent
	Los Angeles - Macy Street Station
	Insulation Repairs
5083	Bethlehem Steel Company
	S. S. "Fremont Older" - To Repair Two (2) Boilers
(A)	To Repair Galley Range
. ,	••• •• •• •• •• •• •• •• •• •• •• •• ••

5084	Bethlehem Steel Company	
mare in the term	S. S. "Robert LaFollette" - To Repair Port Boiler	
(A)	To Repair Starboard Boiler	
5085	Bethlehem Steel Company	
	DD-859 - To Repair Boiler	
5086	Wilmington Welding & Boiler Works	
	LST-222 - To Renew Boiler Brickwork	
. Lauren		
5087	Standard Shipbuilding Corporation	
	SS-344 - To Rebrick Galley Range	
5088 .	Rubber Reserve Company	2
	Southern California Gas Company, Agent	
	Los Angeles - Ducommun Street Station	1
	To Repair Insulation	1
5089	Rubber Reserve Company	
	Southern California Gas Company, Agent	
	Los Angeles - Aliso Street Plant	
	To Repair Insulation	
5090	Todd Shipyards Corporation	
بها دفیق در سد ددد	S. S. "Wallowa" - To Repair Port Boiler	
5091	Bethlehem Steel Company	
	S. S. "Winslow Homer" - To Repair Two (2) Boilers	
(A)	To Repair Galley Range	
5092	Sierra Steel Forging Co Torrance	Ì
	To Repair Furnace Brickwork	
5093	The Texas Company - Fillmore /#	Ln.
2473	Repairs to Crude & Cracking Furnaces Press. Pipe St	
MPGen		

	July 19	<u>45</u>
7	5094	McKeon Canning Company, Inc Burbank
		To Repair Bake Bean Oven
	7	
	5095	Acme Brewing Company - Vernon
		To Reline Incinerator
W. S.	5096	Standard Shipbuilding Corporation
		LST-611 - To Repair Galley Range (cancelled)
	(A)	LCI-233 - To Repair Galley Range
2.	, ,	
0.00	5097	Craig Shipbuilding Company
	,	S. S. "Mission San Diego" - To Repair Two (2) Blrs
	(A)	To Reline Air Casing Doors
	(B)	To Renew Insulation under Steam Drum on Fire Side
	5098	General Chemical Company - El Segundo
		Acid Tank Lining in C. I. Pump Tank
	5099	Pacific Coast Borax Company - Boron
		To Reline Fused Rasorite Furnace
	5100	Bethlehem Steel Company
*		S. S. "Sparrows Point" - To Repair Two (2) Boilers
	5101	Bethlehem Steel Company
		S. S. "Charles Lummis" - To Repair Two (2) Boilers
	(A)	M. V. "Anacapa" - To Repair Boiler
	(B)	S. S. "Charles Lummis" - Bake Oven Repairs
1		
Ť	5102	Martin Ship Service Co.
		S. S. "San Luis Liciano" - To Repair Boiler
	5103	Bethlehem Steel Company - "+ dram"
		S. S. "Sagua" - To Repair Galley Range

	5104	Bethlehem Steel Company
		S. S. "John W. Searles" - To Rebrick Galley Range
	5105	National Mining & Milling Co Solvang, Calif.
		To Install Brickwork for One (1) Single Mercury
		Retort
	5106	Stauffer Chemical Company - Torrance
-1 - 4		Brickwork Repairs to Experimental Plant Furnace
	5107	Todd Shipyards Corporation
	Acceptance of the control of the con	S. S. "Wallowa" - To Repair Starboard Boiler
	State of the state	
	5108	Todd Shipyards Corporation
	Marian	S. S. "Elk Bason" - To Repair Port & Starboard Boilers
	(A)	Insulation Repairs
	90 mm m m m m m m m m m m m m m m m m m	
	5109	Bethlehem Steel Company
	10040110vm 3-4400000	S. S. "Henry V. Alvarado" - To Repair Two (2) Boilers
	CONTRACTOR	
	5110	Bethlehem Steel Company
		M. V. "Anacapa" - To Repair Galley Range Firebox
	nosti fordireabilities	
	5111	Federated Metals Division, Amer. Smelting & Refining Co.
	And investigation	Los Angeles - Repairs to Aluminum Reverberatory Furnace
	5112	Bethlehem Steel Company
	-48-cocyntradas	S. S. "Cecil G. Sellers" - To Repair Two (2) Boilers
	5113	Bethlehem Steel Company
	As a second seco	S. S. "Antigua" - To Repair Boiler Insulation
	5114	Consolidated Steel Corporation (Cancelled)
	·	S. S. "Talbot" - To Repair Boiler

	,	Southern California Gas Company, Agent
. 1		Los Angeles - Jackson Street Station
		Insulation Repairs
e. O. do inter R marines. A.	5116	Consolidated Steel Corporation
		S. S. "Edwin C. Musick" - To Repair Two (2) Blfs.
	(A)	To Repair Galley Range
	5117	Richfield Oil Corporation - Watson
		To Repair Boiler #12 in #1 Boiler House
	(A)	To Repair Brickwork on Battery #3 Heater & Crude
		Stills
	5118	Consolidated Steel Corporation
		APA-56 - To Rebrick Oven
	(A)	To Repair Incinerator
	5119	Consolidated Steel Corporation
		S. S. "Henry Durant" - To Repair Two (2) Boilers
	(A)	To Repair Galley Stove
	5120	Consolidated Steel Corporation - Pico Yard
		S. S. "Lundy's Lane" - To Repair Boilers
	5121	Bethlehem Steel Company
		S. S. "Cape Victory" - To Repair Floor and Corbel
	5122	Pacific Hard Rubber Company, Div. of Stauffer Chem. Co.
		Vernon - Repairs to Incinerator
	5123	Bethlehem Steel Company - Long Beach, Berth #68
		S. S. "Henry V. Alvarado" - To Rebrick Cook Stoves
	9.	

Reconstruction Finance Corp., Office of Rubber Reserve

5115

5124	Morse Boulger Destructor Company
	U. S. Naval Hospital - Corona
	Alterations to Incinerator
5125	Wilmington Welding & Boiler Works
	U. S. S. "Hamilton" - To Repair Aft Boiler #4
* ***	
5126	Anaheim Citrus Products Company Ltd Anaheim
	Boiler Brickwork Repairs
5127	Todd Shipyards Corporation
	APD-31 - To Repair Boiler #2
5128	Consolidated Steel Corporation
	S. S. "C. Crocker" - To Repair Galley Range
	e de la companya de
5129	Bethlehem Steel Company
	S. S. "Fairland" - To Repair Boilers
(A)	To Repair Galley Range
5130	Hercules Forge Corporation - Los Angeles
	To Rebuild #2 Forge Furnace
5131	Southwestern Engineering Company
	Harshaw Chemical Company - El Segundo
	Brick Setting for One (1) 85 h.p. Oilfield Boiler
(A)	Brick Paving
(B)	Flue Lining
*:	
5132	Wilmington Welding and Boiler Works
	LSM-405 - To Repair Boiler #4
5133	Bethlehem Steel Company
	DM-28 - To Repair #1, #2, #3, and #4 Boilers

	5134	Pittsberg Chemical Company - Los Angeles
-		Sulphur Burner Repairs
	5135	Consolidated Steel Corporation - Wilmington
		Fire Brick and Insulation Linings for 20 Foster-
		Wheeler Boilers (Two to a hull) - Hulls #1358-#1367
3	5136	Western Pipe & Steel Company of Calif.
edice and		APD-8 U. S. S. "Waters" - Repair Blrs. #1 & #2
() er	(A)	To Rebrick Galley Range (Cancelled)
1 10 10 10		
rui um	5137	The Harshaw Chemical Company - El Segundo
		Furnace Repairs
	(A)	To Plug Holes in Reverberatory Furnace
	(B)	Brickwork in Reverb Furnace and Converter
}	Aug. 19	45
	5138	Fibreboard Products Inc Vernon - Plant #3
		Repairs to #1 Boiler, due to Explosion
	5139	Kaiser Industries - Fontana, Shell Division
		Repairs to Hearth #4 Furnace
	5140	Bethlehem Steel Company
		S. S. "Sea Corporal" - Galley Range and Ovens
	(A)	Boiler Repairs
	5141	Consolidated Steel Corporation
		S. S. "Walter Colton" - To Repair Two (2) Boilers
<i>,</i>	5142	Standard Shipbuilding Corporation
		APD-79 - To Repair Two (2) Boilers
-	5143	Gonzales & Blanco - San Luis Rey, Calif.
		To Reline Fireboxes on Two (2) Air Heaters

5144	General Refractories Company - Vernon
	To Repair Stack Lining in Kiln
(A)	To Repair Firebox
(B)	To Renew Bottom in No. 1 Kiln
- (C)	Kiln #7 Repair
and the second	ALCOHOLOGICAL STATE OF A STATE OF
5145	Harbor Boat Building Co.
	LST-219 - To Repair Boiler
5146	Wilmington Welding & Boiler Works
	S. S. "Cape Constance" - To Repair Two (2) Boilers
5147	The Texas Company
	S. S. "Contreras" - To Repair Two (2) Boilers
5148	Consolidated Steel Corporation
	S. S. "Elliott" - AG-104
	To Repair Three (3) Boilers
5149	Wilmington Welding & Boiler Works
	S. S. APD-78 - To Repair #1 and #2 Boilers
5150	Ralph E. Homann Company
	Los Angeles County General Hospital - Los Angeles
	Boiler Brickwork
5151	Brunswick Radio Corp.
	Decca Records, Inc Hollywood
Section Andrews	Furnace Repairs to Two (2) Class "E" #10 Stirling Blrs
5152	Bethlehem Steel Company
	S. S. "Tanamo" - Repairs to Starboard Boiler
5153	Bethlehem Steel Company /Boilers
	S. S. "Paul M. Gregg" - Patch up & Renew Brickwork on

	5154	Stauffer Chemical Company - Vernon
	*	Brickwork - CO <sub>2</sub> Generator
)		
	5155	Bethlehem Steel Company - San Pedro
	777	U. S. S. APA-105 - Repairs to Boiler Brickwork
	(A)	Repairs to Incinerator
	(-"/	
es Li	5156	C C Moore & Co Fraincers
in i	טעבע	C. C. Moore & Co. Engineers
Glad person		Patton State Hospital - Patton, Calif.
The same		Brick Setting - One (1) Class H3 #28 Stirling Blr.
Į.	5157	Todd Shipyards Corporation
		U. S. S. APD-76 - Repairs to #2 Boiler
	5158	Consolidated Steel Corporation
•		S. S. "Santa Cruz" - Repairs to Port Boiler
)		
	5159	Consolidated Steel Corporation
		APA-179 - S. S. "Lauderdale" - Repairs to Blrs. #1,
		#2
	E160	Consolidated Stool Comparation
	5160	Consolidated Steel Corporation
	• •	S. S. "J. Field" - To Rebrick Galley Range
	5161	Standard Shipbuilding Corporation
		PA-209 - Repairs to Boilers
	5162-A	Consolidated Steel Corporation
		AVD #12 - S. S. "Gillis" - Repairs to Galley Range
	5163	Western Pipe & Steel Company of Calif.
)		S. S. "Yokes" (APD-69) - Plastic Front in #2 Boiler
	5164	Bechtel McCone Corporation
		Reconstruction Finance Corp., Office of Rubber Reserve
		Standard Oil Co. of Calif., Agent El Segundo - Butadiene Plant - Brickwk. Reprs. in Houdry Reactors
		producting trans . Direvay. Wahrs. In mounty were our

5165	Bethlehem Steel Company
	APA-36 - To Rebrick Two (2) Galley Ranges
5166	Bethlehem Steel Company
5 ty	"George Luks" - To Repair Boilers
(A)	To Repair Galley Range
5167	(Cancelled)
	Bethlehem Steel Corp.
	"Cape Meddick" - To Repair Two (2) Boilers
5168	Consolidated Steel Corporation
	S. S. "Kinzer" (APD-91) - To Repair Boilers
5169	Stauffer Chemical Co., Dominguez Division - Dominguez
	Insulation Work
5170	Great Lakes Carbon Corp., Dicalite Division
gm u 💌 mm	Walteria, Calif To Repair Firing Hood of Rotary Kiln
5171	Federated Metals Division, Amer. Smelting & Ref. Co.
	Los Angeles - Brick Setting, Breeching and Brick
	Stack for Aluminum Sweat Furnace
5172	Consolidated Steel Corporation - Pico Yard
	S. S. APD-102 - To Repair Two (2) Boilers
5173	Smoot-Holman Company - Inglewood
	To Reline #6 Ball Mill
-	
5174	Bethlehem Steel Company
•	S. S. "Sagua" - To Repair Galley Range

5175	Wilmington Welding & Boiler Works
· · · · · · · · · · · · · · · · · · ·	LST-122 - To Repair Boiler
(A)	Galley Range and Oven Repair
5176	Wilmington Welding & Boiler Works
	AP-171 - Two (2) Galley Ranges
(A)	Port and Starboard Boiler Repairs
5177	Bethlehem Steel Company
	S. S. "Frank J. Irwin" - To Repair Starboard Blr.
(A)	To Repair Port Boiler
j P	
5178	Bethlehem Steel Company
	S. S. "Edward L. Livingston" - To Repair Two (2)
5179	Bethlehem Steel Company
	S. S. "Wm. Luckenbach"
w	To Repair Fireboxes of Three (3) Galley Ranges
(A)	Repair #5 Boiler
(B)	Repair #2 Boiler
(C)	Material Only
(0)	
5180	California-Oregon Paper Mills - Los Angeles
	To Line Concentrator Flue Plate with Acid Brick
(A)	Lining Tower and Floor
, ,	
5181	Bethlehem Steel Company
•	DD-860 - Hull #9029
	To Repair Chrome Ore in #1 Boiler
)	
5182	Standard Shipbuilding Corporation
	LST-34 - Bake Oven and Galley Range Repairs
5183	Bethlehem Steel Company /Boilers
	S. S. "George Eastman" - Repr. Port & Starboard

5184	Standard Oil Company of Calif El Segundo
	#3 Battery - Stack Repairs
	and the state of t
5185	(Cancelled)
	Bethlehem Steel Corp.
	S. S. "Tanamo" - To Renew Arch in Boiler
5186	The M. W. Kellogg Co.
	General Petroleum Corp Torrance
ge mediche Agre i = i side i i i	Enclosures for Kellogg Furnaces B-1 and B-2 and
	Petro-Chem Furnace
(A)	To Insulate Header Boxes on Bl and B2 Furnaces
(B)	To Dril 24 Holes for Thermocouples for Furnaces
5187	Todd Shipyards Corporation
	S. S. "Orson D. Munn"
	To Renew Floors, Burner, Peepholes and Walls in
	Boiler.
5188	Bethlehem Steel Company
	APA-9 - To Repair #2 Boiler
5189	Stauffer Chemical Company - Torrance
	Repairs to Sulphur Hopper Duct
5190	Acme Brewing Co Vernon
	Repairs to #3 Boiler
5191	San Diego Gas & Electric Company
	San Diego - To Rebuild Front Wall in Boiler #25
5192	C. C. Moore & Co. Engineers
	Ganado Mission - Ganado, Arizona
	Brick Setting for One (1) FF15 #20 B. & W. Boiler
'	
-obremanna et a a	

	5193	Standard Shipbuilding Corporation
~	,	AK-17 - Repair Galley Ranges and Ovens
	(A)	Repair Boilers #1, #2 and #3
		Approximate Approximate the first transfer of the companion of the compani
	5194	Coast Fishing Company, Inc Wilmington
		To Repair Dryer Furnace
er V	=10=	Ama Draving Go Vozago
	5195	Acne Brewing Co Vernon
alies Burg	(4)	To Remodel #2 Kidwell Boiler
oz T	(A)	Tearing out Brickwork
1 1 2 2	(B)	Tearing out Concrete
ž	(C)	Brickwork "A", "B", "C"
	(D)	New Monolithic Baffles
	5196	West End Chemical Company - Westend
		To Reline 5'-0" dia. x 15'-0" long Dryer Furnace
	5197	J. A. Bauer Pottery Co Los Angeles - Plant #3
		To Reline Two (2) Small Ball Mills
	5198	Craig Shipbuilding Company - Long Beach - Berth #33
		S. S. "Stephen M. White"
		To Repair Furnaces in Two (2) Boilers and Galley
		Range
	5199	Consolidated Steel Corporation
	7-77	S. S. "Michael Casey" - To Repair Two (2) Boilers
	(A)	Repair Galley Range
	(42)	
	5200	Consolidated Steel Corporation
	<i>J</i> 200	
		S. S. "Bald Eagle" - To Repair Two (2) Boilers
	- L	Mha Marca Componer Lidhaineatan Tag Angalag Marka
	5201	The Texas Company - Wilmington - Los Angeles Works
		To Renew Bolted Tile in Upper Part of DeFlorez Htr
		Furnace H-M - L. U. Battery

	1		the state of the s
		5202	Wilmington Welding & Boiler Works
			Hull #LCI-1015 - To Repair Galley Range
		5203	Wilmington Welding & Boiler Works
			Hull #LCI-1018 - To Repair Galley Range
		5204	Consolidated Steel Corporation
			LCI-962 - To Repair Galley Ranges #1 and #2
	TO COLOR OF THE CO		
200		Sept. 1	- The state of the
		5205	Craig Shipbuilding Company
	Table State		S. S. "Ignatius Donnelly" - To Rebuild Galley Stove
	- The state of the		Anna Charling a Darbining Ca
	alpha and a second	5206	Federated Metals Division, Amer. Smelting & Refining Co.
	- Committee of the comm	7	Los Angeles - To Repair #2 Brass Reverb. Furnace
	out-out-property of		
,	Committee	5207	Standard Shipbuilding Corporation
ļ	CONTRACTOR OF THE PROPERTY OF		S. S. "Alfred C. True" - To Rebrick Galley Range
	ear or and or an and or an		The American Law
	Description of the second	5208	Western States Lacquer Co Los Angeles
	and the second s	· · ·	Lining Ball Mill 6'-8" dia. x 6'-0" long
	ACTION AND ADDRESS OF THE ACTION ADDRESS OF THE ACTION AND ADDRESS OF THE ACTION AND ADDRESS OF		
	Section 1	5209	Consolidated Steel Corporation
	Street de contraction de la co	SERVICE CONTRACTOR CON	LCI-961 - To Repair Galley Range
		-010	Pomona Tile Mfg. Co Pomona
		5210	Repairs to Tunnel Kiln
		All a savel demonstration	Repairs to Tunnet Alin
		5211	Bethlehem Steel Company
İ		7211	S. S. "Tilde" - To Repair Galley Range
	American desired	An expression of the second	S. S. IIIde - 10 hepair derrich immge
	All forms around further	5212	Forest Lawn Memorial-Park Association, Inc Glendale
	man and and	) Callet	Repairs to Three (3) Crematory Furnaces
		en oormoopalyepskalde	Rebails to Turse (2) oremetory remetors
		Argent-cognition	
	**		

	5213	Howes & Whitaker
~	* * * * * * * * * * * * * * * * * * *	Southern California Gas Co Los Angeles
1		Aliso Street Station - #1 Exhauster House -
		Pipe Insulation
	5214	Standard Shipbuilding Corporation
ė.		S. S. "LCI-1014" - To Repair Galley Range
e E		
Jun Mari	5215-A	Stauffer Chemical Company - Dominguez
56		Acid Cooling Tower Repair
	(B)	Rotary Kiln - To Renew Lining
ģ at		
	5216	West Coast Shipbuilding and Drydock Company
		S. S. "Mission Dolores" - To Repair Two (2) Boilers
1	5217	Hodgson-Græne-Haldeman Shipbuilders
/		S. S. "Carrier Pigeon" - To Repair Boiler
	5218	Consolidated Steel Corporation
		S. S. "LCI-579 - To Repair Two (2) Galley Ranges
	5219	Pacific Coast Borax Company - Wilmington
		To Rebuild Borax Glass Furnace
	5220	White Heat Treating Company - Huntington Park
		Repairs to Lindberg Heat Treating Furnace #8
	5221	Leahy Manufacturing Company
		Clougherty Bros. Meat Packing Co Vernon
i		Brick Settings for Two (2) Titusville Locomotive Blr
j		
	5222	Stauffer Chemical Company - Dominguez
		Insulation Repairs to Caustic Tank

5223	Stauffer Chemical Company, Dominguez Division
	Dominguez - Brickwork for Filter for D. C. Unit
	Converter
5224	Southern California Edison Company - Long Beach Steam
	Repair Bridge Wall in #42 Boiler
5225	Wilmington Welding & Boiler Works
	Hull #ATR-66 - To Repair #1 and #2 Boilers
5226	Wilmington Welding & Boiler Works
	Hull #AP-67 - To Repair Boilers #1 and #2
(A)	Galley Range Repairs
5227	Bethlehem Steel Company
	S. S. "John H. Marion" - Repair Brick and Chrome
	Ore of firebox of Galley Range
(A)	To Repair Two (2) Boilers
5228	Standard Shipbuilding Corporation
	S. S. "AN-31" - To Repair Boiler
5229	Stauffer Chemical Company - Torrance
	Insulation Repairs to Converter System
5230	Los Angeles Steel Casting Co Los Angeles 11
	To Install Burner Throats in Annealing Furnace
5231	Consolidated Steel Corporation
	S. S. "General Freeman" (AP-143)
	To Repair Firebox in Incinerator
(A)	To Repair Boilers #1 and #2
(B)	To Renew Side Walls of both Boilers

Plant

	5232	Consolidated Steel Corporation
		S. S. AKA-110 - Galley Range Repair
ř		
	5233	Anaheim Citrus Products Co. Ltd Anaheim
		Plant #1 - Repairs to Dryer Furnace
	5234	Bethlehem Steel Company
		S. S. "Albert J. Berres" - To Repair Boilers
	5235	Consolidated Steel Corporation
		S. S. "Tumacacori" - To Repair Two (2) Boilers
	5236	Shell Oil Company, Inc Wilmington Refinery
		Repairs to #7 and #8 Boilers
	5237	Union Oil Company of Calif Wilmington
		T. C. C. Unit - To Reline Airline Heater Ducts
		and Burner
	5238	Leon Finch, Ltd Los Angeles
		To Reline Two (2) Ball Mills
	(A)	Ball Mill Lining Repairs
	5239	Bethlehem Steel Company
		S. S. "Mary Ball" - To Repair Boiler
	(A)	To Repair Port Boiler
	5240	Globe Lumber Company, Ltd Los Angeles
		To Repair Incinerator
	5241	Wilmington Welding & Boiler Works
		Hull #AVP-48 - Boiler Repairs
	5242	Consolidated Steel Corporation /Boilers
		APA-115 - "General Randall" - Repair #1, #2, & #3

7643	Filtroi corporation - sackson, miss.
	4,000,000 B.t.u. Line Burner Shell
	(Material only)
	and the second of the second o
5244	Union Oil Company of Calif Wilmington
	Los Angeles Refinery - #1 Boiler Plant
	Boiler #1 - Brickwork Repairs
5245	A. L. Haney, Residence - West Covina, Calif.
	To Build a Fireplace
5246	Reconstruction Finance Corp., Office or Rubber Reserve
A-Z	Southern California Gas Company - Los Angeles
	Brickwork and Insulation Repairs
5247	The Fluor Corporation, Ltd.
	Fletcher Oil Company - Wilmington
v	U. O. P. Heater - Furnace Brickwork Repairs
(A)	To Repair Fire Wall
5249	Exeter Refining Company - Long Beach
	Insulation Repairs at A. B. Plant
5249	Consolidated Steel Corporation
	S. S. (AK-91) "Cor-Caroli" - To Rebrick Front Wall and
	Renew Plastic and Corbel of #1 and #2 Boilers
(A)&(B)	Rebrick Galley Range Firebox
	Renew Top Course of Firebox Floors in #1 & #2 Boilers
5250	Bethlehem Steel Company
	S. S. "Coeur d'Ale" - To Repair Two (2) Boilers
5251	Standard Shipbuilding Corporation
1	S. S. "Trinity Victory" - To Repair Two (2) Boilers

	5252	Liquid Carbonic Pacific Corp. Ltd Los Angeles
<u>)</u>	Processing Control of	Repairs to Rear Wall of One (1) 300 h.p. Kroeschell Boiler
	(A)	To Rebuild Burner Tunnels #1 and #2 Boilers
	<b>525</b> 3	Standard Oil Company of Calif El Segundo
		Detrick End Walls #2A and #2B Pressure Stills -
		Rebuild East Side Wall of #2A Furnace at Cracking Plant
	5254	W. C. Hardesty Co., Inc Los Angeles
		To Construct One (1) Fatty Acid Pot Still Furnace
		and Flue
	5255	Union Oil Company of Calif Wilmington
		Los Angeles Refinery - Lummus Heater #34 Repairs
	Oct. 19	<u>5</u>
	5256	Todd Shipyards Corporation
		S. S. DE-696 - To Rebrick Two (2) Boilers
	5257	Wilshire Oil Company, Inc Norwalk
		To Repair #3 Boiler
	5258	Harbor Boat Building Co.
		LST-219 - To Rebrick Galley Range
	5259	Standard Shipbuilding Corporation
		S. S. "Crater Lake" - To Repair Boilers
	5260	J. T. Thorpe & Son, Inc.
		Calaveras Cement Co Calaveras, Calif.
		Kiln Lining

5261	Bethlehem Steel Company
	S. S. "M. V. Manoeran" - Repair Officer's Galley
	Range - Item #47
	Repair Lascar Galley Range - Item #48
5262	C. C. Moore & Co. Engineers
	Santa Barbara Cottage Hospital - Santa Barbara
	Brickwork - One (1) Class H2 No. 13 Stirling Boiler
5263	Federated Metals Division, Amer. Smelting & Refining Co.
	Los Angeles - Repairs to #2 Brass Reverb. Furnace
(A)	To Repair #1 Brass Reverberatory Furnace
(B)	To Repair U. S. Brass Furnace #4
(C)	To Repair Crucible Furnace #5
5264	Consolidated Steel Corporation
	S. S. (AP-133) "General Ernest"
	Repairs to Two (2) Boilers
(A)	Galley Range Repair
5265	San Diego Gas & Electric Company - San Diego -
	Station "B" - Boiler Furnace #23 -
	Brickwork Repairs to Front Wall
5266	Bethlehem Steel Company
	S. S. "L. P. St. Claire" - To Repair Boilers
(A)	To Repair Galley Range
(B)	To Repair Port Boiler
5267	Bethlehem Steel Company
	U. S. S. AP-147 - To Repair Galley Range
5268	Consolidated Steel Corporation
(A) (B)	S. S. "Santa Monica" - To Repair Galley Range & Oven Repair Troop Bakery Bake Ovens To Rebrick Troop Galley Range

<b>,</b>	Salt River Valley Water Users' Assn Tempe, Arizona
*	Brickwork Repairs to Class "F" B. & W. Boilers
5070	Consolidated Ctool Componetion
5270	Consolidated Steel Corporation  DE-697 - U. S. S. "George" - Repair Two (2) Blrs.
5271	The Dow Chemical Co Los Angeles - L. A. Styrene Plant
	Agent for Reconstruction Finance Corp., Office of Rubber
	Line and Install Partition Walls in /Reserve
	One (1) 6'-5" I. D. x 42'-0" Vertical
	Ethylbenzene Reactor
5272	Ford Motor Company - Long Beach'
	To Repair Two (2) Erie City Boilers
\ \	
T-5273	Tin Processing Corp Texas City, Texas
(See T-516)	Boiler Enclosures for Two (2) Combustion Engineering
,	Company Boilers
5274	Bechtel-McCone Corporation
	General Petroleum Corp Burrel, Calif.
	One (1) Ten-million B.t.u. Oil Heater
5275	Bechtel-McCone Corporation
	General Petroleum Corp Burrel, Calif.
	Three (3) Llewellyn Water Tube Boilers
5276	C. C. Moore & Co. Engineers
)	("Everglades") - Hulls #66 and #67
	To Renew Peepholes of Back Walls
5277	Richfield Oil Corporation - Watson Refinery
	Brickwork Repairs #810 Heater - Asphalt Plant

5269

C. C. Moore & Co. Engineers

5278	Reconstruction Finance Corp., Office of Rubber Reserve
	Southern California Gas Co., Agent
	. Los Angeles - Aliso Street Station
	Insulation Repairs
5279	Wilmington Welding & Boiler Works
	Hull #AM-57 -
	To Repair Boiler Insulation around Coils
5280	Todd Shipyards Corporation - San Pedro
	To Reline Forge Furnace in Blacksmith Shop
5281	English and Lauer, Inc.
	St. Francis Hospital - Lynwood
	Firebox for Two (2) Brownell Boiler Settings
Ţ-5282	Kinzbach Tool Company, Inc Houston, Texas
(see T-517)	To Reline One (1) Carburizing Pot Furnace and
	to Brick up One (1) Welding Platform
5283	Bethlehem Steel Company
	AO-24 - To Remove Brick, etc. in Four (4) Boilers
(A)	To Renew Brick in Incinerator and Spark Arrester
(B)	To Renew Brickwork in Four (4) Boilers
5284	U. S. A. WAR DEPARTMent
	March Field - Riverside, Calif.
	To Repair Two (2) Erie City Water Tube Boilers
5285	Craig Shipbuilding Company
	M. V. "Tjisadane" - To Rebrick Bake Oven
5286	Bethlehem Steel Company
	S. S. "Illinois" - Rebrick Three (3) Boilers

	5287	Western Pipe & Steel Co. of Calif.
		U. S. S. "Raby" (DE-698)
		Repair #1 and #2 Boilers
	(A)	To Rebrick Doors on Superheater
	5288	Shell Oil Company, Inc Dominguez
		To Repair Dubbs Furnaces #1 and #2
4		
e e e e e e e e e e e e e e e e e e e	5289	Consolidated Steel Corporation - Pico Yard
is- re		S. S. "Extavia" - To Repair Galley Range
	(A)	To Rebrick Superheater Door
2	(B)	To Rebrick Troop Galley Range
	5290	California Metal Enameling Co Los Angeles 11
		To Repair #1 Enameling Furnace
	5291	Bethlehem Steel Company.
		M. V. "Tabinta" - To Rebrick Galley Range
	5292	Shell Oil Company, Inc Dominguez
		Boiler #3 - Brickwork Repairs to Bridge Wall
	5293	Stauffer Chemical Co., Dominguez Division - Dominguez
		Acid Brickwork, Leonard-Montsano Filter Box
	(A)	Mannheim Furnace Repairs
	5294	Shell Chemical, div. of Shell Union Oil CorpDomingue
		To Patch Floor of D. M. K. Converters #F-1 and #F-2
	5295	Bechtel Brothers McCone Company
		The Texas Company - Wilmington
		Brickwork and Insulation Repairs - V-2 Reactor

Column - Catalytic Cracker

5296	Bethlehem Steel Company - Vernon Plant
	Brickwork for Furnace, Covers and Stack for 12"
	Mill, Annealing Furnace
	washamita da maka aya aya aya aya aya aya aya aya aya
5297	Wilmington Welding & Boiler Works
	Hull #AP-47 - To Repair Boiler
5298	Todd Shipyards Corporation
	U. S. S. APD-104 - To Repair Two (2) Boilers
5299	Shell Oil Company, Inc Wilmington Refinery
	Brickwork Repairs to Heater #4, Trumble #2
(A)	Heater #1, Trumble #1
(B)	Heater #1, Distilling Unit #2
(D)	Heater #3, Unit #1
(C)	Heater #5, Trumble #3
5300	Standard Oil Company of Calif El Segundo
	To Renew Lining in Concrete Stack at #2 Pressure Stills
(A)	To Repair #2A Furnace Base
5301	Consolidated Steel Corporation - Pico Yard
	S. S. "Bexar" (APA-237)
	To Repair #1 and #2 Boilers
5302	Consolidated Steel Corporation - Pico Yard
	S. S. "Fickway" (APA-222)
	To Repair #1 and #2 Boilers
5303	Harboar Boat Building Company
	LST-224 - To Rebrick Galley Stove

	Nov. 194	
	5304	Wilmington Welding & Boiler Works
		"Woodworth" (DD-460) - To Repair Four (4) Boilers
		Blr. #1 - Renew Plastic Front and Patch Deck
		Blr. #2 - Patch Plastic Front & Patch Deck
		Blr. #3 - Renew Plastic Front & Patch Deck
J.		Blr. #4 - Patch or Renew Front & Furnace Deck
8		
<u> </u>	5305	California Portland Cement Co Colton
1 24		Insulation of 16 ft. dia. Sturtevant Air Separator
		and Precipitator
g g	(A)	Insulation of 39 ft. of 10" Piping
	5306	Bethlehem Steel Company
		S. S. "Uruguay" - To Repair #2 Boiler
1		
,	5307	Craig Shipbuilding Company
		S. S. "AN-11" - To Repair Boiler
	5308	Consolidated Steel Corporation
		S. S. "Gen. Hansford" (APA-106) - To Repair Two (2)
		Boilers
	(A)	To Repair Two (2) Bake Ovens
	(B)	To Repair Galley Range
	5309	Warner Welded Products - Glendale
	,	G-E Brazing Furnace
	E010	Courthorn Colifornia Cos Co Tos Angolos
	5310	Southern California Gas Co Los Angeles
)		Aliso Street Station
		Agent of R. F. C., Office of Rubber Reserve
		Insulation Repairs
		Desirie Oler Preducts Teg Angeles
	5311	Pacific Clay Products - Los Angeles  Remove & Replace Fire Brick Lining in 3 Brick Stack
		The state of the the state of t

	5312	Wilmington Welding & Boiler Works
		APA-96 - To Repair Boilers
	(A)	To Repair Firebox and Oven
	(B)	To Repair Seven (7) Galley Ranges
	2	
	5313	Swift & Company - Vernon
-	promovement of the first of the	Brickwork Repairs to C-E Boiler
	5314	Stauffer Chemical Company - Torrance
		Brickwork for Installing Stoker in Experimental
3300		Decomposer Furnace
	200 pto 1 500 c c c c c c c c c c c c c c c c c c	
	5315	Southern California Gas Company - Los Angeles
		Agent of Reconstruction Finance Corp., Office of Rubber
	·	Ducommun Street - Insulation Repairs /Reserve
	5316	Standard Shipbuilding Corporation
		S. S. "Young America" - To Repair Two (2) Boilers
	5317	Bethlehem Steel Company
		DD-554 - To Repair Boilers #1, #2, #3 and #4
	5318	Union Oil Company of Calif Wilmington - T. C. C. Plan
		To Reline Upper Cone of Airline Heater in Cracking
		Side of Unit
	5319	Standard Shipbuilding Corporation
	The second secon	APA-107 - To Repair Galley Ranges
	(A)	To Repair Bake Ovens and Fireboxes
	(B <u>)</u>	To Repair Boilers #1 and #2
	5320	Bethlehem Steel Company
		U. S. S. DD-693 - To Repair Blrs. Nos. 1, 2, 3 & 4
	V .	

	5321	The Harshaw Chemical Co El Segundo  To Repair Original Antimony Reverberatory Furnace
	5322	Exeter Refining Company - Long Beach
	J. J. ton ton	Brickwork Repairs to #3 Retort
	5323	(Cancelled)
40 60 60	7343	Consolidated Steel Corporation
Section of the sectio		FMS #5 - To Repair Galley Range
panel		The Home to to be the terminal transfer.
	5324	Consolidated Steel Corporation
740°. 96	And the second second	S. S. "Howell Lykes" - To Repair Boiler
	(A)	To Repair Fireboxes of Three (3) Galley Ranges
	• •	
	5325	Bethlehem Steel Company
		S. S. "Laurel Hill" - To Repair Boilers
)		
	5326	Wilmington Welding & Boiler Works
		U. S. S. AM-59 "Chickadee" -
		To Repair Plastic on Boiler
	5327	Bethlehem Steel Company
		U. S. S. DE-372 - To Repair #1 and #2 Boilers
	5328	Southern California Edison Co., Ltd.
		Long Beach Steam Plant
		Boiler #53 - To Repair Furnace Walls
	5329	Bethlehem Steel Company
.)		S. S. "Santa Teresa" - To Repair Boiler
	)	
	5330	Southern California Gas Co., Agent of
		Reconstruction Finance Corp., Office of Rubber Reserve
		Los Angeles - Jackson Street Station -
		Alant Areas #1 and #2, Insulation Repairs

53.	3 <b>1</b>	The Harshaw Chemical Co El Segundo
		Pipe Insulation
53 A-		Southern California Gas Company, Agent of Reconstruction Finance Corp., Office of Rubber Reserve
		Los Angeles - Brickwork Reprs. to Various Equipment
()	K)	Ducommun St. Station - Repairs to Blrs. #18 and #20
53.	33	(Cancelled)
		Todd Shipyards Corporation
		DD-532 - To Renew Plastic and Chrome Ore in Four
		(4) Boilers
*		
53.	34	Consolidated Steel Corporation
		S. S. "Santa Isabel" - To Repair Two (2) Boilers
. (,	A)	To Renew Corbel Brick and Patch Chrome and Cones;
		To Replace Chrome Ore around Tubes.
53.	35	Bechtel-McCone Corporation,
		Reconstruction Finance Corp., Office of Kubber Reserve
		Standard Oil Company of Calif., Agent - El Segundo
		Butadiene Plant - To Repair Reactors
53.	36	Wilmington Welding & Boiler Works
		AP-112 - To Rebrick Two (2) Bake Ovens
(.	A)	APA-20 - To Rebrick Air Casing Doors
,		
53	37.	Consolidated Steel Corporation
,	~ 1 .	U. S. S. 'Mercy" (AH-8)
		To Repair Galley Range and Ovens
(.	A)	To Repair Boilers Nos. 1, 2 and 2A
	B)	To Rebrick Boiler Casing Doors
	y	
52	38	Pacific Coast Borax Co Boron
	ncelf	

······································	5339	Consolidated Steel Corporation  APA-234 - To Repair Two (2) Boilers
	5340	Bethlehem Steel Company
		DD-449 - Remove Plastic & Chrome Ore on Boilers
	(A)	Brickwork Repairs to Boilers #1, #2, #3 and #4
	(B)	To Rebrick Rear Wall of Boiler #1
8.5.8.	, ,	
A.s.	5341-A	Shell Oil Company, Inc Dominguez
3-dea 	/ -	Dubbs Furnace #3 - Brickwork Repairs
	(B)	Dubbs Furnace #4
¥ Ž	(C)	Dubbs Furnace #5
	(D)	Dubbs Furnace #6
	5342	Reconstruction Finance Corp., Office of Rubber Reserve
		Southern California Gas Co., Agent
		Los Angeles - Aliso Street Station
		Insulation Repairs
		Actual of Contract of the Cont
	5343	Richfield Oil Corp Wilmington - Watson Refinery
		Furnace Brickwork Repairs - Odor Abatement Heater
	(A)	Repairs to Firebox of #4 Vacuum Still
	5344	Ship Repair Work
		Additional Charges account of Retroactive Billing
	5345	Harbor Boat Building Co.
		U. S. S. "Erben" (DD-631)
		To Repair Boilers #1, #2, #3, and #4
	(A)	To Rebrick Superheater Door
	5346	Bethlehem Steel Company
		S. S. "Marmac Hawk" - To Repair Boilers

5347	Wilshire Oil Company, Inc Norwalk
	Brickwork for Burning-Stack
5348	West End Chemical Co Westend
	Brick Lining 13' dia. x 45' Lime Kiln #4
5349	West End Chemical Co Westend
	Brickwork - Light Ash Furnace and Carbonate
	Dryer Firebox
5350	West End Chemical Co Westend
	Brickwork - Dense Ash Calciner Firebox
(A)	Cement Wall Block
(B)	Repairs to Lime Kiln
The second second second	
5351	Wilmington Welding & Boiler Works
	APA-214 - Boiler Repairs
(A)	To Reline Fireboxes in Five (5) Galley Ranges
Dec. 19	45 - C.
5352	Wilmington Welding & Boiler Works
	APD-55 - To Rebrick One (1) Boiler
5353	Wilmington Welding & Boiler Works
	APD-130 - To Rebrick Two (2) Boilers
5354	Todd Shipyards Corporation
	S. S. "J. H. Tuttle" -
	To Tear out and Rebrick Both Boilers
5355	Smoot-Holman Company - Inglewood
	To Reline #4 Ball Mill
5356	Forest Lawn Memorial-Park Association, Inc Glendale
Mrs.	To Repair Middle Retort

5357	Eastern Smelting & Refining Co Los Angeles
	To Construct Brickwork on One (1) 10-ton Lead
	Furnace
5358	Rubber Reserve Company
	Shell Chemical, div. of Shell-Union Oil Corp., Agent
	Torrance Plant - Los Angeles
4 21 22	To Replace Tube Baffle Tiles in B-201-B Superheater
	Furnace
VSB GEOGRAPHIC B	To Replace Roof Tiles and Insulation on B-201-A
	Superheater
5359	Alco Steamship Company, Inc., Box 458, Wilmington
	S. S. "Bringham Victory, V/4 -
	To Repair Galley Stove
) 5360	The Fluor Corporation, Ltd.
	Shell Oil Company of British Columbia, Limited
	Vancouver, B. C., Canada - Shellburn Refinery
	One (1) B. & W. Class H-3 #18 Boiler
5361	Filtrol Corporation - Vernon Plant
	Lining a Combustion Furnace and Connecting Duct
	for One (1) Air Heater for Pellet Calciner
5362	Consolidated Steel Corporation
	S. S. "Glacier Park - Port and Starboard Boiler Rps
5363	The Fluor Corporation, Ltd.
	Shell Oil Company of British Columbia, Limited
<i>.</i>	Vancouver, B. C., Canada - Shellburn Refinery
	One (1) U. O. P. Heavy Oil and One (1) Light Oil
	Heaters

.

5364	The Fluor Corporation, Ltd.
	Shell Oil Company of British Columbia, Limited -
	Vancouver, B. C., Canada - Shellburn Refinery
	One (1) Type "B" Gas Heater
5365	Craig Shipbuilding Company
	U. S. S. "Walker" (DD-517)
	Brickwork Repairs to Boilers #1, #2, #3 and #4
5366	Queen of Angels Hospital - Los Angeles
	Brickwork Repairs to Firebox of #2 Stirling Boiler
5367	The Luer Packing Company - Vernon
	Repairs to HRT Boiler Arch
5368	Apex Steel Corporation, Ltd Los Angeles
	Brickwork Repairs - #1 and #2 Core Ovens
5369	Scriver & Quinn, Inc Los Angeles
	To Reline Ball Mills
5370	(Cancelled) which and the same way of the same with
	Pioneer Division, The Flintkote Co Vernon
	Renew Floor and Patch Chrome Ore on Tubes in #2
	Boiler
5371	C. C. Moore & Co. Engineers
	Pacific Coast Borax Co Boron
	Brickwork - 4'-0" x 5'-0" Experimental Borax Melt-
	ing Furnace
5372	Reconstruction Finance Corp., Office of Rubber Reserve
	Shell Chemical Corporation, Agent Torrance Plant., L.
(A)	Brickwork Repairs to #6 Yarrow Boiler Repairs to #2 Yarrow Blr. (C) Rebuild Rear Wall #7
(B)	Repairs to #4 Yarrow Blr. Yarrow Boiler

California Metal Enameling Co Los Angeles 11
To Install New Burners on Large Enameling Furnace
and the community of the first of the community of the co
El Rey Products Company - Los Angeles 33
Repair Firing Tunnel on Asphalt Still
To Repair Incinerator
To Enlarge Oil Burner Ports in #1 Boiler
Southern Service Company, Ltd.
Santa Ana Laundry - Santa Ana
Brick Setting for One (1) 250 h.p. Lewellyn Boiler
Wilshire Oil Company, Inc Norwalk
Brickwork - Dubbs Alcorn Furnace Stack
Holladay & Chase - Los Angeles
To Line One (1) 75-gal. Ball Mill
To Install Brick in Door
To Line Gate for Ball Mill
W. C. Hardesty Co., Inc Los Angeles
Bricking in Tar Tank
The second secon
Standard Oil Company of Calif.
San Pedro, Marine Terminal - Brickwork Repairs to
#1 Boiler
Goodyear Tire & Rubber Company of Calif Los Angeles
Repairs to #2 Boiler
California Portland Cement Co Colton
Remodelling of #10 Kiln Hood
Brickwork Repairs to Stack Base
Repairing West Wall of Physical Laboratory Bldg.

5382	Los Angeles Soap Co Los Angeles Boiler Repairs
(A)	#7 Boiler - Fire-Brickwork
\ <del>(\$</del> )	
5383	C. C. Moore & Co. Engineers
	Blue Diamond Corp Arden, Nevada
• • •	Brickwork - One (1) Class H3 No. 13 Boiler
c > Q).	Shall Oil Commons Too. Domingues Definers
5384	Shell Oil Company, Inc Dominguez Refinery Heater #6 - Brickwork Repairs
i.	Housest to a principle to bear a
5385	Fred Meyer - Glendale
J3.47	Residence Chimneys
	and a and an out amount of m
5386	Reconstruction Finance Corporation
73.00	Southern California Gas Co., Agent - Los Angeles
	Santa Fe Avenue Plant - To Rebrick #11 Generator
	Sales of the sales
5387	Pacific Coast Boras Company - Boron
7301	To Rebrick Fused Rasorite Furnace
January	1946
5388	Hodgson-Greene-Haldeman Shipbuilders
	S. S. "David F. Barry"
	To Rebrick Firebox of Galley Range
5389	White Heat Treating Co Huntington Park
	Brickwork Repairs in Door of #1 Box Furnace
(A)	Brickwork Repairs on Cover of Cylindrical Furnace
(B)	To Line Door on Box Furnace #5
	and the state of t
5390	Federated Metals Div., American Smelting & Refining Co.
	Los Angeles - To Repair #2 Brass Reverb. Furnace

.....

ļ.....

5391	Wilmington Welding & Boiler Works
	APA-68 - Repairs to Two (2) Boilers
5392	Process Equipment Company
	Pittsberg Chemical Company - Los Angeles
	One (1) 250 h.p. Shipping Board Boiler
(A)	To Rebuild Tile Wall of old Boiler House at
	Richfield Oil Corp Watson
5393 & <b>A-</b> Z	Stauffer Chemical Co., Dominguez Division - Dominguez Insulation Repairs
5394	Southern California Edison Company, Ltd Alhambra
	Brickwork and Insulation Repairs to Testing
	Laboratory Oil Heater
5395	Asbestos Company of California
	Sun Harbor Packing Co San Diego
	Boat "Pan American" - Pipe Insulation Repairs
5396	Wilmington Welding & Boiler Works
	APA-546 - #1 Boiler Repairs
(A)	#2 Boiler Repairs
(B)	#3 Boiler Repairs
(C)	#4 Boiler Repairs
5397	Consolidated Steel Corporation
	"Abercrombie" (DE-343) - Repairs to Two (2) Blrs.
5398	Consolidated Steel Corporation
	"W. C. Wann" (DE-412) - To Rebrick Two (2) Boiler
E200	Oil Field Construction Co.
5399	Tog Angeles Brewing Co - Tog Angeles
	Los Angeles Brewing Co Los Angeles /Boiler
	Brick SettingOne (1) 750 h.p. Union Iron Works

540	Harbor Boat Building Co.
	DE-342 - To Rebrick Two (2) Boilers
540	Consolidated Steel Corporation
	S. S. "McMurray Victory"
The state of the s	To Rebrick Fireboxes of Galley Range
540	Richfield Oil Corporation - Watson Refinery
a-ody-in-terming-a-a	Brickwork - Odor Abatement Furnace
(A	Partition Walls in Dehexanizer Furnace
110000000000000000000000000000000000000	
540	Stauffer Chemical Co Torrance
	Acid Brickwork - Lead Tower
540	C. C. Moore & Co. Engineers
	City of Pasadena, Power Plant
and the second s	Installing Monolithic Baffles in B. & W. Straigh
Validentii in territori in terr	Tube Boiler
El arregi y como en el	impe porrer
r lo	American Debark C. Chemical Come
540	
	To Repair upper Furnace Wall in Boiler #15
(A	To Rebrick #2 Soda Products Dryer Furnace
540	• • • • • • • • • • • • • • • • • • •
per constant as a manual po	S. S. AP-77 - To Repair Two (2) Boilers
THE PROPERTY OF THE PROPERTY O	
540	C. C. Moore & Co. Engineers
	Standard Gypsum Co. of Calif Long Beach
	Brick Setting -
	One (1) Class H-4 No. 22 B&W Stirling Boiler
The state of the s	the state of the s
540	C. C. Moore & Co. Engineers
	General Petroleum Corp Torrance
	Brickwork and Insulation -
	One (1) F-19-BB20/48 Integral Furnace Boiler

	7409	Sherr our Company, inc wriming con
)		To Repair Boiler #3 Brickwork
	5410	Kiss Crane Service General Chemical Co El Segundo
		Acid Brick Lining in Two (2) 61'-8" x 14'-6" Tank
*		
<u>5</u>	5411	Lohman Bros.
indent ident		Sears Roebuck & Co Vermont & Slauson, Los Angeles
61		Brickwork - Two (2) Brownell #268 Boilers
ei Zi	5412	Standard Shipbuilding Corporation
		DE-411 - To Repair Two (2) Boilers
	5413	U. S. Naval Base - Public Works Department
4		U. S. Naval Hospital - Corona, Calif.
)		Brickwork Repairs -
		Two (2) Class "J" No. 15 Connelly Boilers
	1 1	
	5414	Hodgson-Greene-Haldeman Shipbuilders
		S. S. YMS-164 - To Patch Small Boiler
	5415	Consolidated Steel Corporation
		Terminal Island - Dock Street Yard
		To Rebrick Firebox in Donkey Boiler
	5416	National Ship Service Co. Inc.
		S. S. "Oxford" (APA-189)
		To Renew Floors and one Back Wall in Two (2) Blrs
)	5417	Consolidated Steel Corporation
		S. S. "Midwest Farmer" -
		The state of the s

To Rebrick Galley Range Firebox

5418	Eastern Smelting & Refining Co Los Angeles
	Repairs to #1 Lead Furnace
5419	Stauffer Chemical Co Torrance
	To Repair Insulation on Experimental Unit
	The state of the s
5420	Craig Shipbuilding Company
	M. V. "Tjisadane" - To Repair Brickwork Disturbed
·.	in Removing Baffle
	Language to Carlot and the second of the second
5421	Morse Boulger Destructor Company
	New York Merchandise Co Los Angeles
	Construction of One (1) Type 2-R Incinerator
5422	Union Oil Company of Calif Wilmington - Los Angeles Refinery - Incinerator Brickwork
Processing	
5423	Shell Oil Company, Inc Dominguez Refinery
special endings	#2 Boiler - Furnace Brickwork Repairs
5424	Shell Chemical Corporation - Dominguez
	Acid Brickwork Repairs on Acid Cooling Tank #T-74
5425	Bethlehem Steel Company
	S. S. "Hadley" - To Repair Two (2) Boilers
(A)	Material only
5426	W. P. Fuller & Co Los Angeles
•	Repair 600 gal. Pebble Mill
5427	Reconstruction Finance Corp.
	Southern California Gas Co., Agents
	Los Angeles - Aliso Street Station
	Insulation Repairs

	5428	Standard Shiphuilding Corporation - San Fedro	
	,	S. S. "Marigold"	
		To Rebrick Fireboxes of Four (4) Galley Ranges	
		and the second s	
	5429	Oil Field Construction Co.	
		Ardens Farms Company - Los Angeles	
		Brick Setting - One (1) 66" x 16'-0" HRT Boiler	
8.S.B			
7 (S ) 27 (S ) 28 (S )	5430	Anaheim Citrus Products Co. Ltd Anaheim	
		Dryer Furnace Brickwork	
901-:+ R			
o S	5431	Consolidated Steel Corporation	
		Terminal Island - Dock Street Yard	
		S. S. "Bradford" (DD-545	
		To Repair #1, #2, #3 and #4 Boilers	
	Feb. 1946		
	5432	Reconstruction Finance Corp.	
	A-Z	Southern California Gas Company, Agents	
		Los Angeles - Aliso Street Station - Insulation	
	5433	Travis Milling Company - Blythe	
		Repairs to Ardrier Furnace	
	5434	Pomona Tile Mfg. Co North Hollywood	
		Brickwork on Four (4) Tunnel Kilns of Allied	
		Eng. Company Design	
	5435	Reconstruction Finance Corp.	
		Southern California Gas Co., Agents - Los Angeles	
7		Aliso Street Station - Insulation Repairs	
	5436	Standard Oil Company of Calif El Segundo	
	pr = 40°	Pressure Stills 1A and 1B - Detrick End Walls	

Work

2431	President Off Company of Court Br pesmino
	Pressure Stills 1A and 1B
	To Rebuild One (1) Center Wall
(A)	Replacement of One (1) 18" Side Wall
(B)	Partial Relining of #1 Unit Stack
	a Albana de la carón tradición.
5438	Consolidated Steel Corporation - Wilmington Yard, Berth #8
	Hull #1360 - S. S. "Ocean Royer" - Port Boiler Repairs
5439	Eastern Smelting & Refining Co Los Angeles
	Brickwork Repairs to Brass Furnace
5440	Pioneer Boiler Works
	California Rendering Company - Los Angeles
	Brick Setting for One (1) Class "K" No. 27 Stirling
	Boiler
5441	Bethlehem Steel Company
	S. S. "California" - To Rebrick Fireboxes of Three
	(3) Boilers
,	
5442	Standard Shipbuilding Corporation
	A0-61 - To Repair Four (4) Boilers
(A)	To Rebrick Three (3) Galley Ranges
(B)	To Remove and Renew Front and Back Walls of #2 Boiler
(C)	Insulation on Walls
5443	Wilmington Welding & Boiler Works
	DD-513 - Repairs to Four (4) Boilers
* *	
5444	Industrial Engineers, Inc.
	Halliburton Company - Los Angeles
	Acid Brick Lining in One (1) 3 x 25 x 4 ft. Sul-
*	phuric Acid Tank
(A)	Additional Acid Brickwork

		Southern California Gas Company - Los Angeles
		Aliso Street Plant
		To Install Floor of One (1) Oven
	5446	San Diego Gas & Electric Company - San Diego
		Furnace #24 - Brickwork Repairs
U. S. A.	(A)	To Rebuild Front Wall and Two Front Side Piers -
<b>A</b>	·	Furnace #21
\$9 6x	(B)	Furnace #28 Repairs
2	(C)	Furnace #25 - To Rebuild Front Wall
o o zr	(D)	Furnace #23 Repairs
	, ,	
	5447	Craig Shipbuilding Company
		S. S. "Kaposia" - Brick Two (2) Boiler Fronts
	(A)	To Repair Brickwork on Two (2) Boilers and Seal
	, ,	
4	5448	Morse Boulger Destructor Company
		St. Mary's Hospital - Long Beach
		To Construct One (1) Incinerator
	5449	Wilmington Welding & Boiler Works
	7 7	DD-547 - Renew Plastic Fronts on #1, #2, #3 and
		#4 Boilers
	(A)	To Renew Chrome
	(~~)	
	5450	Consolidated Steel Corporation - Dock Street Yard
		To Rebrick Firebox of Stationary Boiler
	5451	Hodgson-Greene-Haldeman Shipbuilders
	7.7	S. S. "Edwin M. Stanton" -
		To Rebrick Firebox of Galley Range
	5452	Hodgson-Greene-Haldeman Shipbuilders /Boiler
	- "	S. S. "Sea Runner" - Patch Corbel on Floor of Por

Ribesco Iron & Steel Company

5445

5453	Foster Wheeler Corporation
	Standard Oil Company of Calif El Segundo
	Brickwork - One (1) F-W Steam Generator
5454	Bethlehem Steel Company /es
	S. S. "Frank G. Drum" - To Repair Nine (9) Furn. Arch-
(A)	To Rebrick One (1) Galley Range
5455	Todd Pacific Shipyards, Inc.
	S. S. "W. S. Miller" - To Renew Nine (9) Furnace
	Fronts and Nine (9) Furnace Horse Collars
5456	Consolidated Steel Corporation
	S. S. "Grande Ronde" - To Repair Two (2) Boilers
(A)	To Repair Four (4) Superheater Doors
	The second of th
5457	Consolidated Steel Corporation
	LST-1066 - To Renew Refractory Lining in Small Blr.
(A)	To Rebrick Galley Oil Range
5458	C. C. Moore & Co. Engineers
	Southern California Edison Co., Ltd Long Beach Steam
	Plant #3 - Baffle Work on Three (3) Boilers
(A)	Insulate Piping for Boilers #49, #50, and #51
5459	Todd Pacific Shipyards, Inc.
	S. S. "W. Windom" - To Repair Two (2) Boilers
(A)	To Renew Baffle Tile in Port and Starboard Boilers
5460	Pacific Hard Rubber Co. (div. of Stauffer Chem. Co.)
	Vernon 11 - Incinerator Repairs
(A)	Building Brickwork Repairs
5461	California Metal Enameling Co Los Angeles 11
	Brickwork Repairs - 5 x 12' Enameling Furnace

	5462	The M. W. Kellogg Company
1		General Petroleum Corp Torrance
		Brickwork for K-2 Switch House Building Fresh-Air
		Inlet Duct
	5463	The Texas Company
		S. S. "Roanoke" - To Rebrick Galley Range
U.S.A.		
	5464	Bethlehem Steel Company
il ar		S. S. "John W. Searles"
20 20 20 20		Port and Starboard Boiler Repairs
ģ		
	5465	(Cancelled)
		Oil Field Construction Co.
		Krieger Oil Company - Clearwater
1,2,1		Brickwork for One (1) 72" x 18'-0" HRT Boiler
,		
	5466	Tide Water Associated Oil Co., Associated Division
		Watson - Brickwork Repairs to #1 Heater
	5467	Consolidated Steel Corporation
		S. S. "J. W. Gibbs" - To Rebrick Firebox on
		Galley Stove
	5468	Consolidated Steel Corporation
		S. S. "E. C. Gardner" - To Repair Port Boiler
	5469	Shell Oil Company, Iznc Wilmington .
		Boilers #3 and #4 - Brickwork Repairs
	(A)	Boilers #1 and #2
	(B)	Boiler #6
	5470	California Vinyards Assn.
		Roma Wine Company - Fresno
		Brickwork Repairs to Dryer Furnace

5471	Consolidated Steel Corporation
	S. S. "Wagon Box" - To Repair Two (2) Boilers
5472	Consolidated Steel Corporation
	S. S. "Casper S. Yost" - To Repair Galley Range
(A)	To Repair Port and Starboard Boilers
V***	
5473	West End Chemical Company - Westend
/ · 1 · d	To Renew Brick Lining in Tapered Lime Kiln #1
(A)	To Repair Calciner #L
\*** <i>,</i>	
5474	Hodgson-Greene-Haldeman Shipbuilders
フェー・	S. S. "Sea Fiddler" - To Renew Brickwork in Fireboxes
	of Two (2) Bake Ovens in Troop Galley
5475	Eastern Smelting & Refining Co Los Angeles
	Repairs to Lead Furnace Flue
(A)	Install Inverted Arch Bridge Wall in Lead Furnace
(**)	
5476	Southwestern Engineering Company
	Johns-Manville Corp Slauson Avenue Plant
	Brickwork and Insulation Lining for Three (3)
ia i	Asphalt Pots; and Burner Equipment
March 19	46
ALLEGE CONTRACTOR OF THE PROPERTY OF THE PROPE	Todd Pacific Shipyards Inc.
/ * * · * · * · · · · · · · · · · · · ·	S. S. "F. H. Hillman" - To Repair Eleven (11) Front
	Arches and Eleven (1) Horse Collars in Three (3) Blrs.
5478	Modd Pacific Shinyards Inc
, ,	S. S. "Sea Star" - Repair Port Boiler and Super-
(A)	Additional Repairs to Walls and Renew Entire Floor
(B)	Remove and Renew Tile on Three (3) Breeching Doors
3." f	of Starboard Boiler
(C)	Additional Brickwork on Starboard Boiler
% " /	5

	5479	Todd Pacific Shipyards Inc.
1	,	S. S. "Lucian Labaudt" - Brick Seal on One (1)
/		Furnace
	5480	Todd Pacific Shipyards Inc.
	6	S. S. "Syosset" - To Repair Port and Starboard Blrs.
2	(A)	To Remove and Renew Vitrecast on Four (4) Heater
THE USA		Panels and Patch Front Wall of Starboard Boiler
A.		
A ec	5481	Consolidated Steel Corporation
( a ( a)		S. S. "Sea Flyer" - To Renew Floor in Port Boiler
é		and Tubes
	5482	Wilmington Welding and Boiler Works
		LST-901 - To Rebrick Firebox in Galley Range
)	(A)	To Repair Fire Brick in Boilers
	5483	Consolidated Steel Corporation
		S. S. "Marshall Victory"
		Brick Seal in Two (2) Boilers
	(A)	To Rebrick Galley Range
	5484	Shell Oil Company, Inc Dominguez
		To Install Burner Tile in Boiler #5
	يعتم ي	
	5485	Shell Chemical Corporation - Dominguez
		To Repair Acid Tank #74
	-1.07	
	5486	Consolidated Steel Corporation
		S. S. "Arapahoe" - To Renew Plastic Fire Brick
		in Galley Range
	e l. Ora	Cohumanhay Hall Danya Commention Court Cont
	5487	Schumacher Wall Board Corporation - South Gate
		Brickwork Repairs - Dryer Furnace #2

5488	Scriver & Quinn, Inc Los Angeles	a. 38.27
a de Medicas conde	To Reline Pebble Mills	
5489	General Petroleum Corp Torrance	
	Brickwork and Insulation	and the second second
	One (1) 25,000,000 B.t.u. Oil Heater	
(A)	To Install Roof on Gas Plant Heater #2	n asa pina mina j
(B)	To Install Precast Hanging Bridge Wall on	Gas Plant
	Heater #2	g
5490	Todd Pacific Shipyards Inc. (Cancelled)	
	S. S. "Kingsbury" - Repair Three (3) Front	Arches
5491	Mohawk Petroleum Corp Bakersfield	· · · · · · · · · · · · · · · · · · ·
	Brickwork Repairs to Heater D-11	
	and the second has been a substituted in the second	,
5492	Southern California Edison Company Ltd.	
	Long Beach Steam Plant	
	To Repair Furnace Front Wall on Boiler #2	in Plant #3
(A)	Boiler #49 Repairs	
	The second secon	
5493	Todd Pacific Shipyards Inc.	
	S. S. "A. C. Rubel" - To Repair Boilers	
5494	V. V. Lokie	
	Melody Record Company - Hollywood	
	Boiler Brickwork and Insulation	
	· ·	
5495	Great Lakes Carbon Corporation	Section 18
	Dicalite Division - Walteria, Calif.	
	To Rebrick Two (2) Furnaces	
	· ·	
5496	Forest Lawn Memorial-Park Association, Inc	Glendale
	To Reline Two (2) Crematory Retorts	
(A)	To Repair One (1) Greenhouse Boiler	

	5497	Wilmington Welding & Boiler Works
¥		HULL DE-420 - To Rebrick #2 Boiler
	(A)	To Rebrick #1 Boiler
	5498	Consolidated Steel Corporation - Newport Beach
		LCS-46 - To Rebrick Galley Range
«€ «€	(A)	To Insulate Aux. Boiler
	5499	Todd Pacific Shipyards Inc.
ar ar		S. S. "Robert L. Hague" - To Repair Two (2) Blrs.
8 6 6	5500	Consolidated Steel Corporation
		S. S. "Bear Paw" o
		To Repair and Patch Chrome on Two (2) Boilers
	(A)	To Renew Insulation in Five (5) Superheater Doors
· ·		in Boilers
-		
	5501	Richfield Oil Corporation - Long Beach, Marine Term. #3
		Repairs to Firebox of HRT Boiler
	5502	Todd Pacific Shipyards Inc.
		S. S. "Broad River" - To Repair Two (2) Boilers
	5503	Pacific States Oil Co Wilmington
		#3 Boiler Brickwork Repairs
	5504	Consolidated Steel Corporation
		S. S. "Moses Brown" - To Renew Brick in Galley Rang
	(A)	Brick Seal in Two (2) Boilers
	5505	Standard Shipbuilding Corporation
		AO-22 - To Repair Four (4) Boilerslabor only
	(A)	Brickwork per Item 189E on all Boilers

	550	Reconstruction Finance Corporation
		Southern California Gas Company, Agents - Los Angeles
		Aliso Street Station - Insulation Repairs
	550	7 Consolidated Steel Corporation
		S. S. "Oneida Victory" - To Repair Boiler
	(A	Boiler Repairs
	550	8 Wilmington Welding & Boiler Works
	meson-constitutivity description	Hull #DE-345 - To Repair Two (2) Boilers
	55°	9 Consolidated Steel Corporation
		S. S. "Hector" (AR7)
E -		To Rebrick Four (4) Boilerslabor only
- <u>4 - 1 - 1</u>	10.546 10.546	
	551	O Western Pipe & Steel Company of California
	Silver Color	Hull #110 - To Patch Floor of Starboard Boiler
	(A	
	A CONTRACTOR OF THE CONTRACTOR	
	551	Axelson Manufacturing Co Vernon
	Sandi Constitution	Brickwork - General Electric Tempering Furnace
	551	2 The Dow Chemical Company, Agent of
	. ,	Reconstruction Finance Corporation
		Los Angeles Styrene Plant - Los Angeles -
	Target video on the control of the c	To Line and install Partition Walls in One (1)
	Spiritual and the spiritual and spiritual an	6'-5" I. D. x 42'-0" Vertical Ethyl-Benzene Reactor
	Tara Salah S	0 1) 1. p. x 42 10, you drough house the
	ce)	
	551	
		LCS-48 - To Insulate and Rebrick Galley Range
	(A	To Repair Fire Walls of Steam Generator
	9	
	551	4 Consolidated Steel Corporation
	•	LSM-857 - To Repair Boiler

	5515	Consolidated Steel Corporation - Newport Beach
	er i mer in i	S. S. LCI-818 - To Rebrick Two (2) Galley Ranges
	5516	Harbor Boat Building Co.
		U. S. S. "Key" (DE-348) - To Renew Brickwork
		and Insulation in Two (2) Boilerslabor only
5,5	5517	Consolidated Steel Corporation
		S. S. "Lumberlady" - To Repair Arches of Main Blr.
M m		
21 22 43	5518	Consolidated Steel Corporation
ė.		S. S. "Point Pleasant" - To Repair Two (2) Blrs.
	(A)	Insulate Two (2) Superheater Doors
	5519	Norris Stamping and Manufacturing Co Los Angeles
<b>\</b>		Acid Resistant Brickwork in Stainless Steel
		Cooking Utensil Plating Sump and Trenches
	(A)	Acid Resistant Brickwork - Sand Trap in Pickle
		Room for Porcelain Plant
	(B)	Acid Resistant Brickwork - Sand Trap for Cronak
		Machine
	April 19	<u> 46</u>
	5520	Filtrol Corporation - Vernon
		Exterior Insulation of Calciner
	5521	Reconstruction Finance Corporation
		Southern California Gas Co., Agents - Los Angeles
		Jackson Street Station - Insulation Repairs
	5522	Reconstruction Finance Corporation
		Southern California Gas Co., Agents - Los Angeles
		Ducommun Street Station - Insulation Repairs

5523	Reconstruction Finance Corporation
	Southern California Gas Co., Agents - Los Angeles
And a single state of the state	Macy Street Station - Insulation Repairs
5524	Bethlehem Steel Company
	M. V. "Rhode Island" -
	To Reline Ovens and Casing of Two (2) Galley Ranges
(A)	Tear out and Renew Back Wall of Two (2) Boilers
5525	Standard Shipbuilding Corporation
	S. S. "Young America" - To Rebrick Bake Oven
. (A)	To Renew Brick on Four (4) Inspection Doors
(B)	To Renew Brick on Four (4) Inspection Doors on
	Starboard Side
5526	Standard Shipbuilding Corporation
	S. S. "Commando" - To Repair Boiler
5527	Wilshire Oil Company, Inc Norwalk Refinery
	Brickwork Repairs to Rerum Heater
5528	Richfield Oil Corporation - Watson Refinery
	Watson Gasoline Treating Plant
	Brickwork - Skirts of Two (2) Agitators
5529	Stauffer Chemical Company - Vernon
	Acid Brick Lining for Surge Box
5530	Morse Boulger Destructor Company
	American Airlines, Inc Los Angeles
	To Construct One (1) Destructor
Now the second of the	
5531	Hodgson-Greene-Haldeman Shipbuilders
	DE-347 - Rebrick and Insulate Two (2) Boilerslabor
	only

	5532	Bechtel Bros. McCone Company
	,	Standard Oil Company of Calif.
		Mohawk Plant #2 - Bakersfield
		Brickwork and Insulation Repairs on H-1, H-2,
		and Boiler #1.
	5533	Standard Shipbuilding Corporation
R THE WAS A		To Rebrick Two (2) Boilers in Yardlabor only
A .		
Ĭ	5534	Consolidated Steel Corporation
i i i i i i i i i i i i i i i i i i i		S. S. "Claremont Victory"
8		Repairs to two (2) Boilers
	5535	California Portland Cement Co Colton
		Repairs to #8 Kiln Hood, Stackbase, and Cooler
1		Hopper
7		
	5536	National Ship Service Co., Inc.
		U. S. S. "Rowan" (DD-782)
		Repairs to #1, #2, #3, and #4 Boilers
	5537	Pacific Clay Products - Los Nietos - Plant #6
		Allied Sewer Pipe Tunnel Kiln #1
	(A)	Tunnel Kiln Car Tops
	5538	National Ship Service Co., Inc.
		U. S. S. "Pratt" (DE-363)
		Labor only, Two (2) Boilers
j	5539	National Ship Service Co., Inc.
/		U. S. S. "Goss" (DE-444)
		Labor only, Two (2) Boilers
	5540	National Ship Service Co., Inc.
		DE-360 - Labor only, Two (2) Boilers

5541	Eastern Smelting & Refining Co Los Angeles
	To Repair Lead Smelter
an argument and argument argument and argument	and the state of the
5542	(Cancelled)
	Harbor Boat Building Co.
	LCI-1003 - Galley Range
5543	Todd Pacific Shipyards Inc.
	S. S. "Cape Sandy" - To Repair Port Boiler
5544	Union Oil Company of Calif Wilmington Refinery
	Repairs to Lummus Heater B-3B, Unit #33
5545	Anaheim Citrus Products Co., Ltd Anaheim
	To Construct Refractory Lining in One (1) Cylin-
	drical Air Heating Furnace
5546	Reconstruction Finance Corporation
	Shell Chemical Corporation, Agent
	Los Angeles - Torrance Plant -
	Yarrow Boiler #5 - Furnace Brickwork Repairs
(A)	To Renew Brick Lining in Yarrow Boiler #3
(B)	Yarrow Boiler #6 Repairs
	And the second s
5547	Morse Boulger Destructor Company
	Queen of Angels Hospital - Los Angeles
	To Construct One (1) Destructor
5548	Shell Oil Company, Inc Dominguez
	Catalytic Cracking Plant - Regenerator D-2 Lining
	Alterations
(A)	Furnace #13 Brickwork Repairs
(B)	B-1 Heater Brickwork Repairs

	5549	Eastern Smelting & Refining Co Los Angeles
1		To Repair Brass Furnace
	(A)	Brickwork Repairs
	5550	Hotel del Coronado - Coronado
	1	To Renew Brickwork for Two (2) Kidwell Water Tube
1. S.A.	(X) (A) 5551	Boilers To Patch Boiler Bridge Wall To Repair Bridge Wall of #2 Boiler Reed Roller Bit Company - Los Angeles
er er		To Renew Hearth on One (1) 3' x 6' Knapp Furnace
<u>0</u> 2	5552	The Harshaw Chemical Company - El Segundo
		To Reline Refining Furnace
	(A)	To Install Fire Brick Lining in Ladle
1,000	5553	Southwestern Engineering Company
		Standard Oil Company of Calif El Segundo
		Brickwork and Insulation -
		One (1) Fired Asphalt Heater
	5554	Wilmington Welding & Boiler Works
		Hull #LCI-969 - To Rebrick Firebox in Galley Range
	5555	Wilmington Transportation Company - Wilmington
		Berth #184 - S. S. "Catalina"
		To Repair Four (4) B. & W. Boilers
	(A)	Metal Repairs and Painting
	5556	Southern California Edison Company Ltd Long Beach
		Steam Plant - Furnace Repairs to #54 Boiler
	5557	Coast Fishing Company, Inc Wilmington
		To Rebrick Boiler Front

5558	Todd Pacific Shipyards Inc.
	S. S. "Paul M. Gregg" - To Repair Two (2) Boilers
5559	Standard Oil Company of Calif El Segundo
	Incinerator Erection
May 19	<u> 16</u>
5560	Hercules Forge Corporation - Los Angeles
	To Rebrick 4 x 3' Forge Furnace
(A)	To Rebrick 3½ x 2' Forge Furnace
,	
5561	Western Talc Company - Los Angeles
,	Construction of One (1) 1,800,000 B.t.u. Air Heater
(A)	Insulation on 20" dia. Hot Air Duct on Air Heater
5562	Gladding, McBean & Company - Los Angeles -
	Glendale Plant - Brickwork of One (1) 430 ft.
	long Sewer Pipe Tunnel Kiln
~ ~ C ~	Control of Control of Control of the
5563	Great Lakes Carbon Corporation - Wilmington
	Repair Kiln, Stack and Breeching
ee().	C. C. Marray C. Co. The prima care
5564	C. C. Moore & Co. Engineers
	Santa Barbara Cottage Hospital - Santa Barbara One (1) Class H-3 No. 14 Stirling Boiler - Brick-
	work Repairs
5565	Bethlehem Steel Company
	S. S. "Coast Shipper" - To Repair One (1) Boiler
5566	Consolidated Steel Corporation - Terminal Island
7,00	Dock Street Yard - S. S. "Sea Runner"
•	To Rebrick Starboard Boiler
/ a \	
(A)	To Repair Port Boiler

	5567	C. C. Moore & Co. Engineers
	. A man man war	United Linen Supply Co Los Angeles
		Brick Setting - One (1) Class H4 No. 30 Stirling Blu
	5568	C. C. Moore & Co. Engineers
		Blue Diamond Corporation - Arden, Nevada
		#1 Boiler Brickwork Repairs - A Class H-30 No. 10
5.5.A		
_	5569	Process Equipment Co.
A		Kern Food Products, Inc Los Angeles
7.		Refractory and Insulation Enclosure -
- 55 - 6		One (1) 250 h.p. Heine Shipping Board Boiler
	5570	Fernstrom Paper Mills, Inc Pomona, Calif.
		Aertite Work on One (1) Class H3 No. 17 BWW Blr.
	5571	Arthur E. Gray, Plumbing
)	) / I ····	Alvadale Apts., 1443 No. Alvarado, Los Angeles
		Insulation - One (1) Domestic Heating Boiler
	5572	Pacific Coast Borax Company - Wilmington
	&(A)	Install Brickwork in Borax Fusing Furnace
	5573	Edge Moor Iron Works, Inc.
	));J	United States Gypsum Company - South Gate
		Boiler Enclosures - Two (2) Edge Moor Steam
		Generating Units
	5574	Standard Oil Company of Calif El Segundo
	7717	Petro-Chem Furnace F-2 Roof Arch Repairs
)	5575	C. C. Moore & Co. Engineers
		Stone & Webster Engineering Corp. Southern California Edison Company, Ltd Redondo
* *		New Steam Plant - Four (4) type "RB" B. & W.
		Boilers - Brickwork and Insulation

5576	Great Lakes Carbon Corp., Dicalite Division - Torrance
	Permalite Plant #1 - Special Products Division
ere e spark e skoatenska de oakte	Repairs to Furnace #1
(A)	Repairs to Furnace #1 - Permalite Division, Torrance
(B)	Laboratory Furnace - Permalite Division, Torrance
5577	Consolidated Steel Corporation
•	S. S. "Moina Michael" - Repair Two (2) Boilers
5578	Gaffers & Sattler - Vernon
	To Repair Muffle in Enameling Furnace
5579	Standard Gypsum Company of California - Long Beach
ø · .	Brickwork - One (1) 10' x 8' Calcining Kettle
5580	Eastern Smelting & Refining Co Los Angeles
	To Repair Stack on Brass Furnace
5581	OFCCO Construction Co., Inc. (formerly Oil Field Const. Co
	Van Camp Sea Food Co San Diego
	Brick Setting - One (1) Single, type "A" Union Bent
	Tube Boiler
5582	Shell Oil Company, Inc Dominguez Refinery
	Boiler #3 - Furnace Brickwork Repairs
5583	Reconstruction Finance Corporation
	The Dow Chemical Company, Agent - Los Angeles
	Los Angeles Styrene Plant - Brickwork - One (1)
	6'-5" I.D. x 42'-0" Vertical Ethylbenzine Reactor
5584	The Texas Company - Wilmington /Still #1
*	Brickwork Repairs in Heater Furnace of Pressure Pipe
(A)	Los Angeles Works: Misc. Brickwork Repairs #2 Boiler
	in #2 Boiler House; & Blrs. #3 to #8 incommon )# holder.
*****	

	5584 (co	ntd.)
	(B)	Los Angeles Terminal
, promote programme of the second of the sec		To Renew Walls and Floor Line Inside Boiler
	5585	Hodgson-Greene-Haldeman Shipbuilders
		S. S. "Elbrus" - To Repair Plastic around Burner Cones
U.S.A.	5586	U. S. Naval Base - Public Works Dept.
100 A		U. S. Naval Hospital - Corona, Calif.
661 		Brickwork Repairs to Firebox of One (1) Cleaver- Brooks Boiler
5	5587	Averill-Morgan Company, Inc Hollywood
	))O <sub>1</sub>	To Repair Boiler
)	5588	Eastern Smelting & Refining Co Los Angeles To Repair Brass Furnace
	5589	San Diego Gas & Electric Co San Diego, Sta. "A"  Gas Generator #7 - Brickwork Repairs
	5590	Los Angeles Soap Company - Los Angeles
		Brickwork Repairs to Boiler #6
	(A)	New Boiler Baffles
	5591	The Texas Company - Wilmington S. S. "Arkansas" - To Repair Brickwork on Front
		and Rear Walls on One (1) Boiler
	5592	Todd Pacific Shipyards Inc.
)	- "	S. S. "Charles S. Jones" - To Patch Two (2) Blrs
	5593	Eastern Smelting & Refining Co Los Angeles

To Repair #1 Lead Furnace

DD94	S. S. Freeman & Company
	Steamer "Daisy Gray" - To Renew Brick and Insula-
*	tion of Brick Wall - #1 Boiler
5595	Los Angeles Soap Company - Los Angeles - Boiler House
	Repairs to Walls in #6 Llewellyn Boiler
June 19	46
5596	Bethlehem Steel Company
Market I state when a	S. S. "Coxcombe Hills" - Repairs to Starboard Boiler
5597	Consolidated Steel Corporation
	S. S. "Fort Dearborn"
	To Patch Burner Chrome in Two (2) Boilers
(A)	To Renew Brickwork in Port Boiler
(B)	To Insulate Four (4) Superheater Doors
5598	Bechtel Brothers McCone Co.
	Reconstruction Finance Corporation
	Standard Oil Company of Calif., Agent - El Segundo
	Butadiene Plant - Brickwork Repairs to Reactors, etc.
(A)	Brickwork Repairs to Airling and Heaters
(B)	To Install 5" Sleeves in Heaters B-ll and B-12
5599	Filtrol Corporation - Jackson, Miss.
	One (1) 4,000,000 B.t.u. Line Burnermaterial only
e was a second	
5600	Associated Molding Company - Los Angeles
	Incinerator Brickwork Repairs
5601	Lohman Bros.
	The United Rexall Drug Co Los Angeles
	Brick Bases for Three (3) Titusville Boilers

¥....

	5602	Mead Johnson and Company - Torrance
)	e de la companya de l	Boiler Brickwork Repairs
	5603	Goodyear Tire and Rubber Company of Calif L. A.
	g Principal Common to	#2 Boiler Repairs
		#3 Boiler Repairs
		#4 Boiler Repairs
\$1 \$2 \$2		
1	5604	The Petrol Corporation - Los Angeles - Bandini Refinery
A æ		Brickwork Repairs to Fireboxes and to Install New
15		Burners in Three (3) Shell Stills
ģ		
	5605	Shell Oil Company, Inc Wilmington Refinery
		Boiler #3 - Brickwork Repairs to Curtain Wall,
		Side Wall and Bridge Wall
1		
	5606	Southern California Edison Co., Ltd Long Beach Steam
		Plant - Boiler #28 - To Rebrick Front Wall
	5607	American Cyanamid & Chemical Corp Azusa
		Fire Brick and Insulation Lining -
		Synthetic Resin Kettle
	5608	Harbor Boat Building Co.
		U. S. S. "Jaccard" (DE-355)
		Boiler Brickwork and Insulation
	5609	Harbor Boat Building Co.
		U. S. S. "Acree" (DE-356)
)		Boiler Brickwork and Insulation
f		
	5610	Federated Metals Division, Amer. Smelting & Ref. Co
		Los Angeles - To Repair #2 Brass Reverb. Furnace

5611	Todd Pacific Shipyards, Inc.
	DD-660 - To Renew Brickwork on Four (4) Boilers
5612	Todd Pacific Shipyards, Inc.
	S. S. "Day Star" - To Renew Brickwork in One (1)
	Donkey Boiler
de caracteristic constitue de caracteristic cons	
<b>561</b> 3	Foster Wheeler Corporation
	Standard Oil Company of Calif El Segundo
Working and the state of the st	To Repair #33 Boiler
5614	Wilmington Welding & Boiler Works
,	S. S. "Oregon Coast" -
	To Repair Two (2) B. & W. Boilers
F500	
5615	Sorcha Boru Ceramics - San Carlos, Calif.
	Minton Sliding Slab Kiln
5616	California Portland Cement Co Colton
Out the state of t	To Repair Baffle Walls - Wet End Rooms
(A)	To Repair Draft Pipe #14
<b>(B)</b>	To Repair Stack Base on #15 Kiln (old #6)
(C)	To Repair #10 Kiln Hood
5617	Action Trucking Co San Pedro - Pier 54, Outer Harbor
· · · · · · · · · · · · · · · · · · ·	S. S. "West Coast"
Party in the Control of the Control	Remove and Renew Brickwork on One (1) Boiler
(A)	Remove and Renew Brickwork in Boiler; 2nd unit
5618	Southern California Edison Company, Ltd.
	Long Beach Steam Plant #2
	Boiler #37 - Furnace Repairs
5619	Consolidated Steel Corporation /#4
The state of the s	U. S. S. "Black" (DD-666) - Repr. Blrs. #1, #2, #3, &

5620	Consolidated Steel Corporation
en e	U.SS. "Chauncey" (DD-667 - To Repair Boilers
5621	Consolidated Steel Corporation
	U. S. S. "Benham" (DD-796)
	To Repair Floor and Chrome in Boiler #1
5622	Union Oil Company of Calif Wilmington
	To Repair Cracking Kiln at T. C. C. Unit
(A)	To Install Access Doors and Partitions, zones
	1 through 7
5623	Foster Wheeler Corporation
	for Blaw Knox Construction Co.
	for General Electric Co Anaheim
	One (1) Dowtherm Vaporizer Setting
5624	The Texas Company - Fillmore Works - Fillmore
	Repairs to Settings of HRT Blrs. #4, #5, and #6
•	
5625	California-Oregon Paper Mills - Vernon
	Acid-Brick Lining Repairs
5626	Bethlehem Steel Company
	S. S. "Enid Victory"
	To Repair Starboard and Port Boilers
(A)-	To Repair Floor in Port Boiler
5627	The Texas Company - Wilmington - Los Angeles Works
	To Remove and to Renew West Furnace Wall -
	Pressure Pipe Still #2
5628	Hercules Forge Corporation - Los Angeles
	To Repair Arch in #1 Furnace

10. 301-11 R CONTROLS U.S.A.

5629	Pacific Coast Borax Co Boron
&(A)	To Rebrick One (1) Beik Furnace and to Repair
	Calciner #6
(B)	To Repair Brickwork in Calciner #6
	The second secon
5630	California Portland Cement Co Colton
	One (1) 10 ft. dia. Rotary Kiln Firing Hood
(A)	Brick Repairs to #15 Cooler Hopper
5631	San Diego Gas & Electric Co Gas Plant, 10th & Imperial
	San Diego - Brickwork on Dome of Generator
5632	The Paraffine Companies, Inc South Gate
	Repairs to Ducts of Calcining Furnace
5633	Federated Metals Division, Amer. Smelting & Refining Co
)- <b>3</b> 3	Los Angeles - To Repair U. S. Furnace
July 19	46
5634	Morse Boulger Destructor Co.
	Western Airlines, Inc Los Angeles Airport
	One (1) Model 2-R Destructor
5635	The Arrow Plating Company - Los Angeles
	Acid Brickwork
5636	Federated Metals Division, Amer. Smelting & Ref. Co LA
7-0-	To Rebuild #3 Aluminum Reverberatory Furnace
(A)	To Change Chlorine Ports of Reverb. Furnace
(B)	To Change Puddler Well Arch
(c)	To Change Chlorine Ports
5637	Eastern Smelting & Refining Co Los Angeles
	To Repair Small Lead Furnace

	5638	Consolidated Steel Corporation
1	,	S. S. "Hope" - To Rebrick Five (5) Galley Ranges
	(A)	To Repair Boiler #2
	5639	Vegetable Oil Products Co., Inc Wilmington To Repair B. & W. Boiler #3
	5640	The Texas Company - Los Angeles Works - Wilmington Repairs to #1 Furnace in #1 Pressure Pipe Still
	5641	Wilshire Oil Company, Inc Norwalk Refinery To Spray-Coat Fireboxes of Boilers Nos. 1, 2, 3 &
	5642	Stauffer Chemical Company - Vernon To Line Firebox of Sulphur Melting Pot
- Andrews	5643	Socal Oil & Refining Company - Huntington Beach Brickwork Repairs to Re-Run Heater
	5644 <b>A-</b> U	Southern California Gas Co., Agent of Reconstruction Finance Corp.  Ducommun Street and Aliso Street Stations Brickwork Repairs
	5645	Los Angeles Union Passenger Terminal - Los Angeles Boiler #1 - Brickwork and Insulation Repairs
)	5646	General Chemical Co El Segundo  Brickwork Repairs to Linings of Two (2) Combustion  Chambers and Arch in Hydrofluric Acid Furnace
,	5647	Todd Pacific Shipyards Inc.  S. S. "Victor H. Kelly" - To Repair Two (2) Boiler

5648	Acme Brewing Company - Vernon
ing Guileann an ann a	Repair Baffles - Boiler #1
	The second secon
5649	Utility Electric Steel Foundry - Vernon
	To Repair Annealing Furnace
	The second of th
5650	Shell Oil Company, Inc Dominguez
-	#7 Dubbs Brickwork Repairs - Fire Damage Portion
(A)	Regular Repair Work on Dubbs Furnace #7
5651	Twentieth Century-Fox Film Corp West Los Angeles
<i>)</i>	Brickwork Repairs - Boiler Plant #1 -
	Boilers #1, #2, #3, and #4;
	Boiler Plant #2Boilers #1, #2 and #3;
	Upright Portable Boiler; and Portable Scotch
	Marine Boiler
	Partition Bollion
5652	Union Oil Company of Calif Wilmington, Berth #150
<i>)</i>	S. S. "Paul M. Gregg" - To Repair Boiler
	D. D. 1888 H. Grope To Hopelan Bound
5653	Amling Brothers - 2420 W. 5th, Santa Ana
<i>J</i> • <i>J</i> •	Repairs to Rear Wall and Arch in Boilers at Nursery
	The state of the second
5654	Todd Pacific Shipyards Inc.
***	S. S. "The Dalles" - To Repair Two (2) Boilers
(A)	To Patch Chrome Ore in Port and Starboard Boilers
5655	Los Angeles Soap Company - Los Angeles
2022	#5 Boiler Repairs
5656	Todd Pacific Shipyards Inc.
5656	
/ 4 3	S. S. "Hamilton Victory" - To Repair Two (2) Blrs.
(A)	To Patch Superheater Header of Starboard Boiler

	5657.	Bethlehem Steel Company
1		S. S. "Admiral Benson" -
1		To Remove Brickwork of Four (4) Boilers
	(A)	To Repair #1, #2, #3, #4 Boilers
	5658	Process Equipment Company
		El Tejon Oil & Refining Corp Bakersfield
		Settings for Two (2) 250 h.p. Shipping Board Blrs.
	5659	North Ontario Dried Fruit Co Los Angeles
		Repairs to Brick Wall
	5660	Consolidated Steel Corp.
		S. S. "Mormacreed" - To Renew Brickwork in Rear
		Wall of Port Boiler
	5661	Todd Pacific Shipyards Inc.
		S. S. "E. W. Eberle"
		To Repair Boilers Nos. 1, 2, 3, & 4
	(A)	To Renew Insulation
	5662	Southern Pacific Company - Colton
	*	To Rebrick Two (2) 75 h.p. Liberty Water Tube Blrs.
	5663	The Harshaw Chemical Company - El Segundo
		To Insulate Two (2) Norblo Dust Arresters,
		One (1) 85 h.p. Oil Field Boiler, and
		One (1) 3 x 6 ft. Vertical Boiler

Eastern Smelting & Refining Company - Los Angeles

To Repair #2 Brass Furnace

August 1946

5665	Federated Metals Division, Amer. Smelting & Ref. Co.
	Los Angeles - Zinc Pot Furnaces
(A)	Retort Furnaces Landau Frances
(B)	Condensers
(C)	Ladle Heater Repairs
(D)	Material
(E)	Changes on New Zinc Retort
(F)	To Line Small Ladle
m///	
5666	Wilmington Welding & Boiler Works
	Hull #APD-101 - To Remove and to Repair Brickwork
	in Two (2) Boilers
5667	Patten-Blinn Lumber Company - Wilmington
	To Repair Brickwork - One (1) Llewellyn Water Tube
	Boiler
5668	City of Glendale - Steam Plant
	To Repair Castable Areas at Tube Supports in Boiler
	Furnaces
5669	Bethlehem Steel Company
	S. S. "J. J. Coney" - To Repair Nine (9) Furnace
	Arches in Three (3) Boilers
5670	Los Angeles Soap Company - Los Angeles
	Repairs to Boiler #1 for Leahy Burner Installation
5671	Pacific Tankers, Inc.
	S. S. "Fort Stanwix" - To Repair Main Boilers
5672	Pacific States Oil Co Wilmington
	To Repair Still Furnace at Unit #1

2013	The Texas Company - wilmington
1	To Repair Heater Furnace in #3 Crude Unit Pipe Still
5674	Standard Oil Company of Calif El Segundo
	Brick Skirts for V13 and V12 Vessels at
and the second of the second	Plopylene Polymer Plant
5675	Eljer Company of California
  -  -	To Reline #4 Ball Mills in Enamel Department
(A)	To Reline Ball Mill
5676	Hodgson-Greene-Haldeman Shipbuilders
, , , , , ,	S. S. "Chaco Canyon" - To Repair Two (2) Boilers
	5. 5. Onaco canyon - 10 hapair 140 (2) Borrers
c Grara	The demonstrate Market to Definite the Among Charleston to Deep Charleston
5677	Federated Metals Division, Amer. Smelting & Ref. Co.
)	Los Angeles - To Construct One (1) Copper Cupola
	Crucible
m. C O	
5678	C. C. Moore & Co. Engineers
	Cudahy Packing Co. (formerly Tovrea Packing Co.)
	Phoenix, Arizona
	Brickwork and Insulation - One (1) FF15 No. 24 Blr.
5679	Federated Metals Division, Amer. Smelting & Ref. Co.
	Los Angeles - To Repair #2 Brass Reverb.
5680	California Portland Cement Co Colton
	To Repair #10 Cooler Hopper
5681	Pacific Clay Products - Los Nietos - Plant #6
}	To Rebuild 35 ft. dia. Downdraft Sewer Pipe Kiln
(A)	To Repair Kiln #27 (E) - To Repr. Kiln #19
(B)	To Repair Kiln #6 (F) - To Repr. Kiln #17
(C)	To Repair Kiln #23 (G) - To Repr. Kiln #3 To Repair Kiln #40
(D)	to vebout vitti 440

5682	Pacific Clay Products - Los Angeles - Plant #4
	To Repair Brickwork of #2 Tunnel Kiln
(A)	To Reline Ball Mill
5683	California Metal Enameling Co Los Angeles
	To Construct 5 x 12 ft. "V" Bottom Enameling Furnace
5684	Stauffer Chemical Company - Vernon Plant
	Acid-Proof Brick Lining in Paddle Mixer
5685	Mercy Hospital - San Diego
	Brickwork Repairs - One (1) Llewellyn Water Tube Blr.
(0)	
5686	Pacific Tankers, Inc Terminal Island
* *	S. S. "Choctaw Trail" -
	To Repair Burner Arches and to Patch Chrome
5687	Bethlehem Steel Company
	S. S. "Everglades" (AD-24) - To Repair Boiler
(A)	Superheater Doors
5688	Reconstruction Finance Corp.
	The Dow Chemical Co., Agent - Los Angeles -
	Los Angeles Styrene Plant
	New Brick Lining - One (1) 6'-5" I. D. x 42'-0"
	Vertical Ethyl Benzene Reactor
5689	Shell Oil Company, Inc Dominguez
	To Repair Boiler #7
5690	Eastern Smelting & Refining Co Los Angeles
	To Repair Heat Furnace
(A)	To Repair Throat of Draught Furnace
	· ·

	5691	The Fluor Corporation, Ltd.
1		Shell Oil Company of British Columbia, Limited
)		Vancouver, B. C., Canada
		To Rebrick North Wall in Distilling Unit of
		Crude Oil Heater
	(A)	To Install Three (3) Burners in Topping Unit of Crude Oil Heater
Parri U.S.A.	(B)	To Repair Front Wall
	5692	Southern California Edison Co., Ltd Long Beach Steam To Repair Boiler Furnace #18 - Plant #1
6 6 7	(A)	To Repair Boiler Furnace #38 - Plant #2
	5693	R. T. Collier Corporation
		Union Oil Company of Calif Wilmington Refinery
1		Brick Setting - One (1) Radiant Type Recycling
,		Gas Superheater
	5694	Federal Works Agency
	÷	Public Buildings Administration
		U. S. Post Office & Court House Building - Los Angeles
	·	Alterations to Boiler Front of Boiler #1
	5695	Hotel Del Coronado - Coronado
		To Rebuild Boiler Stack Flue
9 .	5696	Maywood Shops - Maywood
		To Repair Incinerator
	5697	The Cudahy Packing Co Los Angeles
)	7-71	Repairs to Boilers #1 and #2
	·	
	5698	General Petroleum Corporation - Vernon
	J~ J~	Power Plant #2 - Edge Moor Boiler #10 Baffle Work
		TOROT TIMES AS - DASS MOST DOTTET ATO BUTTON HOLD

Sept. 1	<u>.946</u>
5699	Los Angeles Soap Co Los Angeles
	Repairs to #2 Boiler
5700	Todd Pacific Shipyards Inc.
	S. S. "Kettle Creek" - To Repair Two (2) Boilers
5701	R C S Engineering Co.
	Stauffer Chemical Co Torrance
	Three (3) 85 h.p. Boiler Settings
(A)	Insulation of Two (2) 85 h.p. Oil Field Boilers
(B)	Insulation of Drums
J	
5702	Todd Pacific Shipyards Inc.
-	S. S. "Kings Canyon" - To Repair Two (2) Boilers
V Sterring	
5703	Warner Welded Products - Glendale
	To Reline G. E. Furnace
5704	C. C. Moore & Co. Engineers
. T	Philadelphia Quartz Co South Gate
	Brick Setting - Two (2) B. & W. Class H-3 No. 17
	Boilers
gene yang yirk jeri	G. G. Marine and G. Tharine and
5705	C. C. Moore & Co. Engineers
	Mercy Hospital - San Diego
(4)	Brick Setting - One (1) Single Class H-3 No. 14 Blr.
(A)	Extra Work
5706	C. C. Moore & Co. Engineers
7100	Pacific Coast Borax Co Wilmington
	Brick Setting - One (1) Single Class H-4 No. 24 Blr.
,	
5707	Mutual Citrus Products Company - Anaheim /box Boilers
* * *	Brick Settings - Three (3) 175 h.p. Kewanee #588 Fire-
	tanan kacamatan da k

	5708	City of Pasadena
	,	Repairs to Boilers #14 and #15
- /		
	5709	Los Angeles Soap Company - Los Angeles
		Repairs to #7 Boiler
	•	
3	5710	Wilmington Welding & Boiler Works
TELESTON OF STA		Hull #APD-91 - To Repair Two (2) Boilers
	5711	Todd Pacific Shipyards Inc.
0 0		S. S. "Tullahoma" - Remove and Replace Front
é		Walls of Two (2) Boilers
	(A)	Renew Two (2) Floors; Patch Chrome Ore in Two
		(2) Boilers
1	5712	Mercy Hospital - Bakersfield
		HRT Boiler Brickwork Repairs
	5713	American Potash & Chemical Corp Trona
		Boilers #15 and #18 - Furnace Brickwork Repairs
	(A)	#2 Furnace Repairs
	5714	Morse Boulger Destructor Co.
		Bullock's Department Store - Pasadena
		To Construct One (1) Incinerator
	(A)	To Install Two (2) Checkerworks in Incinerator
	5715	El Tejon Oil & Refining Corp Bakersfield
		To Repair Two (2) Heine Boilers
)		
	5716	Johns-Manville Products Corp Vernon
		Repairs to Asphalt Still
	5717	Todd Pacific Shipyards Inc.
		S. S. "Big Bend" - To Repair Two (2) Boilers

o de

	5718	Goodyear Tire and Rubber Co. of Calif.
	gista del transita de la companya d	Power House - Los Angeles
	Management of the control of the con	Reline Three (3) Boiler Furn. on B. & W. Boilers
	(A)	To Install Soot Blowers
	5719	Union Oil Company of Calif Wilmington -
	-	Los Angeles Refinery - T. C. C. Unit -
		Brickwork and Insulation Repairs to Kiln Lining
	5720	The Luer Packing Co Vernon
		Repairs to #1 Boiler Furnace
	(A)	Brickwork Repairs to #2 Boiler Furnace Firebox
	5721	(Cancelled)
		OFCCO Construction Co., Inc.
5700		U. S. Naval Air Base - San Diego
	Section Conference Con	Reserve Fleet Berthing Facility - Brickwork and
		Insulation - Three (3) Union Iron Works Boilers
	5722	(Cancelled)
		OFCCO Construction Co., Inc.
		U. S. Naval Repair Base - San Diego
	·	Brickwork - One (1) 400 h.p. Union Iron Works Blr.
	5723	Sierra Steel Forging Co.
		C B S Steel & Forge - Vernon
	, and the second	Furnace Repairs
	5724	Southern California Edison Co., Ltd.
		Long Beach Steam Plant
		Boiler #42 - Furnace Brickwork Repairs
	(A)	Boiler #40 Repairs (E) - Boiler #26 Repairs Boiler #39 Repairs (F) - Boiler #46 Repairs
	(B) (C)	Boiler #39 Repairs (F) - Boiler #46 Repairs Boiler #47 Repairs (G) - Boiler #35 Repairs
	(D)	Boiler #33 Repairs (H) - Boiler #36 Repairs

	- 1	
		S. S. "Jordan Valley"
<i>*</i>		Necessary Repairs to Port and Starboard Boilers
		and the common the control of the first of the control of the cont
	October	<u>1946 </u>
	5726	Simons Brick Co 7101 Rivera Rd., L. A. County,
ď	* * *	South of Montebello -
		Brick Setting - Two (2) Firebox Boilers
	(A)	Boiler Insulation
	(B)	Repair Insulation
801-11 <b>R</b>	(C)	Insulation Repairs
é	(D)	Brickwork on Firebox of Boiler
	5727	Robert L. Johnson Co.
		City of Pasadena
4		Brickwork & Insulation - Two (2) C-E Boilers
)	(A)	RCS Engineering Co.; City of Pasadena
	•	Repairs to Insulation Damaged by RCS Eng. Co.
	5728	Eastern Smelting & Refining Co Los Angeles
		Repairs to Lead Furnace
	5729	West End Chemical Co Westend
		Insulate Eight (8) Heat Exchangers and One (1)
		7'-0" dia. x 23'-8" Water Tank
	5730	General Petroleum Corp Vernon
		Vernon Power Plant No. 2 - Edge Moor Two-Drum
		Boiler #9 - Remove and Replace entire Cross
		Baffle System
)		
	5731	Todd Shipyards, Inc.
		S. S. "L. P. St. Clair" - /Boiler
		Insul., Refractory and Baffle Repairs to Forward
	(A)	Baffle Work in Aft Boiler and Repairs to Fort and
	• •	

Todd Pacific Shipyards, Inc.

5732	Pomona Tile Manufacturing Co North Hollywood Plant
	Cut Allied Kilns into Three (3) Sections
5733	Pacific Coast Borax Company - Boron
	Fabricate and Install One (1) Air Heating Furnace
ge verses ig entro	
5734	Federated Metals Division, Amer. Smelting & Ref. Co.
	Los Angeles - Brickwork Repairs to U. S. Brass Furn.
5735	OFCCO Construction Company, Inc.
	U. S. Naval Hospital - Corona
	Brick Setting - One (1) Union Type "L" Boilers
5736	Hodgson-Greene-Haldeman Shipbuilders
	S. S. "Fort Donelson" - Repair Starboard Boiler
(A)	Repair Floor in Port Boiler
, ,	
5737	Todd Pacific Shipyards Inc.
, , , ,	S. S. "Agwiworld" -
	To Repair Three (3) Furnace Fronts
5738	Reconstruction Finance Corp., Office of Rubber Reserve
,	Shell Chemical Corp., Agent - Los Angeles -
e ye	Torrance Plant - Repairs to Flat Suspended Arch on
	C-E Superheater Furnace B-201-B
5739	Buttress & McClellan, Inc.
	Republic Steel Corp Los Angeles
	Acid Brickwork to One (1) Pickle Pit
(A)	Republic Steel Corp., Union Drawn Steel Division
	Acid-Proof Brick Lining for Acid Pickle Tanks
	<u>. 111 J. 140 S. 17 No.</u>
5740	Eastern Smelting & Refining Co Los Angeles
The second secon	Repair Brass Reverberatory Furnace
(A)	Repairs to Lead Smelting Furnace

	5741	Pacific Clay Products - Los Nietos
		Insulation on Tunnel Kiln Recirculation and Pre-
	e and english the	heater Duct Work
	(A)	Insulate Hot Oil Piping
		generalization and the state of
	5742	San Diego Gas & Electric Co Station "B" - San Diego
		Boiler #26 - Brickwork Repairs
4.5.8		
ages services	5743	Richfield Oil Corporation - Watson
a -   ac		Building Construction - Labor only
1 -1 -0 2	(A)	Repair Trumble Retort
ó z	(B)	Brickwork on #799 Boiler
	(¢)	Repair Heater #810
	(D)	Polly Unit
	5744	The Texas Company - Pier 173
)		S. S. "Roanoke" - Repair Galley Range
	5745	Los Angeles Soap Company - Los Angeles
		Repairs to Boilers #3 and #4
	5746	Mission Dry Corporation - Vernon
		Repairs to Scotch Marine Boilers
	5747	The Dow Chemical Company, Agent for
		Reconstruction Finance Corporation
		Los Angeles - Los Angeles Styrene Plant
		Repairs to FF15-24 Boiler #1
	(A)	Repairs to FF Boiler #2 Firebox
		and the second of the second o
)	5748	Star Brass Foundry Co Los Angeles
		Install Carbofrax Lining in Schwarts Furnace
	5749	Associated Molding Company - Los Angeles
	-	Renaira to Incinerator

5750	Bernuth Lembcke Company, Inc.
• 	S. S. "Trimountain" - To Remove and Replace
	Chrome Ore of Back Wall, Studded Tubes and Fronts
5751	Portland Tug & Barge Company
	Tugboat "Luna" - Repairs to Galley Range
5752	Stauffer Chemical Company - Vernon
	Acid Brick Lining of 22" Pipe
5753	Federated Metals Division, Amer. Smelting & Ref. Co.
	Los Angeles
Novembe:	The state of the s
5754	Vegetable Oil Products Company, Inc Wilmington
	Install New Burner and Repair Bridge Wall of
	Superheater
5755	Great Lakes Carbon Corp., Permalite Division - Torrance
	Lining Kiln
5756	Great Lakes Carbon Corp Carbon Plant - Wilmington
	Repairs to Kiln
5757	Smoot Holman Company - Inglewood
	To Reline Ball Mill
5758	Bethlehem Steel Company
	Union Oil Company of Calif.
	Tanker S. S. "Santa Paula" - Repairs to Boiler
5759	The Petrol Corporation - Los Angeles - Bandini Refinery
	To Install Two (2) Doors in Road Oil Heaters

	5760	Gaffers & Sattler - Enamel Plant - Vernon
		To Repair Enameling Furnace #3
)		A second of the
	5761	Griffith Company
		City of Los Angeles
		Rotary Waste Disposal Plant - Brickwork
-		
	5762	Lohman Bros.
Ω.,		United Rexall Drug Co Warehouse - Vernon
2		Brick Bases - Two (2) Kewanee Boilers type 7-L-83
e e	5763	Todd Pacific Shipyard, Inc.
		S. S. "Chisholm Trail"
		Repairs to Port and Starboard Boilers
	(A)	Superheater Doors
)	5764	Morse Boulger Destructor Co.
		May Department Stores Co Wilshire & Fairfax, L. A.
		One (1) Morse Boulger Incinerator
	(A)	Material Only
	(B)	T-S Construction Engineers, Inc.; May Dept. Stores Co.
	29	Brickwork - Basement Wall
	5765	Morse Boulger Destructor Co.
		May Department Stores Co Crenshaw & Santa Barbara, L.
		One (1) Morse Boulger Incinerator
	(A)	Extra Material
	5766	The Exchange Orange Products Co Ontario
	÷ ~	Repairs to Ardrier Furnace #4
)	(A)	Repair Dryer Furnace #2
	5767	Federated Metals Division, Amer. Smelting & Ref. Co
		Los Angeles - To Install Burner Block -
		#4 Zinc Retort

5768	Old Ranchers Company - Upland
	Insulation Work on One (1) Cannery Retort
	One (1) Cleaver Brooks Boiler,
	One (1) Hot Water Tank, and Misc. Piping
(A)	Extra Pipe Insulation
5769	Reconstruction Finance Corp.
	Southern California Gas Co., Agent - Aliso Street Sta.
	Insulation Work
5770	Hickman Bros., Inc Terminal Island
	Piers "C" and "D"
	Three (3) #125 Erie Boilers - Brick Foundations
	and Fireboxes
5771	Todd Pacific Shipyard Inc.
	S. S. "Smoky Hill" - Patch Boiler Brickwork
8 v j	
5772	City of Pasadena - Light & Power Plant
	Complete Removal of Old Refractory.
	Installation of New Refractory and Supporting Steel
	necessary in Repairing Municipal Incinerator.
(A)	Twin Setting
5773	The Harshaw Chemical Company - El Segundo
	Elevator and Conveyor Insulation
(A)	Insulate $30\frac{1}{4}$ " Fume Duct
(B)	Insulate 1/2" x 1" Oil Line
5774	Federated Metals Division, Amer. Smelting & Ref. Co.
	Los Angeles - Repair #2 Brass Reverb. Furnace
(A)	Reline #4 Zinc Retort Furnace Condenser and
$\frac{\partial \mathcal{L}}{\partial x} = \left( \mathbf{v} - \mathbf{v}_{\mathbf{k}} - \mathbf{a} \right)$	Raising Burner Blocks 7"
(B)	Reline #1, #2, #3 Retort Condenser and Choked Flues
	to 11" Opening t

	······································	
	5775	Reconstruction Finance Corp.
	,	Shell Chemical Corp Torrance Plant - Los Angeles
		Re-insulate One (1) Reactor D-201-B
	5776	Bethlehem Steel Company
		S. S. "Silver Star"
		Patch Burner Front and Rear Wall
8.5.A.	•	
å.	5777	C. F. Braun & Co.
Space of patricial	7111	Arabian-American Oil Company (Export) - Arabia
		Material only - Two (2) 10 x 10 x 20 Heaters
- 19 - 19		
<i>7</i>	:	
	5778	C. F. Braun & Co.
		Standard Oil Company of New Jersey - Baton Rouge, La.
		Material only - Two (2) 12 x 15 x 30 Heaters
1		
	5779	Los Angeles Union Passenger Terminal - Los Angeles
		Boiler #2 - Brickwork and Insulation Repairs
	5780	Stauffer Chemical Co Torrance
		To Construct New Pipe Heating Furnace
	December	1946
	5781	Shell Oil Company, Inc Dominguez
		To Repair #2 Dubbs
	5782	Shell Oil Company, Inc Wilmington Refinery
		Boiler #5 - Furnace Brickwork Repairs
		The second of th
	5783	Coen Company
)		Riverside Cement Company - Oro Grande
		To Construct Two (2) Air Heating Furnaces
	5784	Bethlehem Steel Company - S. S. "White Sands"
	,	Tear out and Replace Front in Port Boiler. Blr.
	(A)	Tagr One wire wolfman

2192	Bethlenem Steel Company
	S. S. "John Goode"
	Repairs to both Boilers
5786	Federated Metals Division, Amer. Smelting & Ref. Co.
	Los Angeles - Brick Paving - #1 Reverb.
	Life his section that is a section of the section o
5787	C. C. Moore & Co. Engineers
	Fernstrom Paper Mills Inc Pomona
	Brick Setting - One (1) B. & W. H3 #27 Boiler
5788	Todd Shipyards Corporation - Los Angeles Division
- 1	S. S. "Markay" -
	Repairs to Port and Starboard Boilers
(A)	Replace Floor and Chrome on Two (2) Boilers
5789	Eljer Company of California - Vernon
	To Reline Two (2) Ball Mills, Reline One (1)
	Rotary Smelter, Install Thermocouple Protecting
	Tube in #1 Smelter, Install Gas and Oil Burners
	in #4 Enamel Furnace
5790	General Petroleum Corporation - Vernon
7,74	Vernon Power Plant #2 - #8 Boiler Repairs
5791	Swift & Company - Vernon
	Repairs to C. E. Boiler
•	
5792	C. C. Moore & Co. Engineers - CANCELLED
	Carnation Company - Culver City
	Brickwork and Insulation -
	Two (2) FF12 No. 20 Boilers
*	
5793	E. K. Wood Lumber Co Los Angeles
	Repairs to #2 (West) Incinerator Arches

	5794	George Falkenberg - Santa Monica	
7	e de la composition della comp	To Construct One (1) 4 x 6 ft. Incinerator	
	5795	C. C. Moore & Co. Engineers - CANCELLED	
		Standard Oil Company - El Segundo	
		One (1) Class H-4, #29 Stirling Boiler	
à			
ණ ක ං	5796	Bethlehem Steel Company	
Q.,		S. S. "William F. Coty"	
1 2 1 1 1 1 2		To Rebrick Back Wall of Port Boiler Firebox	
O at	5797	Bethlehem Steel Company	
	,	S. S. "Alamo Victory"	
		To Repair Port and Starboard Boilers	
	5798	Bethlehem Steel Company	
	2190	S. S. "Granville Hall"	
		One Coat of Brick Seal - Port and Starboard	RI:
		ollo oogo ol briog boot - rore card boot boot	Apple Service
	5799	Shell Chemical Corp Dominguez	
		Acetone Furnaces - Brickwork Repairs	,
	5800	Socal Oil & Refining Co Huntington Beach	
		Boiler Furnace Brickwork Repairs	
	5801	Todd Shipyards Corp., Los Angeles Division	
		S. S. "Joshua L. Chamberlain"	
		To Repair Port Boiler	
	5802	Western Pipe & Steel Co. of Calif.	
,		Hull #209 (U. S. S. #AG-88)	
		Repair Two (2) Boilers	

W. 1. S. 1. S.	( )	
	5803	Pacific Pipeline & Engineers Limited
	government of the second	Kaiser Company, Inc., Irnn & Steel Div Fontana
		Acid-Proof Linings and Cratings for Five (5)
	200	Manholes
		The state of the s
	5804	Pacific Clay Products - Los Angeles
		To Reline Ball Mill in Bottle Dept.
*.	5805	Federated Metals Division, Amer. Smelting & Ref. Co.
		Los Angeles - To Repair #1 Brass Reverb. Furnace
	5806	Eastern Smelting & Refining Co Los Angeles 21
		To Repair Brass Reverb.
	(A)	To Repair Lead Reverb.
	5807	Filtrol Corporation - Vernon
,	[5800]	Repairs to Air Heating Furnace
	5808 ° <b>/ ^</b>	Southern California Edison Co. Ltd.
	& (A) & (B)	Long Beach Steam Plant - Plant #2
		Miscellaneous Repairs to Insulation
	5809	Patten-Blinn Lumber Company - Wilmington
		To Repair Mill Incinerator
	5810	Coast Fishing Co., Inc Wilmington
		To Repair Boiler
	January	Annual contractions
	5811	Stauffer Chemical Co., Dominguez Division - Dominguez
	/43	Insulation Repairs and Acid Brickwork for January
	(A)	Ditto for February
	(B)	" " March
	(C)	Whi TT
	(D)	" May

	5812	Southern California Edison Co. Ltd Long Beach
Y	(A)	Boiler #50 Repairs To Pensir Boiler #12 (F) To Densir Boiler #16
	(A)	To Repair Boiler #42 (E) To Repair Boiler #46
	(B)	To Repair Boiler #43 (F) To Repair Boiler #17 To Repair Boiler #31 (G) To Repair Boiler #51
	(C)	To Repair Boiler #31 (4) To Repair Boiler #41
	(D)	10 Weball Politer #52 (H) 10 Weball Politer #+1
	5813	California Rendering Company, Ltd Los Angeles 23
: : : : :	-	Brickwork Setting - New Stirling Boiler
	5814	Modern Plastic Co Los Angeles
ž		To Repair Incinerator Brickwork
	5815	Tide Water Associated Oil Co Wilmington Refinery
		Brickwork Repairs to Badger Furnace
	5816	C. F. Braun & Co.
		Shell Oil Company - Wood River, Illinois
		Enclosures for Two (2) 20 x 20 x 40 Fired Heaters
		Material only
	(A)	Two (2) Sets of Detrick Fan End Construction
	e 0 2 e 2	Tubernational Department Co. Samona
	5817	International Derrick & Equipment Co Torrance
		To Rebrick Furnace
	5818	Federated Metals Division, Amer. Smelting & Ref. Co.
	•	Los Angeles 23 - To Line Zinc Retort
	5819	The Texas Company - Wilmington - Los Angeles Works
		To Repair Stack Lining - Trumble Heaters
	5820	American President Lines, Ltd. (Pier 155)
		S. S. "Sea Blenny" - To Repair Brickwork

	5821	Morse Boulger Destructor Co.
	· · · · · · · · · · · · · · · · · · ·	United Air Lines Commissary - Los Angeles Airport
	large and the second	Morse Boulger Destructor - Model 2A
·		
1	5822	The Texas Company - Fillmore Works - Fillmore
Co-sideral according		Brickwork Repairs to Cracking Furnace at Pressure
		Stills
	5823	C. C. Moore & Co. Engineers
a ALICO Antimoderation		Fibreboard Products, Inc Vernon
nifermed planed of Alexander		Tear out and Install New Brickwork -
o Jope de mary par		One (1) Class "M" No. 18 Stirling Boiler
G-Age	5824	Pacific Coast Borax Co Boron
ation contains		To Rebrick Beik Furnace
	5825	General Refractories Company - Los Angeles 11
1047		To Repair Kilns
	Charles and the control of the contr	
Spotonialistic	5826	Johns-Manville Products Corporation - Watson
kar qerjine de qui a de	*- '	To Repair Boiler Brickwork
Shipping and the second		
	5827	Chaffey Union High School - Ontario, Calif.
		Repairs to Boiler and Pipe Insulation
	- 5828	Federated Metals Division, Amer. Smelting & Ref. Co.
	1	Los Angeles 23 - To Reline #1 Brass Reverb. Furnace
	± 200	Handram Dragger Paul mont Co
		Western Process Equipment Co.
		Pacific Coast Borax Co Boron
		To Install Acid-Proof Brick Lining in Two (2)
		ll'-8" x l0'-9" Reactor Tanks

	5830	Newall Refining Company - Newhall
	* · · · · · · ·	To Rebuild Fire Brick Lining in Side Wall and
and the second		Front Wall of One (1) HRT Boiler
		The state of the s
	5831	New York Ohio Chemical Corp.
		Affiliated with Stauffer Chemical Co Dominguez
Ja		To Install Acid-Proof Brick Lining in One (1)
70 15		12'-0" dia. x 7'-0" high Reaction Vessel
2	t a super of the con-	and the second s
) 24	5832	R C S Engineering Company
		Exeter Oil & Refining Co North Long Beach
ž		To Install Refractories and Insulation -
		One (1) 12-million Btu Petro-Chem Oil Heater
	5833	West End Chemical Co Westend
\.		To Reline 20 ft. of Tapered Lime Kiln
<i>)</i>	(A)	To Rebrick Bicarbonate Dryer
	5834	Southern California Edison Co. Ltd Long Beach Steam
	& (A) & (B)	Unloading Refractory Material Plant
	~ (~ ,	Francisco de la Companya de Co
	5835	Los Angeles Steel Casting Co Los Angeles 11
		Repairs to Annealing Furnace
	5836	Matson Navigation Company - Wilmington
		S. S. "Matsonia" - Wilmington, Berth #160
		To Repair #6 Boiler
	(A)	Wilmington, Berth #160 - To Repair #9 Boiler
	(B)	Berth #159 - To Repair #8 Boiler
)	(C)	To Repair Boiler #3
1		
	5837	Todd Shipyards Corporation
		S. S. "Hovenweep" -
		To Repair Two (2) Boilers

5838	Kaiser Company, Inc., Iron & Steel Division - Fontana
	To Reline Hot Metal Mixer in Open Hearth Dept.
5839	Montrose Chemical Company - CANCELLED
	C/o Stauffer Chemical Company - Torrance
and men a superior	One (1) Brine Tank Insulation
٠ ح	
5840	Todd Shipyards Corporation
	S. S. "Scofield" - To Repair Three (3) Boilers
	and the second of the second o
5841	Bethlehem Steel Company
	M. V. "Rhode Island" - To Repair Two (2) Boilers
5842	Bethlehem Pacific Coast Steel Co Vernon
	Open Hearth Dept Brickwork Repairs
5843	R C S Engineering Company
	Sun Harbor Packing Company - San Diego
	Brickwork - Riley Boiler, type "RO", class "G"
-	
5844	Todd Shipyards Corporation
	S. S. "Swan Island" - To Repair Starboard Boiler
5845	Industrial Manufacturers, Ltd Vernon
	To Repair Fireplace
01.6	
5846	Schurs Oil Burner Company
	••• · · · · · · · · · · · · · · · · · ·
	Plant - Vernon
(A)	Install Burner Block for Furnace at Schurs' Plant -
	Vernon
= 9 h = 7	Union Oil Company of Colif Newwolk Dump Cto Newwolk
5847	Union Oil Company of Calif Norwalk Pump Sta., Norwall
	Relining of Fireboxes of Three (3) 250 h.p. Heine

	5848	Pacific Tile & Porcelain Company - Hynes
		Relining of Two (2) Ball Mills
		and the second
	5849	Todd Shipyards Corporation
		S. S. "Torrance Hills" -
		To Rebrick Two (2) Boilers
2 5	Februar	1947
<u>a.</u>	5850	The Cudahy Packing Company - Los Angeles
Sales sales 22.		Old Dutch Cleanser Furnace
Ĭ.		Lighting to a single property of the second
9 2	5851	Todd Shipyards Corporation
	4 - 4 - 4	S. S. "William J. Gray" -
		To Repair Two (2) Boilers
	5852	Southern California Edison Company, Ltd.
	& (A) to (G)	Long Beach Steam Plant - Plant #3
	(a)	Miscellaneous Repairs to Insulation
	5853	Morse Boulger Destructor Company
		St. Bernardine Hospital - San Bernardino
		To Construct One (1) Model 2-E Morse Boulger
		Destructor
	5854	Bethlehem Steel Company
		S. S. "Rogue River" - To Tear out and Replace
		Brickwork on Two (2) Boilers
	(A)	To Renew Brick Insulation on Five (5) Large
		Access Doors of Port Boiler
		Salar and Salar
	5855	California Portland Cement Company - Colton
		To Repair #10 Kiln Hood
	(A)	To Repair #9 Kiln Stack Base

5856	Los Angeles Steel Casting Co Los Angeles 11
· ·	To Repair Draw Furnace
(A)	To Insulate Doors and Arches of Five (5) Ovens
5857	Eastern Smelting & Refining Co Los Angeles 21
	Repairs to Brickwork
5858	The Petrol Corporation - 4020 Bandini Blvd., L. A. County
	Miscellaneous Repairs to Brickwork
5859	Bethlehem Steel Company
	S. S. "Mesa Verde"
	Repair Brickwork to Port and Starboard Boilers
(A)	To Repair around Tubes
(B)	To Reline Eleven (11) Superheater Doors
5860	Southern California Edison Co., Ltd Long Beach
	To Repair Boiler #52
(A)	To Repair Boilers #29 and #30
(B)	To Repair Boilers #31 and #32
(C)	To Repair Boilers #13 and #14
(D)	To Repair Boilers #21 and #22
(E)	To Repair Boilers #54
(F)	To Repair Boilers #27 and #28
(G)	To Repair Boiler #44
(H)	To Repair Boilers #3 and #4
<b>(I)</b>	To Repair Boiler #25
(J)	To Repair Boiler #23
5861	Bethlehem Steel Company
	S. S. "Brookfield" - To Repair Two (2) Boilers
(A)	Repairs to Port Boiler

Ford Motor Company - Los Angeles  Brickwork and Insulation Enclosure for Two (2	)
Brickwork and Insulation Enclosure for Two (2	)
500 h.p. Wickes type "B" Boilers	
5863 Eljer Company of Calif Vernon	
To Repair Three-Burner Enameling Furnace #1 a	ıd
to Repair Six-Burner Enameling Furnace	
5864 Henry Asphalt Company - Los Angeles 1	
Setting for Asphalt Mixer	
(A) Installation of One (1) Burner and Regulator	
5865 American Pacific Steamship Co.	
S. S. "Scotts Bluff"	
To Rebrick Front Wall of Port Boiler	
5866 Bethlehem Steel Company	
S. S. "Rock Landing" - To Repair Two (2) Boile	rs
(A) To Renew Insulation on Five (5) Superheater Ac	cess
Doora	
5867 Richfield Oil Corporation - Hynes	
To Rebrick Shipping Board Boiler	
5868 Pacific Coast Borax Co Wilmington	
To Repair Fusion Furnace	
5868 Federated Metals Division, Amer. Smelting & Ref. (	0.
Repairs to Firebox Lining of #2 and #3 Zinc Re	tort
Furnaces	
5870 Todd Shipyards Corporation	× .
S. S. "J. W. Meldrum"	
To Repair Two (2) Boilers	

20	T DIE	err our company, inc wrimington
		To Construct Firebox for Temporary Oil Field Blr.
58	72 Be	chtel Corporation
	Sta	andard Oil Company of Calif El Segundo
	es modern	Butadiene Plant - Reactor V5 - Brickwork Repairs
(	A)	Repair Throats of Air Heaters
(:	B)	Repair Fl and F2 Furnaces
(	C)	Brickwork Repairs to Floor, etc., in F2 Furnace
58	73 Tod	ld Shipyards Corporation
		S. S. "Samblade" - Point up Brickwork
	- convenience	
58	74 Cal	Lifornia Metal Enameling Co.
		To Construct Two (2) Dryer Fireboxes and Flat
		Dryer Walls
	W 100 100 100 100 100 100 100 100 100 10	•
58	75 Sta	andard Oil Company of Calif El Segundo Refinery
		To Erect One (1) 8 x 20 x 5' Annealing Furnace
	· ·	
58	76 Pac	cific Clay Products - Los Angeles
		Plant #4 - Repairs to Two (2) Downdraft Kilns
(1	A)	To Repair #2 Tunnel Kiln
	TO COMPANY TO THE PARTY OF THE	
58′	77 <b>Gr</b> e	eat Lakes Carbon Corp Torrance
	and the second s	To Construct One (1) Permalite Furnace and to Line
	nave admir requirement	Stack
	October 1 transporter and 10	
58	78 <b>U</b> ni	on Oil Company of California - Wilmington Refinery -
	e de la constante de la consta	Brickwork Repairs to B2A Heater at Unit #33
	The second supplementation of the se	
581	79 <b>S</b> ta	andard Enameling Co Culver City
	in these sold to serve	Ball Mill Lining
	2 de la constante de la consta	
	. confilling and the state of t	

	2000	Bethlehem Steel Company - Terminal Island
	The same advantage of the same	S. S. "A. C. Rubel" - To Repair Boilers
	(A)	To Rebrick Galley Range
		La contrata de  contrata de la contrata del contrata de la contrata del contrata de la contrata del contrata de la contrata del contrata del contrata de la contrata de la contrata del contrata del contrata de la contrata del
	March l	947
	5881	Arrow Plating Company - Los Angeles 1
		Acid-Proof Brick Lining to One (1) Tank 4'-0" x
		8'-0" x 9'-0"
	5882	The Petrol Corporation - Bandini Refinery - Los Angeles
		Repairs to Brickwork on #1 Still
	5883	George Falkenberg - Santa Monica
		To Add 10 ft. to Incinerator Stack
	5884	Great Lakes Carbon Corp Wilmington
		Repairs to Kiln
	(A)	Grinding Kiln Blocks
	***	
	5885	San Diego Gas & Electric Co Sta. "B"
		Boiler #23 - Furnace Brickwork Repairs
	(A)	Boiler #26 Repairs
	5886	C. C. Moore & Co. Engineers
		Southern California Edison Company, Ltd.
		Long Beach Steam Plant - Boiler Insulation
	5887	Eastern Smelting & Refining Co Los Angeles
		Repairs to Lead Furnace
· \		
1	5888	The Petrol Corporation - Bandini Refinery, Los Angeles
		To Repair Boiler #4

5889	Bethlehem Steel Company
	S. S. "Pilot Butte" - To Repair Two (2) Boilers
(A)	To Reline Superheater Doors
(B)	To Remove and Renew Brickwork and Insulation to
	Facilitate Removal of Tubes
5890	Tide Water Associated Oil Co., Associated Division -
	Watson - Badger Furnace Brickwork Repairs
5891	Federated Metals Division, Amer. Smelting & Ref. Co
	Los Angeles 23 - To Reline U. S. Furnace Pivot Stack
5892	V. V. Lokie
	Consolidated Orange Growers Assn Orange, Calif.
	Brickwork for One (1) 50 h.p. Kewanee Firebox Boiler
5893	Bethlehem Steel Company
	S. S. "Benjamin Hawkins"
	To Tear out and Replace Back Wall of Boiler
(A)	To Renew 15 sq. ft. Upper Panel on Starboard Blr.
(B)	To Patch Brickwork on Port Boiler
5894	Todd Shipyards Corporation
	S. S. "Broad River"
	To Tear out and Replace Brickwork and Insulation
	on Two (2) Boilers
5895	Todd Shipyards Corp.
	S. S. "Allen Seegar" - To Tear out and Renew Two (2)
	Boiler Fronts and Patch Brickwork
•	
5896	Todd Shipyards Corp San Pedro Yard
	To Rebrick Donkey Boiler

	5897	Lohman Bros.
7		Standard Oil Building - Los Angeles
,*	v	To Construct Firebrick Combustion Chamber under
		New Kewanee Garbage Burner
	5898	Eljer Company of Calif Vernon
		To Repair Furnace #4
	(A)	Loading Chute on Smelting Glass Furnace #2
M N	(B)	Incinerator Lining
: -		
	5899	Pacific Clay Products - Los Nietos - Plant #6
:		To Repair Crown of #1 Kiln
	(A)	Stack #4 (K) Kiln #24 Repairs
	(B)	Kiln #3 Repairs (L) Kiln #44 Repairs
	(C)	Kiln #23 Repairs (M) Kiln #38 Repairs
	(D.)	Kiln #31 Repairs (N) Kiln #11 Repairs
	(E).	Kiln #20 Repairs (0) Kiln #37 Repairs
	(F)	Kiln #32 Repairs (P) Kiln #28 Repairs
	(G)	Kiln #18 Repairs (Q) Kiln # 9 Repairs
	(H)	Kiln #41 Repairs (R) Kiln #12 Repairs
	(I)	Kiln #22 Repairs (S) Kiln # 8 Repairs
	(J)	Kiln #17 Repairs
	5900	Pacific Clay Products - Los Nietos - Plant #6
		Miscellaneous Repairs
	5901	Patten-Blinn Lumber Co Wilmington
		Repairs to Boiler
	5902	San Pedro Dry Kiln Co San Pedro
)	•	To Repair Boiler

Long Beach Steam Flant - Boiler #49 Repairs Boiler #24 Repairs (J) Boilers #5 & #6 (B) Boilers #9 and #10 (K) Boilers #19 & #20 (C) Boiler #55 Repairs (L) Boiler #37 (D) Boiler #55 Repairs (M) Boilers #21 & #22 (E) Boilers #11 and #12 Rprs. (N) Boilers #24 & #22 (E) Boilers #11 and #12 Rprs. (N) Boilers #34 (F) Boilers #29 and #30 Rprs. (O) Boilers #1, #2, #3, #4 (G) Boilers #13 and #14 Rprs. (Q) Boilers #7 & #8 (I) Boilers #15 and #16 Rprs.  5904 California Portland Cement Co Colton Rebuild Arch #9 Stack Base  5905 Federated Metals Division, Amer. Smelting & Ref. Co. Los Angeles 23 - To Repair Aluminum Reverb. Furnace Brickwork  To Repair U. S. Furnace Brickwork  5906 Southern Service Co., Ltd. Sanitary Laundry - Pomona To Repair Boiler Brickwork  5907 Reconstruction Finance Corp. Shell Chemical Corporation, Agent - Los Angeles Torrance Flant - To Replace Roof Tiles and Insulation on B-201-A Superheater  5908 Standard Steel Corp. City of Los Angeles - Asphalt Flant One (1) Sand Dryer Firebox Lining		5903	Southern California Edison Company, Ltd.
(B) Boilers #9 and #10 (K) Boilers #19 & #20 (C) Boiler #53 Repairs (L) Boiler #37 (D) Boiler #37 Repairs (M) Boilers #21 & #22 (E) Boilers #11 and #12 Rprs. (N) Boiler #34 (F) Boilers #29 and #30 Rprs. (O) Boilers #1, #2, #3, #4 (G) Boiler #42 Repairs (P) Boiler #33 (H) Boilers #13 and #14 Rprs. (Q) Boilers #7 & #8 (I) Boilers #15 and #16 Rprs.  5904 California Portland Cement Co Colton Rebuild Arch #9 Stack Base  5905 Federated Metals Division, Amer. Smelting & Ref. Co. Los Angeles 23 - To Repair Aluminum Reverb. Furnace Brickwork  To Repair U. S. Furnace Brickwork  5906 Southern Service Co., Ltd. Sanitary Laundry - Pomona To Repair Boiler Brickwork  5907 Reconstruction Finance Corp. Shell Chemical Corporation, Agent - Los Angeles Torrance Plant - To Replace Roof Tiles and Insulation on B-201-A Superheater  5908 Standard Steel Corp. City of Los Angeles - Asphalt Plant One (1) Sand Dryer Firebox Lining	-		Long Beach Steam Plant - Boiler #49 Repairs
(C) Boiler #53 Repairs (L) Boiler #37 (D) Boiler #37 Repairs (M) Boilers #21 & #22 (E) Boilers #11 and #12 Rprs. (N) Boiler #34 (F) Boilers #29 and #30 Rprs. (O) Boilers #1, #2, #3, #4 (G) Boiler #42 Repairs (P) Boiler #33 (H) Boilers #13 and #14 Rprs. (Q) Boilers #7 & #8 (I) Boilers #15 and #16 Rprs.  5904 California Portland Cement Co Colton Rebuild Arch #9 Stack Base  5905 Federated Metals Division, Amer. Smelting & Ref. Co. Los Angeles 23 - To Repair Aluminum Reverb. Furnace Brickwork  To Repair U. S. Furnace Brickwork  5906 Southern Service Co., Ltd. Sanitary Laundry - Pomona To Repair Boiler Brickwork  5907 Reconstruction Finance Corp. Shell Chemical Corporation, Agent - Los Angeles Torrance Plant - To Replace Roof Tiles and Insulation on B-201-A Superheater  5908 Standard Steel Corp. City of Los Angeles - Asphalt Plant Cne (1) Sand Dryer Firebox Lining	At months and a second	(A)	Boiler #24 Repairs (J) Boilers #5 & #6
(D) Boiler #37 Repairs (M) Boilers #21 & #22  (E) Boilers #11 and #12 Rprs. (N) Boiler #34  (F) Boilers #29 and #30 Rprs. (O) Boilers #1, #2, #3, #4  (G) Boiler #42 Repairs (P) Boiler #33  (H) Boilers #13 and #14 Rprs. (Q) Boilers #7 & #8  (I) Boilers #15 and #16 Rprs.  5904 California Portland Cement Co Colton  Rebuild Arch #9 Stack Base  5905 Federated Metals Division, Amer. Smelting & Ref. Co.  Los Angeles 23 - To Repair Aluminum Reverb.  Furnace Brickwork  To Repair U. S. Furnace Brickwork  5906 Southern Service Co., Ltd.  Sanitary Laundry - Pomona  To Repair Boiler Brickwork  5907 Reconstruction Finance Corp.  Shell Chemical Corporation, Agent - Los Angeles  Torrance Plant - To Replace Roof Tiles and Insulation on B-201-A Superheater  5908 Standard Steel Corp.  City of Los Angeles - Asphalt Plant  One (1) Sand Dryer Firebox Lining		(B)	Boilers #9 and #10 (K) Boilers #19 & #20
(E) Boilers #11 and #12 Rprs. (N) Boiler #34  (F) Boilers #29 and #30 Rprs. (O) Boilers #1, #2, #3, #4  (G) Boiler #42 Repairs (P) Boiler #33  (H) Boilers #13 and #14 Rprs. (Q) Boilers #7 & #8  (I) Boilers #15 and #16 Rprs.  5904 California Portland Cement Co Colton  Rebuild Arch #9 Stack Base  5905 Federated Metals Division, Amer. Smelting & Ref. Co.  Los Angeles 23 - To Repair Aluminum Reverb.  Furnace Brickwork  To Repair U. S. Furnace Brickwork  5906 Southern Service Co., Ltd.  Sanitary Laundry - Pomona  To Repair Boiler Brickwork  5907 Reconstruction Finance Corp.  Shell Chemical Corporation, Agent - Los Angeles  Torrance Plant - To Replace Roof Tiles and Insulation on B-201-A Superheater  5908 Standard Steel Corp.  City of Los Angeles - Asphalt Plant  One (1) Sand Dryer Firebox Lining		(C)	Boiler #53 Repairs (L) Boiler #37
(F) Boilers #29 and #30 Rprs. (0) Boilers #1, #2, #3, #4 (G) Boiler #42 Repairs (P) Boiler #33 (H) Boilers #13 and #14 Rprs. (Q) Boilers #7 & #8 (I) Boilers #15 and #16 Rprs.  5904 California Portland Cement Co Colton Rebuild Arch #9 Stack Base  5905 Federated Metals Division, Amer. Smelting & Ref. Co. Los Angeles 23 - To Repair Aluminum Reverb. Furnace Brickwork  To Repair U. S. Furnace Brickwork  5906 Southern Service Co., Ltd. Sanitary Laundry - Pomona To Repair Boiler Brickwork  5907 Reconstruction Finance Corp. Shell Chemical Corporation, Agent - Los Angeles Torrance Plant - To Replace Roof Tiles and Insulation on B-201-A Superheater  5908 Standard Steel Corp. City of Los Angeles - Asphalt Plant One (1) Sand Dryer Firebox Lining	value of the state	(D)	Boiler #37 Repairs (M) Boilers #21 & #22
(G) Boiler #42 Repairs (P) Boiler #33 (H) Boilers #13 and #14 Rprs. (Q) Boilers #7 & #8 (I) Boilers #15 and #16 Rprs.  5904 California Portland Cement Co Colton Rebuild Arch #9 Stack Base  5905 Federated Metals Division, Amer. Smelting & Ref. Co. Los Angeles 23 - To Repair Aluminum Reverb. Furnace Brickwork To Repair U. S. Furnace Brickwork  5906 Southern Service Co., Ltd. Sanitary Laundry - Pomona To Repair Boiler Brickwork  5907 Reconstruction Finance Corp. Shell Chemical Corporation, Agent - Los Angeles Torrance Plant - To Replace Roof Tiles and Insulation on B-201-A Superheater  5908 Standard Steel Corp. City of Los Angeles - Asphalt Plant One (1) Sand Dryer Firebox Lining		(E)	Boilers #11 and #12 Rprs. (N) Boiler #34
(H) Boilers #13 and #14 Rprs. (Q) Boilers #7 & #8  (I) Boilers #15 and #16 Rprs.  5904 California Portland Cement Co Colton Rebuild Arch #9 Stack Base  5905 Federated Metals Division, Amer. Smelting & Ref. Co. Los Angeles 23 - To Repair Aluminum Reverb. Furnace Brickwork  To Repair U. S. Furnace Brickwork  5906 Southern Service Co., Ltd. Sanitary Laundry - Pomona To Repair Boiler Brickwork  5907 Reconstruction Finance Corp. Shell Chemical Corporation, Agent - Los Angeles Torrance Plant - To Replace Roof Tiles and Insulation on B-201-A Superheater  5908 Standard Steel Corp. City of Los Angeles - Asphalt Plant One (1) Sand Dryer Firebox Lining		(F)	Boilers #29 and #30 Rprs. (0) Boilers #1, #2, #3, #4
(I) Boilers #15 and #16 Rprs.  5904 California Portland Cement Co Colton Rebuild Arch #9 Stack Base  5905 Federated Metals Division, Amer. Smelting & Ref. Co. Los Angeles 23 - To Repair Aluminum Reverb. Furnace Brickwork  To Repair U. S. Furnace Brickwork  5906 Southern Service Co., Ltd. Sanitary Laundry - Pomona To Repair Boiler Brickwork  5907 Reconstruction Finance Corp. Shell Chemical Corporation, Agent - Los Angeles Torrance Plant - To Replace Roof Tiles and Insulation on B-201-A Superheater  5908 Standard Steel Corp. City of Los Angeles - Asphalt Plant One (1) Sand Dryer Firebox Lining		(G)	Boiler #42 Repairs (P) Boiler #33
5904 California Portland Cement Co Colton Rebuild Arch #9 Stack Base  5905 Federated Metals Division, Amer. Smelting & Ref. Co. Los Angeles 23 - To Repair Aluminum Reverb. Furnace Brickwork To Repair U. S. Furnace Brickwork  5906 Southern Service Co., Ltd. Sanitary Laundry - Pomona To Repair Boiler Brickwork  5907 Reconstruction Finance Corp. Shell Chemical Corporation, Agent - Los Angeles Torrance Plant - To Replace Roof Tiles and Insulation on B-201-A Superheater  5908 Standard Steel Corp. City of Los Angeles - Asphalt Plant One (1) Sand Dryer Firebox Lining		(H)	Boilers #13 and #14 Rprs. (Q) Boilers #7 & #8
Federated Metals Division, Amer. Smelting & Ref. Co.  Los Angeles 23 - To Repair Aluminum Reverb.  Furnace Brickwork  To Repair U. S. Furnace Brickwork  5906 Southern Service Co., Ltd.  Sanitary Laundry - Pomona  To Repair Boiler Brickwork  5907 Reconstruction Finance Corp.  Shell Chemical Corporation, Agent - Los Angeles  Torrance Plant - To Replace Roof Tiles and Insulation on B-201-A Superheater  5908 Standard Steel Corp.  City of Los Angeles - Asphalt Plant  One (1) Sand Dryer Firebox Lining	The second secon	(I)	Boilers #15 and #16 Rprs.
Federated Metals Division, Amer. Smelting & Ref. Co.  Los Angeles 23 - To Repair Aluminum Reverb.  Furnace Brickwork  To Repair U. S. Furnace Brickwork  5906 Southern Service Co., Ltd.  Sanitary Laundry - Pomona  To Repair Boiler Brickwork  5907 Reconstruction Finance Corp.  Shell Chemical Corporation, Agent - Los Angeles  Torrance Plant - To Replace Roof Tiles and Insulation on B-201-A Superheater  5908 Standard Steel Corp.  City of Los Angeles - Asphalt Plant  One (1) Sand Dryer Firebox Lining	ne production de la constitución		
5905  Federated Metals Division, Amer. Smelting & Ref. Co.  Los Angeles 23 - To Repair Aluminum Reverb.  Furnace Brickwork  To Repair U. S. Furnace Brickwork  5906  Southern Service Co., Ltd.  Sanitary Laundry - Pomona  To Repair Boiler Brickwork  5907  Reconstruction Finance Corp.  Shell Chemical Corporation, Agent - Los Angeles  Torrance Plant - To Replace Roof Tiles and Insulation on B-201-A Superheater  5908  Standard Steel Corp.  City of Los Angeles - Asphalt Plant  One (1) Sand Dryer Firebox Lining	(September 1999)	5904	California Portland Cement Co Colton
Los Angeles 23 - To Repair Aluminum Reverb.  Furnace Brickwork  To Repair U. S. Furnace Brickwork  5906 Southern Service Co., Ltd. Sanitary Laundry - Pomona  To Repair Boiler Brickwork  5907 Reconstruction Finance Corp. Shell Chemical Corporation, Agent - Los Angeles  Torrance Plant - To Replace Roof Tiles and Insulation on B-201-A Superheater  5908 Standard Steel Corp. City of Los Angeles - Asphalt Plant One (1) Sand Dryer Firebox Lining	over the property of the prope		Rebuild Arch #9 Stack Base
Los Angeles 23 - To Repair Aluminum Reverb.  Furnace Brickwork  To Repair U. S. Furnace Brickwork  5906 Southern Service Co., Ltd. Sanitary Laundry - Pomona  To Repair Boiler Brickwork  5907 Reconstruction Finance Corp. Shell Chemical Corporation, Agent - Los Angeles  Torrance Plant - To Replace Roof Tiles and Insulation on B-201-A Superheater  5908 Standard Steel Corp. City of Los Angeles - Asphalt Plant One (1) Sand Dryer Firebox Lining	oodeenseen .		
Furnace Brickwork  To Repair U. S. Furnace Brickwork  5906  Southern Service Co., Ltd. Sanitary Laundry - Pomona To Repair Boiler Brickwork  5907  Reconstruction Finance Corp. Shell Chemical Corporation, Agent - Los Angeles Torrance Plant - To Replace Roof Tiles and Insulation on B-201-A Superheater  5908  Standard Steel Corp. City of Los Angeles - Asphalt Plant One (1) Sand Dryer Firebox Lining	Personal	5905	Federated Metals Division, Amer. Smelting & Ref. Co.
5900  Southern Service Co., Ltd. Sanitary Laundry - Pomona To Repair Boiler Brickwork  5907  Reconstruction Finance Corp. Shell Chemical Corporation, Agent - Los Angeles Torrance Plant - To Replace Roof Tiles and Insulation on B-201-A Superheater  5908  Standard Steel Corp. City of Los Angeles - Asphalt Plant One (1) Sand Dryer Firebox Lining	poperation and the second		Los Angeles 23 - To Repair Aluminum Reverb.
5906  Southern Service Co., Ltd.  Sanitary Laundry - Pomona  To Repair Boiler Brickwork  5907  Reconstruction Finance Corp.  Shell Chemical Corporation, Agent - Los Angeles  Torrance Plant - To Replace Roof Tiles and Insulation on B-201-A Superheater  5908  Standard Steel Corp.  City of Los Angeles - Asphalt Plant  One (1) Sand Dryer Firebox Lining	econoportare property		Furnace Brickwork
5906 Southern Service Co., Ltd. Sanitary Laundry - Pomona To Repair Boiler Brickwork  5907 Reconstruction Finance Corp. Shell Chemical Corporation, Agent - Los Angeles Torrance Plant - To Replace Roof Tiles and Insulation on B-201-A Superheater  5908 Standard Steel Corp. City of Los Angeles - Asphalt Plant One (1) Sand Dryer Firebox Lining		(A)	To Repair U. S. Furnace Brickwork
Sanitary Laundry - Pomona  To Repair Boiler Brickwork  Reconstruction Finance Corp.  Shell Chemical Corporation, Agent - Los Angeles  Torrance Plant - To Replace Roof Tiles and Insulation on B-201-A Superheater  5908  Standard Steel Corp.  City of Los Angeles - Asphalt Plant  One (1) Sand Dryer Firebox Lining	134m		
To Repair Boiler Brickwork  Reconstruction Finance Corp.  Shell Chemical Corporation, Agent - Los Angeles  Torrance Plant - To Replace Roof Tiles and Insulation on B-201-A Superheater  Standard Steel Corp.  City of Los Angeles - Asphalt Plant  One (1) Sand Dryer Firebox Lining	000000000000000000000000000000000000000	5906	Southern Service Co., Ltd.
Shell Chemical Corporation, Agent - Los Angeles Torrance Plant - To Replace Roof Tiles and Insulation on B-201-A Superheater  Standard Steel Corp. City of Los Angeles - Asphalt Plant One (1) Sand Dryer Firebox Lining	Military Inc. Company		Sanitary Laundry - Pomona
Shell Chemical Corporation, Agent - Los Angeles  Torrance Plant - To Replace Roof Tiles and Insulation on B-201-A Superheater  5908 Standard Steel Corp.  City of Los Angeles - Asphalt Plant  One (1) Sand Dryer Firebox Lining			To Repair Boiler Brickwork
Shell Chemical Corporation, Agent - Los Angeles  Torrance Plant - To Replace Roof Tiles and Insulation on B-201-A Superheater  5908 Standard Steel Corp.  City of Los Angeles - Asphalt Plant  One (1) Sand Dryer Firebox Lining			
Torrance Plant - To Replace Roof Tiles and Insulation on B-201-A Superheater  5908 Standard Steel Corp.  City of Los Angeles - Asphalt Plant  One (1) Sand Dryer Firebox Lining	77170	5907	Reconstruction Finance Corp.
sulation on B-201-A Superheater  5908 Standard Steel Corp.  City of Los Angeles - Asphalt Plant  One (1) Sand Dryer Firebox Lining	THE PROPERTY OF THE PROPERTY O		Shell Chemical Corporation, Agent - Los Angeles
5908 Standard Steel Corp.  City of Los Angeles - Asphalt Plant  One (1) Sand Dryer Firebox Lining			Torrance Plant - To Replace Roof Tiles and In-
City of Los Angeles - Asphalt Plant One (1) Sand Dryer Firebox Lining			sulation on B-201-A Superheater
City of Los Angeles - Asphalt Plant One (1) Sand Dryer Firebox Lining			
One (1) Sand Dryer Firebox Lining		5908	Standard Steel Corp.
			City of Los Angeles - Asphalt Plant
5909 Eastern Smelting & Refining Co Los Angeles 21			One (1) Sand Dryer Firebox Lining
5909 Eastern Smelting & Refining Co Los Angeles 21			
		5909	Eastern Smelting & Refining Co Los Angeles 21
To Repair Brass Reverb. Furnace			To Repair Brass Reverb. Furnace

15	100	
	<b>#03</b> 0	
	5910	Union Oil Company of Calif Wilmington
77		Repair Brickwork in Heater B3B of Unit 33
	(A)	Brickwork Repairs in Heater in "A" Cracking Area
	. Ann S	Unit #33
	(B)	Change Peephole and Thermowell Holes in Heater
		B3B, Unit #33
a]	(C)	Repair Boiler #2 at Boiler Plant #2
in the second	(D)	Install Six (6) Burners in Unit #3 Crude Heaters
Gu wine		
	5911	Todd Shipyards Corp San Pedro
		U. S. S. R. "Victory"
÷ .		Brickwork on Port and Starboard Boilers
	5912	Todd Shipyards Corp San Pedro
		U. S. "Victory"
		Brickwork - Port and Starboard Boilers
	w	
	5913	Pacific Coast Borax Co Wilmington
		To Rebuild Glass Furnace
	5914	Todd Shipyards Corp.
		S. S. "Allan C. Balch" - To Patch Burner Ring
	5915	Standard Oil Company of Calif El Segundo
		To Repair Crude Still - Battery #4
	5916	Robert L. Johnson Company
		City of Burbank
	(4)	Enclosure for One (1) C-E Boiler Patch around Soot Blower
	(A)	ratch around Soot brower
	5917	Phelps Dodge Corporation - Morenci, Arizona -
		Installation of Lining in One (1) "Unox" Rotary
		Lime Kiln

	DATO '	Stauffer Chemical Company, Dominguez Division
		Dominguez - To Install Brick Lining in Stack
. 6	alala ale.	Breeching Inlet and Change Seal
	5919	Wilshire Oil Company, Inc Norwalk Refinery
		To Repair Front Wall of B. & W. Integral Furnace
		Boiler and the second second second second (4)
	Kinna Albania	(x, y) = (x, y) + (
	5920	The Cudahy Packing Company - Los Angeles
		To Install Burner Blocks in Old Dutch Cleanser
		Furnace Type 19 71
	5921	Morgan Laundry Service, Inc Los Angeles
		Brickwork Repairs to HRT Boiler #3
	5922	C. C. Moore & Co. Engineers
		Central Arizona Light & Power Co Phoenix, Ariz.
		Enclosure for One (1) B. & W. Two-Drum Boiler
	(A)	Premium Time
	(B)	Insulation Finish on Piping to and from Attemperator
	5923	Todd Shipyards Corp.
		S. S. "Oleum" - Brickwork Repairs
	5924	General Petroleum Corp. of Calif.
		Vernon - #2 Power Plant
		Brickwork Repairs to #5 Stirling Boiler

	5925	Todd Shipyards Corporation
1	,	S. S. "A. J. Pothier" - To Repair Starboard Boiler
	5926	Bechtel Corporation
		Standard Oil Company of Calif.
		Bakersfield - Mohawk Plant #2
		Furnace Brickwork Repairs
	5927	Bechtel Corporation
		Standard Oil Company of Calif.
		El Segundo - Crude Unit #1
		Installation of Refractory and Insulation Materials
		for One (1)/Vacuum Heater and One (1)/Atmospheric
		Heater
1	5928	Pacific Coast Borax Co Wilmington
		To Repair Fusion Furnace #2
	5929	C. F. Braun & Co.
		Shell Chemical Corp Dominguez
		To Install Acid Brick in Tank T-77 and in Karbate
		Cooler Area
	5930	San Diego Gas & Electric Co San Diego - Sta. "B" Furnace #25 Repairs
	5931	Richfield Oil Corp Watson Refinery, Wilmington
		Repairs to #8 Oxidized Asphalt Still
	5932	Todd Shipyards Corporation
}	& (A)	S. S. "Plymouth Victory" - To Repair Boilers
	5933	Bethlehem Steel Company
		S. S. "Coquille" - To Rebrick Two (2) Boilers
	(A)	To Reline 12 Superheater Access Doors

5934	Coast Fishing Co Wilmington
7	To Repair Furnace
5935	Pacific Clay Products - Los Nietos
	Insulation on Humidity Dryer
5936	Bethlehem Steel Company
	S. S. "James J. Maguire" - To Repair Boiler
5937	Acme Brewing Company - Vernon
	To Reline Incinerator Stack
5938	El Rey Products Co Los Angeles
	To Widen Doorway 30" in Roofing Machine Bldg.
5939	Union Oil Company of Calif Wilmington
	To Repair Still #95 make the week to be a second to the se
5940	Kaiser Company, Inc., Iron & Steel Division
	at Santa Fe R. R. Shops - San Bernardino
The Committee of C	To Install Heavy Service Inner Lining in Torpedo
	Ladle
5941	Eljer Company of California - Vernon
	Six-Burner Enamel Furnace
(A)	Repairs to Dross Furnace
(B)	Repairs to Brass Reverberatory Furnace
5942	Eastern Smelting & Refining Co Los Angeles
	To Repair Lead Furnace
(A) (B)	Repairs to ButkdingxWakk Dross Furnace Repair Brass Reverb. (C) Repairs to Bldg. Wall
5943	Standard Oil Company of Calif El Segundo
	2nd Battery Cracking Unit - Brickwork Alterations Installation of Air Preheater at #12 Unit; Repair Work on Stack and Furnace

for

	5944	C. F. Braun & Co.
1	T. Contraction of the Contractio	Creole Petroleum Corporation - Mulata, Venezuela
	ere e vere e verendos que	One (1) 12 x 12 x 20 HeaterMaterial Only
	TO THE PERSON OF	
	5945	Shell Chemical Corporation - Dominguez
	and delivery of the second	Temporary Repair to Acid Brick Lining on Tank
	en elliphichem e diperi	No. F-74
5		
9	May 1947	, -
il or	5946	Shell Oil Company, Inc Wilmington
1 - 3)	- I dispressive with	To Repair Boilers #1 and #2
ģ	(A)	To Repair Incinerator
	- Section of the sect	
	5947	The Petrol Corporation - Bandini Refinery - Los Angeles
		To Replace Brick on Top of Bridge Wall of Stirling
\.		Boiler #3
I		
	5948	Socal Oil & Refining Company - Huntington Beach
		Light Oil Heater Furnace - Brickwork Repairs
	5949	Lohman Bros.
	den contact of	May Company - Los Angeles, Wilshire & Fairfax
		Firebox Boiler Brickwork
	-	
	5950	Todd Shipyards Corp.
	- Property of the Property of	S. S. "James Weaver"
		To Patch Brickwork of Port and Starboard Boilers
	A Company	
	5951	Bethlehem Steel Company.
		M. V. "Henry Dundas" -
,	T	To Patch Brickwork of Two (2) Scotch Boilers
	5952	Great Lakes Carbon Corp Permalite Division
		Torrance - To Patch Brickwork
	(A)	To Repair Furnace

5953	California Portland Cement Co Colton
	#11 Kiln Hood - Brickwork Repairs
5954	The Cudahy Packing Company - Los Angeles
	Repairs to #3 Boiler
5955	Miller Soap Products - Division of Swift & Company
	Los Angeles - Repairs to HRT Boiler
5956	Eljer Company of California - Vernon
	To Patch Melting Furnace #2
(A)	To Reline Ball Mill
5957	Todd Shipyards Corp.
	S. S. "Lompoc" - To Repair Brickwork
5958	Federated Metals Division, Amer. Smelting & Ref. Co
	Los Angeles 23 - To Repair #2 Brass Reverb. Furnace
5959	Forest Lawn Memorial-Park Assn., Inc Glendale
	To Scrape and Paint Insides of Three (3) Crematory
	Retorts ,
5960	University of California - Royce Hall, Los Angeles 24 -
	Installation of New Burner Tile and Fugrnace Repairs
	of One (1) #3 500 h.p. Stirling Boiler
5961	V. V. Lokie
	McKinney Lumber Co Los Angeles
	Firebox Boiler Brickwork
(A)	Insulation Repairs
(B)	Repair Front Wall
5962	Todd Shipyards Corp San Pedro
	S. S. "Charles S. Jones" - Necessary Brickwork Repairs

	2903	Bethlenem Steel Company - Terminal Island
)		S. S. "Baldwin Hill" - To Tear Out and Renew
		Brickwork on Two (2) Boilers
	(A)	To Reline Twelve (12) Doors
	5964	C. C. Moore & Co. Engineers
		Salt River Valley Water Users' Assn Tempe, Arizona
rs'n ac		Brickwork and Insulation for Three (3) AP-3 Victory Ship Boilers
	5965	Todd Shipyards Corp San Pedro
		S. S. "Joshua Royce" - Repairs to Boilers
	5966	J. B. Gill Company
		Victorville Lime Rock Company - Victorville, Calif.
		Installation of 4" Hewn Stone Lining in One (1)
,		8' dia, x 20' long Pebble Mill
	5967	Standard Oil Company of Calif El Segundo Refinery
		Acid Plant - Acid-Proof Brick Lining in One (1)
		32'-0" dia. x 17'-0" high Lead Lined Steel Tank #343
	5968	Southern California Edison Co., Ltd Long Beach
		Plant #1 (to be billed each month)
		Emergency Miscellaneous Brickwork Repairs
	5969	C. C. Moore & Co. Engineers
		Fernstrom Paper Mills, Inc Pomona
		Renew Ignition Arch and Replace Flat Baffle on
)		#10 Tube of Class "H" #17 Boiler
	5970	L. M. Scofield Company
		United Airlines - Mines Field - Los Angeles
		To Repair Incinerator

W. C. Hardesty Company - Los Angeles 5971 Repair #2 Fatty Acid Pot Furnace General Refractories Co. - Los Angeles 11 5972 To Repair Downdraft Kiln Standard Oil Company of Calif. - El Segundo Refinery 5973 Alterations to Brickwork at #9 Unit, Second Battery. Cracking Plant American Potash & Chemical Corp. - Trona 5974 To Repair Pyroborate Furnace #2 Eljer Company of California - Vernon 5975 To Repair Enamel Smelter Southern California Pottery Co. 5976 4513 West 153rd St., Lawndale To Repair Minton Kiln C. C. Moore & Co. Engineers 5977 Fernstrom Paper Mills, Inc. - Pomona To Repair Collins Boiler Settings June 1947 Todd Shipyards Corp. 5978 S. S. "Wm. D. Howles - To Repair Two (2) Boilers The Fluor Corporation, Ltd. 5979 Fletcher Oil Company - Wilmington To Repair Insulation and Brickwork on U.O.P. Htr. 5980 Bethlehem Steel Company - Terminal Island S. S. "Elbrus" - Two (2) Boiler Settings

	5981	The Cudahy Packing Co Los Angeles
)	·	Boiler #4 - Furnace Brickwork Repairs
	5982	California Metal Enameling Co Los Angeles County
		To Line Ball Mill
MAN U.S.A.	5983	C.B.S Steel & Forge Vernon - To Repair #1 Forge Furnace
	5984	California Portland Cement Co Colton
	(A)	New Firing Hood - #11 Kiln Cooler Hopper - #11 Kiln
	5985	E. K. Wood Lumber Co Los Angeles To Repair #2 Burner Combustion Chamber
)	5986	Pacific Coast Borax Co Wilmington To Repair Furnace
	5987	Finkelstein Supply Company Southwest Steel Rolling Mills - Los Angeles 2
		Remodeling Rail and Billet Heating Furnaces
	(A)	Furnace Demolition and Repair
	(B) (C)	Control Building (D) Repairs to Furnac East Wall & Hearth Repairs / Discharge Trough
	5988	The Fluor Corporation, Ltd.
		Filtrol Corporation - Vernon
		Linings for Four (4) Dryer Furnaces
	5989	C. C. Moore & Co. Engineers
-		Southern California Edison Co., Ltd Redondo
	U <b>x</b> se of Elevator	New Steam Plant - Refractories and Heat Insulation
·	(A) Renta	
	5990	Wilshire Oil Company, Inc Norwalk Refinery
	•	Brickwork Repairs to Arch in Stack of Alcorn

Furnace

5991	Wilmington Welding & Boiler Works  To Repair Sationary Boiler	Personal Training
5992	May Co. Dept. Store - Wilshire & Fairfax, Los A	ngeles
	To Repairs to Firebox of International Boil	er
5993	City Dye Works of Los Angeles Repairs to B. & W. Stirling Boiler	
5994	Todd Shipyards Corp San Pedro S. S. "Kenyon Victory" - To Patch Brickwork	
5995	Bethlehem Steel Company S. S. "Peter B. Daniel" - To Patch Brickwor	રાજ્યો(જે) <b>k</b>
5996	Todd Shipyards Corp.  S. S. "Hot Creek"  To Replace Brickwork in Two (2) Boilers	
5997	El Rey Products Company - Los Angeles	t Santa di
	To Repair Brickwork on Shell Still	
(A)	To Repair Insulation on Mixing Tank	
5998	Bethlehem Steel Company - Terminal Island S. S. "McKetrick Hills"	Market 1
(A)	Completely Renew the Lining in Two (2) Boil Eight (8) Superheater Doors	ers
<b>599</b> 9	Eastern Smelting & Refining Co Los Angeles Repairs to Lead Furnace	
6000 .	Shell Chemical Corp Dominguez	
	Repairs to Acid-Brick Lining	

	POOT	U. S. Naval Base, Public works Dept Terminal Island
		U. S. Naval Hospital - Corona
		To Reline Two (2) Model OB-20 Cleaver Brooks Blrs.
	6002	Bethlehem Steel Company
		S. S. "Paul M. Gregg"
		Necessary Repairs to Two (2) Boilers
5.5.A		
	6003	Todd Shipyards Corp.
FI ~		S. S. "Santa Paula" - To Patch Brickwork
11 11 13 43		
e e	6004	Coast Fishing Company, Inc Wilmington
		Boiler Brickwork Repairs
	6005	Eljer Company - Vernon
ĭ		To Repair Enemel Smelter
Ì		4
	6006	Johns-Manville Products Corporation - Wilmington
		Necessary Repairs to Boiler
	6007	Union Oil Company - Wilmington
		Repairs to #3 Heater, Side "B"
	6008	Standard Oil Company of Texas
		El Paso, Texas
		Detrick End Walls - 1930 Pressure Still
	(A)	To Remove and to Rebuild Furnace Floor
	(B)	To Remove and to Rebuild Two (2) Bridge Walls
	(C)	To Remove and to Rebuild Corner Columns
4	(D)	To Renew Insulation on End Tube Sheet & Corner Column
)		
	6009	C. F. Braun & Co.
		Richfield Oil Corp North Coles Levee, Kern Co., Calif
		One (1) 10 x 10 x 20 Fired HeaterMaterial Only
	(A)	Labor on Heater

	<b>60T</b> 0	National Metal & Steel Corp Terminal Island	
		Repairs to Beiler	
	\$600\\$\T\$\$		
	6011	Warman Steel Casting Company - Vernon	
		Roof Insulation on Core Ovens & Misc. Brickwo	ork
	, precionaliza		
	6012	Vegetable Oil Products Company, Inc Wilmington Repairs to Boiler	L
	adoroida parasona		
	6013	Great Lakes Carbon Corp Torrance	
	ana platicological popular	Repair Furnaces and Install Carborundum Arche	8
	(A)	To Repair Furnace	-
	(B)	To Repair Furnace	
	Million and the second		
	6014	The Texas Company - Wilmington - Los Angeles	
	Aurentatoriologischen Ausgeb	To Reline Stacks at PPS #2	
	6015	L. M. Scofield Company	
	001)		
		Bullocks Dept. Store - Pasadena Repairs to Morse Boulger Incinerator	
6000	6016	Pacific Clay Products - Ave. 26, Los Angeles	
		To Reline Ball Mill	
	6017	Todd Shipyards Corporation - San Pedro	
	vision that the second	S. S. "Luther Martin" - To Patch Brickwork	
	(A)	Six (6) Doors	
	· ·		
	6018	California Portland Cement Company - Colton	
		To Repair #12 Kiln Stack Base	
	Account of the Control of the Contro		
	<b>60</b> 19	Union Oil Company of Calif Wailmington Refiner	• A.
		T. C. C. Heater - Brickwork Repairs	ď
	(A)	To Repair Unit #33	
	Speciment of the Control of the Cont	್ರಾಯಾಯ್ಯ ತರ್ಶಾ ಶ್ರೀಯಾ <b>ತ್ ಸ್ವಾಪ್</b> ಯ ತಿಳ್ಳಿ ಕಿಳ್ಳು ಅತ್ಯ ಅತ್ಯ ಕ್ರಾಪ್ ಕ್ರಿಯಾಗಿ ಕಿಳ್ಳು ಅತ್ಯ ಕ್ರಿಯಾಗಿ ಕ್ರಿಯಾಗಿ ಕಿಳ್ಳು ಕ್ರಿಯಾಗಿ ಕ್ರಿಯಾಗ	

60	20 <b>s</b>	alt River Valley Water Users! Assn Tempe,	Ariz.
	CANCELLI	To Renew Front Wall in B. & W. Boiler in	- N
<i>.</i>	CAMORIAL	(U. S. Navy Mobile Unit	to s
	A Constitution of the Cons	Sale of Marine Anchor Bolts only	
60	el G	reat Lakes Carbon Corp Wilmington	
	**	To Repair Kiln	
:			j
<u>5</u> 60	22 <b>S</b> 1	uperior Paint & Lacquer Works - Huntington Pa	ark
	PARTICIPATION OF THE PARTICIPA	Repairs to 5' dia. x 4' Ball Mill	
#1 #2	New York Control of the Control of t		* *
60%	23 <b>E</b> 4	astern Smelting & Refining Co Los Angeles	
d re	The second secon	Repairs to Brass Reverberatory Furnace	
(1	A)	To Rebuild Dross Furnace	to the second of the second
(1	B)	To Repair Charging Arch of Brass Reverb. 1	furnace
602	24 Mo	orse Boulger Destructor Co.	
ŕ	В	ullocks Palm Springs Store - Palm Springs	
(4	<b>A)</b>	One (1) Morse Boulger Incinerator Extra Material	
602	25 <b>S</b> v	wift & Company - Vernon	v
		Repairs to Boiler	
602	26 Wh	n. P. Neil Company, Ltd.	
	Fo	ord Motor Company - Los Angeles	
		To Construct Incinerator	
	Anne Tradition of Agreement		
602	27 N±	ichols Engineering & Research Corp.	
	Ci	ity of Beverly Hills	
	T T T T T T T T T T T T T T T T T T T	To Line One (1) 7'-6" I. D. Brick Lining	110'
, and the second		High Self-Supporting Steel Stack for Munic	cipal
<i>J</i>		Incinerator (Labor Only)	
	and the second		
602	28 <b>s</b> c	outhern California Edison Co., Ltd Long Be	each
	Asses management	Boiler #38 Repairs	
A-1	Q (cont	đ)	

6028	Southern California Edison Co., Ltd Long Beach (cont
(A)	Boilers #17 and #18
(B)	Boilers #23 and #24
(C)	Boiler #41 (R) - Boiler #42
(D)	Boilers #25 and #26 (S) - Boiler s#1 and #2
(E)	Boiler #39 (T) - Boilers #17 and #18
(F)	Boilers #31 and #32 (U) - Boiler #43
(G.)	Boiler #45 (V) - Boiler #35
(H)	Boilers #29 and #30 (W) - Boiler #36
(I)	Boiler #40
(J)	Boiler #46
(K)	Boilers #27 and #28
(L)	Boilers # 9 and #10
(M)	Boilers # 7 and # 8
(N)	Boiler #47
(0)	Boiler #37
(P)	Boilers #15 and #16
(Q)	Boilers #13 and #14
6029	Pacific Clay Products - Los Angeles Plant
	To Repair Circular Tunnel Kiln
6030	Foster Wheeler Corporation - CANCELLED
	Blaw-Knox Construction Co. for
	General Electric Company - Anaheim
	One (1) FW Special Dowtherm Vaporizer Setting
6031	Eljer Company - Vernon
	To Install New Brick Stack
(A)	To Install Burner Blocks
6032	Douglas Oil Company - Bakersfield Refinery

Repairs to Furnace Floors in Two (2) Cracking Furn.

6042 Hickman Brothers, Inc. - San Pedro
To Repair Three (3) Boilers

To Repair G-E Furnace

6043	Todd Shipyards Corp San Pedro	
 A Same Annual Control	S. S. "Winter Hills"	
	To Repair Side Wall of Boiler	
6044	Douglas Oil Company - Clearwater	
	To Repair HRT Boiler	
(A)	To Repair Blowdown Pier - #1 Boiler	
6045	Patten-Blinn Lumber Co Wilmington	( )
	To Repair Boiler	
		the second
6046	Consolidated Lumber Co Wilmington	
	To Repair Incinerator	
6047	Shell Oil Company, Inc Dominguez	
	#1 Dubbs Furnace Repairs	
(A)	#5 Dubbs Furnace Repairs	
(B)	#3 Dubbs Furnace Repairs	
6048	California Institute of Technology - Pasadena	
	To Repair #1 Boiler	
And C	Land (N) explain a section will be a second	
6049	Stauffer Chemical Company - Dominguez	
~	8 ft. dia. Absorbing Tower - Acid-Proof Bri	ckwork
6050	Blackie's Blacksmith & Welding Shop - Burbank	
	To Install Lining in Asphalt Pavement Heater	r
<b>6</b> 051	B. F. Goodrich Company - Los Angeles 22	
	Brickwork Repairs to B. & W. Boiler Furnace	3
	#1 and #3	
6052	Union Oil Company - Wilmington	
	To Repair Furnace Unit #33	
(A)	Repairs to Crude Still	

المائية المائية

	6053	OFCCO Construction Company, Inc. Cityof Los Angeles, Dept. of Water & Power
		Wilmington - Harbor Steam Plant
	Department of the second of th	Refractories and Insulation, Blrs. #3, #4, and #5
Manager of the second s	()	
	6054	Southwest Steel Rolling Mills - Los Angeles
o d ass	regularization of the control of the	To Repair Skid Rail Tile on Heating Furnace
Walls	6055	Redondo Tile Company - Redondo Beach
P F	. ex	To Construct Pottery Kiln
Side We in H	To the state of th	
in S. Tille Orry	6056	Union Oil Company of Calif Lomita
42	Grander and Control of the Control o	Repairs to Boiler
Holes Baffle Refract	dimonstration of the state of t	and the second of the second o
H Bed H	6057	Great Lakes Carbon Corp., Permalite Div Torrance
Drill I able E able E of Bin		Repairs to Heater
on Hot	(A)	Furnace Repairs
A T B M I d	(B)	Repairs to Furnace
g O 4 a	(C)	Repairs to Furnace
cate an #3 and we Top Install r Corpo Angele	• ·	
a # o d &	6058	West End Chemical Company - Westend
To Relocation Boilers; To Remover and to In Stoker of Ios Iro Patch	The state of the s	One (1) Borax Melting Furnace /Chimney
~ 17 ~ 19 00 45 ~	(A)	John Dorward, Residence To Build New Fireplace and
Transport of the second of the	6059	McKinley Home for Boys - Van Nuys
<b></b>	. 60/9	HRT Boiler Brickwork Repairs
0000	n die company	
\$5B, S		Tributant and an artist and an artist and an artist and artist artist and artist artist and artist
The second secon	6060	Pacific Coast Borax Company - Wilmington
	re-criciosas de la constante d	Repairs to Furnace
	(A)	Repairs to Furnace (no material)
	(B)	To Patch Furnace
	and the state of t	
	6061	H. Levine Cooperage - 5400 S. Soto St., Vernon
	reuss with the control of the contro	Repairs to Boiler
	A .	

6062	Todd Shipyards Corp San Pedro	
	S. S. "Coxcomb Hill" - To Repair Boiler	de meriodo
	Andreas (Andreas Andreas Andre	
6063	Pacific Coast Borax Co Boron	
	To Rebrick Beik Furnace	
	was para man a man a man and the first of the contraction of	419.
Septemb	er 1947	
6064	C. C. Moore & Co. Engineers	
	Claremont College - Claremont	11.0
	Brick Setting for One (1) Single Class H4	No. 29
	B. & W. Boiler	
	the state of the s	
6065	Lohmen Brothers	
	Sun Lumber Company - Van Nuys, Calif.	
a la Aastras es	One (1) Kewanee Boiler	1.1.3
6066	Eastern Smelting & Refining Co Los Angeles	N N N N N N N N N N N N N N N N N N N
	Repairs to Brass Reverb. Furnace	
(A)	Repairs to Lead Furnace	
6067	C. C. Moore & Co. Engineers	
A STATE OF THE STA	PIGNEER DIVISION, The Flintkote Co Vernon	
	Repairs to Arch on 1935 Boiler	
6068	Upland Lemon Growers Association - Upland	
	Boiler and Pipe Insulation	
	Control of the Contro	
6069	The Fluor Corporation, Ltd.	
	Filtrol Corporation - Vernon	
	Acid Lining - Effluent Sump	
6070	Gaffers & Sattler - Vernon	
	Repairs to Enameling Furnace	

6071	Hammond Lumber Company - Los Angeles
	To Reline Concrete Incinerator
6072	Todd Shipyards Corp San Pedro
	S. S. "Crater Lake" - Repairs to Brickwork
	prediction of the computing
6073	The Texas Company - Los Angeles Works - Wilmington
र्ब (१)	Repairs to Crude Unit
607	
6074	Todd Shipyards Corp San Pedro
0	S. S. "Grande Mesa" - Brickwork Repairs
Ž. Š	
6075	Todd Shipyards Corp San Pedro
age of the state o	S. S. "A. C. Rubel"
The state of the s	To Repair Insulation on Boiler
6076	Swindell-Dressler Corporation
	American Radiator & Standard Sanitary Corp.
t en	Torrance - Brickwork - Four (4) Tunnel Kilns
6077	R. M. Gunzel & Company
	American Radiator & Standard Sanitary Corp.
	Torrance - Brick Settings for Two (2) #587 Kewanee
	Boilers and Stack
6078	Golden Bear Oil Company - Oildale
	One (1) Southwestern Fired Heater Enclosure
6079	Gentry, Incorporated - Oxnard
\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	(Successor to C. B. Gentry Company)
	To Rebuild and Repair Eight (8) Heaters
	Bourse To the John Color of the
6080	National Metal & Steel Corp Terminal Island
	Repairs to Boiler

6081	C. C. Moore & Co. Engineers
	Fibreboard Products, Inc South Gate
	To Renew Baffle in B. & W. Boiler
6082	White Heat Treating Co Huntington Park
	White Heat Treating Co Huntington Park  Furnace Brickwork Repairs
e, Linkaman magaziren erre ete	
6083	W. P. Fuller & Co. (Paint Factory) - Los Angeles
	Patch Lining in Ball Mill
,	$+$ 0 0 $m$ $\approx$
6084	San Diego Gas & Electric Co San Diego
	Silver Gate Station - Boiler Brickwork -
	Two (2) F25 AB-25 B. & W. Boilers
	TWO (2) F20 AB-20 B. & W. Bollers  Electrical Hopp
6085	Stauffer Chemical Company - Dominguez Division, Dominguez
(A)	Caustic Pit - Brickwork
6086	in the second se
	Ehrhart & Arthur, Inc.  Liquid Carbonic Pacific Corp., Ltd Los Angeles  Acid Brick Lining for Two (2) Scrubber Towers
	Acid Brick Lining for Two (2) Scrubber Towers
6087	The Cudahy Packing Company - Los Angeles  Boiler #2 - Furnace Brickwork Repairs
	Boiler #2 - Furnace Brickwork Repairs
6088	Shell Oil Company, Inc Deminguez
(A) (B) Oct. 194	Repairs to #6 Dubbs Repair Heater, #6 Distilling Unit #3 Repair #5 Boiler
6089	The Tide Water Associated Oil Co., Associated Division
0009	Watson - Badger Furnace - Brickwork Repairs
	The second of th

6090

Stauffer Chemical Co. - Vernon
Acid-Brick Lining of Pipe

	6091	Frederick O'Brien Paint & Varnish Works
	8 - x	Huntington Park - Repairs to Ball Mill Lining
7		
	6092	Great Lakes Carbon Corp Wilmington
		Repairs to Boiler
	6093	Standard Steel Corp.
5 2 2		Union Sugar Company - Betteravia, Calif.
		One (1) Direct Fired Calciner
	(A)	Sinton & Brown, Betteravia - Repairs to Dryer
1 NO, 801-11 R	6094	California Portland Cement Co Colton
- 0 2	•	Repairs to #8 Kiln Hood
	6095	Bechtel Corporation
		Bethlehem Pacific Coast Steel Corp Vernon
_		Electric Furnace Brickwork
1 )	(A)	Lining Slag Car
	6096	The Texas Company - Watson
		To Repair D. S. Heater #2
	6097	The Texas Company - Wilmington
	,	To Install Detrick Arch Section Feed -
		Preheater Furnace #B3
-	6098	Old Colony Paint & Chemical Co Los Angeles
	0090	To Reline Ball Mill
		IO MOLLING DOLL PILLE
	6099	Norris Stamping & Manufacturing Company - Los Angeles
		To Reline Ball Mill
	(A)	Relining Door
1	6100	Union Oil Company - Wilmington
		Repairs to Asphalt Still
	(A)	Repair Boiler
	6101	Pacific Coast Borax Co Wilmington
		#2AD Furnace Repairs (A) Repair #1 Furnace with

	6102	Todd Shipyards Corp San Pedro
	OTOZ	S. S. "Agriworld"
		Repairs to Burners of Three (3) Boilers
	6103	The Fluor Corporation, Ltd.
	0103	
		American Potash & Chemical Corp Trona
٠		Refractory and Insulation Enclosures for Caldiner
	(B)	Monohydrate Dryer Furn. (C) - Bleacher Furnace
	6104	Todd Shipyards Corp San Pedro
	11 TEST - 11 TES	S. S. "L. P. St. Clair" - Insulation on Aft Boiler
	(A)	Necessary Repairs to Boiler
	6105	Pacific Clay Products - Los Angeles - Plant #4
		Repairs to Kiln #5
	The state of the s	moraris of inter #7
	6106	Smoot-Holman Company - Inglewood
	6106	Brickwork on Incinerator
	eriin	Brickwork on Incinerator
	6107	Shell Oil Company, Inc Wilmington Refinery
		Repairs to Suspended Arch of Boiler #9
	6108	Standard Oil Company of Calif El Segundo
		Cracking Plant - Brickwork Alteration for Installa-
		tion of Air Preheater at #10 Unit, Second Battery;
	-	and Repairs to Furnace and Stack
	6109	Combustion Engineering Company
	· · · · · · · · · · · · · · · · · · ·	Imperial Irrigation District - El Centro
	(A)	C-E Boiler - Brickwork and Insulation Labor to Install Bigelow Castings
	6110	C. C. Moore & Co. Engineers
	VV	Arizona State Hospital - Phoenix, Arizona
		Brick Setting for One (1) Class FF12 No. 20 Boiler
	The second secon	grand and the second control of the

	Marie Marie and a series	domination from the state of th
	,	One (1) 4' x 10' Air Heating Furnace
	6112	C. F. Braun & Co.
	V shorts for	Arabian American Oil Co Saudi, Arabia
		lOxlOx20 Fired Heater - Material Only
	•	TOTALONEO LITTOR HEREET - Madellat Only
8. S	6113	Creat Iskas Camban Camp Harmonea Barnelita Division
	رستی	Great Lakes Carbon Corp Torrance, Permalite Division Repairs to Furnace
in the second se		nopally to rainage
NO, 861-11 R	6114	American Mineral Co Los Angeles
40, 86	V.J. J. ~	Furnace Brickwork
84		rathace brickwork
	K115	This or of Colifornia Harman
	6115	Eljer Co. of California - Vernon
		Repairs to #1 Melting Furnace and Add Dryer to
· Approximately	(A)	#2 Melting Furnace Install Thermocouple in Furnace
	6116	Matson Navigation Company - Wilmington, Berth #159
		S. S. "Matsonia" - Repairs to #5 Boiler
	6117	Todd Shipyards Corp San Pedro
		S. S. "General Brewster" - Repairs to Boilers
	6118	Todd Shipyards Corp San Pedro
		S. S. "Nidar" - Repairs to Boiler
	6119	Pacific Coast Borax Co Wilmington
	~	Repair #1 Fusion Furnace
	(A)	Change Burner in Furnace
	3	
)	6120	C. C. Moore & Co. Engineers
		Spencer Kellogg Co Long Beach
		Brick Setting - One (1) H3 No. 10 Boiler

PT5T	wilshire Oil Company, Inc Norwalk Refinery
	Brickwork Repairs to Rerun Heater
6155	Federated Metals Division, Amer. Smelting & Ref. Co.
	Los Angeles 23 - To Reline U. S. Furnace
6123	Todd Shipyards Corp San Pedro
	S. S. "Oleum" - To Patch Brickwork
6124	Southwest Steel Rolling Mills - Los Angeles
	Repairs to Furnace Arch
Nov. 1	947
6125	The Petrol Corporation - Los Angeles, Bandini Blvd.
	Petro-Chem Heater - Brickwork Repairs
(A)	Repair Floor of Firebox in #4 Boiler
6126	Standard Steel Corp.
	Minnesota Mining & Mfg. Co Corona
	To Line Dryer Firebox
(A)	Kiln Hood
(B)	Stack Base
(C)	Kiln Lining
6127	Southwest Steel Rolling Mills - Los Angeles
	To Repair Furnace
6128	Southwestern Engineering Company
	Shell Oil Company, Willbridge, Oregon
	Asphalt Heater
6129	Lohman Bros.
	Sears-Roebuck & Co Slauson & Vermont, Los Angele

Repairs to Incinerator Doors

	6130	Patten Blinn Lumber Co Wilmington
		To Repair Boiler
	6131	Eastern Smelting & Refining Co Los Angeles
		Repairs to Dross Furnace
	(A)	Repairs to Brass Furnace
% 5 5	6132	Eljer Co. of Calif Vernon
9.		To Construct Dryer Brickwork
22	(A)	Enameling Furnace Brickwork
NO, 803-11	<b>(</b> B)	To Construct Incinerator Stack
*	6133	Boaz Plumbing Company - North Hollywood
		Hot Water Tank Insulation
	(A)	Inglewood - Hot Water Tank Insulation
*	6134	Todd Shipyards Corp San Pedro
		S. S. "Colina" - To Tear Out and Replace all
	٨	Chrome Ore, Burner Cones, and Top Course of Brick i
		Port and Starboard Boilers
	6135	Filtrol Corporation - Vernon
		To Install Pier in Dryer Firebox
	6136	Todd Shipyards Corp San Pedro
		S. S. "Cornell" - To Patch 8 sq. ft. of Deck in
		Port and Starboard Boilers
	6137	Federated Metals Division, Amer. Smelting & Ref. Co.
		Los Angeles 23 - To Renew Bottom of #2 Brass Reverb
)	(A)	To Repair Aluminum Reverb.
	6138	Great Lakes Carbon Corp Wilmington
		Repairs to Kiln

6139	Standard Oil Company of Calif El Segundo
	Demolition of #9 Still Damaged by Explosion
6140	Los Angeles Steel Casting Co Warman Plant
	Vernon - To Construct Two (2) Car Type Anneal-
	ing Furnaces
6141	C. C. Moore & Co. Engineers
	American Potash & Chemical Corp Trona
	Brickwork and Insulation for
	Two (2) FH26 - 22'-6" B. & W. Boilers
(A)	Premium Time
6142	Bechtel Corporation
	Bethlehem Pacific Coast Steel Corp Vernon
	Paving on Platform
6143	Pacific Soap Company - San Diego
	Repairs to Union Iron Works Boiler and to 250 h.p
	Llewellyn Boiler
6144	American Processing Co San Diego
	Brickwork Repairs to Heine Boiler #2
6145	Union Oil Company of Calif Wilmington
4.	Unit #33 - Repairs to Heaters on "A" Side
(A)	Repairs to Boiler #2 in Boiler House
, .	
6146	Todd Shipyards Corp San Pedro
	S. S. "Sideling Hills" - Tear out and Replace
	all Brickwork and Chrome Ore in both Boilers
6147	Filtrol Corporation - Vernon
	Acid Brick in Tower

•	6148	Matson Navigation Company - Wilmington
		S. S. "Matsonia" - To Repair #3 Boiler
)		
	6149	Los Angeles Period Furniture Co Los Angeles
		Steam Plate Insulation
moreogo um m	6150	The Texas Company - Wilmington - Los Angeles Works
4.5.A		To Repair Tile Lining in Regenerator at F. C. C.
		Unit - Labor only
æ		
808	6151	The Arrow Plating Company - Los Angeles
ć z		Acid Brickwork - Chrome Tank
		and the second of the second o
	Dec. 19	<u>+7</u>
	6152	Douglas Aircraft Company, Ind Santa Monica
1		Acid Brick Lining in One (1) 41" x 105" x 72" deep
/		Chrome Plating Tank
	6153	Todd Shipyards Corp San Pedro
		S. S. "Bradley" - Necessary Repairs to Boiler
	6154	Natural Soda Products Co Keeler, Calif.
	**	#1 Burn Heater - Firebox Brickwork Repairs
	(A)	Brickwork Repairs to HRT Boiler
		a figure of the contract of th
	6155	Western Process Equipment Co.
		Decca Records, Inc Hollywood
		To Install Acid-Proof Brick Lining in
		One (1) 34 x 77 x 35" deep Chrome Tank
,		
,	6156	Todd Shipyards Corp San Pedro
		S. S. "Indian Navigator" - To Remove and Renew
		Tile and Chrome in Way of Tube Replacements in
		Starboard Boiler

6157	Standard Oil Company of Calif El Segundo
	#9 Unit - Second Battery - Cracking Plant
	Brickwork
(A)	Extra Brickwork (T. & M.)
(B)	To Insulate Tube Sheets (T. & M.)
(C)	To Install Millboard in Floor (contract)
(D)	To Install Sil-O-Cel Coarse Grade on Stack Flues (cont
* *	
6158	Mandarin Food Products, Inc Los Angeles
	Repairs to Firebox - Scotch Marine Boiler
gr.	
6159	The Texas Company - Fillmore
	Brickwork Repairs to Cracking Unit
6160	O'Keefe & Merritt Co Los Angeles 23
	To Line Two (2) 4 ft. dia. x 5 ft. Ball Mills
6161	Uddo Taormina Corp Buena Park
	Boiler Brickwork Repairs
(A)	Brickwork Repairs to #4 Boiler
(B)	To Repair Boiler Blow-off Pier
61.62	Wilmington Welding & Boiler Works
	Standard Oil Company of Calif San Pedro
	Repairs to Stationary Boiler on Loading Dock
6163	Wilson & Co., Inc Los Angeles
	Repairs to #3 Boiler
6164	Richfield Oil Corporation - Watson Refinery
	Repairs to Front Wall of Marine Boiler #7
(A)	Asphalt Heater #81
(B)	T-79 - #2 Terminal - Install Door Jamb and Window
	in Building

	6762	General Paint Corporation - Los Angeles
		To Reline Two (2) Ball Mills
F		
	6166	Todd Shipyards Corp San Pedro
		S. S. "Millicoma" - Brickwork Repairs in Port and
		Starboard Boilers
W.S.A.	6167	Inglewood Park Cemetery Assn Inglewood
<b>4</b>		To Install Two (2) Double Chamber Moore Type Cre-
		mation Retort and Stack
801-11 R		
9	6168	The Celotex Corporation (formerly El Rey Products Co
		Los Angeles - Brickwork Repairs to Combustion
		Tunnel Arch of Tubular Heater #3
		Fig. 1. Sec. 1
1	6169	Eastern Smelting & Refining Co Los Angeles
Į.		Repairs to Throat of Brass Furnace. Repairs to
		Lead Furnace
	6170	Wilmington Welding & Boiler Works
		San Pedro Dry Kiln Co San Pedro
		Boiler Repairs
	6171	Southern California Edison Co., Ltd Long Beach
		(Replaces Job No. 6028 for 1947)
		Repairs to Boiler #33
	(A)	Boiler #44
	(B)	Boilers #35, #38, #39, #37, #40
41	(C)	Boilers #42, #43, #46, #47, #41, #45
1	(D)	Boilers #21, #22
£	(E)	Boilers # 5, # 6
	(F)	Boilers #52
	(G)	Boilers # 9, #10
	(H)	Boilers #13, #14, #15, #16 (contd. over)
		(confor over.)

.

6171	Southern California Edison Co. (contd.)
(I)	Boilers #50, #51
(J)	Boilers #1, #2
(K)	Boilers #11, #12
(L)	Boilers #49
(M)	Boilers #3, #4
(N)	Boiler #53
(0)	Boilers #7, #8
(P)	Boiler #52
(Q)	Boiler #54
6172	W. C. Hardesty Co., Inc Los Angeles
	Repairs to Pot Furnace
6173	Todd Shipyards Corp San Pedro
	S. S. "Wm. Pepperell" - To Renew Brickwork in
	Four (4) Panel Doors and Patch Burner Cones
	with Plastic
6174	Wilmington Welding & Boiler Works
	J. H. Baxter Company - Long Beach
	Boiler Repairs
61.75	Eastern Smelting & Refining Co Los Angeles
	Repairs to Brass Furnace
6176	United States Gypsum Co South Gate
	Brickwork Repairs to Two (2) Edge Moor Boilers
(A)	Completely Seal all Crevices in Boiler Furnace Walls
(B)	Baffle Repairs
(C)	Baffle Repairs
6177	Matson Navigation Company - Wilmington
	Repairs to Front Wall, Floor, and Curtain Walls in
Serving agency	#4 Boiler

	6178	C. C. Moore & Co. Engineers	
		Southwest Lumber Mills, Inc McNary, Arizona	<b>3.</b>
	TITE TO THE TITE T	To Rebrick One (1) Class XII No. 38 Boiler	to medical
	(A)	Brickwork Repairs to Boilers	
	(B)	Material only	
	(C)	Material only	· don ·
	The second second second		
٠.	§ <b>61</b> 79	Amling Brothers, Inc Santa Ana	
	255 425	Repairs to HRT Boiler	
	6180	W. C. Hardesty Co., Inc Los Angeles	
		To Construct #3 Fatty Acid Pot Still	
•	Jan. 194	8	, ¥
	6181	Todd Shipyards Corp San Pedro	
		S. S. "River Raisin" - To Renew Brickwork	in Two
,	- Company	(2) Boilers, Door Insulation and to Replace	ce Top
		Water Wall Tile	
	(A)	To Rebrick Boiler on Crane	
	6182	Todd Shipyards Corp San Pedro	
		S. S. "Paul M. Gregg"	
		To Renew Insulation on Two (2) Boilers	
	(A)	Repairs to Top Headers in both Boilers and	l to
		Patch Burners	
	6183	Filtrol Corporation - Vernon	
	*	Repairs to Air Heating Furnace	
	(A)	To Rebuild Pier - Dryer C-202	
	6184	Great Lakes Carbon Corp Wilmington	and the second
		Repairs to approx. 40 ft. Kiln Lining and	Stack.
		Tearing out and Replacing Detrick Arch in	Settling
		Chamber and Center Wall around Feed Pipe;	Replace
		Nose Blocks (contd.)	

6184	Great Lakes Carbon Corp. (contd.)
(A)	To Patch Kiln with Quigley Gun
(B)	Repair Nose Block on Kiln
(C)	Repairs to Retaining Blocks at Feed End of Kiln
6185	Bethlehem Steel Company - Terminal Island
* * * * * Oselez Welenson normanie	S. S. "McKittrick Hills" - To Tear out and Replace
	Headers on Rear Walls and Kastset on End of Side
	Walls for both Boilers
6186	Shell Oil Company, Inc Wilmington Refinery
	Repairs to Furnace of Boiler #6
6187	Southern California Edison Co. Ltd Long Beach
	Unloading Material for Year 1948
1	(Replaces Job No. 5834 for 1947)
4	
6188	Swindell-Dressler Corporation
	Universal Sanitary & Manufacturing Co Mentone, Calif.
	Brickwork for One (1) New Tunnel Kiln
6189	Pacific Clay Products - Los Nietos
Appropriet	Miscellaneous Brickwork Repairs
	(Refer to Job No. 5900 for 1947)
(A)	March (F) August
(B)	April (G) September
(C)	May (H) October
(D)	June (I) November
(E)	July (J) December
6190	West End Chemical Co Westend
R	Repairs to Heine Kiln and Borax Glass Furnace
i i i	
6191	California Portland Cement Co Colton
	Repairs to #10 Kiln Hood

	6192	The Luer Packing Company - Vernon
		To Furnish Labor and Materials Required to Repair
<i>y</i>		Brickwork on Incinerator
	6193	Bechtel Corporation
		Reconstruction Finance Corp., Office of Rubber Reserve
		Standard Oil Company of Calif., Agent
U.S.A		El Segundo - Butadiene Plant
		Brickwork in Reactors and Manifold
S) ac	(A)	Brickwork Repairs to Throats of Air Heaters
801-118	(B)	Brickwork Repairs to Fl and F2 Hurnaces
NO.		
	6194	The Texas Company - Wilmington
		Labor only to Renew Brick Lining in Bottom 14 ft.
		Section of Stack at H.M.V.S. No. 1
,		
)	6195	Harvey Machine Co ye Torrance
		Brickwork Repairs
	6196	American Potash & Chemical Corp Trona
		Pyroborate Furnace #3 - Brickwork
	6197	American Potash & Chemical Corp Trona
		#2 Soda Ash Furnace - Brickwork Repairs
	6198	Great Lakes Carbon Corp Torrance
		Repairs to Brickwork
	(A)	Repairs to Brickwork
	(B)	Repairs to Brickwork
. 1	(C)	Repairs to Brickwork
,		
	6199	B. F. Goodrich Co Los Angeles
		Brickwork Repairs to Front Wall of B. & W. Boiler

6200	C. C. Moore & Co. Engineers
whoeyer or top, two or yet	Carter Oil Company - Billings, Montana
	Brickwork and Insulation for Four (4) Class FF16
	No. 40 B. & W. Boilers
6201	Federated Metals Division, Amer. Smelting & Refining Co.
·,	Los Angeles - Line Aluminum Dross Hopper
6202	Harshaw Chemical Co El Segundo
	Repairs to Rotary Kiln
6203	Bethlehem Steel Co Terminal Island
	S. S. "Arkansas" - Repairs to Boilers
27 R	
6204	Pacific Coast Borax Co Wilmington
	Patch Furnace
(A)	Repairs to #1 Furnace
(B)	Patch #1 Furnace
6205	The Fluor Corporation Ltd Los Angeles
	Repairs to Incinerator
6206	Stauffer Chemical Company, Dominguez Division
•	Dominguez - Insulation Repairs for 1948
	(See Job No. 5811 for 1947)
(A)	Maintenance Repairs to Insulation
(B)	Insulation Repairs to Two (2) Heat Exchangers
6207	Bechtel Corporation
	Bethlehem Pacific Coast Steel Corp Vernon
	To Install Brickwork on Incinerator Battery Room
(A)	and Stopper Rod Oven Brickwork for Manhole and for Ventilation
	Tunnel Wall
(B)	Extra Work in Connection with Piers, etc.
	§

	6208	OFCCO Construction Company, Inc.
~	*	Good Samaritan Hospital - Los Angeles
		To Install Brickwork in Two (2) 216 h.p. Union
		Type "L" Boilers
J.	6209	Standard Oil Company of Calif El Segundo
		Cracking Plant - Brickwork Alteration for Instal-
U.S.A		lation of Air Preheater at #11 Unit, Second Battery;
4		and Repairs to Furnace and Stack
NO. 601-11 R cam Pres U.S.	6210	Forster Shipbuilding Co., Inc Terminal Island
MO, 6(		S. S. "Maya" - Repairs to Galley Range
	6211	Standard Gypsum Company of Calif Long Beach
		Brickwork - Calcining Kettle
	6515	The Texas Company - Wilmington
		Repairs to Top 8 ft. of East Wall on Tube Still
	6213	Pacific Coast Borax Co Boron
		To Reline Beik Furnace
	Februar	y 1948
	6214	M. H. Whittier Company Ltd Los Angeles
		Brickwork Repairs to One (1) HRT Boiler
	6215	C. C. Moore & Co. Engineers
		So. Calif. Edison Company, Ltd Long Beach
		Brickwork Repairs at Soot Blower - Boiler #44
3	(A)	Remove and Relocate First Baffles in Boiler #44
	(B)	Insulation Repairs at Superheater of Boiler #44
	(C)	Insulation of Soot Blowers
	6216	California Fire Proof Door Co Los Angeles
		Repairs to Firebrick Lining of Incinerator

Firebox Extension to Hang-up Dryer Firebox  6218 Wilshire Oil Company, Inc Norwalk  To Install Plastic Chrome Ore on Tubes and Replace Tile and Insulation Casing on Side Walls of B. & Class "F" Boiler #5  (A) Brickwork Repairs to Alcorn Furnace Stack Lining  (B) Brickwork Repairs to Equiflux Furnace  6219 Bethlehem Steel Company - Terminal Island  S. S. "Contreras" - To Tear oug and Replace Two  (2) Fronts on Port and Starboard Boilers  6220 L. W. Lefort Company  Norris Stamping & Manufacturing Co Vernon  Acid Brickwork for Metal Wash Machine  To apply Acid-Proof Coment under Lead Cap, as requested.  6221 Union Sugar Company - Betteravia, Calif.  To Reline Lime Kiln  6222 Bethlehem Steel Co Terminal Island  S. S. "Luciana" - Repairs to Five (5) Fireboxes in Return Tubular Boilers	
To Install Plastic Chrome Ore on Tubes and Replatile and Insulation Casing on Side Walls of B. & Class "F" Boiler #5  (A) Brickwork Repairs to Alcorn Furnace Stack Lining (B) Brickwork Repairs to Equiflux Furnace  6219 Bethlehem Steel Company - Terminal Island S. S. "Contreras" - To Tear oug and Replace Two (2) Fronts on Port and Starboard Boilers  6220 L. W. Lefort Company Norris Stamping & Manufacturing Co Vernon Acid Brickwork for Metal Wash Machine To apply Acid-Proof Cement under Lead Cap, as requested.  6221 Union Sugar Company - Betteravia, Calif. To Reline Lime Kiln  6220 Bethlehem Steel Co Terminal Island S. S. "Luciana" - Repairs to Five (5) Fireboxes	
To Install Plastic Chrome Ore on Tubes and Replatile and Insulation Casing on Side Walls of B. & Class "F" Boiler #5  (A) Brickwork Repairs to Alcorn Furnace Stack Lining (B) Brickwork Repairs to Equiflux Furnace  6219 Bethlehem Steel Company - Terminal Island S. S. "Contreras" - To Tear oug and Replace Two (2) Fronts on Port and Starboard Boilers  6220 L. W. Lefort Company Norris Stamping & Manufacturing Co Vernon Acid Brickwork for Metal Wash Machine To apply Acid-Proof Cement under Lead Cap, as requested.  6221 Union Sugar Company - Betteravia, Calif. To Reline Lime Kiln  6220 Bethlehem Steel Co Terminal Island S. S. "Luciana" - Repairs to Five (5) Fireboxes	
Tile and Insulation Casing on Side Walls of B. & Class "F" Boiler #5  (A) Brickwork Repairs to Alcorn Furnace Stack Lining Brickwork Repairs to Equiflux Furnace  6219 Bethlehem Steel Company - Terminal Island S. S. "Contreras" - To Tear oug and Replace Two (2) Fronts on Port and Starboard Boilers  6220 L. W. Lefort Company Norris Stamping & Manufacturing Co Vernon Acid Brickwork for Metal Wash Machine (Extra) To apply Acid-Proof Cement under Lead Cap, as requested.  6221 Union Sugar Company - Betteravia, Calif. To Reline Lime Kiln  6222 Bethlehem Steel Co Terminal Island S. S. "Luciana" - Repairs to Five (5) Fireboxes	
Class "F" Boiler #5  (A) Brickwork Repairs to Alcorn Furnace Stack Lining (B) Brickwork Repairs to Equiflux Furnace  6219 Bethlehem Steel Company - Terminal Island S. S. "Contreras" - To Tear oug and Replace Two (2) Fronts on Port and Starboard Boilers  6220 L. W. Lefort Company Norris Stamping & Manufacturing Co Vernon Acid Brickwork for Metal Wash Machine (Extra) To apply Acid-Proof Cement under Lead Cap, as requested.  6221 Union Sugar Company - Betteravia, Calif. To Reline Lime Kiln  6222 Bethlehem Steel Co Terminal Island S. S. "Luciana" - Repairs to Five (5) Fireboxes	W.
(A) Brickwork Repairs to Alcorn Furnace Stack Lining (B) Brickwork Repairs to Equiflux Furnace  6219 Bethlehem Steel Company - Terminal Island S. S. "Contreras" - To Tear oug and Replace Two (2) Fronts on Port and Starboard Boilers  6220 L. W. Lefort Company Norris Stamping & Manufacturing Co Vernon Acid Brickwork for Metal Wash Machine (Extra) To apply Acid-Proof Cement under Lead Cap, as requested.  6221 Union Sugar Company - Betteravia, Calif. To Reline Lime Kiln  6222 Bethlehem Steel Co Terminal Island S. S. "Luciana" - Repairs to Five (5) Fireboxes	• • •
Bethlehem Steel Company - Terminal Island S. S. "Contreras" - To Tear oug and Replace Two (2) Fronts on Port and Starboard Boilers  6220 L. W. Lefort Company Norris Stamping & Manufacturing Co Vernon Acid Brickwork for Metal Wash Machine (Extra) To apply Acid-Proof Cement under Lead Cap, as requested.  6221 Union Sugar Company - Betteravia, Calif. To Reline Lime Kiln  6222 Bethlehem Steel Co Terminal Island S. S. "Luciana" - Repairs to Five (5) Fireboxes	
6219 Bethlehem Steel Company - Terminal Island S. S. "Contreras" - To Tear oug and Replace Two (2) Fronts on Port and Starboard Boilers  6220 L. W. Lefort Company Norris Stamping & Manufacturing Co Vernon Acid Brickwork for Metal Wash Machine (Extra) To apply Acid-Proof Cement under Lead Cap, as requested.  6221 Union Sugar Company - Betteravia, Calif. To Reline Lime Kiln  6222 Bethlehem Steel Co Terminal Island S. S. "Luciana" - Repairs to Five (5) Fireboxes	
S. S. "Contreras" - To Tear oug and Replace Two  (2) Fronts on Port and Starboard Boilers  6220 L. W. Lefort Company  Norris Stamping & Manufacturing Co Vernon  Acid Brickwork for Metal Wash Machine  (Extra) To apply Acid-Proof Cement under Lead Cap, as requested.  6221 Union Sugar Company - Betteravia, Calif.  To Reline Lime Kiln  6222 Bethlehem Steel Co Terminal Island  S. S. "Luciana" - Repairs to Five (5) Fireboxes	
(2) Fronts on Port and Starboard Boilers  6220 L. W. Lefort Company  Norris Stamping & Manufacturing Co Vernon  Acid Brickwork for Metal Wash Machine  (Extra) To apply Acid-Proof Cement under Lead Cap, as requested.  6221 Union Sugar Company - Betteravia, Calif.  To Reline Lime Kiln  6222 Bethlehem Steel Co Terminal Island  S. S. "Luciana" - Repairs to Five (5) Fireboxes	
L. W. Lefort Company Norris Stamping & Manufacturing Co Vernon Acid Brickwork for Metal Wash Machine (Extra) To apply Acid-Proof Cement under Lead Cap, as requested.  6221 Union Sugar Company - Betteravia, Calif. To Reline Lime Kiln  6222 Bethlehem Steel Co Terminal Island S. S. "Luciana" - Repairs to Five (5) Fireboxes	
Norris Stamping & Manufacturing Co Vernon  Acid Brickwork for Metal Wash Machine  (Extra) To apply Acid-Proof Cement under Lead Cap, as requested.  6221 Union Sugar Company - Betteravia, Calif.  To Reline Lime Kiln  6222 Bethlehem Steel Co Terminal Island  S. S. "Luciana" - Repairs to Five (5) Fireboxes	
Norris Stamping & Manufacturing Co Vernon  Acid Brickwork for Metal Wash Machine  (Extra) To apply Acid-Proof Cement under Lead Cap, as requested.  6221 Union Sugar Company - Betteravia, Calif.  To Reline Lime Kiln  6222 Bethlehem Steel Co Terminal Island  S. S. "Luciana" - Repairs to Five (5) Fireboxes	
Acid Brickwork for Metal Wash Machine  (Extra) To apply Acid-Proof Cement under Lead Cap, as requested.  6221 Union Sugar Company - Betteravia, Calif.  To Reline Lime Kiln  6220 Bethlehem Steel Co Terminal Island  S. S. "Luciana" - Repairs to Five (5) Fireboxes	
(Extra) To apply Acid-Proof Cement under Lead Cap, as requested.  6221 Union Sugar Company - Betteravia, Calif. To Reline Lime Kiln  6220 Bethlehem Steel Co Terminal Island S. S. "Luciana" - Repairs to Five (5) Fireboxes	
requested.  6221 Union Sugar Company - Betteravia, Calif.  To Reline Lime Kiln  6220 6222 Bethlehem Steel Co Terminal Island  S. S. "Luciana" - Repairs to Five (5) Fireboxes	
6221 Union Sugar Company - Betteravia, Calif.  To Reline Lime Kiln  6220 Bethlehem Steel Co Terminal Island  S. S. "Luciana" - Repairs to Five (5) Fireboxes	
To Reline Lime Kiln  Bethlehem Steel Co Terminal Island  S. S. "Luciana" - Repairs to Five (5) Fireboxes	
To Reline Lime Kiln  Bethlehem Steel Co Terminal Island  S. S. "Luciana" - Repairs to Five (5) Fireboxes	
Bethlehem Steel Co Terminal Island S. S. "Luciana" - Repairs to Five (5) Fireboxes	
S. S. "Luciana" - Repairs to Five (5) Fireboxes	
S. S. "Luciana" - Repairs to Five (5) Fireboxes	
in Return Tubular Boilers	
6223 The Texas Company - Wilmington	
Brickwork Repairs to Hot Oil Circulating Furnace	
and to Install Four (4) Zink Burners	
(A) Renew Brickwork on Seven (7) Pilasters of HMLU	
Upshot Heater; Point up Cracks in #8 Pilaster	
(B) Brickwork Repairs to #7 Separator Pit	
(C) To Renew Two (2) Burners on #3 Pressure Heater	
(D) Brickwork Repairs to Heater Furnace of #1 PPS	

	6224	Refinery Maintenance Company, Inc.
		Union Oil Company of Calif Wilmington
)		Fireproofing with Red Brick, Skirt of Vessel
		D-101 in Unit #34
	6225	Holmes Tuttle (Ford Dealer) - Los Angeles 36
		Repairs to Incinerator
40 50 20		
	6226	Rocklite Company - Ventura
<b>8</b>		Rotary Kiln - Firebrick Lining
801-11	(A)	Remove 42" Projection in Fire Brick Lining of
S .		Rotary Kiln
	(B)	To Install about 28 ft. of $4\frac{1}{2}$ " Fire Brick Lining
		in Kiln
*	6227	Standard Steel Corporation
)	,	Sinton & Brown Company - Betteravia, Calif.
		To Install 2500 - 6" Kiln Blocks in Rotary Kiln
	6228	C. F. Braun & Co.
		Stanolind Gas & Oil Company - Slaughter Field -
		Coble, Texas - Two (2) 15 x 20 x 30 Fired Heaters-
		Material Only
	(A)	Two (2) Fired Heaters Labor Only
	6229	Eljer Company of Calif Vernon
		To Repair One (1) Ball Mill #6
	(A)	To Build Incinerator Stack
	(B)	Repairs to Hearth and Walls of Frit Smelting Furn.
	6230	The Fluor Corporation, Ltd.
		American Potash & Chemical Corp Trona
		Underground Flue from Calciner to Bicarbonate
		Dryer

6231	Shell Oil Company, Inc Wilmington Refinery
	Repairs to #5 Boiler
(A)	Repairs to Bigelow Arch on #9 Boiler
6232	Pacific States Oil Company - Wilmington
	Repairs to Boiler
6233	Eastern Smelting & Refining Co Los Angeles 21
	Repairs to Lead Furnace
(A)	Repairs to Brass Furnace
(B)	Repairs to Dross Lead Furnace
(C)	Repairs to Brass Furnace #1
(D)	Repairs to Throat on #1 Brass Furnace
6234	California Portland Cement Co Colton
	Repairs to #13 Kiln Hood
6235	Superior Paint & Lacquer Works - Huntington Park
	To Repair 5' dia. Ball Mill
6236	Richfield Oil Corporation - Wilmington
	To Patch Brickwork - #4 Oxidized Still
(A)	Building Office for Gas Agitator
(B)	To Patch Brickwork on #6 Oxidized Still
6237	Federated Metals Division, Amer. Smelting & Ref. Co.
	Los Angeles 23 - Reline U. S. Furnace
(A)	Repairs to #2 Brass Reverb.
	List of the transfer of the first fi
6238	Norris Stamping & Mfg. Co Vernon
	To Install Brick Piers under Lefort Metal Wash
	Machine Andrew State Andrew State St
_	
6239	Todd Shipyards Corporation - San Pedro /Boilers
	S. S. "Oleum" - Patch Brickwork in Port & Starboard

6240	Standard Oil Company of Calif El Segundo Refinery
· · · · · · · · · · · · · · · · · · ·	Brickwork Repairs to Crude Still 53 Unit
(A)	To Insulate 15 Tie Plates in 53 Crude Furnace
(B)	To Remove and Replace Tube Support Casting In-
	sulation for Rear of Furnace #53
6241	White Heat Treating Co Huntington Park
	To Install Piers in Furnace to Support Hearth Plates
6242	Fibreboard Products Co Vernon
	Repairs to #5 Boiler
March	1948
6243	Bethlehem Steel Company - Terminal Island
	S. S. "San Rafael" - Repairs to Port and Starboard
	Boilers
( m ! )	
6244	Standard Oil Company of Calif El Segundo -
	El Segundo Refinery - #3 Unit Cracking Plant -
	Brickwork Repairs and Detrick End Walls and In-
4 . 3	sulating Roof Tube Sheets
(A)	#3 Still - Additional Repair Work, including In-
	sulating Radiant Tube Sheets and Convection Bank
	Sheets who have being the common of the state of the stat
(B)	Centerwall Renewals
(C)	Repairs on Trumbles
6245	Bethlehem Steel Co Terminal Island -
	S. S. "Rhode Island" - Repairs to Boiler
Color	
6246	Rust Furnace Company
	Bethlehem Pacific Coast Steel Corp Vernon -
	Repairs to Rust Furnace

624 (	American Potash & Chemical Corp Trona
	Coarse Granular Potash Plant - To Install Brick-
	work for a 6 x 6 x 11' LaClede Christy Air
	Heating Furnace
(A)	Pyrobor Furnace Repairs
6248	Shell Oil Company, Inc Dominguez - Catalytic Cracker
	Regenerator Brickwork Repairs
6249	Max Weil of California - Los Angeles
	Brickwork Repairs to Pottery Kiln
(A)	Repairs to #1 Kiln
(B)	Repairs to #1 Kiln
(C)	Repairs to #1 Kiln
6250	International Derrick & Equipment Co Torrance
	To Install Acid Brickwork in Pickling Tank
6251	Todd Shipyards Corporation - San Pedro Renew
	S. S. "General Freeman" -/Brickwork and In-
	sulation in Three (3) Superheater Doors
6252	Bethlehem Steel Company - Terminal Island
	S. S. "City Carlisle" - Patch Brickwork
6253	C. C. Moore & Co. Engineers
	Southern California Edison Company Ltd Long Beach
	Rental of Scaffolding
(A)	Insulation Repairs - Boilers #50 and #51
(B)	Insulation Repairs - Boiler #49
(C)	Rental of Scaffold for Boilers Nos. 49, 52, 53,
	and 54; Rental of Two (2) Air Tampers
(D)	Repairs to Boiler #53
(王)	Repairs to Boiler #52 (contd.)

	6253	(contd.)
1	(F)	Insulation Repairs - Boiler #34 - #2 Plant
*	(G)	Boiler #33 Insulation Repairs
	(H)	Boiler #54 - To Repair with Quigley Gun
	(I)	Boiler #33 - Cutting Baffle Tile
	(J)	Boiler #34 - To Install Baffle
	(K)	Boiler #36 - Insulation
	(L)	Boiler #35 - Material
	(M)	Boiler #35 - Labor
	, A common V	
	6254	C. C. Moore & Co. Engineers
		The Exchange Orange Products Co Ontario
		Repairs to First Baffle in Class FF15 No. 32 Blr.
		r de la companya de l
	6255	Shell Oil Company, Inc Wilmington Refinery
		Repairs to #4 Boiler
ļ		
	6256	The Texas Company - Wilmington
		To Furnish Labor only to Replace approx. 50 sq. ft.
		of Brickwork and to Patch Seven (7) Peepholes on
		H.M.L.U. Upshot Heater
		was to the second secon
	6257	Union Oil Company of Calif Wilmington
		Repairs to Crude Still in Unit #33
	6258	General Tire & Rubber Company of Calif.
		Naval Ordnance Test Station - Inyokern, China Lake, Calif
		Labor to Line G. E. Furnace
	<i></i>	
)	6259	Eastern Smelting & Refining Co Los Angeles
		Repairs to Dross Furnace
	6260	American Lumber & Treating Co Wilmington
		To Install One (1) Complete Fire Brick and Plastic /rine Boiler
		Combustion Chamber in New Farrar & Trefts Scotch Ma-

6261	C. F. Braun & Co.
	Stearns-Roger Manufacturing Co.
	Humble Oil & Refining Company
	Katy (Johnsue), Texas
	Three (3) 15 x 15 x 40 Fired HeatersMaterial only
6262	C. F. Braun & Co.
	Esso Standard Oil Company, Louisiana Division
	North Baton Rouge, Louisiana - Vacuum Unit #7, TK
-9	One (1) 15 x 20 x 40 Fired HeaterMaterial only
6263	Eljer Company of Calif Vernon
* * * * * * * * * * * * * * * * * * * *	To Rebuild New Smelter
(A)	To Build New Enamel Furnace
(B)	Repairs to #1 Melting Furnace
(C)	Build 8" Red Brick Wall between Grinding Room
	and Enameling Room
(D)	To Reline #4 Ball Mill, 5 ft. dia. x 4 ft. long
(E)	#2 Enamel Furnace
(F)	Repairing done in Building
(G)	To Reline Slush Mill #3 in Millroom
(H)	Repair #6 Enamel Furnace
(I)	Replace Insulation Brick over Door Openings on
	#1 and #2 Enamel Furnaces
(J)	Replace Insulation Brick over Door Openings on
	#3 and #4 Enamel Furnaces
(K)	Repairs to #2 Smelting Furnace
(L)	To Line Two (2) Furnace Doors
April .	
6264	Pacific Clay Products - Los Nietos Plant #6
	(Refer to Job No. 5899 for Mar. 1947 to Apr. 1, 1948)
	Repairs to Kiln #7
(A)	Repairs to Kiln #30 (contd.)

```
6264 (dontd.)
 (B)
           Repairs to Kiln #1
 (C)
           Repairs to Kiln #21
 (D)
           Repairs to Kiln #42
 (E)
           Repairs to Kiln #29
           Repairs to Kiln #2
 (F)
 (G)
           Repairs to Kiln #33
 (H)
           Repairs to Kiln #35
 (I)
           Repairs to Kiln #34
       Swindell-Dressler Corporation
6265
       Vernon Kilns - Vernon
           To Install Brickwork for One (1) Tunnel Kiln
6266
       Swindell-Dressler Corporation
       Cook Manufacturing Company - Puente, Calif.
           To Install Brickwork for One (1) Tunnel Kiln
       Bethlehem Steel Company - Terminal Island
6267
           S. S. "A. C. Rubel" - Brickwork Repairs to Boilers
6268
       The Babcock & Wilcox Company
       Stone & Webster Engineering Corp. for
       El Paso Electric Company - Las Cruces, New Mexico
           Setting for One (1) F-25 AG 20 - 16/54" Integral
           Furnace Boiler
       Federated Metals Division, Amer. Smelting & Ref. Co.
6269
           Los Angeles 23 - Repairs to #2 Brass Reverb
 (A)
           Repairs to Zinc Smelter
           Brickwork Repairs to Aluminum Furnace
 (B)
6270
       San Diego Gas & Electric Co. - Sta. "B" - San Diego
           Furnace Brickwork Repairs - Boiler #27
```

6271	Southwestern Engineering Company
	Standard Oil Company of Calif.
	To Install One (1) 7'-4" x 8'-3" x 17'-10 3/4"
	(inside dia.) Brick Setting in Portable Rerun Heater
	in S. E. Co. Santa Fe Avenue Shop, Los Angeles 11
(A)	To Insulate Header Boxes
(B)	To Install 2" of Insulating Concrete in Flue Gas
	Duct Add with the second of th
6272	Todd Shipyards Corp San Pedro
	S. S. "Lifjord" - Renew Chrome Ore and Headers in
	Port and Starboard Boilers; Renew Curtain Walls in
	Starboard Boilers
6273	Shell Chemical Corp Dominguez Refinery - #1 DMK Furnace
	To Remodel Brickwork to Install Five (5) Coppus
	"Fanmix" Burners, and Misc. Brickwork Repairs
6274	Latchford-Marble Glass Co Los Angeles
	To Rebuild Glass Tank
(A)	To Break up Glass in Bottom of Tank
6275	The H. K. Ferguson Company, Inc.
	The Procter & Gamble Mfg. Company - Long Beach
	To Install Refractory Linings in One (1) Air Heater
	Breeching and One (1) Peabody Air Heater
(A)	To Point up
5 4	
6276	Baker-Perkins, Inc.
	Helms Bakeries - Montebello
	To Install Brickwork and Insulation for One (1)
	Baker-Perkins Bake Oven

	05//	Todd Snipyards Corp San Pedro
	*	S. S. "Mission Soledad" - Miscellaneous Brickwork
<i>)</i>		and Insulation Repairs to Port Boiler and Starboard
	n p	Boiler
	6278	Harbor Boat Building Co.
,		W. R. Grace & Company - San Pedro - Berth 55
4,5,14		S. S. "Corsair" - To Patch Four (4) Boilers
2		
EN DE	6279	Pacific Coast Borax Company - Wilmington
		Repairs to B. & W. Boilers #1 and #2
2		
	6280	Angelus Steel Treating Co Vernon
	v	To Rebuild 5'-2" x 9'-0" Heat Treating Furnace
	(A)	To Repair Hearth
)	6281	Patten Blinn Lumber Company - Wilmington
		To Patch Incinerator
	(A)	Repairs to Donkey Boiler
	6282	General Tire & Rubber Co. of Calif.
		U. S. Navy - N. O. T. S Inyokern, China Lake, Calif.
		Repairs to Four (4). Ajax Furnaces
	m in it is the second	
	6283	Kelco Company - San Diego
		To Install Lining in a Cleaver Brooks OB45 Boiler
	6284	Todd Shipyards Corp San Pedro
		S. S. "John H. Marion" - Brickwork and Insulation
, pomer		Repairs to Port and Starboard Boilers
	(00-	
	6285	Lohman Bros.
		Sears-Rebuck & Co Long Beach
	(A)	Brick Settings for One (1) Brownell S-266 Boiler; One (1) Brownell S-266 Blr.; (B) One (1) Brownell

6286	C. C. Moore & Co. Engineers
e e e e e e e e e e e e e e e e e e e	Southern California Edison Company Ltd.
	Long Beach - Plant #2
	Rental of Scaffolding - Boilers Nos. 33, 34, 35 & 36
6287	Harvey Machine Company
	To Furnish Labor only to Renew Top of Swindell-
	Dressler Ladle
6288	Bechtel Corporation
	Bethlehem Pacific Coast Steel Corp Vernon
	Wire Patenting Furnace, Lead Pot, and Duct Work
6289	Southern California Edison Company Ltd Long Beach
	Boiler #34 - Burner Repairs
(A)	Baffle Repairs
(B)	Balance of Work Required
6290	Union Oil Company of Calif Wilmington
	Repairs to T. C. C. Unit - Treater Kiln
* (A)	Cracker Kiln
6291	Ehrhart & Arthur, Inc.
	Eagle Oil & Refining Company - Santa Fe Sprints Refinery
	To Install about 300 Fire Brick in Boiler being
	Revemped
6292	Great Lakes Carbon Corp Torrance
A. A. A. A.	Repairs to Furnace
(A)	Repairs to Burners
ar reservations	
6293	Socal Oil & Refining Company - Huntington Beach
	#1 Boiler - Repairs to Bridge Wall

6294	C. C. Moore & Co. Engineers
· Vergen	American Potash & Chemical Corp Trona
· )	To Furnish Labor to Install Refractories for New
	Furnace 16'-0" x 13'-3" x 8'-0", Designed by
	LaClede-Christy for Potash Process Dryer #1
6295	C. C. Moore & Co. Engineers
	Tide Water Associated Oil Co Ventura
	To Install Insulation and Refractories for One (1)
	FF-15 No. 32 B. & W. Boiler
6296	C. C. Moore & Co. Engineers
	General Brewing Company - Azusa
	To Install Insulation and Refractories for One
	(1) FF-12 No. 20 B. & W. Integral Furnace Boiler
6297	Pacific Hard Rubber Co., div. of Stauffer Chemical Co.
	Vernon - Brickwork Repairs to Building Wall
*	
6298	United States Gypsum Co South Gate
	#3 Boiler - To Rebuild Front Arch
6299	Bethlehem Steel Company - Terminal Island
	S. S. "Lompoc" - Necessary Repairs to Boilers
6300	National Enameling & Foundry Co Compton
	To Construct One (1) Enameling Furnace
(A)	Stack for Enameling Furnace
May 1948	
6301	The Harshaw Chemical Co El Segundo
	Rebrick Three (3) Rotary Kilns
6302	W. P. Fuller & Co Los Angeles
	To Patch $4\frac{1}{2}$ x 5 ft. Ball Mill

A STATE OF STATE

	6303	Bethlehem Steel Company - Terminal Island
	Beron, and a second	S. S. "St. Nidar" - To Tear Out and Replace
	Back to the control of the control o	Brickwork in Two (2) B. & W. Boilers; and Six
		(6) Superheater Doors
	Water Control of the	
	6304	Richfield Oil Corporation - Wilmington - Watson Refinery
		#1 Boiler House - Repairs to Front Wall in #1 Boiler
		A Section 1. The second of the
	6305	Acme Brewing Company - Vernon
		Repairs to #3 Boiler
	6306	Southwestern Engineering Co.
		Century Oil Company - Refinery - Long Beach
	***	Brickwork Repairs to Portable Tube Still
	6307	Great Lakes Carbon Corp Wilmington
		Repairs to Nose Block on Kiln
	6308	General Paint Corporation - Los Angeles, 544 Mateo St.
		To Reline One (1) 5'-0" x 6'-0" Pebble Mill
	6309	Forest Lawn Memorial-Park Association, Inc Glendale
		To Paint and Scrape all Three (3) Retorts at
	and the second s	Crematory
6300		
	6310	Bechtel Corporation
	Technique de la company de la	Standard Oil Company of Calif El Segundo
	-	To Install Acid-Proof Tile in Trench at Cracked
	-	Naptha Treating Plant
	Table of the state	
:	6311	Matson Navigation Company - Wilmington -
	wage	S. S. "Lurline" - Repairs to Baffle in Six (6)
	rate or a second	Boilers in Aft Boiler Room

		The state of the s
		S. S. "St. Clair" - Insulation on Forward Boiler
No.	(A)	Necessary Brickwork Repairs to Forward & Aft Blrs.
	(B)	Insulation on Aft Boiler
	6313	Foley Brothers, Inc.
		Phelps-Dodge Corporation - Ajo, Arizona
751		New Cornelia Plant - To Construct Enclosures for
Olive solvet		Two (2) C-E, Type "VU" Boilers
£1 22	(A)	To Apply External Insulation on C-E Boilers
2 2 40 48	(B)	Brickwork, Second Unit
si se	(C)	Insulation Work, Second Unit
	(D)	Phelps Dodge Corporation - Ajo, Arizona (direct)
		Blacksmith Shop - Repairs to Heating Furnace
\	6314	Spencer Kellogg & Sons, Inc Terminal Island
1	*	Necessary Repairs to Boiler
	6315	Southern California Edison Co. Ltd Long Beach -
		Boiler #33 - Burner Repairs
	(A)	Baffle Repairs
	(B)	Balance of Work
	6316	California Portland Cement Co Colton
		New Brick Setting for One (1) 72" x 16'-0" Flush
		Front HRT Boiler
	6317	OFCCO Construction Company, Inc.
		Veterans Administration Hospital - Sawtelle
Ì		Refractory and Insulation Enclosure for Two (2)
ž.		New 50,000 lb. per hr. Union Iron Works Boilers and
		One (1) Relocated 500 h.p. Badenhausen Boiler
	(A)	To repair a Section 2 ft. x 2 ft. in North Side Wall
		of Dutch Oven in North Boiler

6312 Todd Shipyards Corp. - San Pedro

6318	Bechtel Corporation
	Standard Oil Company - Salt Lake City, Utah - Refinery
	#11 Battery - Crude Unit #1
	Brickwork of One (1) Furnace
(A)	Floor in Stack of Crude Unit
(B)	Premium Time
and the distribution of processing the state of the state	
6319	White Heat Treating Company - Huntington Park
	To Reline Circular Door on Pit Furnace
(A)	To Repair Heat Treating Furnace
6320	Bethlehem Steel Company - Terminal Island
	S. S. "Chas. S. Jones" -
	Repairs to Forward and Aft Boilers
6321	Gladding, McBean & Company - South Gate
	To Install Brickwork for Renewing #3 Downdraft
	Kiln, 31'-6" inside dia. x 9'-0" high
(A)	To Spray-Coat Interior of Kiln
6322	California Portland Cement Co Colton
	#11 Hood Repair
(A)	# 8 Cooler Repair
(B)	#15 Cooler Repair
officers of the section of the secti	
6323	Federated Metals Division, Amer. Smelting & Ref. Co.
	Los Angeles 23 -
	Brickwork Repairs to Three (3) Zinc Retorts
(A)	Repair Rear Wall Brass Reverb. #2
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
6324	Fernstrom Paper Mills, Inc Pomona
. We	Brickwork Repairs to Boiler #3

. 6325	(Cancelled)
· · · · · · · · · · · · · · · · · · ·	Griffith Company
**************************************	City of Los Angeles, Calif.
*	To Remodel Stack Base Brickwork Lining to Accom-
	modate Alloy Flashing Plates
6326	J. H. Baxter & Company - Long Beach
	To Reline Incinerator
*	
6327	Tide Water Associated Oil Co., Associated Division
	San Pedro - at Ship Loading Dock -
	Necessary Repairs to Stationary Boiler
6328	Pacific Coast Borax Co Wilmington
	To Patch #1 Furnace
(A)	#1 Furnace To Overhaul Roof & Back Wall & Flue
(B)	#2 Furnace To Repair with Quigley Gun
(C)	#1 Furnace to Point up
6329	Todd Shipyards Corp San Pedro
	S. S. "Mission Capistrano"
	Brickwork Repairs to Port and Starboard Boilers
(A)	Repairs to Two (2) Boilers
6330	Shell Chemical Corporation - Dominguez
	To Install a 42" thick Acid-Proof Brick Lining
	in 17'-4" dia. x 11'-0" high Tank
6331	Shell Chemical Corporation - Dominguez Alcohol Plant
	To Construct No. 3 DMK Furnace F-4
)	
6332	Pacific Hard Rubber Company, div. of Stauffer Chem. Co
	Vernon - Repairs to Class HIII #12 Stirling Boile:

6333	American Potash & Chemical Corp Trona
e de la constitución de la const	#3 Soda Products Furnace Repairs
6334	Vernon Kilns - Vernon
	Installing Burners in Prouty Kiln
6335	Shell Oil Company, Inc Wilmington - Watson Refinery
(A)	Shell Oil Company, Inc Wilmington - Watson Refinery Repairs to Trumble Retort in Unit #4 Repairs to Trumble Retort in Unit #3
(B)	Repairs to #9 Boiler
June lo	<u> </u>
6336	San Diego Gas & Electric Co San Diego - Silver Gate Sta.
	Boilers #1 and #2 - To Rebuild Burner Wall
6337	Bethlehem Steel Co.
	Union Oil Company's Ship, "Santa Paula" -
	Terminal Island - Repairs/to Two (2) Boilers
6338	Todd Shipyards Corp San Pedro
	"Victor H. Kelley" - Repairs to Two (2) Boilers
6339	Superweld Corporation - Glendale
	Repair Brickwork in General Electric Furnace
6340	Stauffer Chemical Company - Dominguez
7 7000-	To Tear out and Replace Brickwork for Renewing
	Cast Iron Caustic Pits in Two (2) Furnaces
(A)	To Install Burner Tile in #4 Caustic Fusion Furnace
n Kamatan kacamatan	and the second of the second o
6341	Great Lakes Carbon Corp Permalite Division -
	Torrance - To Install Liner in Pearlite Kiln
. (A)	To Install Liner in Pearlite Kiln
6342	Shell Chemical Corp Dominguez
e eren	#2 DMK Furnace (F-2) - To Remodel Brickwork and to Install Five (5) Coppus "Fanmix" Burners

	6343	C. F. Braun & Co.
	e de la companya del companya de la companya del companya de la co	ESSO Standard Oil Company, Louisiana Division -
<i>)</i>		No. Baton Rouge, Louisiana
		Material OnlyRefractories and Insulation for
		Three (3) Fired Heaters:-
		(1) The Splitter Reboiler Fl, 12 x 12-30
		(2) The Rerun Feed Preheater, F2, 10 x 12-20
# .		(3) The Rerun Reboiler, F3, 8 x 8-20
i i		Control of the contro
ı	6344	American Ceramics Products, Inc Santa Monica
- - - - -		To Install a Patterson Lining in a 24" dia. x 36"
ó z		long Ball Mill
	6345	C. C. Moore & Co. Engineers
	(PT)	Tucson Gas, Electric Light & Power Co.
1	Prem. Time	Tucson, Arizona - Brick and Insulation Setting for
)	1.11110	One (1) B. & W. Class FH-26 - 21'-0" x 16'-0" wide
	(A)	Gas and Oil Fired Integral Furnace Boiler Covering of Outstanding Legs, also Weatherproofing the Externally Applied Insulation
	6346	Pacific Clay Products - Los Angeles - Plant #4
		Repairs to Kiln #16
	6347	Refinery Maintenance Company, Inc.
		Barnsdall Oil Company - Newhall
		To Install Refractories and Insulating Materials
		for One (1) Petro-Chem Oil Heater
	(A)	To Insulate with red brick 8-12" WF 27# Columns
		51'-8" high on Petro-Chem Heater
	(B)	To Insulate with red brick 4-6x6" WF 20# Columns
		8'-10" high on D-3
1		
	6348	Bethlehem Steel Company - Terminal Island
		Repairs to Three (3) Superheater Doors

6349	Standard Oil Company of Calif El Segundo
e compressioner com consistency and consistency production of	Repairs to #2 Heater
(A)	Repairs to #10 Cracking Unit Furnace
1	
6350	Nichols Engineering & Research Corp.
	City of Beverly Hills, Calif.
	Repairs to Incinerator Flue
6351	Douglas Oil Company of Calif Clearwater - Exeter Plant
	Repairs to #3 Asphalt Still
(A)	Repairs to Dutch Oven of Vertical Asphalt Still
6352	Old Colony Paint & Chemical Co Los Angeles
	To Patch Lining in Ball Mill
	and the second s
6353	United States Gypsum Company - South Gate
	Brickwork Repairs to Edge Moor Boilers
6354	Richfield Oil Corporation - Watson Refinery - Watson
	Repairs to Front Wall of #2 Vacuum Still Heater
6355	Oil Operators, Inc Long Beach
	Boiler Brickwork Repairs
6356	Pacific Coast Borax Co Wilmington
	Repairs to Boilers #4 and #5
6357	The Texas Company - Fillmore Refinery
	Brickwork Repairs to Two (2) Fired Heaters
6358	Richfield Oil Corporation - Watson Refinery, Watson
	To Construct Refuse Destructor and Stack
(A)	To Remodel Brickwork to Install Burner in Refuse
	Destructor

6359	C. F. Braun & Co Alhambra
	One (1) 10 x 10 x 20 Fired HeaterMaterial Only
(A)	Labor Only for Fired Heater
	the second of th
July 1	
6360	General Metals Corporation - Vernon
	To Construct Refractory and Insulation Linings in:
	One (1) G. E. High Temp. Elevator Furnace,
******	Two (2) G. E. Low Temp. Elevator Furnaces,
	Four (4) G. E. Elevator Furnace Car.
6361	Todd Shipyards Corp San Pedro
	S. S. "Destina" - To Renew Front Wall on
	Starboard Boiler
6362	San Diego Gas & Electric Co Gas Plant -
	Repairs to Gas Generator #4
6363	Shell Oil Company, Inc Wilmington Refinery -
	Boiler #9 - Repairs to Arch
6364	Southern California Edison Co., Ltd Long Beach
	Boiler #54 - Insulation Repairs
6365	Bethlehem Steel Company - Terminal Island
	"Paul M. Gregg" - Repairs to Boiler Refractories
(A)	To Renew Brickwork on Forward Boiler
6366	Twentieth Century-Fox Film Corp West Los Angeles
	Brickwork or Insulation Repairs:-
<i>)</i>	Boiler House #1: Boilers #1, #2, #3, #4;
	Power House #2: Boilers #1, #3;
	Portable Vertical Boiler,
	Scotch Type Boiler

6367	San Diego Gas & Electric Co Station "B" -
 Barguaryaga papan engelente etropasan	Boiler #25 Repairs
	the state of the s
6368	Union Oil Company of Calif.
	Wilmington Refinery - To Fireproof Pipe Support
	Columns
6369	C. C. Moore & Co. Engineers
	Cedars of Lebanon Hospital - Los Angeles - Boiler Room
	Brick and Insulation Settings for Three (3) Class
	H-2 No. 15 Boilers
(A)	A & S Air Conditioning Co.
	Cedars of Lebanon Hospital
	Boiler #1 - Repairs to Damaged Brickwork
6370	Gaffers & Sattler - Vernon
	To Reline Ball Mill
6371	Federated Metals Division, Amer. Smelting & Ref. Co
	Los Angeles 23 - To Install Carbofrax Lining in
	U. S. Furnace #4
(A)	To Repair #2 Brass Reverb.
6372	The Cudahy Packing Company - Los Angeles
	Repairs to Boiler #1
6373	The Texas Company - Wilmington - Los Angeles Works
	Furnish Labor Only to Repair North End and South
	End at Pressure Pipe Still #2
6374	Ehrhart & Arthur, Inc.
	U. S. Perlite Products Company - Los Angeles
	To Install Refractory and Insulation Lining in an
	Expander Furnace

	6375	C. F. Braun & Co Alhambra
1		Repairs to Riley Boiler
*		The second secon
	6376	Shell Oil Company, Inc Watson Refinery
		Repairs to Boilers #7 and #8 in battery
	6377	Coast Fishing Company, Inc Wilmington
		Necessary Repairs to Boiler Walls
Algoria Maria	(A)	Repairs to Arch in Meal Plant Furnace
	ge comment ge co	
	6378	Richfield Oil Corporation - Watson
2		Repairs to Circular Flat Arch in a DeFlorez Heater
	6379	Great Lakes Carbon Corp Wilmington
		To Grind Blocks for Kiln
	(A)	To Reline 20 ft. of Kiln; to Replace Retaining Ring
)		and Nose Block; and to Patch Stack
	6380	Pacific Clay Products - Los Angeles - Plang #4
		Kiln #2 Repairs
	6381	The Texas Company - Fillmore
		Miscellaneous Insulation Repairs to Piping
		the state of the s
	6382	Shell Chemical Corporation - Dominguez
•		To Install Five (5) "Farmix" Burners in No. F-4
		MEK Furnace; and to Repair BrickworkRebuilding
		Bridge Wall and Installing New H2S Burner Port
		in above Furnace
-		
,	6383	The B. F. Goodrich Company - Los Angeles
		Furnace Brickwork Repairs to Two (2) B. & W. Blrs.

August	1948
6384	American Potash & Chemical Corp Trona
	Brickwork Repairs to #4 Potash Furnace
6385	C. F. Braun & Co.
	Virginian Gas & Oil Co Hubball, West Virginia
	Refractories and Insulation for One (1) 12 x 12 x 20
	Fired Heater Material Only
6386	Federated Metals Division, Amer. Smelting & Ref. Co.
	Los Angeles 23 - Repairs to Aluminum Furnace
6387	Bechtel Corporation
	Standard Oil Company of Calif Salt Lake City, Utah
	Refinery - Boiler and Furnace Enclosure for Two (2)
	FF15 No. 44 B. & W. Boilers
(A)	Premium Time
(B)	To Install Brick Flooring in Boiler Stack
6388	Southwestern Engineering Co.
	Union Oil Company of Calif Oleum, Calif.
	Furnaces BN-1 and BP-101Engineering Only
6389	Southern California Edison Co., Ltd Long Beach
	Boiler #36 - Necessary Brickwork Repairs
6390	C. C. Moore & Co. Engineers
	Southern California Edison Co., Ltd Long Beach
	Boiler #36 - To Remove and Reinstall Brickwork in
	Burners
(A)	To Furnish Labor to Install New Baffles and to
* * * * * * * * * * * * * * * * * * * *	Replace Refractories
(B)	Boilers #35 and #36 - To Install Baffle Tiles

	6391	Richfield Oil Corporation - Long Beach, 1400 W. 7th St.
	e	S. S. "Coxcombe Hills" - Brickwork Repairs
	6392	Swift & Company - Vernon Furnace Brickwork Repairs - C-E Boiler
	6393	Hammond Lumber Company - Los Angeles
학. 강 구		To Reline Stack of Concrete Incinerator
Caban parket		and the second s
61 2.	6394	Bethlehem Steel Company - Terminal Island
		S. S. "Mission Capistrano"
ž.		To Cut Chrome Ore from Studded Tubes
	(A)	To Remove and Renew Brickwork, Tiles and Insula-
		tion in Way of Tube Renewals, Casing and Front,
		and to Insulate both Ends of Economizer Tubes in
		Port and Starboard Boilers
and		
	6395	Bechtel Corporation - Somastic Division - Wilmington
		To Line Furnace
	6396	Haddock Engineers, Limited
		University of California - Riverside
		Citrus Experiment Station - Shop & Heating Plant
		Building - To Install Stack Lining
	6397	American Potash & Chemical Corp Trona
		Repairs to #2 Pyroborate FurnaceLabor Only
	6398	United States Gypsum Co South Gate
		Repairs to Boiler #1
1		
	6399	Wilson & Company, Inc Los Angeles
		Repairs to #2 Collins Boiler

6400	City of Pasadena, Calif Light & Power Dept.
^	Steam Plant - Repairs to Boilers #12 and #13
6401	The Celotex Corporation - Los Angeles 33
	Repairs to Combustion Tunnel in #3 Tubular Heater
6402	The Texas Company - Wilmington - Los Angeles Works
	To Tear Out and Replace One (1) Wall of #3 Crude
	Unit approx. 12' wide x 18' high and 22" thick
	Labor Only
6403	California Metal Enameling Co Los Angeles County (
-	To Reline One (1) 500# Patterson Ball Mill
(A)	To Reline One (1) Ball Mill
*	
6404	Pacific Coast Borax Co Wilmington
	Repairs to #2AB Furnace
(A)	Patch #1AB Furnace
6405	Eljer Company of Calif Vernon
040)	Repairs to #7 Enamel Furnace
/a\	
(A)	Replace and Reline Furnace Door
(B)	Reline Ball Mill
(C)	Reline Furnace Doors
(1) 0(	
6406	Union Oil Company of Calif Wilmington
	Tank Farm - Repairs to Trumble Heaters
6407	Southwest Steel Rolling Mills - Los Angeles
	Repairs to Heating Furnace
6408	The Fluor Corporation, Ltd Los Angeles 22
	Repairs to Incinerator

(Z22)

	6409	Luer Packing Company - Vernon
1		Repairs to #2 Boiler
	98	
	6410	Los Angeles Steel Casting Co Vernon
		Repairs to 6 ft. x 10 ft. Car Type Annealing
		Furnace
er er		
	6411	Bethlehem Steel Company - Terminal Island
<u>4</u>		S. S. "Contreras" - To Furnish Labor Only to
es es		Tear Out and Replace Deck and Side Walls in
:		Port and Starboard Boilers
Ž		
	6412	Standard Gypsum Company of California - Long Beach
		To Reline Kettle
	6413	Richfield Oil Corp Wilmington - Wilmington Refinery
( )	0413	Labor Only to Tear Out and Replace Front and Back
		Walls in #4 Boiler in #1 Boiler House
	(A)	To Repair #5 Heater in #3 Crude Battery
	(4)	TO ROBELLE WY LISARDE THE WYS OF MAD DECORATE
	Septemb	er 1948
	6414	White Heat Treating Co Huntington Park
		To Repair Furnace Arch 48" wide x 36" high
	6415	Eastern Smelting & Refining Co Los Angeles
	r	Brass Melting Furnace Repairs
		the state of the s
	6416	Max Weil of California - Los Angeles
		Kiln Repairs
		opposition of the control of the con
( )	6417	California Portland Cement Co Colton
		#9 Hood - Brickwork Repairs
	6418	Majestic Bakery - Los Angeles, 1412 West 54th St.
		Repairs to Bake Oven

6419	Todd Shipyards Corporation - San Pedro
	S. S. "General Walker" - To Remove and Renew
	approx. 16 cu. ft. of Plastic Brick in Way of
	Burner Arches on #1 and #2 Boilers
(A)	Repairs to Four (4) Boilers
6420	Southern California Edison Co., Ltd Long Beach
	Boiler #38 Repairs
(A)	Boilers #29 and #30
(B)	Boiler #39 Repairs
6421	San Diego Gas & Electric Co San Diego
	Boiler #28 - Furnace Brickwork Repairs
(A)	Boiler #21 - Brickwork Repairs
6422	Pacific Clay Products - Los Angeles
	To Reline 4 ft. x 4 ft. Ball Mill
(A)	To Reline Ball Mill
(B)	To Reline #5 Ball Mill
6423	Federated Metals Division, Amer. Smelting & Ref. Co.
	Los Angeles 23 - To Repair Aluminum Reverb.
6424	Pacific Coast Borax Co Boron
**************************************	To Reline Beik Furnace
6425	Todd Shipyards Corporation - San Pedro
	S. S. "Bunker Hill" - To Replace Chrome Ore at
	Ends of Side Walls and Back Wall
6426	Bethlehem Steel Company - Terminal Island
	S. S. "Lomboc" - Repairs to Boilers
	•

	6427	Todd Shipyards Corporation - San Pedro
/ ~ Ye		S. S. "Chepachet" - To Tear Out and Replace Front
		and Patch approx. 30 sq. ft. Chrome Ore in Port
		and Starboard Boilers
	6428	The Cudahy Packing Co Los Angeles
		Repairs to Boiler #2
47.2		
Ch.	6429	Southern California Edison Co., Ltd Long Beach
e e		Boiler #35 - Necessary Repairs to Brickwork
ģ	6430	C. C. Moore & Co. Engineers
		Southern California Edison Co. Ltd Long Beach
		Boiler #35 - Furnish Labor to Remove and Install
		Brickwork in Burner Front
	(A)	Furnish Labor to Remove and Install Baffle as
*		Directed in Boiler #35
	6431	Acme Brewing Company - Vernon
		Boiler #1 - Furnace Brickwork Repairs
	6432	Todd Shipyards Corporation - San Pedro
		S. S. "Mission Santa Ana" - Necessary Repairs to
		Boiler in Way of Tube Repairs
	6433	Todd Shipyards Corporation - San Pedro
		S. S. "Alamo Victory" - To Furnish Labor and
		Material to Renew Front Deck and Six (6) Super-
		heater Doors in Starboard Boiler
,		
)	October	1948
	6434	E. K. Wilson Lumber Company - Compton, P. O. Box 150
		To Repair Eight (8) Air Vents and One (1) Door with
		Castable Refractories; Renew Top three (3) Courses
C.	(A)	or Brick and Give brickwk., Incinerator, Coat of Ter To Build Incinerator Air Vents

	0437	pecucer Corporation
	The manufacture of the same of	Revere Copper and Brass, Inc Los Angeles County
	100° 100° 100° 100° 100° 100° 100° 100°	Acid Brickwork for Pickle Pit
	6436	Southern Service Company, Ltd.
		Hub City Laundry - Colton
		Boiler Furnace Repair
	6437	Pacific Coast Borax Co Wilmington
		Necessary Repairs to #1 and #2 Boilers
	(A)	To Patch #LAB Furnace
	(B)	To Patch #2AB Furnace
	(C)	To Patch #1 and #2AB Furnaces
	6438	Todd Shipyards Corporation - San Pedro
		S. S. "Mission Carmel" - To Reline Six (6)
		Superheater Doors and to Replace approx. 15
		sq. ft. of Corbel
	6439	Federated Metals Division, Amer. Smelting & Ref. Co.
		Los Angeles 23 - Repairs to Brass Furnace
	6440	Queen of Angels Hospital - Los Angeles
		Repairs to Boiler #2
	6441	Bethlehem Steel Company - Terminal Island
		S. S. "Stanvac" - To Tear Out and to Replace Brick-
		work in Front and Floor of Port and Starboard Boilers
	6442	Bethlehem Steel Company - Terminal Island
		S. S. "Mission Buena Ventura" - To Brush all
		Brick Surface and Give One (1) Coat of Brick Seal;
		Renew Burner Shapes and Patch Chrome Ore in Port and
	(A)	Starboard Boilers Renew Floors & Damaged Corbels in Port & Starbd. Blrs.
	(B)	To Reline Six (6) Superheater Doors (C) Ins. Econ. Side
· Personal		

	6443	Natural Soda Products Co Keeler, Calif.
		To Repair Fireboxes
7		
	6444	J. W. MacPherson - Glendale
		Fireplace and Chimney
	6445	Union Oil Company of Calif Wilmington Refinery
5.2		#7 Boiler - To Rebuild Five (5) Burner Arches
٠.		
(c)	6446	The Fluor Corporation, Ltd Los Angeles County (22)
		Incinerator Brickwork Repairs
ž Ž	(A)	Additional Brickwork Repairs to Incinerator
	(**)	
	6447	The Harshaw Chemical Co El Segundo
	0447	
		To Rebuild Brickwork on Antimony Reverb. Furnace
-	(1) 0	
	6448	Filtrol Corporation - Vernon
		Repairs to Leahy Burner Arch in Erie City Boiler
	(1)	
	6449	Reconstruction Finance Corp., Office of Rubber Reserve
		Standard Oil Company of Calif., Agent - El Segundo
		Butadiene Plant - Brickwork Repairs
	6450	Eljer Company of Calif Vernon
		To Reline #6 Enamel Furnace
	(A)	To Reline Door and to Repair #5 Furnace
	6451	C. C. Moore & Co. Engineers
	,	Tucson Gas, Electric Light & Power Co Tucson, Ariz.
		To Install Refractory and Insulation for One (1)
)		FH-26 #21 Gas and Oil Fired Integral Furnace Blr.
,	(A)	Covering of Outstanding Legs, also Weatherproofing
	6452	the Externally Applied Insulation Filtrol Corporation - Vernon - Syntrol Plant
	-	Reline #C-202 Dryer Firebox Burner
		t and the second

6453	Frederick O'Brien Paint & Varnish Works - Huntington Park
	To Repair 1,000 gal. Ball Mill Lining
6454	The Exchange Orange Products Co Lindsay, Calif.
	To Construct Refractory Lining for Dryer Firebox
Extra	To Install Target Wall
·····	
Novemb	er 1948
6455	Federated Metals Division, Amer. Smelting & Ref. Co.
	Los Angeles 23 - To Repair #3 Zinc Retort
(A)	Aluminum Sweater Furnace Brickwork Alterations
6456	Union Oil Company of Calif Wilmington
	Unit #33 Heater - Brickwork Repairs
(A)	Repairs to Still #57
(B)	Repairs to Still #58
(C)	Repairs to Acid-Handling Plant
(D)	Repairs to T. C. C. Unit
(E)	Repairs to T. C. C. Unit
6457	Stauffer Chemical Division - Dominguez Division
	Dominguez - To Install Acid Brick Lining in #3
	Absorbing Tower
6458	White Heat Treating Co Huntington Park
·	To Repair Pot Furnace
(A)	To Replace Bricks in Furnace Door
6459	Combustion Engineering Co., Inc.
2 · · · · · · · · · · · · · · · · · · ·	Central Arizona Light & Power Co Phoenix, Ariz.
- and incomp	Enclosure for One (1) C-E "VE" Type Boiler
A	
6460	Peter Kiewit Sons' Co. & Fred J. Early, Jr. Co., Inc.
OOS) GOOD Come of Page and	City of Los Angeles, Board of Public Works
amiliationessery.	Hyperion Activated Sludge Plant - El Segundo
reservation (Control of Control o	Refractory Lining for Waste Gas Burners
**************************************	

	6461	W. P. Fuller & Company - Los Angeles
		To Patch Small Ball Mill
)	(A)	To Reline One (1) 250 gal. Porcelain Lined Pebble
	6462	The Texas Company - Wilmington
		Repairs to F. C. C. U. Unit
U.S.A.	(A)	To Patch Boilers
And the second s	(**)	
pilot 61 Ltt	6463	Bechtel Corporation
	0,05	Revere Copper & Brass, Inc Los Angeles County
9		To Construct Dempsey Bright Anneal Furnace
	(A)	To Construct Dempsey Billet Furnace
	(B)	Brickwork Repairs to Rundown Anneal Furnace
	()	
4	6464	The Lummus Company
)-		General Petroleum Corp Torrance
		To Install Refractories and Insulation on Two (2)
		Lummus Oil Heaters
	6465	Queen of Angels Hospital - Los Angeles
		Repairs to Morse Boulger Incinerator
	6466	Stauffer Chemical Company - Torrance
		To Line Sulphuric Acid Converter
	6467	Pacific Division Bendix Aviation Corp North Hollywood
		To Reline Brazing Furnace
	6468	H. C. Smith Co. (Refer to Job No.
1		E. B. Badger & Sons Company 6526 for addl. work)
		Hancock Chemical Company - Wilmington
		To Install Acid-Proof Brick Lining for One (1) 12 ft
	(A)	dia. Sulphur Converter To Install Brickwork in Waste Heat Blr; also to Replace Burner Blocks in Auxiliary Boilers

6469	Forest Lawn Memorial-Park Association, Inc Glenda
	To Scrape and to Paint the Three (3) Crematory
a waya aa ah	Retorts 20 20 20 20 20 20 20 20 20 20 20 20 20
(A)	To Scrape and Point up Crematory Retorts
6470	Shell Oil Company, Inc Dominguez Refinery
	Repairs at #7 Dubbs
6471	Pacific Coast Borax Co Wilmington
	To Repair #1 A. B. Furnace
(A)	To Patch #2 A. B. Furnace
**************************************	
6472	American Potash & Chemical Corp Trona
	Calciner Furnace - Brickwork Alterations
6473	American Potash & Chemical Corp Trona
	Bicarbonate & Bleecher Furnaces - Brickwork Rprs.
6474	Harvey Machine Company, Inc Torrance
	To Tear out Brickwork in Furnace
6475	Coast Fishing Company - Wilmington
	Boiler Repairs
De cemb	er 1948
6476	Standard Gypsum Company - Long Beach
	Brickwork - Calcining Kettle #3
6477	Todd Shipyards Corporation - San Pedro
	S. S. "John Goode" - To Renew approx. 15 sq. ft.
	of Aft Side Wall in Port Boiler
e de la companya de	
6478	Craig Shipbuilding Company - Long Beach
	S. S. "Mormacland" - To Tear out and Replace
	Deck down to Top of Tubes and Burner Cones in
	Front Wall of Port Boiler

	6479	Pacific Coast Borax Co Wilmington
		Repairs to #2 A. B. Furnace
<i>)</i>	(A)	To Brick #2 Furnace Discharge Spout
	(B)	To Patch #1 and #2 A. B. Furnaces
	6480	Shell Oil Company, Inc Dominguez Refinery
ngan in		To Furnish Labor and Material to Recondition
(25.0 U.S.)		Flasher Heater #8
A DE	6481	Southern California Edison Company, Ltd Long Beach
- 0		Boiler #44 Repair
. ģ	(A)	Repairs to Boiler #45
	(B)	Boiler #40
	* *	
	6482	Upland Citrus Association - Upland
		Insulation - One (1) #125 Erie City Economic
)		Boiler
	6483	Bechtel Corporation
		Standard Oil Company of Calif El Segundo Refinery
		Boiler #37 - Foundation Brickwork
	6484	The Texas Company - Fillmore
		Cracking Furnace - Brickwork Repairs
	6485	Bethlehem Steel Company - Terminal Island
		S. S. "Santa Paula" - Necessary Repairs to Port
		and Starboard Boilers
	6486	City of Long Beach - Harbor Department - Long Beach
1		To Rebrick Boiler on Floating Pile Driver
90	6487	Union Oil Company of Calif Wilmington
		Unit #34 - Repairs to Furnace
	(A)	Unit #33 - Repairs to Furnace

6488	Southwestern Portland Cement Co Victorville
	Lining of Kiln End Housing
6489	W. G. Johnson and Son Tile Mfg. Co Pomona
	Brickwork on One (1) Test Sliding Slab Tunnel Kiln
6490	Liquid Carbonic Corporation - Los Angeles
	Repairs to Burner Arches - Boiler #2
6491	Johns-Manville Products Corporation - Lompoc, Calif.
	To Repair Crown in "B" Periodic Kiln
6492	Smoot-Holman Company - Inglewood
	To Repair Muffle in Continuous Enameling Furnace
	And the second terminal and the second
6493	Federated Metals Division, Amer. Smelting & Ref. Co.
	Los Angeles 23 - Repairs to Brass Reverb.
(A)	Repairs to Aluminum Reverb.
6494	The Exchange Orange Products Company - Ontario
	Repairs to Boiler #3
(A)	Repairs to Boiler #4
(B)	Renew Lining in #2 Dryer Furnace
(C)	To Install Brick Lining in #4 Dryer Furnace
(D)	Dryer Furnace #1 - Brickwork Repairs
(E)	Boiler #1 - Brickwork Repairs
(F)	Boiler #2 - Brickwork Repairs
6495	The Celotex Corporation - Los Angeles
	Repairs to Heater #2
6496	West End Chemical Company - Westend
	#2 Lime Kiln - To Reline Hot Zone, approx. 25 ft.

	6497	Griffith Company	
		City of Los Angeles - Los Angeles	engi <sup>a</sup>
Ä		Municipal Incinerator - Repairs to Rotary 1	Kiln
	6498	Eljer Company of Calif Vernon	
		To Repair #7 Mill	
J			5.4
\$ 5 m	6499	West End Chemical Company - Westend	
Q.,		#2 Light Ash Furnace - Brickwork Repairs	
71 42	•		
	6500	C. C. Moore & Co. Engineers	
gi P		C. F. Braun & Co.	
		Standard Oil Company of Calif Bakersfield	
		Refractory and Insulation Materials only for	or ,
		Two (2) FF15 No. 28 B. & W. Boilers	
	6501	Wilshire Oil Company, Inc Norwalk	
		To Remodel Burner Tunnel in Alcorn Heater a	at Dubbs
	6502	Shell Chemical Corporation - Dominguez Refinery	<b>7</b>
		To Install Acid-Proof Brick Floor and Trend	:h
		Paving for the Concentrator and the Acid Ma	mifold
	(A) (B)	Acid Brickwork - Karbate Cooler Concentrator To Repair Brick Floor under Concentrator	)r
	6503	Great Lakes Carbon Corporation - Torrance	
		Furnace Repairs	
			jejo Jejo
	6504	Taylor Forge & Pipe Works - Fontana, Calif.	
		To Recondition 17' dia. Rotary Forge Furnac	ю
j.	6505	Maritime Petroleum Company - Wilmington	
		Repairs to Two (2) Llewellyn Boilers and	
		One (1) Tube Still	

ayaasaa aa qaa aa		7		
		Wild And Control of the Control of t		
		ing photosopy regions		
		Januar	y 1949	
		6506	Stauffer Chemical Company, Dominguez Division	· · · · · · · · · · · · · · · · · · ·
			Dominguez - Maintenance and Repairs to	
		and the second s	Insulation for Year of 1949	
,			(For Year of 1948, see Job No. 6206)	
		(A)	Month of June	
		(B)	Month of November	
	<b>*</b> .	6507	Union Oil Company of Calif Wilmington Repairs to T. C. C. Unit	
		(A)	Repairs to Unit #33	
		(**)	Tiopario do director (155	
		6508	Pacific Clay Products - Los Nietos	
			(For Year of 1948, See Job No. 6189)	
			Miscellaneous Brickwork Repairs for Year of	1949
		(A)	February 1949 (G) - August 1949	
	,	(B)	March 1949 (H) - September 1949	
		(C)	April 1949 (I) - October 1949	
		(D)	May 1949 (J) - November 1949	
		(E)	June 1949 (K) - December 1949	
		(F)	July 1949	
			The state of the s	
		6509	Pacific Clay Products - Los Nietos - Plant #6	* * * * * * * * * * * * * * * * * * *
			(For Year of 1948, Refer to Job No. 6264)	
		SERVING COLUMN C	Repairs to Kiln #18	
	(65)	00 (A)	Repairs to Kiln #5	
	900, G000000000	(B)	To Tear Down One (1) Stack Serving Kilns #1	3 & #14
		(C)	Kiln #6 Repairs	
		(D)	Repairs to Kiln #43	
		(E)	Repairs to Kiln #7	·4
		(F)	Repairs to Kiln #31	
		ed-recognition little		
		Management of the Control of the Con		

6510	The Fluor Corporation, Ltd.
*	American Potash & Chemical Corp Trona
	To Install Internal Dutch Oven in Calcining Furnace
6511	Southern California Edison Company - Long Beach
	To Repair Boilers #23, #24, #21, #22
(A)	Boiler #38
(B)	Boilers #46, #47
(C)	Boiler #52 Furnace Repairs
(D)	Boiler #43
6512	Caltex Boiler Works
	Kroehler Manufacturing Co Inglewood
	To Repair Boiler Brickwork with "Plibrico"
	Land to the second of the seco
6513	Bethlehem Steel Company - Terminal Island
	S. S. "Argomonte" - Brickwork Repairs to Port
*	and Starboard Boilers
6514	Eljer Company of California - Vernon
	Brickwork Repairs to #2 Smelter
(A)	To Patch #4 Mill
(B)	To Reline Three (3) Enamel Furnace Doors
(C)	To Repair Ball Mill #6
(D)	To Repair #6 Enamel Furnace
(E)	To Repair Ball Mill #7
(F)	To Repair #4 Enamel Furnace
(G).	To Repair #1 Frit Melting Furnace
(H)	To Repair #7 Ball Mill /Door
(I)	To Patch Bottom of #7 Furnace & to Reline #7 Furn.
Only.	
	A STANDARD OF STANDARD STANDARD STANDARD STANDARD
	Service of the Padrie Alexander Color

Pacific Clay Products - Los Angeles 31
To Demolish One (1) Brick Stack

6516	United States Gypsum Company - South Gate	(Early	
	To Repair and Reinsulate Boiler Furnace Roo	f	
and the second	in #2 Mill . / A.C. A. (A. (A. (A. (A. (A. (A. (A. (A. (A.		,
6517	The Texas Company - Wilmington	ARGA	
	Brickwork Repairs to Heater in Pressure Pip	e Still	#2
		(5)	
6518	Wilshire Oil Company, Inc Nerwalk	(4)	
	Norwalk Refinery - Burner Brickwork Alterat	ions -	
	U. O. P. Centerwall Updraft Heater	(1)	
6519	Bethlehem Steel Company - Terminal Island		
	S. S. "Buccimun" - To Renew Front Wall Top 1	Boiler	
,	Wall Tile; Patch Chrome Ore and Corbels		ý
(A)	To Renew Insulation in Eight (8) Superheater	r Doors	
	for detailed the grade of design and the contract of the contr		1
6520	Union Oil Company of Calif Wilmington Refiner	ry	)
	Necessary Repairs to #5 Boiler in #1 Boiler	House	
6521	Pomona Tile Manufacturing Co Pomona	alaig e	
·	Brickwork Repairs to #5 Allied Prouty Type !	Funnel	
	Kiln		
et avele	rand remark in more in the first of	(()	
6522	Bethlehem Steel Company - Terminal Island		
	S. S. "Sparrows Point" - To Patch Corbels as	nd	
	Burner Cones in Port and Starboard Boilers	* * * * * * * * * * * * * * * * * * *	
6523	Federated Metals Division, Amer. Smelting & Ref.	. Co.	
i androne de la company	Los Angeles 23 - To Line U. S. Rotary Furnac	ce	
e e je ji regjirasi ko e kare			
6524	Stauffer Chemical Company - Torrance	1	)
	Insulation Work on Converter and Ducts		
* (A)	To Repair Insulation as directed		

	6525	Union Oil Company of Calif Wilmington
		D-3 Reboiler - Unit #91
<i> J.</i>		Fired Preheater Brickwork Repairs
	(A)	Necessary Repairs to #6 Boiler
	(B)	Necessary Repairs to Unit #20
	(C)	Necessary Repairs to Unit C.R.T.
	(D)	Necessary Repairs to Unit #34
35.9	(E)	Necessary Repairs to D-3 Reflux Vessel
Adam salara	(F)	Necessary Repairs to Unit #67
28 H - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -	(G)	Necessary Repairs to Roof on Unit #67
(2) (2) (3)	6526	H. C. Smith Company
		E. B. Badger & Sons Company
		Hancock Chemical Company - Wilmington
		To Furnish Labor only to Brick Burner on Waste
7 \		Heat Boiler
<i>. </i>		(Refer to Job No. 6468)
	6527	Southwest Steel Rolling Mills - Los Angeles
	-	Repairs to Mill Furnace
	6528	Shell Oil Company, Inc Dominguez Refinery
		To Recondition Dubbs Furnace #5
	6529	Great Lakes Carbon Corp Torrance
	(A)	#2 Furnace Repairs (B) Reprs. to #1 & #2 Furnace Repairs to Furnace #2 (C) Reprs. to #2 Furnace
	6530	Richfield Oil Corporation - Watson - Watson Refinery
		Repairs to #5 and #7 Boilers
	(A)	To Repair Heater #4
	6531	Todd Shipyards Corporation - San Pedro
		S. S. "Ocklawaha" - To Renew Oil Burner Shapes
		and to Paint Brickwork with High Temperature Cement
		and to Patch Chrome Ore

reprus	<b>Fy</b> 1949
6532	Great Lakes Carbon Corp Torrance
(A)	Two (2) Rotary Furnaces - Fire Brick Linings Adjustment to #1 Furnace
6533	Bethlehem Steel Company - Terminal Island
	S. S. "Victor H. Kelly"
	Repairs to Two (2) BoilersForward and Aft
6534	General Chemical Division, Allied Chem. & Dye Corp.
	El Segundo - Repairs to Combustion Chamber
6535	Lockheed Aircraft Corporation - Burbank
	Plant B-1, Building #176 - To Install New Fire
	Brick Baffles in #1 Edge Moor Boiler
J	
6536	Pacific Clay Products - Los Angeles - Plant #4
	#4 Tunnel Kiln - To Replace 30 ft. of Muffle
6537	E. B. Badger & Sons Co.
	Hancock Chemical Company - Wilmington
	Repairs to Waste Heat Boiler
(A)	Repairs to Waste Heat Boiler
6538	Morse Boulger Destructor Co.
	Prudential Insurance Building - Los Angeles
(A)	To Repair Destructor /Renew Counterweight Cables To Install Automatic Draft Adjuster in Breeching & to
6539	C. F. Braun & Co.
	Standard Oil Company of Calif Bakersfield
	Refinery TK - One (1) Crude Heater,
	Two (2) Heavy Oil Heaters,
	One (1) Light Oil Heater
( - )	II A D Demonstration

	6540	Shell Oil Company, Inc Dominguez Refinery
		To Repair Dubbs Furnace #2
. **		
	6541	Standard Oil Company of Calif El Segundo
		Cracking Plant - To Repair Side Walls of #14
	en Men	Unit Furnace
	(X)	Repairs to Furnace Roof and Pointing up and Re-
8.8.4		placing Bricks in Side and End Walls
4	(A)	To Repair North End Wall, South End Wall, and
		Roof of #14 Unit Furnace, 2nd Battery
# C		
ó	6542	United States Gypsum Company - South Gate
		Labor only to Repair Brickwork in #1 Boiler
	6543	Mr. L. E. Brooksby
1		Moulton Ceramic Company - Inglewood
1		To Repair Kiln Brickwork
	6544	Stauffer Chemical Company - Dominguez Division
		Dominguez - To Install Refractories and Insula-
		tion for One (1) 21" I. D. x 15'-0" long H2S
		Firing Tunnel, including Connecting Flue
	6545	Pacific Coast Borax Co Wilmington
		Repairs to Furnace #1 A. B.
	(A)	Repairs to #2 A.B. Furnace
	(B)	To Patch #1 A. B. Furnace with Quigley Gun
	6546	Federated Metals Division, Amer. Smelting & Ref. Co.
		Los Angeles 23 - To Repair #2 Brass Furnace
* *	(A)	To Rebrick Doors of #3 Aluminum Furnace
		and the contract of the contra
	6547	Pacific Tile & Porcelain Co Paramount, Calif.
		To Repair Tunnel Car Kiln

•

6548	J. G. Warner - Residence - Whittier
	To Construct Fireplace
6549	Bethlehem Steel Company - Terminal Island
	S. S. "Standac Hong Kong"
	To Repair Two (2) Boilers, Port and Starboard
6550	Union Oil Company of Calif Wilmington
	To Repair #2 Boiler in #2 Boiler House
(A)	To Repair Asphalt Stills #95 and #96
(B)	Repairs to #3 Boiler in #2 Boiler House
(C)	Repairs to #1 and #2 Boilers in #1 Boiler House
(D)	Repairs to "A" Side of Unit #33
(E)	Repairs to Asphalt Stills #97, #98
(F)	Repairs to Superheater Asphalt Still
(G)	Repairs to Unit #20
	The state of the
6551	Consolidated Lumber Company - Wilmington
	To Patch #2 Incinerator
March	1949
6552	The Texas Company - Wilmington
	To Repair F. C. C. Unit
6553	Bechtel Corporation
	Southern California Edison Company - Long Beach
(A)	To Repair Boiler #33 (B) To Repair Boiler #35 To Repair Boiler #34 (C) To Repair Boiler #36
6554	San Diego Gas & Electric Co San Diego
	Station "B" - To Repair Boiler #24
6555	United States Gypsum Company - South Gate
	To Remove Brick Setting and Install Steel Base
	and Lining for One (1) Erie City Economic Blr. #1

.

	6556	Standard Oil Company of Calif El Segundo
		El Segundo Refinery - Vacuum Acid Concentrator -
		Acid-Proof Brick Lining
	6557	City of Pasadena, Calif.
		Municipal Light & Power Department -
W.S.A.	(X)	Boiler #12 - Furnace Brickwork Repairs Additional Labor
gen Jackson Jackson	6558	Richfield Oil Corporation - Wilmington
54 54		To Repair #3 Boiler in #1 Boiler House
型: (デージン) (デージン) (デージン) (デージン) (デージン) (デージン) (デージン) (デージン) (デージン) (デージン) (デージン) (デージン) (デージン) (デージン) (デージン) (デージン) (デージン) (デージン) (デージン) (デージン) (デージン) (デージン) (デージン) (デージン) (デージン) (デージン) (デージン) (デージン) (デージン) (デージン) (デージン) (デージン) (デージン) (デージン) (デージン) (デージン) (デージン) (デージン) (デージン) (デージン) (デージン) (デージン) (デージン) (デージン) (デージン) (デージン) (デージン) (デージン) (デージン) (デージン) (デージン) (デージン) (デージン) (デージン) (デージン) (デージン) (デージン) (デージン) (デージン) (デージン) (デージン) (デージン) (デージン) (デージン) (デージン) (デージン) (デージン) (デージン) (デージン) (デージン) (デージン) (デージン) (デージン) (デージン) (デージン) (デージン) (デージン) (デージン) (デージン) (デージン) (デージン) (デージン) (デージン) (デージン) (デージン) (デージン) (デージン) (デージン) (デージン) (デージン) (デージン) (デージン) (デージン) (デージン) (デージン) (デージン) (デージン) (デージン) (デージン) (デージン) (デージン) (デージン) (デージン) (デージン) (デージン) (デージン) (デージン) (デージン) (デージン) (デージン) (デージン) (デージン) (デージン) (デージン) (デージン) (デージン) (デージン) (デージン) (デージン) (デージン) (デージン) (デージン) (デージン) (デージン) (デージン) (デージン) (デージン) (デーシ) (デージン) (デーシ) (デーシ) (デーシ) (デーシ) (デーシ) (デーシ) (デーシ) (デーシ) (デーシ) (デーシ) (デーシ) (デーシ) (デーシ) (デーシ) (デーシ) (デーシ) (デーシ) (デーシ) (デーシ) (デーシ) (デーシ) (デーシ) (デーシ) (デーシ) (デーシ) (デーシ) (デーシ) (デーシ) (デーシ) (デーシ) (デーシ) (デーシ) (デーシ) (デーシ) (デーシ) (デーシ) (デーシ) (デーシ) (デーシ) (デーシ) (デーシ) (デーシ) (デーシ) (デーシ) (デーシ) (デーシ) (デーシ) (デーシ) (デーシ) (デーシ) (デーシ) (デーシ) (デーシ) (デーシ) (デーシ) (デーシ) (デーシ) (デーシ) (デーシ) (デーシ) (デーシ) (デーシ) (デーシ) (デーシ) (デーシ) (デーシ) (デーシ) (デーシ) (デーシ) (デーシ) (デーシ) (デーシ) (デーシ) (デーシ) (デーシ) (デーシ) (デーシ) (デーシ) (デーシ) (デーシ) (デーシ) (デーシ) (デーシ) (デーシ) (デーシ) (デーシ) (デーン) (デーン) (デーン) (デーン) (デーン) (デーン) (デーン) (デーン) (デーン) (デーン) (デーン) (デーン) (デーン) (デーン) (デーン) (デーン) (デーン) (デーン) (デーン) (デーン) (デーン) (デーン) (デーン) (デーン) (デーン) (デーン) (デーン) (デーン) (デーン) (デーン) (デーン) (デーン) (デーン) (デーン) (デーン) (デーン) (デーン) (デーン) (デーン) (デーン) (デーン) (デーン) (デーン) (デーン) (デーン) (デーン) (デーン) (デーン) (デーン) (デーン) (デーン) (デーン) (デーン) (デーン) (デーン) (デーン) (デーン) (デーン) (デーン) (デーン) (デーン) (デーン) (デーン) (デーン) (デーン) (デーン) (デーン) (デーン) (デーン) (デーン) (デーン) (デーン) (デーン) (デーン) (デーン) (デー) (デーン) (デーン) (デーン) (デー) (デー) (デー) (デー) ( ( ( ( ( ( ( ( ( ( ( ( ( ( ( ( ( ( (		
si W	6559	Filtrol Corporation - Vernon
		To Line Acid Surge Tank
	6560	Filtrol Corporation - Vernon
N.		Syntrol Plant - To Repair Erie City Boiler
<i>)</i>	(A)	To Repair C-202 Dryer
	6561	California Portland Cement Company - Colton
,		Kilns #7, #8, and #15 -
		Brickwork Alterations to Kiln Hoods
	6562	Taylor Forge & Pipe Works - Fontana
		Brickwork and Insulation on 3'-0" x 7'-6" Forging
		Furnace
	6563	The Texas Company - Fillmore
		Miscellaneous Insulation Repairs
\ \	6564	Todd Shipyards Corporation - San Pedro
/		S. S. "Paul M. Gregg"
		To Repair Boiler as directed by port engineer
	6565	Shell Oil Company, Inc Dominguez Refinery
		Necessary Repairs to Burner Throat (conta.)

6565 (	
(A)	Cat-Cracker Plant - To Install New Burner on
	Steam Superheater
(B)	Make Necessary Repairs to Brickwork on Re-
	generator
	The state of the s
6566	Leahy Manufacturing Company
	State of California - Los Angeles, 2nd & Spring
	Highway Department - Firebox Brickwork for Three
	(3) Fitzgibbons Boilers
6567	Todd Shipyards Corporation - San Pedro
	S. S. "Dartmouth Victory" - To Furnish Labor and
	Material to Renew Floors and Patch Chrome Ore on
	Port and Starboard Boilers
6568	Acme Brewing Company - Vernon
	To Repair #3 Boiler
6569	C. C. Moore & Co. Engineers
	U. S. Potash Company - Loving, New Mexico
	Refractory Setting for One (1) Single Class VIII
	No. 23 B. & W. Stirling Boiler and Detrick Flat
	Suspended Arch
6570	The Fluor Corporation Ltd Los Angeles County
	To Rebuild Floor Air Ducts and to Repair Arch
	over Sawdust Chute of Incinerator
6571	Arco Company of Calif., Ltd Los Angeles
	To Reline Ball Mill
13	
6572	Quality Machine & Boiler Works - Wilmington - /heater Door
(A)	S. S. "China Transport" - To Repair Three (3) Super To Renew Deck, One (1) Superheater Door and Patch Top Header

6573	Douglas Oil Company of Calif Long Beach
gang tang	Exeter A-B Plant - Necessary Repairs to Asphalt
	Still #1
6574	Southern California Edison Co Long Beach Plant
	Plant #1
The second development of the second develop	Steam Line - Miscellaneous Insulation Repairs
(A)	Feedwater Line
<u>.</u> (B)	. Fuel Oil Piping and the same and the
[] E	Light in the same same should be discussed to the control of the c
් න	
· · · · · · · · · · · · · · · · · · ·	
6575	Southern California Edison Co Long Beach Plant
	Plant #2
<b>V</b>	Steam Line - Miscellaneous Insulation Repairs
(A)	Feedwater Line
(B)	Fuel Oil Piping
6576	Southern California Edison Co Long Beach Plant
e e e e e e e e e e e e e e e e e e e	Plant #3
	Steam Line - Miscellaneous Insulation Repairs
(A)	Feedwater Line
(B)	
(C)	Piping and Equipment - Plant #2
(D)	Piping and Equipment - Plant #3
(E)	Piping and Equipment - Plant #1
6577	Stauffer Chemical Company - Dominguez Division
	Dominguez - Brickwork to 10'-0" dia. Sulphur
	Burner

6578	Macco Corporation - Paramount, Calif.
and the state of t	Yacht "Salchanik" - To Repair Range
6579	San Diego Gas & Electric Co San Diego
. Sa Jamesayan an	Silver Gate Station - Boilers #1-and #2 -
(A)	Burner Wall Repairs Boiler #1 Burner Wall Repairs
6580	The Procter & Gamble Manufacturing Co Long Beach
	Brickwork Repairs to One (1) B. & W. Stirling Blr.
(A)	To Replace First Pass Baffle in Boiler
(B)	Extra Work: Cleaning Bricks, Unloading Car, etc.
6581.	Federated Metals Division, Amer. Smelting & Ref. Co.
	Los Angeles 23 - To Repair #2 Zinc Retort
6582.	Sinton & Brown Co Betteravia, Calif. To Repair Dryer Firebox
	A Commence of the Commence of
6583	Southern California Edison Co Long Beach
	Brickwork Repairs to Boiler #37
(A) (C) (E)	Boiler #49 Repairs (B) - Boiler #51 Boiler #52 (D) - Boiler #53 Boiler #39 (F) - Loading Brick on Pallet
6584	The Texas Company - Wilmington
	Pressure Pipe Still #1 - Labor only to Patch Brick-
	work at North and South Ends of Furnace; Renew
	approx. 10 sq. ft. of Brickwork in Curtain Wall
(A)	Repairs to #5 and #9 Boilers
6585	Gilmore & Nolan, Inc. (Successor to Holladay & Chase)
	Los Angeles - Pebble Mill Door Lining
6586	The Robert L. Johnson Corporation
·	City of Glendale, Calif.
	Boiler #3 - Brickwork Repairs

(contd.)

	6586 (¢	contd.)
· V	(A)	City of Burbank
J		To Remodel Brickwork to Suit New Superheater By-
		pass Damper
	(B)	City, of Pasadena
		To Remodel Brickwork to Suit New Superheater By-
		pass Damper
į	6587	Filtrol Corporation - Vernon
		Syntrol Plant - To Reline #C-202 Dryer Firebox
		Burner
	6588	Pioneer Division, The Flintkote Company - Vernon
	-	Repairs to Lower Front Wall, Bridge Wall, and
		East Side Wall - Boiler #1
1		
)i	6589	Bethlehem Steel Company - Terminal Island
		S. S. "Great Republic" - To Renew Insulation in
		Lower Half of Starboard Casing Door of Boiler
		gradian in the second of the s
	April l	949
	6590	The Liquid Carbonic Corporation - Los Angeles
		B. & W. Class "H" #15 Boiler Brickwork
	6591	Ehrhart & Arthur, Inc.
		Union Oil Company of Calif Wilmington Refinery -
		H2S Recovery Plant - To Fireproof Two (2) Vessel
		Skirts
		▼
	6592	Shell Oil Company, Inc Dominguez
		Repairs to #5 Boiler
	(A)	#8 Boiler - To Renew Burner Tile and Replace Plas
		tic Refractory around Tubes

6593	Baker Perkins Inc. (Saginaw, Mich.)
······································	Helms Bakeries - Montebello Plant
	Brickwork Repairs to Bake Oven
6594	Quality Machine & Boiler Works - Wilmington
The state of the s	S. S. "American Transport" - Port Boiler: To
	Furnish and Install approx. Ten (10) Tile Brick
	in after outboard Furnace Corner
6595	Union Oil Company of Calif Wilmington
	Unit #33 - To Repair Crude Still B-1-A, demaged
	by Fire (Field Order #2180)
(A)	To Tear out Existing Burners (F. O. #AFE-42612-2)
**************************************	and to Install New Burners (F. O. #AFE-42613-3)
	in BlA and BlB and a second
(B)	Brickwork Repairs to BLA Crude Heater except
	Roof and Burners; and to BlB except Burners
	(F. 0. #2184)
(C)	Brickwork Repairs to B2B and B3B of "B" Side
	Cracking Unit of Unit #33 (F. O. #2232)
(D)	Brickwork Repairs to "A" Side Cracking Plant of
	Unit #33 (F. O. #2197)
(王)	Patching Common Brick in Skirt of #2 Vessel (F.O.#2185)
( mm/	
6596	California Portland Cement Co Colton
	To Repair #7 Kiln Stack Base
6507	G C Manna a Ga Theories and
6597	C. C. Moore & Co. Engineers
	Reconstruction Finance Corp.
	Dow Chemical Company, Agent Los Angeles Styrene Pl.
	Los Angeles - Brickwork and Insulation for One
(4)	(1) FH-26 - 22'-6"/16 NG-54 B. & W. Boiler
(A)	Additional Insulation of Flues

	6598	Triangle Oil & Refining Co., Ltd Venice
		To Repair Firebrick Lining of 1937 SWECO Oil Htr.
	(A)	To Rebuild upper Metal Cased Walls
	6599	Santa Anita Potteries - Los Angeles 41
		To Construct Refractory and Insulation on One (1)
		Robertson Company Tunnel Kiln and for 36 Kiln
V. S. A		Car Tops
40.601-11 R coma∰Page U.S.A.	(X)	To Install Rowlock Course on Top of Present Walls
2		of Robertson Kiln
		•
40,00	6600	Richfield Oil Corporation - Watson
		Watson Refinery - To Repair Side Walls on #7
		Vacuum Still
	(A)	To Repair Side Walls on #4 Vacuum Still
	•	
	6601	Chas. W. Pettifer
		City of Signal Hill, Calif.
		Incinerator Lining
	6602	The Robert L. Johnson Corporation
		Taylor Forge & Pipe Works - Fontana
		C-E Boiler Brickwork
	6603	Todd Shipyards Corporation - San Pedro
		S. S. "James Cook"
		Repairs to Port and the Starboard Boilers
	6604	Federated Metals Division, Amer. Smelting & Ref. Co.
1 10		Los Angeles 23 - To Install Lining in Flue of
* * * * * * * * * * * * * * * * * * *		U. S. Furnace

	6605	Foley Brothers, Inc.
		Phelps Dodge Corporation - Ajo, Arizona
	The state of the s	Brickwork Repairs to Boiler #1, Damaged by Gas
		Explosion
	· · · · · · · · · · · · · · · · · · ·	Let Marie Commercial Section of the Control of the
	6606	Pacific Far East Line, Inc Long Beach, Pier "A", Ber
		S. S. "Hiram Maxium" - To Renew Back Wall,
		Floor, and Front Wall in Starboard Boiler
,	July processors are a second of	and the control of th
	6607	C. F. Braun & Co.
	g gapana a a a a a a a a a a a a a a a a a	Stearns Rogers Manufacturing Co.
de la constitución de la constit		Stanolind Oil & Gas Co Odessa, Texas
	and the second s	12 x 15 x 30 Fired Heater-Material Only
	- And Andrews Control of the Control	
	6608	C. F. Braun & Co.
sion or production of the state	-	The Pure Oil Company - Worland, Wyoming
		15 x 15 x 30 Fired Heater-Material Only
	(A)	Labor onlyOne (1) 15 x 15 x 30 Fired Heater
	(B)	Labor onlyThree (3) Erie City Iron Works Type VE
7		#28-26-18, 300 h.p. Boilers
LLLLL, Constitution of the American		
	6609	Florence Ceramics, Pasadena
	st	To Construct Refractory and Insulation Work on One
		(1) C. R. Minton Sliding Slab Muffled Tunnel Kiln
'		
	6610	Morse Boulger Destructor Company
		Sears, Roebuck & Company - Santa Ana
5600		To Construct One (1) Model 8-R Destructor
	Experience of the second secon	
	6611	Arizona Portland Cement Company
		Rillito, Arizona - To Install Brickwork and
		Detrick Suspended Arch for Fuller Cooler
	(A)	Lining for Kiln Firing Hood

11003 22	
6612	C. C. Moore & Co. Engineers
	Southern California Edison Co Long Beach -
	Plant #3 - Rental of Scaffold for Installing Bailey
	Blocks Latter and the control of the
(A) (B)	To Insulate Rear and Side Walls of Boiler #54 Labor to Install Brickwork on Boiler #54
6613	Pacific Coast Borax Co Wilmington
(A) (B) 6614	Repairs to #1 A. B. Furnace #2 A. B. Furnace - Brickwork Repairs #2 Anhydrous Borax Furn To Install One (1) Specia Union Oil Company of Calif Wilmington / Yang Type Bur
(A)	Repairs to Cracking Heaters Repairs to T. C. C. Unit
6615	U. S. Naval Receiving Station - Long Beach (Term. Is.)
	Heating Plant - To Repair Boilers #1 and #2
6616	Great Lakes Carbon Corp., Dicalite Division
	Walteria, Calif To Install Castable Refractory
	Lining in Auxiliary Furnace
6617	Pacific Transport Lines - Terminal Island - Berth 230-A
* * *	S. S. "Philippine Island Transport"
	Brickwork Repairs to Boilers
	The second of th
6618	Bethlehem Steel Company - Terminal Island
	S. S. "St. Clair" - Brickwork Repairs to Boiler
6619	Pulverizer Combustion Engineering-Superheater, Inc., Raymond/Div.
	City of San Diego - Sewage Disposal Plant -
	To Install Refractories and Insulation for
	One (1) Air Heating Furnace
6620	Filtrol Corporation - Vernon (D) Acid-Brick Paving for Pump
(A) (B)	Acid-Brick Lining in Wash Tower and Treating Tower To Precut Brick for Bottom of Wash Tower To Point & Line Edge of Flume
(c)	To Enlarge Outlet Nozzle Linings on Treating Tower

a maka mana maga a a a a a a a a a a a a a a a a a	Brickwork Repairs to #12 Kiln Hood and Hopper
6622	Todd Shipyards Corporation - San Pedro
	S. S. "Steel Chemist" - To Tear out and Renew
(Extra	Front Wall on Port and Starboard Boilers ) - To Furnish Labor & Mat. to Install Ref. in Panel & Three (3) Bridges
6623	Lockheed Aircraft Corporation - Burbank
an i wan in ni	Plant Bl, Bldg. #176 - To Install Baffles in #2
and the second of the second	Edge Moor Boiler
6624	Pacific Transport Lines - Terminal Island, Berth 230-A
	S. S. "Hong Kong Transport"
	To Rebrick Galley Range
6625	The Texas Company - Wilmington
	H.M.V.S. #1 Heater - To Furnish Labor only to
	Renew approx. 77 sq. ft. of Top Section in East
	Wall; and approx. 168 sq. ft. of Lower Section
(A) (B) 6626	in North Wall To Repair Tile Roof Inside Upshot Heater H.M.L.U. Repairs to #1 Pressure Still (C) Deodorizer Furnace Refinery Maintenance Company, Inc.
	Coline Gasoline Corporation - Ventura, Calif.
	Rincon, Seacliff Siding, Ventura County -
(A)	Born Heater Brickwork, Labor only Material
6627	Southern Pacific Company - El Paso, Texas
	To Rebrick Two (2) 278 h.p. Battery Set, Water Tube Stirling Boilers
6628	Pacific Plumbing Co.
	Sears, Roebuck and Co Santa Ana
	To Install Refractories and Insulation in One (1)
	No. S-268 Brownell Boiler

California Portland Cement Co. - Colton

6621

6629	Great Lakes Carbon Corp Wilmington
·	Repairs to Settling Chamber
(A)	To Rebrick Firing Hood (C) Repairs to Breeching (D) Repairs to Cooler
(B)	Repairs to Kiln (E) Reprs. to Stack Lin'g.
6630	Union Oil Company of Calif Wilmington
	#8 Boiler - Brickwork Repairs
(A)	To Repair Brickwork in Pipe Trench South of
	Control House, Unit #33 /of Control House
(B)	To Brick Wall bet. Crude Sec. & Cracking Sec. North To Rep. all Broken Tile in Unit #33 Control on Con-
6631	Utility Steel Foundry /trol Board
	Repairs to Core Oven
*** <u>.</u>	
6632	Queen of Angels Hospital - Los Angeles
	Boiler #1 - Brickwork Repairs
6633	Forster Shipbuilding Company, Inc Terminal Island
	S. S. "Spyros" - To Repair Refractories in
	Starboard Boiler
6634	Todd Shipyards Corporation - San Pedro
	S. S. "Oleum" - To Renew Decks and Side Walls in
	Port and Starboard Boilers
June 19	
6635	Shell Chemical Corporation - Dominguez
	To Install One (1) H2S Burner in Acetone Furnace
	#4; and One (1) Peephole Opening in Each of
	Furnaces #1, #2, and #3
	and the second of the second o
6636	Bethlehem Steel Company
<i>\$</i>	Terminal Island - S. S. "Santa Paula"
	Necessary Repairs to Boilers
6637	Pacific Coast Borax Company - Wilmington
	Repairs to #2 A. B. Furnace (B)(A) To Patch #1 A.B. Furn. w/Quigley Gun

6638	The Petrol Corporation - Los Angeles
(A) .	To Repair Brickwork over Burner in Oil Still To Replace Brickwork around Tube Ends in Heater
6639	Union Oil Company of Calif Torrance Tank Farm
(A)	To Repair Heater To Check Burners and Fill Access Doors with Brick
6640	Stauffer Chemical Company - Torrance
(A)	Acid-Brick Lining for One (1) Cooling Tower /Tower Addl. Opening & Ins. in Crown of Acid Brick in Cooling
6641	C. C. Moore & Co. Engineers
and the state of t	Southern California Edison Company - Terminal Island
	Long Beach Steam Plant #3
	Rehabilitation of Six (6) B. & W. Boilers, Nos.
(A)	49 to 54 inclusive: - Boiler #51, Labor (See J-6810 * Material (B) - Scaffold Rental for Blr. #52)
6642	The Texas Company - Fillmore, Fillmore Works -
	Brickwork Repairs to Cracking Furnace and
	Reducing Furnace
6643	Consolidated Lumber Company - Wilmington
	Incinerator Repairs
6644	Quality Machine & Boiler Works - Wilmington
	S. S. "President McKinley"
	To Tear Out and Replace Back Wall and Patch Corbels
(Extra)	To Repair Deck
6645	Union Oil Company of Calif Wilmington Refinery
	To Inspect Brickwork in all Heaters and Make Neces-
	sary Repairs
(A)	Necessary Repairs to T.C.C. Unit
(B) (C) (D)	To Repair Brickwork in #1 Boiler as Required /Walls Asphalt Still, E-W Pipetrench - To Block Holes in Fire To Rpr. Brickwk. in Plenum Roof & Renew Eye Bolts
6646	Axelson Manufacturing Co Vernon
e manifesta de la companio del companio de la companio del companio de la companio del la companio de a companio del la companio de la companio del la companio de la companio de la compa	To Reline General Electric Furnace
	·

(A)	Los Angeles 23 - Linings in Two (2) Condenser To Repair #2 Brass Reverb. Furnace	8
6648	C. C. Moore & Co. Engineers	
	San Diego Gas & Electric Co San Diego	132
	Silver Gate Station - To Install Superheater	Baf
	fles in Boilers #3 and #4	
Signal Control of the		
<u>e</u> 6649	Scott-Hastorf-Nettles	4)
2	Park LaBrea Housing Project - Los Angeles	
	54 Kewanee Boilers, Type "C" 7L82	
	Language that we have since the	1,32
6650	Calmo Engineering Company	
	Arizona Portland Cement Company	
	Rillito, Pima County, Arizona	1)3
	To Install Refractory Lining in One (1) Kiln I	End.
	Housing Add Manager Lands	
6651	Peter Kiewit Sons' Co. and Fred J. Early, Jr. Co.	
	City of Los Angeles	
	Hyperion Activated Sludge Plant	
	Stack Lining and Tunnel Lining for Filter, Dr	ier
	and Fertilizer Storage System	
6652	C. C. Moore & Co. Engineers	
	Southern California Edison Co Long Beach	- 24.
	Rental of Scaffold for Modernization of Air He	at
(A)	ers on Boilers #49 to #54. Insulation Repairs on Steam Line	
6653	Todd Shipyards Corporation - San Pedro	
*	S. S. "A. C. Rubel"	
	Necessary Repairs to Boiler	
		*, ,

Federated Metals Division, Amer. Smelting & Ref. Co. -

6647

6654	California Portland Cement Co Colton
	Repair #10 Kiln Stack Base;
	Repair #10 Kiln Hood
6655	General Metals Corporation - Vernon
Sagarita Sagarita	To Install Refractories in One (1) 5 ft. wide x
	23 ft. long Whiting Duplexing Type Air Furnace;
	and One (1) 70" dia. x 60 ft. high Steel Stack
(A)	To Install Refractories in Two (2) #4 Whiting Ver-
	tical Melting Furnaces
6656	The Procter & Gamble Manufacturing Co Long Beach
Extra (A)	Repairs to #2 Stirling Boiler To Clean Refractory Tile Used on Boiler #2 Material
	Bethlehem Steel Company - Terminal Island
Fig.	S. S. "Millicoma" - To Renew Front Walls, Side
	Walls and Chrome Ore on Studded Tubes in Port
	and Starboard Boilers
July, 194	
6658	The Celotex Corporation - Los Angeles
	To Repair Tubular Heater
6659	White Heat Treating Company - Huntington Park
•	To Repair Pit Furnace
6660	Craig Shipbuilding Company - Long Beach
	S. S. "Permanente Silverbow" - To Renew Deck, Front
	Half of Side Wall, Top Six Course of Back Wall, &
	Patch Burner Cones on Port Boiler
6661	Eljer Company - Vernon
	Repairs to Enamel Smelters #1& #2
(A)	To Repair #6 Enamel Furnace (D) - Rpr. #4 Ball Mil
(B)	To Repair #4 Ball Mill
(C)	#2 Enamel Furn To Replace Bottom & Line 2 Doors

	6662	Richfield Oil Corporation - Watson
		Watson Refinery - Necessary Repairs to Flue Gas
	(A)	Generator To Repair Incinerator
	6663	Tide Water Associated Oil Co Wilmington
	•	To Repair Brickwork in #1 Burner
U.S.A.	6664	R C S Engineering Company
<b>1</b>		City of Los Angeles - San Pedro
a:		Department of Water & Power
801-11		Three (3) Petro-Chem Heater
% O,	(A)	Unloading Carload of Materials at Crail Trans-
		portation Co. Yard, 3500 Cherry Ave., Long Beach
	6665	Fibreboard Products, Inc Vernon
1		Repairs to Boiler #3
<i>P</i>		
	6666	Union Oil Company of Calif Wilmington
		Wilmington Refinery - Necessary Repairs to
		Asphalt Still #99
	(A)	Necessary Repairs to Asphalt Still #100
*	(B)	Repairs to Unit #34
	(C)	Repairs to Crude Still
	(D)	Repairs to Boiler #3
	(E) (F) (G)	Repairs to #33 Crude Still Brickwork Repairs to Unit #33 Brickwork Repairs to Boiler #2, Plant #2
	6667	California Portland Cement Co Colton
	(A)	To Repair Lime Kiln Stack Base To Repair #15 Hood
)	6668	Pacific Transport Lines - Terminal Island, Berth 230-A
		S. S. "Linfield Victory"
		To Tear out and Renew Deck; Two Top Courses of
		Back Wall and Front Wall

6669	Shell Oil Company, Inc Dominguez Refinery	
and the second second	Repairs to #5 Dubbs Furnace	
(A)	Repairs to Roof on #6 Dubbs Furnace	
		1777
6670	United States Gypsum Company - South Gate	
* * * * * * * * * * * * * * * * * * *	Insulation Repairs on #2 Boiler	
6671	C. C. Moore & Co. Engineers	
	The Procter & Gamble Manufacturing Co Long	Beach
	To Remove Present Bigelow-Liptak Suspended Construction and to Install New Tube-and-T	
Samuelan Samuelan	Walls for One (1) Class XXII #27 B. & W. S	tirling
	Boiler	
		4 1
6672	Queen of Angels Hospital - Los Angeles 26	
	To Repair Firebox in #2 Boiler	e de la companya de l
		7
6673	Frederick O'Brien Paint & Varnish Works - Hunt	ington Pa
	To Repair Lining in 1,000 Gallon Ball Mill	
	And the second s	w construction
6674	General Chemical Division, Allied Chemical & D	ye Corp.
	El Segundo - Repairs to #2 Vestibule	* *
		- N - 17
6675	Pacific Far East Lines, Inc Long Beach	
	Pier "A", Berth 5 - S. S. "Great Republic"	
	To Renew Deck Corbels and Three (3) Burner	Cones
	in Port Boilers; and to Renew Detrick Tile	and
	Insulation in Frtont Wall	
6676	C. C. Moore & Co. Engineers	The second secon
	San Bernardino County Hospital - San Bernardin	<b>o</b>
	Three (3) Class H2 No. 16 B. & W. Boilers	

	August 1 6677	949  Bethlehem Steel Company - Terminal Island  S. S. "Shawnee Trail" - Miscellaneous Repairs to Port and Starboard Boilers
	6678	Wilmington Welding & Boiler Works, Inc.  J. H. Baxter & Company, Long Beach
·.	(A)	To Repair Brickwork in Boiler To Repair Brickwork in Boiler
	6679	California Portland Cement Co Colton To Repair #9 Kiln Hood and Hopper
,	§ 6680	Fabriform Metal Products, Inc.
		(Formerly American Brazing Company)  Los Angeles 1 - To Remove Brick Arch from 100KW  G-E Controlled Atmosphere Electric Furnace; and to Rebuild Arch
,		
	6681	R. W. Cunningham Company
		Huntington Memorial Hospital - Pasadena
	(A) (B)	Firebox Settings for Two (2) Erie City Boilers To Repair Upper Firebox Walls To Repair Boiler Insulation
	6682	Morse Boulger Destructor Co.
		General Petroleum Corp. Building - Los Angeles To Install Checker Baffle in Incinerator
	((0)	
	6683	Triangle Oil & Refining Company, Ltd Venice  To Rebuild Brick Setting - SWECO Portable Still
	6684	Federated Metals Div., Amer. Smelting & Ref. Co.
	· ·	Los Angeles - To Reline U. S. Furnace
	(A)	To Reline #2 Brass Reverb.
	6685	Western Precipitation Corp Burbank To Build 6,000,000 Btu Air Heater complete with
		Lining

0000	Pacific Transport Lines - Terminal Island, Berth 230-A
- Agrap Asses Asses and the second	S. S. "China Transport"
	To Renew Deck and Corbels in One (1) Boiler
6687	Bethlehem Steel Company - Terminal Island
	S. S. "Escambia"
	Item 238Renew Deck, Corbels, Burner Throat and
	and Insulation in way of Soot Blower, in Port and
	Starboard Boilers of Manager in the Manager Communication of the Communi
	Item 245Chip and Release Vertical Expansion Joint
(A)	in Back Wall in Port and Starboard Boilers To Install Approved Inhibited Cement in Port & Starb Boilers
6688	Southern Service Co.
	Ontario Laundry - Ontario
arin goldenser at 1 to	Repairs to HRT Boiler
6689	Southern California Edison Co Redondo Steam Plant
	#4 Boiler Repairs
(A) (C)	#3Boiler Repairs (B) Misc. Insulation Repairs To Repair #2 Boiler (D) Misc. Insul. Rprs. as requi
6690	Southwestern Portland Cement Co Victorville
	Labor only for Dust Chamber; #1 and #6/Kiln Hood,
	including Insulation; and #1 and #6 Fuller Cooler
6691	Jonathan Club - Los Angeles
	Boiler Brickwork Repairs
6692	Morse Boulger Destructor Co.
	University of Southern California
*···	Los Angeles County General Hospital - Los Angeles
	Contagious Disease Research Incinerator Bldg.
	To Furnish Labor and Material to Construct

One (1) Morse Boulger Destructor

	6693	Gladding, McBean & Co Santa Monica Plant Rebuild 30' I. D. Downdraft Kiln
( ) ) ·	(A)	Extra Work on Flue and Stack
		And the state of t
	6694	American Manganese Steel Division of the
		American Brake Shoe Co Vernon
Α,		Repairs to Car Type Furnace
U.S.A.		
4	6695	Hammond Lumber Company - Los Angeles
801-11 R	{	Repairs to Incinerator
NO.8	6696	Leahy Manufacturing Company
		Western Waxed Paper Company - Los Angeles
		To Install Refractory Linings in Two (2) Kewanee
	•	#587 Boilers
1		The second secon
*	6697	Union Oil Company of Calif Wilmington
		33 "A" Cracking Plant
		Repairs to B3A Heater
	(A)	Brick up Hole in Fire Wall at Pipe Trench
	(B)	Brick up East End of Pipe Trench, Foam Caustic Storage Area
	(C)	To Rebuild Portion of Brick Wall that is Knocked
	•	over at 12th & "D" Streets
,	(D)	Inspect & Repr. Refractory Lining in Reversion Htr. Flue and Stack
	(E)	Replace Acid-Mix TankWater Treating Plant, "H" Unit
	(F) (G)	To Repair Treater Side of T. C. C. Unit To Replace Rolled Header Boxes w/Welded Return Bends
	( )	in Zone 6, Install New 18-8 Tube Sheets, TCC Unit
	(H)	Repair #1 & #2 Heater Baffles & Explosion Door
)	6698	
1	0090	The Texas Company - Wilmington
		Labor only to Tear out and Renew Target Wall, ap-
		prox. 100 sq. ft. of West Wall in #1 Preheater and
		Target Wall in #2 Preheater
		(contd. over)

6698-A	The Texas Company - Wilmington (contd.)
	Labor only to Rebrick East and West Walls and
	Patch North and South Walls of #1 Still; and
	East and West Walls of #2 Stills and 8 Holes on
	Top of #1, #2, and #3 Stills in #3 Crude Unit
	the control of the co
6699	Quality Machine & Boiler Works - Wilmington
	S. S. "Wm. Pilghman"
	To Renew approx. 16 sq. ft. of Deck and Patch
	Burner Cones Rendered and California
6700	United States Gypsum Company - South Gate
	Boiler Brickwork Repairs - #1 Mill
6701	Pacific Division Bendix Aviation Corp North Hollywood
	To Repair Box-Type Electric Furnace
(A) (B)	To Reline Air-Draw Furnace To Repair Brazing Furnace
6702	C. C. Moore & Co. Engineers
	Lucky Lager Brewing Company - Azusa
	To Furnish and Install Refractories and Insulating
	Materials for One (1) New Type FF-12, No. 20
4	B. & W. Boiler
# 1 1 2 2 10 1 W 10 1 1	
6703	Stauffer Chemical Company - Torrance Plant
	To Insulate One (1) Steam Pot at Laboratory
6704	San Diego Gas & Electric Co San Diego, Station "B"
	Boiler #27 - Burner Wall Replacement
Septembe	1949
6705	Quality Machine & Boiler Works - Wilmington

S. S. "Thomas Cresat"

Brickwork and Insulation Repairs to Port Boiler

	0100	The Exchange Orange Products Co Ontario	Section 2
	*	To Repair Badenhausen Boiler #4	
		And the second s	N
	6707	Richfield Oil Corporation - Watson	Y
		To Repair #8 Vacuum Heater	a Artistan
- 4 A			
	6708	Stauffer Chemical Company, Dominguez Division	
G.S.A		Dominguez, Calif.	
		Acid-Proof Brick Lining in One (1) Electron	static
0.0		Precipitator	(4)
* ° ° *	6709	C. C. Moore & Co. Engineers	*
		Santa Barbara Cottage Hospital - Santa Barbara	
		Brickwork Repairs to One (1) Class H3 No.	14
		B. & W. Boiler	
			-
<b>\</b>	6710	Averill-Morgan Co., Inc Hollywood	
		To Renew Leahy Burner Tile in Scotch Marine	Boiler
	6711	Shell Oil Company, Inc Dominguez	
	(A)	Brickwork Repairs to #13 and #14 Heaters Brickwork Repair s on Dubbs Furnace #1	80.5 j. j.
	6712 -	Richfield Oil Corporation - Long Beach	
		S. S. "Sparrow Point"	
		To Renew Burner Cone and Paint Front Wall w	ith
		Airset Cament in Port and Starboard Boilers	
	(A)	To Repair Castable Refractories of Rear Walls. S. "Coxcombe Hills"	l.
	6713	Coast Fishing Company, Inc Wilmington	
	(A)	To Repair Fish Meal Furnace as Directed Repair Boiler as directed	
	6714	The Texas Company - Wilmington	
		Detrick End Walls - #1 Crading Still	

6715	Great Lakes Carbon Corp Torrance
,	To Reline Rotating Section of #2 Kiln
(A) (B) (E)	To Repair #1 Kiln (C) - Patch #2 Kiln To Patch #2 Kiln (D) - Reline Rotating Section of Repair Kiln #1 #1 Kiln
6716	The Texas Company - Wilmington
	Labor only to Tear out and Renew Section of Side Wall
	and Front Wall in #1 and #2 Crude Still; and to Renew
	North and South Walls and Roof of Pipe Still Furnace
(A)	Burner Drums in Preheater
(B)	#3 Boiler
6717	Bechtel Corporation
	General Petroleum Corporation - Torrance
	Brickwork and Insulation for B4 Furnace
6718	Shell Oil Company, Inc Dominguez
(A)	Boiler #1 - Furnace Brickwork Repairs  Necessary Repairs to Tunnel of #6 Heater, #3 Unit
6719	Max Weil of California - Los Angeles
· · · · · · · · · · · · · · · · · · ·	Tunnel Kiln - Brickwork Repairs
6720	Quality Machine & Boiler Works - Wilmington
	S. S. "J. L. Luckenbach"
	To Insulate Superheater Supports with "Kastset"
	and the control of the first case of the control of
6721	Todd Shipyards Corporation - San Pedro
	S. S. "Paul M. Gregg"
	To Repair Forward and Aft Boilers
	en de la companya de La companya de la co
6722	OFCCO Construction Co., Inc.
	Tide Water Associated Oil Co Ventura
	Setting for One (1) 300 h.p. Union Iron Works
	Type "L" W. T. Boiler

		6723	OFCCO Construction Co., Inc.
~~~			Los Angeles County General Hospital - Los Angeles
	<b>)</b>		Setting for One (1) Union Iron Works Type "B"
			Steam Generator
		October	. 1949
		6724	C. C. Moore & Co. Engineers
U.S.A.		· · ·	United States Rubber Company - Los Angeles
			Setting for One (1) B. & W. Class 231, #24 Stir-
H Call Post			ling Boiler with Superheater, Air Heater, Oil and
801-11 F			Gas Burners, Watercooled Furnace, Fans and Ducts
10.1			
		6725	Johns-Manville Products Corp Watson
			Boiler Repair
		6726	American Ceramic Products, Inc Santa Monica
			Ball Mill Lining
		6727	Pacific Coast Borax Co Wilmington
		(A)	Necessary Repairs to #1 A. B. Furnace Necessary Repairs to #2 A. B. Furnace
		6728	American Potash & Chemical Corp Trona
			#2 Soda Ash Furnace - Brickwork Repairs
		6729	Globe Mills - East Los Angeles 22 (in County)
			To Rebuild Firebox for Kewanee Boiler
		6730	Lummus Company
, ,			Richfield Oil Corporation
	<b>X</b>		Watson - Watson Refinery
			To Line Oil Reheater
		_	
		6731	Shell Oil Company - Dominguez
		9	Boiler #2 - Furnace Brickwork Repairs

6732	J. T. Thorpe & Son, Inc.
And control and a second a second and a second a second and a second a second and a	States Steam Ship Co Long Beach
	S. S. "Wyoming"
meguana punantika	Labor and Material for Front Wall
mr.coprocu-represent	
6733	Swift & Company - Vernon
remindent of the control of the cont	Repairs to C-E Boiler
and open colors	
6734	Pax Metal Corporation - Los Angeles 1
-	Aluminum Melting Furnace - Brickwork Repairs
6735	W. P. Fuller & Company - Los Angeles
	To Reline 6 ft. x 6 ft. Ball Mill
6736	C. C. Moore & Co. Engineers
	Lockheed Aircraft Corporation - Burbank
	Brick Setting and Insulation for Two (2)
	Class FF-15 No. 36 B. & W. Boilers
6737	Montrose Chemical Corp. of Calif.
	(Stauffer Chemical Co. Plant)
	Torrance - To Install the Acid-Proof Brick Lining
	in One (1) Vertical Steel Tank 41" dia. x 7'-0"
(A)	high To Install an Additional 4½" Acid-Proof Brick Lining
6738	A. K. Wilson Lumber Co Compton
	Labor to Repair Incinerator
November	
	Flian Co of Colif Warman

To Rebuild Hearth Floor and Hearth Sides for

#2 Smelter

6740	C. C. Moore & Co. Engineers
· accommodate	Southern California Edison Co Redondo
Je (A) Je (B) 10 6741	To Insulate Attemperator on Boiler #2 To Insulate Attemperator on Boiler #4 Rental of Scaffolding and Equipment
중 6741	Union Oil Company of Calif Wilmington
A A	To Inspect and Repair all Brickwork in Fireboxes
0	of Cracker T. C. C. Unit
TARGETT RECESSORY (N)  WELLS	Repair all Brickwork in Kiln Lining as Necessary Inspect Brickwork on Boiler #7 and Repair where Necessary Inspect, Clean, & Repair Plenum Tile in BlB Htr. Inspect & Repair all Brickwork in B2A Heater Install Brickwork around Skirt of Caustic Tank #D12 Repair Brickwork necessary to BlA Heater Necessary Repairs to B2B & B3B Heaters, Unit #33 Replace Brick in Opening through Furnace Repair Brickwork in Boilers #3 and #4 Inspect Brickwork and Plenum Tile in Unit #34 Inspect & Repair Brickwork in Reversion Heater Necessary Brick Repairs to #1 Boiler Repr. Brickwk. in Base of Acid Pumps #322 & #329 Macco Corporation
Perposition	Southern California Edison Co Long Beach Steam Plant
TO POPO VA PRILITANTI PRIMA POPO PARA PARA PARA PARA PARA PARA PAR	To Insulate Boiler Feedwater Headers - Unit #9
6743	Wilshire Oil Company, Inc Norwalk
See a se	To Rebuild Five (5) Burner Tunnels in Alcorn
veneronanijelij	Furnace
(A)	Reinsulate Flue Gas Breeching and Breeching to
en e	Stack
6744	The Texas Company - Wilmington
♥ ·· · · · · · · · · · · · · · · · · ·	To Repair Roof on L. U. Preheater
Pyrocedoblowes	2. 2. 2. 2. 2. 2. 2. 2. 2. 2. 2. 2. 2. 2
6745	Todd Shipyards Corporation - San Pedro S. S. "Oleum" - To Renew Front Walls and Chrome
Warring and Continued The Cont	Ore in Port and Starboard Boilers
6746	Harvey Machine Company, Inc Torrance To Furnish Labor only to Rebrick Dempsey Furnace

6747	Luer Packing Company - Vernon
Englantecom skylin	To Repair Incinerator
OF A PRINCIPAL OF A P	
6748	Federated Metals Division, Amer. Smelting & Ref. Co.
(A) (B) 6749	Los Angeles - To Reline U. S. Furnace Repairs to Aluminum Smelter Repairs to Zinc Retort Southern California Edison Company
	Long Beach Steam Plant #2
	To Install and Repair Heat Insulation on Feed-
A Townson	water Piping for 15 Boilers
6750	Lohman Bros.
-	Jonathan Club - Los Angeles
	To Repair Brickwork in Two (2) Llewellyn Boilers,
e de terro en en	set in battery
6751	Bethlehem Steel Company - Terminal Island
	S. S. "Buccinum" - To Renew Chrome Ore, Burner
	Columns, Side Walls, Header and Corbels
6752	Commercial Enameling Co Los Angeles
k is a	To Repair Enemel Smelter
6753	Old Colony Paint & Chemical Co Los Angeles To Reline Ball Mill
6754	Vegetable Oil Products Company, Inc Wilmington Necessary Repairs to Boiler
6755	Matson Navigation Company - Wilmington, Berth #159
	S. S. "Hawaiian Wholesaler"
	Brickwork Repairs to Port Boiler

	6756	Mead Johnson and Co Torrance
		To Repair Two (2) Boiler Fireboxes and to Replace
		Carborundum Tile of Floor
•		
	6757	Pacific Clay Products - Los Angeles Plant
		To Reline Ball Mill
ú		
U.S.A	6758	Jonathan Club - Los Angeles
		To Repair Incinerator
80.00	6759	Alexander H. Kerr & Co., Inc Santa Ana
		To Rebuild Glass Tank
	6760	Todd Shipyards Corporation - San Pedro
		S. S. "Caribbean" - Tear Out and Renew Chrome Ore
1		Side Walls, Deck and Top Wall in Two (2) Boilers
\ <i>p</i>		
	6761	Rothschild Oil Company - Santa Fe Springs
		To Install New Insulation Lining in Flues and
		Breeching of U. O. P. Heavy Oil and Light Oil
		Heaters
	6762	Combustion Engineering-Superheater, Inc.
		Central Arizona Light & Power Co Phoenix, Arizona
		Setting for One (1) C-E Boiler Unit
	6763	Shell Oil Company - Wilmington Refinery
		Boiler #4 - Baffle Repair
/ N	6764	Quality Machine & Boiler Works - Wilmington
\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \		S. S. "Thomas Cresap"
		To Renew 20 sq. ft. Insulation on Side Walls
. (	6765	Griffith Company (contd. over))
		a contract the contract of the

. Commence of the commence of	City of Los Angeles - Los Angeles
	Municipal Incinerator -
	Repairs to #4 Rotary Kiln
	The state of the s
Dec. 19	
6766	The Prudential Insurance Company of America
,	Prudential Building - Los Angeles
(A)	To Repair Morse Boulger Destructor To Repair Hearth Floor of Morse Boulger Incinerator
67 <b>67</b>	American President Lines - Wilmington, Berth #155
	S. S. "President Pierce"
	To Furnish Labor and Insulation Material to Renew
	Front and Back Walls of Port Boiler
ing the same that the same t	
6768	Todd Shipyards Corporation - San Pedro
*	S. S. "Shawnee Trail"
	Labor and Material for three (3) Top Courses of
	Brick and Plastic on Front Wall and Four (4)
	Burner Cones
6769	Santa Anita Potteries - Los Angeles 41
	To Repair Lining in Firebox of #1 Tunnel Kiln
6770	C. C. Moore & Co. Engineers
	Vegetable Oil Products Co., Inc Wilmington
	To Remove and Replace Brick Covering on Top of
	Circulating Tubes and Drums, and Remove and Re-
	place Baffle Tile on One (1) Class VIII No. 12
	Stirling Boiler
6771	C. F. Braun & Co.
	Western Gulf Oil Company - Kern County, Paloma Field

One (1) 3-Drum Riley YKL20 Boiler Setting--Lab. Mat. To Install Capping over Blr. Tubes on Riley YKL20 One (1) Fired Heater F60--Labor only /Blrs. #1,#2

6765

(R)

Griffith Company

	6772	The Texas Company - Wilmington
š		Labor only to Repair North and South Walls on
		H.M.V.S. Furnace
ACADA CALLED	6773	Craig Shipbuilding Company - Long Beach
-		S. S. "Escandia"
	¥.	To Install Insulation of both Ends of Port and
And de la section and designation of the last	0°2°	Starboard Economizers
And March and Advantage of the Persons Inches	W. 601-11-109 .01	
***************************************	6774	Bethlehem Steel Company - Terminal Island
OCCUPATION OF THE PERSON	0 8	S. S. "Tallulah"
***************************************	2	To Renew Brickwork in Way of Mud Drum Header
Contraction of the Contraction o		
	6775	Union Oil Company of Calif Torrance'
	(A)	To Repair South End of Heater Repair Floor and Patch Burners
APPENDING STREET	6776	Bethlehem Pacific Coast Steel Corp Vernon
Contraction of the Contraction o		To Install Brickwork and Erect Steelwork for
The state of the s		One (1) Ladle Stopper Rod Drying Oven
de la Company	*	
DOSDANDANDAN	6777	Luer Packing Company - Vernon
American constitution of the constitution of t		Repairs to #3 Boiler
The second secon	6778	Bethlehem Steel Company - Terminal Island S. S. "Santa Paula"
***************************************		Labor and Material to Tear Out and Renew Chrome
A STANDARD OF THE PERSON NAMED IN COLUMN TWO IS NOT THE PERSON NAMED IN COLUMN TRANSPORT NAMED IN COLUMN TWO IS NOT THE PERSON NAMED IN COLUMN TRANSPORT NAMED IN COLUMN TWO IS		Ore in Back Wall Corbels, Burner Columns, and
oriente continue con		Brickwork in Front Wall
The state of the s		
process and a second	6779	City of Los Angeles - Los Angeles - Lacy Street Plant
+Grindmonton con		To Repair Rotary Kiln #2
	(A)	To Repair Rotary Kiln #1
The field of the same of		
450000000000000000000000000000000000000		
		e de entrédant

6780	Craig Shipbuilding Company - Long Beach 2
	S. S. "Lumberlady"
etpe a collegen per college ;	To Repair Burner Throats on Port and Starboard
	Boilers
	and the second s
6781	Bechtel Corporation
(B) (C) 6782	Salt Lake Refining Company - Salt Lake, Utah  (Kiln-Reactor Lining (Houdriflow Unit HF-2 (A) Petro-Chem Heater Brickwork Peabody Air Heater Brickwork (D) Repair Crude Born Heater-Brickwork & Insulation  Forest Lawn Memorial-Park Assn., Inc Glendale
(A)	To Repair Charging End of Retorts To Scrape and Paint Three (3) Crematory Retorts
6783	Standard Oil Company of Calif El Segundo
	Brick Setting for B&W H-4 No. 29 Boiler#57
6784	Combustion Engineering-Superheater, Inc.
	Phelps-Dodge Corporation - Ajo, Arizona
	Settings for Two (2) C-E Waste Heat Boilers
C () are	
6785	Eljer Co. of California - Vernon
(A)	To Repair Ball Mill #4 /Furnace To Repair Floor, Two (2) Piers and Muffle in #4 Enamel
6786	Stauffer Chemical Company - Vernon
(A) (B)	Acid-Brick Lining for a 22" I. D. x 24" long Pipe To Brick Line "A" Mixer To Brick Line "A" Mixer
6787	National Enameling & Foundry Co Compton
	To Reline One (1) 30" x 30" Ball Mill
a.	And the second of the second o
6788	Federated Metals Division, Amer. Smelting & Ref. Co.
(A)	Los Angeles - To Repair #2 Brass Reverb. Furnace To Repair Sweater Furnace
6789	Pomona Tile Manufacturing Co Pomona
	To Replace Split Brick Floor in Allied Twin Muffle
(A)	Kiln To Replace Split Brick Floor in another Kiln

	6790	Stauffer Chemical Company - Dominguez Division
$\wedge$	*	Dominguez - Refractory Lining for One (1) H2S
		Furnace Connecting Pipe and 4 ft. Extension to
	(A)	Existing Dutch Oven 6 Brickwork Reprs. to Dutch Oven of Combustion Chamber
	6791	Pacific Coast Borax Company - Wilmington
1		Complete Overhaul of #2 A. B. Furnace, Renewing
U.S.A		Front and Back Walls, both Side Walls and
9		Three-Fourths (3/4) of Roof
40,801-11 R ZMM W.S.A.	(A) (B) (C) Jan. 195	Repair #1 A. B. Furnace with Quigley Gun Repair #1 A. B. Furnace Labor to Install Brickwork in Dog House
	6792	The Cudahy Packing Company -
	, ,	Los Angeles - Macy Street Plant
	(A)	To Repair Boiler #1 xxxxx2 To Repair Boiler #2
	6793	Pacific Clay Products - Los Nietos
		Miscellaneous Brickwork Repairs for Year 1950
		(For Year 1949, see Job No. 6508)
	(A)	February 1950
	(B)	March 1950
	(C)	April 1950
	(D)	May 1950
	(E)	June 1950
	(F)	July 1950
	(G)	August 1950
	(H)	September 1950

	6794	Pacific Clay Products - Los Nietos - Plant #6	arya .
		Kiln Repairs for Year of 1950	
		(For Year 1949, Refer to Job No. 6509)	
	(A)	Repair Kiln #8	
	<b>(B</b> )	A STATE OF THE STA	(1)
	(c)	35 ft. Tunnel Kiln Extension	A+13
		To Repair Kiln #27	
	(E)	Harrop Tunnel Kiln Repair - Plant #4	
		ACCUPATION AND ALL AND	
			(a)
	6795	Stauffer Chemical Company - Dominguez Division	i North Lange
		Dominguez - Maintenance and Repairs to Bric	
	e e e e e e e e e e e e e e e e e e e	Insulation for Year of 1950	
		(For Year of 1949, Refer to Job No. 6506)	
			(.)
	6796	California Portland Cement Company - Colton	
	Alleman Communication Communic	To Repair Allis Chalmers Clinker Cooker	
	6797	Utility Trailer Manufacturing Co Los Angele	s 33
		To Reline Electric Furnace	v ×
	6798	The Fluor Corporation, Ltd Los Angeles Coun	ty
		Brickwork Repairs on Incinerator	
1950			
	6799	Todd Shipyards Corporation - San Pedro	
	Particular de la companya del companya de la companya del companya de la companya del la companya de la company	S. S. "A. C. Rubel"	110-120 to 1
		To Renew Top Leaders and to Patch Front Wa	11 in
		Two (2) Boilers	