

JANUARY 1975

- 8627 KERR McGEE CO. - WESTEND
Repairs to #3 Anhydrous Furnace
- 8628 KAISER FABRICATOS - Fontana
Repairs to Normalizing Furnace
- 8629 DOCKSIDE MACHINE BOILER
SS Zim Tolyo - Long Beach
Repairs to port & starboard boiler
- 8630 THATCHER GLASS - Saugus
Hot patch #3 furnace
- 8631 PHILADELPHIA QUARTS - South Gate
Nec repairs to Silicate Furnace
- 8632 STEEL CASTINGS- LA
Nec repairs #4 Furnace
- 8633 GREAT LAKES CARBON - Wilm
Repairs to #4 Kiln
- 8634 GREAT LAKES CARBON - Wilm
Water cooled damper #3 kiln
- 8635 STEEL CASTING - LA
Repairs to #3 furnace
- ~~8636 CONTINENTAL CAN CO INC~~ *cancelled*
Sparrows Point, Maryland *4/75*
Engineering only for installation of one (1)
~~10,000 SCFM Incinerator - Plant 462~~

JANUARY 1975

- 8637 H. KRAMER & CO - El Segundo
Install brick in flue.
- 8638 U S BORAX - Boron
Minor repairs to #6AB furnace
- 8639 PHELPS DODGE TUBE - LA
Form and pour castable in gas generator
- 8640 CYPRESS TUBING - Torrance
Nec repairs to lead pot
- 8641 TEXACO INC - Wilm
Nec repairs to "A" Generator
"A" Nec repairs to "B" Generator
- 8642 U S BORAX CHEMICAL-Boron
Major Refractory Repairs to
Furnace ABA-Plant 26
- 8643 ROSE COOPERAGE-Montebello
Repairs to holes in arch of barrel kiln
- 8644 US BORAX & CHEMICAL-Boron
Major repairs to new doghouse, Plant 26
- 8645 CITY OF PASADENA
DEPT OF WATER & POWER
Unit B1 repair burner throat
- 8646 NORRIS INDUSTRIES-Maywood
Repair to #1 hard furnace

JANUARY 1975

8647 SOUTHWEST STEEL ROLLING MILLS-LA
Labor and material to repair and modify
charge end billet furnace

8648 KERR McGEE CO - WEST END
Repairs to #7 Dryer

8649 KAISER FABRICATORS
DIV KAISER STEEL-Fontana
Supply design and lining for new stress
relief furnace door
"A" Furnish 12 Castiron Furnace Dampers

8650 EARLE M JORGENSEN-Seattle
Design and construct 13' x 2' carbottom
forge furnace F-25

8651 HALL HEAT TREATING-Paramount
Replace blower motor on Furnace #12

8652 INTERPACE-Glendale
Repair to #7 Kiln

8653 MOBIL OIL CO-Torrance
Repairs to Boiler 2F5

8654 MONSANTO CHEMICAL-Long Beach
Repairs to Calciner

~~8655~~ ~~PARAMOUNT FORGE~~

cancelled

8656 KERR-McGEE CHEMICAL-Trona
Refractory repairs to 8'6" OD x 6 hearth
Lithium Carbonate Furnace

JANUARY 1975

- 8657 H KRAMER-El Segundo
Repairs to Rotary Furnace
- 8658 TODD SHIPYARD - San Pedro
SS Idaho
Repairs to port and starboard boilers
- 8659 STAUFFER CHEMICAL - Oxnard
Repairs to kelp burner
"A" Repair fallen Brickwork
- 8660 KAISER CEMENT-Cushenbury
Repairs to #3 cooler and firing hood
"A" Gunite
- 8661 ANACONDA AMERICAN BRASS-Paramount
Ram one lower case
- 8662 MARTIN MARIETTA ALUM-Torrance
Nec repairs to #1 furnace
- 8663 U S BORAX & CHEMICAL-Boron
Major refractory repairs to 6AB furnace-
Main fusing plant
- 8664 POWERINE OIL CO-Santa Fe Springs
Repair slide valve with AA22
- 8665 SOULE STEEL - Long Beach
Repairs to reheat furnace
- 8666 MARTIN MARIETTA ALUM-Torrance
Design and construct bar mill billet heating
furnace

JANUARY 1975

8667

ARIZONA PORTLAND CEMENT

Rillito, Ariz.

Refractory line ductwork from firing hood to cyclone for coal firing sys - Kilns 1,2,3 & 4

8668

FILTROL - Vernon

Install lining in digester tank

8669

STAUFFER CHEMICAL-Dominguez

Install linings on pump base

8670

JORGENSEN STEEL - LA

Nec repairs to #1 & #6 furnaces

"A"

Nec Repairs to #1 Press Furnace

~~8671~~

~~GENERAL ELECTRIC-Ontario~~

~~Replace dividing wall in sweat furnace~~

cancelled 2/4/75

8672

GREAT LAKES CARBON

CALUMENT PLANT - CHICAGO, ILL

Design & construct (1) water cooled damper

8673

US AF - ARNOLD ENGINEERING &

DEVELOPMENT - Tullahoma, Tenn.

Supply and install refractory materials

in pebble air heater.

"A"

Partial Spare Lining

8674

GREAT LAKES CARBON - Wilm

Nec repairs to #1 kiln

FEBRUARY 1975

8675

APEX SMELTING - Long Beach

Repairs to #3 Reverb Furnace

8676

RALPH M PARSONS/ATLANTIC RICHFIELD

Watson - Install refractory linings in Inline Heater & Reactor

FEBRUARY 1975

- 8677 US BORAX & CHEMICAL - Wilm
Repairs to ABA Furnace
- 8678 US BORAX & CHEMICAL - Wilm
Furnish & install tile for salt cake furnace
- 8679 NORRIS INDUSTRIES, Maywood
Repairs to #1 Hard Furnace
- 8680 EGLOFF & GRAPER/
McDONNELL DOUGLAS AIRCRAFT
Huntington Beach
Reline Dispatch Oven
- 8681 U S BORAX - Boron
Repairs to #1 Boiler
- 8682 RALPH M PARSONS/
NORTHERN NATURAL GAS CO
Hobbs, New Mexico
Design and supply (1) Thermal Oxidizer
- 8683 NORRIS INDUSTRIES - Vernon
Nec repairs to solar furnace
- 8684 ATLANTIC RICHFIELD - Watson
Install refractory abrasion lining in
8 Buell cyclones
- 8685 AIROX CORP - Santa Maria
Repairs to reactor roof & cyclone

FEBRUARY 1975

8686 RALPH M PARSONS/
SOUTHERN CALIF EDISON, Alnor Station
Cypress - Repair oil heater

8687 PHELPS DODGE - Morenci, Ariz
Furnish 52 frames

8688 COLLIER CARBON & CHEMICAL, Brea
Repairs to converter

8689 MONSANTO CHEMICAL - Long Beach
Repairs to north unit of Calciner Header
"A" Repairs to Calciner Header

8690 JORGENSEN STEEL - LA
Repairs to #3 Furnace
"A" Additional Material

8691 PROCTOR & GAMBLE - Long Beach
Repairs to #1 Boiler

8692 N L INDUSTRIES - Rowley, Utah
Furnish 1 damper assembly

8693 MARTIN MARIETTA ALUM - Torrance
Repair #5 Furnace.

8694 MARTIN MARIETTA ALUM - Torrance
Repair #3 Normalizing Furnace

~~8695 STANDARD OIL CO - El Segundo~~
~~Repairs to Flare Isomax Plant~~

cancelled 5/75

~~8696 SOUTHWEST STEEL ROLLING MILLS - LA~~
~~Supply & Install Fuel Air Ratio Equip on~~
~~Billet Heating Furnace.~~

cancelled 2/76

FEBRUARY 1975

- 8697 US BORAX & CHEMICAL - Boron
Major repairs to #IRA Furn - Old RA Plant
- 8698 NORRIS INDUSTRIES - Maywood
Nec repairs to #1 Hard Furnace
- 8699 US BORAX & CHEMICAL - Boron
Minor repairs #IAB Furnace - Plant 5
- 8700 CONTINENTAL CAN CO - Commerce
Install access door on 12,000 scfm
Horizontal Fume Incinerator.
- 8701 CELOTEX - LA
Repair to Boiler and Kettles 4 & 5 and
Retort 1 & 2.
- 8702 TEXACO INC - Long Beach
Nec repairs to Burner Chamber for
Lime Burner.
- 8703 H KRAMER - El Segundo
Nec Repairs to #2 Rotary.
- 8704 SELAS CORP OF AMERICA
STANDARD OIL CO - El Segundo
Repairs to Selas Heater.
- 8705 ALCOA - Vernon
Repairs to #1 Furnace
- 8706 US BORAX & CHEMICAL - Wilmington
Repair Spray Dry Furnace
- 8707 MAGNA COPPER CO - San Manuel, Ariz
Install Refr. Lining in Melting & Holding
Furnace.

FEBRUARY 1975

8708 TOSCO PETRO - Bakersfield
Nec Repairs to the Selsas Heater.
"A" Install Burner Tile in the 21H-11 &
21H-12 Feed Heater

8709 STANDARD OIL CO - El Segundo
Repairs to Knapp Stress Relief Furnace
and New Oven

8710 APROS
VULCAN MATERIALS - Benton, Arkansas
(1) Special 80,000# Aluminum Melt. Furnace
"A" Lining for Dryer, Combustor Collector & Misc
Ducts & Chutes

MARCH 1975

8711 MARTIN MARIETTA CARBON - Carson
Nec Repairs to Bullnose in Rotary Kiln

8712 GREAT LAKES CARBON - Wilmington
Nec Repairs to #3 Kiln

8713 JOSLYN MGF & SUPPLY CO - Dominguez
Acid brick repairs, Acid Pickling Tank
"A" Repair Galvanizing Kettle Tank.

8714 U S BORAX & CHEMICAL - Boron
Furnish four (4) Plug Type Forehearth
"A" Modify 1 Forehearth for ABA Furnace.
"B" Change Valve Size from 2" ID to 3" ID.
(Same as A.)

8715 MONSANTO CHEMICAL CO - Long Beach
Repairs to #2 Acid Burner

8716 STANDARD OIL CO - El Segundo
Repairs to Naptha Hydro Treater

MARCH 1975

8720
"E"

Regenerator Riser Lines Chevron Plates.

- 8717 U S BORAX-Boron
Repairs to #3 - 5 Mol Wymont Dryer
- 8718 ATLANTIC RICHFIELD CO-Long Beach
"SS Prudhoe Bay" Remove & Replace
Oceanite in Port & Starboard Boiler.
- 8719 PACIFIC SMELTING CO - Long Beach
Repair Muffle Furnace.
- 8720 ATLANTIC RICHFIELD CO-Wilm
Refractory repairs in FCC Unit
"A" Butter Cyclones "B" Butter 1st & 2nd Stages
"C" Reactor Stand Pipe
"D" Misc repairs reactor cyclone & Plenum
- 8721 US BORAX & CHEMICAL-Boron
Minor REPAIRS TO #2AB FURNACE-Plant 5.
- 8722 SOULE STEEL - Long Beach
Repairs to Reheat Furnace.
- ~~8723 ECLOFF & GRAPER - Santa Fe Springs~~ *cancelled 5/75*
~~Install Lining in Drop Bottom Oven, Labor only.~~
- 8724 FOSTER WHEELER ENERGY CORP
UNITED FABRICATORS - Santa Fe Springs
Install Refractory Lining in Stack.
- 8725 TEVAL CORP
US NAVAL STATION, PEARL HARBOR
REFRACTORY LININGS SMOKE ABATEMENT
FACILITIES:

MARCH 1975

- 8726 GLASS CONTAINERS - Los Angeles
Repair #1 Furnace in Shop 11.
- 8727 GARRETT RESEARCH & DEVELOPMENT
La Verne
Refractory Lined Retort
"A" Dryout Retort
- 8728 PRECISION STAINLESS PRODUCTS
Bell Gardens (Work done at Carson yard)
Repair the Furnace Hood Horn Press.
- 8729 MacDONNELL DOUGLAS-Huntington Beach
Minor Repairs to Lindberg Knapp & Pacific
Scientific Furnace.
- 8730 FOSTER WHEELER CO
SHELL OIL - Wilm.
Design and Supply six (6) Aux. Burners
- 8731 FOSTER WHEELER CO
SHELL OIL - Wilm.
Design and Supply two (2) Inline Burner Mixers
- 8732 MOBIL OIL CO - Torrance
Nec. Repairs to Orifice on Cat Cracker.
- 8733 COMBUSTION ENGINEERING - Orange
Package Boiler No. 6
- 8734 GREAT LAKES CARBON-Wilm
Repairs to #2 Kiln
- 8735 WARCO - Paramount
Install Lining in two (2) Concrete Pits.

MARCH 1975

8736	TEXACO INC - Wilm. Nec. Repairs to HF300 Heater.
8737	US BORAX & CHEM - Boron Minor Repair to #3AB Furnace-Plant 5
8738	N L INDUSTRIES - LA Repairs to Downcomers
8739	US BORAX & CHEM - Boron Major Repairs to #5AB Furnace-Plant 5
8740	ATLANTIC RICHFIELD CO "SS Atlantic Endeavor" Nec Repairs to Port Boiler.
8741	STANDARD OIL CO - El Segundo Repairs to 501B Coker.
8742	JORGENSEN STEEL - LA Remove & replace floor complete on #5 Furnace.
8743	TEXACO INC - Long Beach Repairs to H-301 Reaction Furnace
8744	PACIFIC FAR EAST LINES - San Pedro "SS Hawaiian Bear" Nec Repairs to Starboard Boiler.
8745	C F BRAUN STANDARD OIL CO - El Segundo Labor only to install Lining in Flaregas Ground Flare
"A"	Furnish Extra Material

MARCH

- 8746 J T THORPE & SON - BECHTEL/
STANDARD OIL CO - Richmond
Dryout of Reactors
- 8747 EHRHART DIV OF PROCON
U S BORAX - Wilmington
Construct one Salt Cake Dryer
- 8748 STANDARD OIL CO - El Segundo
Nec repairs to Boiler No. 35
- 8749 STANDARD OIL CO - El Segundo
Repairs to Stack Gas Heater Sulfur
Acid Plant 10 - Unit 107
- 8750 UNION OIL CO - Wilm
Refractory Repairs to B101, B102, B103
Heaters - Unit 89.

APRIL

- 8751 HENDY INTERNATIONAL
SS Lompoc - San Pedro
Construct Starboard Boiler
- 8752 PROCTER & GAMBLE - Long Beach
Nec Repairs to Reformer
- 8753 MARTIN MARIETTA CARBON - Carson
Repair Bullnose on Rotary Kiln
- 8754 BIRD & SON OF MASS: - Wilm
Modify and repair refractory piping system
for 5MM btu/hr Asphalt Heater
- 8755 UNION OIL CO - Wilm
Refractory repairs B201, B202, B203, & B204
Heaters Unit 120

APRIL

8756	PACIFIC SMELTING - Torrance Repair #3 Muffle Furnace
8757	PARSON-JURDEN - Sar Cheshmeh-Iran Supply Burners and Supports.
8758	PROCTER & GAMBLE - Long Beach Nec Repairs to #2 Boiler
8759	US BORAX & CHEM - Boron Minor Repairs to #5 Boiler
8760	STAUFFER CHEMICAL - Dominguez Acid Brick Lining to Pit
8761	GREAT LAKES CARBON - Wilm Repair #4 Kiln
8762	ALCOA - Vernon Repairs to #1 Furnace
8763	GREAT LAKES CARBON - Wilm Repair #1 Kiln
8764	BETHLEHEM SHIPYARDS - San Pedro SS Chevron - Calif Repairs to Port Boiler
8765	STANDARD OIL CO - El Segundo Nec Repairs to Boiler #36
8766	MARTIN MARIETTA ALUM-Torr Nec Repairs to #1 Furnace

APRIL

- 8767 STANDARD OIL CO - El Segundo
Nec Repairs to the Coker
- 8768 RALPH M PARSONS
ECOL-Garyville, Louisiana
Design & Supply Thermal Oxidizer
- 8769 HOLMES & NARVER
FILTROL - Vernon
Install Lining in Upper Section of
Peabody Air Heater
"A" Repairs to Lower Section of Peabody
Air Heater
- 8770 M W KELLOGG - Paramount
Nec Repairs to Bending Furnace
- 8771 EARLE M JORGENSEN - LA
Furnish Five Damper Assemblies & NAM Furnace
Pressure Systems, Press Furn, #1&3 thru 6
- 8772 PACIFIC SMELTING CO - Torrance
Repair #5 Furnace
- 8773 PHELPS DODGE TUBE - LA
Nec Repairs to #682 Aluminum Furnace
- 8774 VISTA METALS - Fontana
Repair Arch in Sweat Furnace Holding Unit
- 8775 HARBOR BOAT BUILDING-Terminal Island
USS Hollister
Nec Repairs to Boilers 1,2,3 and 4

APRIL

8776 HUGHES RESEARCH LABORATORIES
Malibu - Repairs to Ajax Boiler

8777 SHELL OIL CO - Dominguez
Repairs to Heater #24

"A" Repairs to Heater #35

"B" Repairs to Heater #18

8778 UNION OIL CO - Carson Yard
Install AA22 in Flare Stack

8779 VALLEY NITROGEN - El Centro
Nec Repairs to Hydrogen Furnace

8780 C F BRAUN

COLLIER CARBON & CHEMICAL
Kenai-Alaska

Furnish & Install Refractory Linings in
Secondary Reformer and Waste Heat Boiler

"A" Furnish and Install Refractory Lining in
Transfer Line at Anacortes, Wash.

"B" Repair End of 1 Hydrogen Transfer Line 3/77

"C" Misc repairs to primary reformer & start-up heater 7/77

"D" Lost and Standby Time "E" Fireproof Vessel Skirt

8781 STANDARD OIL CO - El Segundo
Necessary Repairs to #33 Boiler

8782 ATLANTIC RICHFIELD-Long Beach
SS Atlantic Endeavot
Repairs to Port Boiler

8783 MONSANTO CHEMICAL - Long Beach
Repairs to #1 Acid Plant

APRIL

- 8784 BETHLEHEM SHIPYARDS-Terminal Is.
SS Wyoming
Repairs to Port & Starboard Boilers
- 8785 WESTER NUCLEAR
DIV ASSOCIATED PIPING & ENGINEERING
POWERINE OIL CO - LA
Install AA22 Lining in Reactor Riser Lining
- 8786 HENDY INTERNATIONAL - San Pedro
SS Lompoc
Nec Repairs to Port Boiler
- 8787 MONSANTO CHEMICAL - Long Beach
Nec Repairs to Calciner
- 8788 MARTIN MARIETTA CARBON - Carson
Repairs to Kiln

MAY

- 8789 STAUFFER CHEMICAL - Dominguez
Repairs to Foster Wheeler Boiler
- 8790 STANDARD OIL CO - Pacoima
Temporary Repair on Heater
- 8791 MARTIN MARIETTA ALUM - Torrance
Design & Supply Flame Supervisory Panel
- 8792 BETHLEHEM SHIPYARD
USS Glacier
Repairs to Starboard Boiler

"F" Repairs & Sandblast Dip Legs of Reactor
"G" Repairs to C-9 Line

MAY

- 8793 PACIFIC PUMP DIV°
DRESSER INDUSTRIES INC
Huntington Park - Replace Burner
Cone Insulation
- 8794 H KRAMER CO - El Segundo
Nec Repairs to #1 Reverb
"A" Nec Repairs to #1 Rotary
- 8795 RUSSELL, BURDSAL & WARD - LA
Repairs to Trenches Surrounding Pickling
Line.
"A" Repairs to Neutralizing Pit
"B" Demolition of Concrete Tanks & Repair of
Concrete Pad.
- 8796 US BORAX & CHEMICAL - Boron
Major Refractory Repairs to #2RA Furnace
Plant RA
- 8797 US BORAX & CHEMICAL - Boron
Refractory Repairs to #3 Air Dryer - Plant 4
- 8798 VISTA METALS - Fontana
Repairs to Holding Furnace.
- 8799 TEXACO - Wilmington
Repairs to Reactor
"A" Repairs to Regenerator
"B" Repairs to Regenerator Cyclone
"C" Repairs to C22 Lines
"D" Repairs to FCC Unit Water Seal Tank
"E" Repairs to C8 Line
- 8800 AEROJET MFG LTD - Fullerton
Design & Construct Stress Relieving
Furnace 24' x 24'
- 8801 O'CONNOR ENGINEERING LABS
Carson Yd. - Furnish & Install Refractory
Lining in Experimental Coal Gasification
Furnace.
"A" Welding of Steel Plates

MAY

- 8802 UNION OIL CO - Carson Yard
 Install AA22 in Stack
- 8803 GENERAL WELDING - Alhambra
 Reline Door in Holden Pacific Furnace
- 8804 UNION OIL CO - Wilmington
 Repairs to the B202 Heater and E103
 Exchanger at Unit 120
- 8805 MARTIN MARIETTA CARBON - Carson
 Repairs to Feed End on Kiln
- 8806 M.G.R.S.
 SS Catalina
 Nec Repairs to Boilers #1, 2, 3, & 4
- 8807 PORT WELDING/EVVON NEWARK
 Long Beach
 Nec Repairs to Boiler
- 8808 DELCO REMY - Anaheim
 Remove & Repalce Floor of Barton Pot
- 8809 BETHLEHEM SHIPYARD-Term. Is.
 SS Sea Chemist
 Nec Repairs to Port & Starboard Boilers
- 8810 GREAT LAKES CARBON-Wilm
 Nec Repairs to #4 Kiln
- 8811 GREAT LAKES CARBON
 Port Arthur, Texas
 Design & Supply Water Cooled Damper for
 #2 Kiln
"A" Start-Up Service on Water Cooled Damper

May

- 8812 US ELECTRIC MOTORS - LA
Nec Repairs Annealing Furnace
- 8813 WESTERN AIR CONDITIONING-Carson Yd.
Install Castable Insulation in Panels for
the USS Hollister.
- 8814 BETHLEHEM SHIPYARDS-Term. Is.
SS Mobil Oil
Nec Repairs to Boiler
- 8815 US BORAX & CHEMICAL-Boron
Repair Complete Front Wall #1 Boiler
- 8816 PROCTOR & GAMBLE-Long Beach
Nec Repairs to the Peabody Furnace
- 8817 US BORAX & CHEMICAL-Boron
Repairs to #1 Wyssmont Dryer in
Plant #4.
- 8818 FOSTER WHEELER
STANDARD OIL/EI Segundo
"A" Intermediate Heater 878 Convection
Section Wall Repairs
"A" "B" Intermediate Heater 878 Covection
Section Wall Repairs
"B" Repairs to Bottom Section
- 8819 ATLANTIC RICHFIELD-Carson
Repairs to the Corbels Convection
Section of Coker

May

- 8820 US BORAX & CHEMICAL-Boron
Major Repairs to #1AB Furnace-Plant 5
- 8821 GREAT LAKES CARBON-Wilm
Furnish & Install Refractories & Support
Steel to Provide Cooler Gas Inlets
Settling Chamber - #1 Kiln
"A" Same - #2 Kiln
"B" Same - #3 Kiln
"C" Same - #4 Kiln
- 8822 US BORAX & CHEMICAL-Boron
Minor Repairs to #2AB Furnace-Plant 5
- 8823 GREAT LAKES CARBON-Wilm
Install Refractories in #3 Kiln Baghouse
Addition
- 8824 STAUFFER CHEMICAL-Dominguez
Nec Repairs to Hot Gas Flue Ducts
- 8825 US BORAX & CHEMICAL-Boron
Minor Repairs to #3 Furnace - Plant 5
- 8826 GREAT LAKES CARBON-Wilm
#3 Kiln Modification.
- 8827 INTERPACE - LA
Misc. Repairs
- 8828 TODD SHIPYARDS-San Pedro
Atlantic Trader
Repairs to Port & Starboard Boilers

May

- 8829 STAUFFER CHEMICAL CO-Oxnard
Nec Repairs to Air Dryer
- 8830 ATLANTIC RICHFIELD-Carson
Nec Repairs to CO Duct
- 8831 GULF OIL CO-Santa Fe Springs
Nec Repairs to HH-1
~~"A" Install Burner in Asphalt Heater~~ *cancelled*
- 8832 HUNTER ENGINEERING/REYNOLDS METALS
Listerville, Alabama
Furnish Four Burner Systems
- 8833 KAISER CEMENT - Cushenbury
Install 20' of Lining - Kiln #3
- 8834 Glass Containers - LA
Repairs to Forehearth
- 8835 STAUFFER CHEMICAL-Dominguez
Install brick air defector in burner throat
of sulfur burner
- 8836 APEX SMELTING - Long Beach
To install tapout block
- 8837 CONTINENTAL CAN CO - LA
Repair of Ross Heat Exchanger Line PC10
- 8838 SHELL OIL CO-Wilmington
Nec repairs to Coker Flasher Heaters

MAY

8839

RUCKER SCHAFFER-Brea
Heat Treating Cylindrical Furnace

8840

PACIFIC SMELTING-Torrance
Nec repairs to A-274 Centered Reverb
Holding Section

JUNE

8841

GULF OIL CORP-Terminal Island
Repairs to Burner Seal of Stationary Boiler

8842

US BORAX & CHEM. CORP.-Boron
Minor Repairs #7 Furnace - Plant 5

8843

MONSANTO CHEMICAL CO-Long Beach
Repairs to North Calciner Head

8844

GLASS CONTAINERS CORP-Los Angeles
Repair Forehearth of No. 1 Furnace-Shop 13

8845

TOSCO PETRO-Bakersfield

Repair #6 Boiler

"A"

Repair #5 Boiler

8846

SHELL OIL CO-Watson
Furnish Labor & Scaffolding for Coke Chamber

8847

SHELL OIL CO-Watson
Furnish Labor & Staging for 2 Chambers

8848

STANDARD OIL CO-El Segundo
Furnish Labor & Mat'l to Point Up Refractory
in Rheniformer Furnaces & ARP Furnaces

JUNE

8849	US BORAX & CHEM-Boron
"A"	Major Repairs to ABA Furnace-Plant 26
"B"	Major Repairs to ABA Doghouse
	Additional work ABA Furnace
8850	GREAT LAKES CARBON-Wilm
	Replace 11' Kiln Lining #2 Kiln
8851	ROSE COOPERAGE-Montebello
	Necessary Repairs to Combustion Chambers
8852	STANDARD OIL CO-EI Segundo
	Nec Repairs to the S202, 205 & 207
	Furnaces, Pox Plant
8853	TEXACO INC Long Beach
	Nec Repairs F-603 Incinerator, H601 Boiler
8854	STAUFFER CHEMICAL-Dominguez
	Repairs to #2 Converter
8855	STAUFFER CHEMICAL-Dominguez
	Plant #1 Install Two Insulating Brick Doors
8856	GENERAL ELECTRIC-Ontario
	Supply H-W Refractories for 1976
	Annual Furnace Repair
8857	POWERINE OIL CO-Santa Fe Springs
	Repairs to Orifice on Cat Cracker
8858	BETHLEHEM SHIPYARDS-Term. Is.
	SS Montana - Repairs to the Port
	and Starboard Boilers.

JUNE

- 8859 APEX SMELTING-Long Beach
Labor only to Tear Out Floor of L1 Furnace.
- 8860 GREAT LAKES CARBON-Wilm
Nec Repairs to #1 Kiln
- 8861 EHRHART PROCON
DOUGLAS OIL CO-Paramount
Install 4 sets of Burner Tile in Oil Heater
- 8862 TEXACO-Wilm
Nec Repairs to Heaters H1 & H2
- 8863 CALIFORNIA METAL ENAMELING
Nec Repairs to a Cont_A Furnace
4005
- 8864 ALCAN ALUMINUM CO-Riverside
Nec Repairs to #65 Furnace
- 8865 STAUFFER CHEMICAL-Dominguez
Nec Repairs to Boiler
- 8866 PROCTOR & GAMBLE-Long Beach
Repair Peabody Furnace
- 8867 PACIFIC SMELTING-Torrance
Repair #5 Muffle Furnace
- 8868 CONTINENTAL CAN COMPANY
Pittsburg, Ca.
~~Design & Install 10,000 scfm Heat Exchanger~~
*Replace 16,000 SCFM Heat Exchanger
(originally installed on job 4540)*

JUNE

- 8869 HUGHES RESEARCH LAB-Malibu
Repair Boiler
- 8870 SHELL OIL COMPANY-Dominguez
Repair Boiler #9
- 8871 MARTIN MARIETTA ALUM
Torrance (Los Angeles)
Rebrick both ends of GE Furnace
- 8872 LE VER BROTHERS-Los Angeles
Repairs to the Gurgler & Dowtherm Furnace
- 8873 TODD SHIPYARDS-San Pedro
SS Santa Maria
Repairs to Port & Starboard Boilers.
- ~~8874 BARRINGTON-MOBAR INC - Torrance~~
~~Repair Floor in all furnace~~ *cancelled 1/22/76*
- 8875 H. KRAMER-El Segundo
Repairs to #3 Furnace
- 8876 VALLEY NITROGEN-El Centro
Labor & Mat'l to Repair Erie City Boiler

JULY

- 8877 PHELPS DODGE-LA
Annual Shutdown Repairs

JULY

- 8878 ~~VISTA METALS-Fontana~~
Replace #2 Furnace Door Sill Jambs &
Lintel. *Cancelled 7/75*
- 8879 CELOTEX-LA
Nec Repairs to #1 & #2 Tubular Still &
#1,2,3,4,5,6, & 7 Kettles.
"A" Repairs to Boiler
- 8880 TODD SHIPYARDS - SS Colorado
Repair Ports & Starboard Boilers.
- 8881 RUSSELL, BURDSALL & WARD-LA
Furnish new Acid Brick Lined Pickling Tank
"A" Install Acid Proof Protection on Concrete
Pad & Trenches.
"B" Install Brick Cap on Rinse Tank
- 8882 SOUTHERN CALIF EDISON CO
GARDEN STATE PAPER CO - Pomona
Nec Repairs to Foster Wheeler Waste
Heat Boiler.
- 8883 MOBIL OIL CO-Torrance
Repairs to CO Boiler
- 8884 KAISER FABRICATING-Fontana
Nec Repairs to 20 x 20 Annealing Furnace
- 8885 FLINTKOTE CO
US LIME DIVISION-Nelson, Az.
Repairs to Lime Kiln
- 8886 US BORAX-Boron
Minor Repairs to #3AB Furnace-Plant 5
- 8887 APEX SMELTING-Long Beach
Clear Bottom of L3 Furnace.

JULY

8892
"E"

Cover Wells of Diecast Furnace

- 8888 HUTCHINSON & SON-Carson Yard
Repair Firebox

- 8889 US BORAX-Boron
Labor to Install Refractory Lining in #4 Air
Mixing Chamber

- 8890 W R GRACE CO-South Gate
Repairs to #1,2,3 Dryers
"A" Misc Repairs in Stacks & on Brick Walls.

- 8891 US BORAX-Boron
Rebuild 1 Forehearth

- 8892 GENERAL ELECTRIC-Ontario
Repairs to A & M Reverb Furnace.
"A" Repairs to Die Cast Furnace & Sweat Furnace.
"B" Modifications to Die Cast Furnace
"C" Nec Repairs to Exalene Furnace
"D" Repairs to Calrod Furnace 8/75
8893 ALCOA-Vernon
Labor only to Rebuild Heat Treat Furnace.
"A" Furnish Matl & Labor to Install Brick Lining
in Door Only.

- 8894 COLLIER CARBON & CHEMICAL-Brea
Nec Repairs to Burner Boxes of the
Hydrogen Reformer

- 8895 NL INDUSTRIES-Rawley, Utah
Furnish Damper Assembly

- 8896 GREAT LAKES CARBON-Wilm
Install Bulk Nead in Flue #2 Kiln

- 8897 STANDARD OIL CO-EI Segundo
Nec Repairs to Boiler #38

- 8898 TOSCO PETRO - Bakersfield
Nec Repairs to #7 Boiler

JULY

8899 GREAT LAKES CARBON-Wilm
Oxygen Sampling in No. 1 Kiln Breeching.

8900 W R GRACE-South Gate
Calcliner Repairs.

8901 KAISER STEEL-Fontana
Design & Construct Mine Roof Bolt Furnace
"A" Furnish Chain Conveyor & Controls

8902 PATHWAY BELLOWS-Carson Yard
Install AA22 in Two Vessels

8903 STEEL CASTING-LA
Repair #3 & #4 Furnaces

8904 ETIBANK-Ankara, Turkey
Design and Supply Borax Melting Furnace
"A" Spare Parts

8905 PACIFIC SMELTING-Torrance
Nec Repairs to Rotary Furnace

8906 ATLANTIC RICHFIELD-MARINE DIVISION
Long Beach - SS Atlantic Endeavor
Repairs to Port Boiler

8907 TEXACO-Wilmington
Repair No. Curtain Wall #1 Heater at #3
Crude Unit. Repair Roof in H1 and H2 Heaters
at HTU #3 Unit.

8908 UNION OIL CO. Wilmington.
Refractory Repair B201 Heater, Unit 90
"A" Refractory Repair B202 Heater, Unit 90
~~"B" Refractory Repair B203 Heater Unit 90~~ cancelled
8/75

JULY

- 8909 GREAT LAKES CARBON-Wilm 7/75
Repair #3 Stack, #3 Settling Chamber,
#4 Settling Chamber & Windows in Shell.
- 8910 UNION OIL CO-Wilm
Nec Repairs - Unit 138
- 8911 H KRAMER-EI Segundo
Reline #2 Rotary Furnace
- 8912 VISTA METALS-Fontana
Repair Thermocouple Well
- 8913 SHELL CHEMICAL CO- Wilm
Acid Brick Lining on Stripper Area Floor
"A " Additional Repair Pump 274
- 8914 ASSOCIATED PIPING & ENGR CORP/
POWERINE OIL CO - Compton
Install AA22 Lining in Expansion Joint.
- 8915 APEX SMELTING - Long Beach
Clean Out L-2 Furnace
- 8916 STANDARD OIL CO-EI Segundo
Furnish Labor & Material to Remove
and Replace 200 Sq Ft of Chrome Cast.
- 8917 GULF OIL CO-Santa Fe Springs
Nec Repairs to #1 Heater.
- 8918 PHILADELPHIA QUARTZ-South Gate
Repairs to Silicate Furnace.

JULY

- 8919 COLLIER CARBON & CHEMICAL-Santa Maria
Repairs to Preheater System.
- 8920 TODD SHIPYARDS-San Pedro
USS San Bernardino
Repair 1A & 1B Boilers

AUGUST-1975

- 8921 DELCO REMY-Anaheim
Repair the Lead Reverb Furnace
- 8922 SHELL OIL CO-Dominguez
Nec Repairs to Boiler No. 1
- 8923 REICHOLD CHEMICAL INC
(KAISER GLASS FIBERS)
Irwindale
Nec Repairs to No. 2 Furnace
- 8924 TUTOR-MYERS CO/US NAVAL SHIPYARDS
Long Beach - Acid Brick Lining for Tank
#14 in Plating Facility
- 8925 ALCAN - Riverside
Repairs to No. 66 Furnace
- 8926 JELCO INC/Salt Lake City, Utah
Furnish & Install Refractory Lining in
KTI Heater
- "A" Repairs to Heater at Anacortes, Wash.
- 8927 GARRETT RESEARCH & DEVELOPMENT
La Verne - Supply one 20 scfm Thermal
Oxidizer

AUGUST

8928 ALCOA - Vernon
Labor only to Repair #3 Furnace
"A" Labor only - #2 Furnace

8929 TOSCO PETRO-Bakersfield
Nec Repairs #8 Boiler

8930 JAMES E HOAGLAND/CALIFORNIA PORTLAND
Majave - Modification to Firing Hoods
1 thru 5 for Coal Firing System

8931 GREAT LAKES CARBON-Wilmington
Nec Repairs to #3 Kiln + *settling chamber*
"A" Additional Work to Repair #3

8932 TEXACO INC - Wilm - Nec Repairs to
Boilers 1,2, & 3, Boiler House

8933 GENERAL ELECTRIC - Ontario
Supply Doors for Die Cast and Sweat Furnace.

8934 KOPPERS CO - Fontana
Nec Repairs to Nathalene Heater

8935 US NAVY-USS CORAL SEA
Terminal Island - Rebricking Boilers
1A, 1C, 2A, 2B, 3A, 3C, 4A & 4C

8936 FOSTER WHEELER ENERGY CORP
AMOCO CHEMICAL
UNITED FABRICATORS
Santa Fe Springs - Refractory Lining
Hot Oil Heater

8937 PACIFIC SMELTING-Torrance
Repairs to #1 Muffler Furnace
"A" Repairs to A-275 Riser
"B" Repairs to A-276 Riser Unit

AUGUST

8938 CALIFORNIA SHIPYARD-Long Beach
USCG Burton Island
Repair #1 Boiler
"A" Repairs #2 Boiler

8939 ARIZONA PORTLAND CEMENT
Rillito, Arizona
Repairs to #4 Kiln Inlet Housing
"A" Repairs to #4 Kiln Firing Hood

8940 US BORAX - Boron
Furnish Spare Top Duct for R46 Dryer
"A" Spare Refractory Lining

8941 C F BRAUN
STANDARD OIL-El Segundo
Repairs to Stack Sections

~~8942 U S BORAX-Boron~~ *Cancelled 8/15*
~~Minor Repairs to #1AB Furnace~~

8943 GREAT LAKES CARBON-Wilm
Repairs to #1 & #4 Kiln

8944 U S BORAX-Boron
Repairs to #4AB Furnace

8945 U S BORAX-Wilmington
Repairs to #2 Boiler

8946 J T THORPE & SON/PHILLIPS PETROLEUM-
Martinez - Refractory Dryout for CO Duct

8947 ATLANTIC RICHFIELD-Carson
Nec Repairs to F1 Coker

AUGUST 1975

- 8948 UNION OIL CO-Wilm
Nec Repairs to Heater D-203 Unit 90
- 8949 STANDARD OIL-El Segundo
Acoustically Insulate Burner Plenums for
Platformer Unit
- 8950 US BORAX & CHEMICAL-Boron
Minor Repairs to #1AB Furnace Plant 5
- 8951 UNION OIL CO-Wilm
Nec Repairs to #3 Boiler
- 8952 STAUFFER CHEMICAL-Dominguez
Modifications to Plant 2 Drying Tower
- 8953 CLEVELAND ERECTORS/TEXACO
Wilm-Repair HC100 Heater
- 8954 SHELL OIL CO-Wilm
Install AA-22 in Lower Section of
Secondary Cyclones
"A" Thermally Dryout AA-22
- 8955 FOSTER WHEELER ENERGY CORP/
SHELL OIL CO - Dominguez
Fireproofing for Vessel Skirts & Columns
- 8956 MARTIN MARIETTA ALUMINUM
Torrance - Tear out #9 Furnace
"A" Replace #9 Furnace

AUGUST 1975

8957 US BORAX & CHEMICAL - Boron
Minor Repairs to #3 Boiler

8958 WESTERN GALVANIZING-Santa Fe Springs
Fabricate & Install Galvanizing Furnace

"A" Install new refractory pad under the kettle.

"B" Overtime reqd to speed up schedule

"C" Damage Repairs

8959 POWERINE OIL CO-Santa Fe Springs
Repair Orifice Chamber.

8960 BETHLEHEM SHIP BUILDING-Term. Is.
USS Monticello

Repairs to Boilers 1 & 2

SEPTEMBER 1975

8961 SOULE STEEL - Long Beach
Nec Repairs to Reneat Furnace

8962 ALCAN - Riverside
Nec Repairs to #8 Furnace

8963 DOUGLAS OIL CO - Paramount
Repairs to Heater

8964 MARTIN MARIETTA CARBON-Carson
Nec Repairs to Settling Chamber

8965 EARLE M JORGENSEN-LA
Repairs to #6 Furnace

8966 STAUFFER CHEMICAL-Dominguez
Refractory lined Duct Work Waste Heat
Boiler Installation Plant 1 & 2

"A"-Backcharge Interpace cutting anchor brick

"B" Remove&Replace castable around super heater tubes

in waste heater boiler

SEPTEMBER 1975

- 8967 UNION OIL CO-Wilm
Nec Repairs to Unit 138 of Sulfur Unit
- 8968 TEXACO INC - Wilm
Nec Repairs to HTU #2 Unit #SD101 Heater
- 8969 STANDARD OIL CO-El Segundo
Repairs to #7 Boiler
- 8970 U S BORAX & CHEMICAL-Boron
Minor Repairs to #2 Boiler
- 8971 SHELL OIL CO-Watson
Nec Repairs to Heater #23 Unit #5
- 8972 UNION OIL CO-Wilm
Remove & Replace Burners in B-1 & B-2
Heaters at Unit #91
- 8973 GULF OIL CO-Santa Fe Springs
Install Burner Tile in Heater
- 8974 PACIFIC SMELTING- Torrance
Nec Repairs to Kiln
- 8975 U S BORAX & CHEMICAL-Boron
Minor Repairs to #6 Boiler
- 8976 JORGENSEN STEEL-LA
Nec Repairs to Aluminum Furnace
- 8977 U S BORAX & CHEMICAL-Boron
Minor Repairs to #3 Air Heater

SEPTEMBER 1975

- 8978 U S BORAX & CHEMICAL-Boron
Major Repairs to #2AB Furnace
- 8979 H KRAMER-EI Segundo
Repairs to #3 Reverb
- 8980 ALLIED CHEMICAL-Carson Yd
Pour Burner
- 8981 MONSANTO CHEMICAL-Long Beach
Reline Carbon Ring #3 Acid Burner
- 8982 Great Lakes Carbon-Wilm
Nec Repairs to #3 Kiln
- 8983 CALIFORNIA PORTLAND CEMENT-Mojave
Repairs to #5 Kiln Hood & Cooler
- 8984 UNION OIL CO-Wilm
Repair Units 26, 27, 28 & Nec Repairs to
ISO Flow Furnace B101 Fireproof Vessel Skirt.

OCTOBER 1975

- 8985 CHAPLIN OIL CO-Wilm
Nec Repairs to Units
- 8986 SELAS CORP OF AMERICA
STANDARD OIL CO-EI Segundo
Repairs to Selas Heaters
- 8987 US BORAX & CHEM - Boron
Minor Repairs to #3AB Furnace - Plant 5

OCTOBER 1975

- 8988 US BORAX & CHEMICAL - Boron
Two 3" Forehearths
- 8989 US BORAX & CHEMICAL - Boron
Minor Repairs to #1AB Furnace Plant 5
- 8990 SHELL OIL CO-Dominguez
Remove & Install Burner Tile in Heater #18
- 8991 APEX SMELTING - Long Beach
Repairs to #6 Sweat Furnace
- 8992 JORGENSEN STEEL - LA
Furnish Labor & Matl to Install Detrick Roof
& Curtain Wall & Repair Jambs to #5 Forge
- 8993 AMERICAN CYANAMID - Azusa
Drive Shims in Kiln
- 8994 PHELPS DODGE TUBE - LA
Nec Repairs to Rotary Furnace
- 8995 PARSONS-JURDEN INTERNATIONAL
SARCHESHMEH COPPER MINING-Iran
Supply Two Sets of Six Burners each
for Copper Reverberatory Furnace.
"A" Supply 3 Anode and Holding Furnace Burners.
- 8996 MONSANTO CHEMICAL CO-Long Beach
Nec Repairs to #2 Acid Burner
- 8997 STAUFFER CHEMICAL-Henderson, Nev.
Point up Joints on Vessel S-24
"A" Repairs to Waste Gas Incinerator.

OCTOBER 1975

8998 US BORAX & CHEMICAL-Boron
Repairs to #4 Air Heater Plant 4

8999 CALTUF-Alhambra
Electricians Services to Adjust & Repair

9000

KAISER ALUMINUM & CHEMICAL-Bedford, Ind.
Design & Construct Two 60,000 Lb Aluminum
Melting Furnaces

"A"

Install Lining in Stack - "B" Install 6" Lining of

IRC in Crucible Header Lid - "C" Crucible

Misc work on saw heater. "E"- Extra Warmers.

9001

KAISER CEMENT-Cushenbury

Repairs to Thinsulite Roof in Cooler

9002

SUPERIOR INDUSTRIES - Van Nuys
Burner Tile for McGowan Alum. Furnace

"A"

Repairs to McGowan Alum. Furnace

9003

SUPERIOR INDUSTRIES - Van Nuys
Repairs to Warwick Furnace.

9004

TODD SHIPYARD - San Pedro
USS Coast Guard Glacier
Nec Repairs to Boiler #2

9005

STAUFFER CHEMICAL-Dominguez
Repairs to Plant #2 Drying Tower Pump Tank
Repairs to Plant 2 Sludge Furnace

"A"

9006

MOBIL OIL CO-Torrance
Nec Repairs to CO Boiler

9007

US BORAX & CHEMICAL-Boron
Minor Repairs to #1 Wyssmont Dryer Plant 4

OCTOBER 1975

- 9008 DELCO REMY-Anaheim
Replace Seal Around Suspended Arch
- 9009 NORRIS INDUSTRIES-Vernon
Repairs to Solar Furnace
- 9010 TEXACO-Long Beach
Repairs to F310 Incinerator, H301 Boiler &
F303 Lime Burner
- 9011 MARTIN MARIETTA ALUM-Torrance
Repairs to Combustion Chamber of
Westinghouse Furnace
- 9012 UNION OIL CO-Wilm
Nec Repairs to the B1 Heater & B3 Heater
- 9013 STANDARD OIL CO-EI Segundo
Repair SM Reformer at Isomax Plant
- 9014 US BORAX & CHEM - Boron
Major Repairs to #7AB Furnace Main
Fusing Plant
- "A" Add experimental sloping brick fill on sides,
front & rear for melting 10 mol borax.
- 9015 STAUFFER CHEMICAL-Henderson, Nev
Install Acid Proof Lining in Two Sewer Manholes
- 9016 CARLTON FORGE-Paramount
Nec Repairs to Carbottom Furnace
- 9017 US BORAX & CHEM-Boron
Repairs to #1 Boiler, Steam Plant

OCTOBER 1975

- 9018 CRANES INDUSTRIAL MAINTENANCE CO
ASHLAND CHEMICAL CO
Mojave - ~~at~~ Carson Yard
"A" Install Mulfrax Brick in 3 Pipe Sections
Reline Burner Chamber 1/76
- 9019 US BORAX & CHEMICAL-Boron
Repairs to #6AB Furnace
- 9020 ALCOA-Vernon
Cut Out 2 Holes in Hearth - #8 Furnace
- 9021 GREAT LAKES CARBON-Wilm
Repairs to the Cooler Chute in #1 Kiln
- 9022 INTERPACE-Glendale
Misc Repairs
- 9023 STANDARD OIL CO - El Segundo
Remove & Replace 150 Burner Tile on
Selas Furnace
- 9024 CAL STATE - Northridge
Repairs to the Burner Throat and Wall of the
Broz Boiler
- 9025 US BORAX & CHEM-Boron
Construct Fluid Bed Dryer & Air Heater
Plants 2, 3 & 4
- 9026 REICHHOLD CHEMICAL-Inwindale
"A" Rebuild Glass Fiber Furnace #5
Tear Out Lining

NOVEMBER 1975

- 9027 STANDARD OIL CO-El Segundo
Nec Repairs to F720 Heater & F731 Furnace.
- 9028 CALIFORNIA SHIPYARD - Long Beach
USS Henderson
Repair #4 Boiler
- 9029 CF BRAUN & CO
STANDARD OIL CO - El Segundo
Install Refractory & Burner Tile in Heaters.
- 9030 US BORAX & CHEMICAL-Wilm
Nec Repairs to AB Furnace
- 9031 STANDARD OIL CO-El Segundo
Repairs to Heater 520-B
- 9032 SHELL CHEMICAL CO-Wilm
Nec Repairs to Stripper
- 9033 STAUFFER CHEMICAL-Cold Creek, Alabama
Install Acid Brick Lining in Vessels
- 9034 GULF OIL CO-Santa Fe Springs
Nec Repairs to Quench Steam Generator
- 9035 US BORAX-Boron
Minor Repairs to #6 Boiler
- 9036 PACIFIC SMELTING-Torrance
Repairs to #4 Melter

NOVEMBER 1975

- 9037 GREAT LAKES CARBON-Wilm
Nec Repairs to #3 Kiln
"A" Repairs to Settling Chamber
- 9038 PACIFIC VALVES - Carson Yard
Line AA22 in 2 46" Slidevalve Discs.
- 9039 MARTIN MARIETTA CARBON-Carson
Nec Repairs to Kiln
- 9040 AMERON-Brea
Nec Repairs to Oil Heater
- 9041 UNION OIL CO-Wilm
Nec Repairs at Burners in B-101, 102, 103,
104 & 105 Heaters at Unit 80
- 9042 GULF OIL CO-Santa Fe Springs
Nec Repairs to the VBH1 Heater (Vis Breaker)
- 9043 GREAT LAKES CARBON-Wilm
Repairs to #2 Furnace
- 9044 UNION OIL CO-Wilm
Repairs to Heater B202 Unit 151
- 9045 ATLANTIC RICHFIELD-Carson
Repairs to the 80" CO Boiler Duct
"A" Install AA22 Around Chevron Plate
- 9046 WESTERN AIR CONDITIONING-Carson Yard
Line Four Panels with Castable.

- 9047 CONTINENTAL CAN CO-Pittsburg, Ca. #80
Design & Install Draft Control Sys and
New Incinerator Burner Lines 1 & 2.
- 9048 ALCOA-Vernon
Repairs to #5 Furnace
- 9049 SUPERIOR INDUSTRIES-Van Nuys
Install 3 Tapout Blocks in McGowan Furnace
- 9050 SHELL CHEMICAL-Dominguez
Repairs to Stripper
- 9051 US BORAX-Boron
Repairs to #3 Air Heater - Plant 4
"A" Additional Minor Repairs
- 9052 HALL HEAT TREAT - Paramount
Service Call & Supply Materials
- 9053 ALCOA-Vernon
Nec Repairs to #1 Remelt Furnace
- 9054 STANDARD OIL CO-El Segundo
Nec Repairs to Boiler #33
- 9055 UNION OIL CO-Wilm
Nec Repairs to Unit 38

DECEMBER 1975

- 9056 SHELL OIL CO
Minor Repair Cat Cracker Super Heater
- 9057 KAY BRUNNER - Alhambra
Nec Repairs to 10-D & 11-D
- 9058 SHELL OIL CO-Dominguez
Nec Repairs to Heater 20-A
- 9059 ALCOA-Vernon
Repair #4 Furnace
- 9060 KAISER STEEL-Light Metal Products Div
Fontana - Design & Construct Plate Normalizing
Furnace
Spare Parts
"A"
"B" Plate Preheat System
"C" PLC Program Panel System
- 9061 FLETCHER OIL & REFINERY - Carson
Repairs to #1 Crude Heater Platformer Furnace.
- 9062 SMITH CHEMICAL - Lynwood
Furnish Flame Safety & Temperature
Control Flame
- 9063 ~~CONTINENTAL CAN CO-Hayward, Ga.~~ *cancelled 12/75*
- 9064 US BORAX & CHEMICAL-Boron
Minor Repairs to #4AB-Plant 5
- 9065 COLLIER CARBON & CHEMICAL-Wilmington
Install Acid Brick Lining in New F-102
Drying Tower Pump Tank

DECEMBER - 1975

- 9066 GREFCO-Torrance
Install Lining in Indirect Fire Rotary Calciner.
- 9067 STANDARD OIL CO-El Segundo
Nec Repairs to Heaters F-1021, F-1022
and F-1023
- 9068 US BORAX & CHEMICAL-BORON
Minor Repairs to #5AB Furnace, Plant 5
- 9069 MGF - City of Commerce
Repair Acid Tank
- 9070 GULF OIL CO-Terminal Island
Nec Repairs to Boiler
- 9071 COLLIER CARBON & CHEM-Brea
Repairs to Secondary Re-former
"A" Repairs to Transfer Line
"B" Repairs to Primay Reformer
"C" Repairs to Prill Tower
- 9072 COLLIER CARBON & CHEM-Santa Maria
Repairs to Pyro Scrubber
- 9073 N L INDUSTRIES-Los Angeles
Reline North Blast Furnace & Crucible
"A" Extra Material
- 9074 ALCOA-Vernon
Repairs to #2 Furnace

DECEMBER - 1975

9075 APEX SMELTING-Long Beach
 Repair Furnace #2
 "A" Repair Furnace #3
 "B" Repair Furnace #5
 "C" Repairs to Dryer

9076 MARTIN MARIETTA ALUM-Torrance
 Repairs & Tearout of #8 Furnace - Labor only.
 "A" Labor only to Replace #8

9077 METROPOLITAN STATE HOSPITAL-Norwalk
 Repair #4 Erie City Boiler

9078 Emery Industries-City of Commerce
 Nec Repairs to Pot Steel

9079 WESTERN PETROCHEM SERVICE
 HUNT WESSON FOODS-Fullerton
 Nec Repairs to Reformer Furnace

9080 NISSIN FOODS USA CO INC-Gardena
 Brick New Noodle Fryer

9081 GREAT LAKES CARBON-Rosamond
 Repairs to #1 Incinerator

9082 DOCKSIDE MACHINE
 "Massachusetts Getty"-San Pedro
 Repairs to Port & Starboard Boiler

9083 PHILADELPHIA QUARTZ-South Gate
 Repairs to Silica Furnace

DECEMBER 1975

9084 DOCKSIDE MACHINE & SHIP REPAIR
"SS Zim Hong Kong"
Repair Starboard Boiler

9085 MATSON STEAMSHIP
"SS Hawaiian Monarch-Terminal Is.
Repair Starboard Boiler

~~9086~~ COLLIER CARBON & CHEMICAL
Rodeo, Ca.
Beck Drive for Water Cooled Damper

9087 J T THORPE CO
RALPH M PARSONS
ECOL - Garyville, La.
Furnish & Install Refractory Linings for
Sulfur Recovery Unit.

9088 GREAT LAKES CARBON-Wilm
Repairs to #4 Kiln

9089 US BORAX-Wilm
Nec Repairs to AB Furnace
"A" Time Spent on Extra Concrete Curbing

9090 BROCKWAY GLASS-Pomona
Refractory 1976 Rebuild of Furnace #23, Plant 16
Repairs to existing rider arches

"A"
"B"
"C"
9091 Modification to Invert & Relief Arches
Extra brick cutting.
RUCKER SHAFFER - Brea
Construct & Lining - One 12' Dia Furnace Base

9092 SUPERIOR INDUSTRIES-Van Nuys
Remove existing Lining on 20,000 #
McGowan Furnace.

DECEMBER 1975

- 9093 GREAT LAKES CARBON-Wilm
Repairs to #2 Kiln
- 9094 US BORAX & CHEMICAL-Boron
Minor Repairs to #1AB Furnace, Plant 5
- 9095 US BORAX & CHEMICAL-Boron
Two 3" Forehearths
- 9096 ALCOA - *Wilm*
#1 Furnace -
"A" Repairs to #1 & #4 Furnace
- 9097 STANDARD OIL CO-EI Segundo
Repairs to Sulfur Acid Plant #F107

JANUARY 1976

- 9098 TEXACO INC - Wilm
 Acidbrick Repairs to Truck Loading Rack
 a ?
- 9099 STANDARD OIL CO-EI Segundo
 Repairs to F2 Furnace at Asphalt Plant.
- 9100 ~~US Borax-Boron~~
 Major Repairs to ABA Furnace, Plant 26
 "A" Replace Doghouse
- 9101 KERR McGEE CHEMICAL CO - WEST END
 Nec Repairs to Lime Kiln
- 9102 BETHLEHEM STEEL
 "SS IDAHO"
 Repairs to Port and Starboard Boiler
- 9103 STAUFFER CHEMICAL - Oxnard
 Repair Dryer Firebox
- 9104 UNION OIL CO-Wilm
 Nec Repairs to Unit 35
- 9105 HUNT-WESSON FOODS - Fullerton
 Refractory Repairs to #8 Boiler
- 9106 US BORAX & CHEMICAL-Boron
 Minor Repairs to #3 Air Heater in Plant 4
- 9107 US BORAX-Wilmington
 To replace Burner Tile and Tile &
 Salt Cake Furnace

JANUARY - 1976

- 9108 STANDARD OIL CO-El Segundo
Acoustically Insulate Burner Plenums
- 9109 FIBREBOARD PAPER PRODUCTS-Vernon
Refractory Repairs to #5 Boiler
- 9110 STANDARD OIL CO-El Segundo
Nec Repairs to F301 Furnace at the SNR
Plant
- 9111 CYPRESS TUBING-Torrance
Nec Repairs to Galvanizing Tank
- 9112 HALL HEAT TREAT-Paramount
Nec Repairs to #12 Furnace
- 9113 CALIF OIL PURIFICATION CO (COPCO)
Ventura - Repairs to Hydrogen Reformer
- 9114 AEROJET MFG CO - Fullerton
Repair Small Hood Furnace
- 9115 STAUFFER CHEMICAL CORP-Dominguez
Hot Patch Repair #1 Furnace
- 9116 KAISER STEEL CORP-Fontana
Material only for One Mine Bolt Furnace
- 9117 STANDARD OIL CO-El Segundo
Repairs to Hydrofiner

JANUARY - 1976

- 9118 SELAS CO
DOWNEY GLASS - Commerce
Nec Repairs to Selas Furnace
- 9119 MOBIL COMPANY - Torrance
Erect Scaffold in Hydrogen Unit
- 9120 CASCADE STEEL ROLLING MILLS
S OUTHWEST STEEL DIVISION
Modify Reheat Furnace
"A" Supply & install motorized combustion air valve
& oil atomizers.
- 9121 ALCOA - Vernon
Repair Reheat Furnace
- 9122 MOBIL OIL CO - Torrance
Repair Sulfur Recovery Unit
- 9123 MONSANTO COMPANY - Paramount
Repair #3 Acid Tower Burner
- 9124 US BORAX - Boron
Repairs to #1 Air Heater, Plant 4
- 9125 STAUFFER CHEMICAL - Dominguez
Install Brick in a Sump Drain
- 9126 MH DETRICK CO-Carsen Yard
Oven for Baking Detrick Slide Gate Valve
for Ameron/Tamco
- 9127 INTERPACE - Los Angeles
Repairs to Kiln #19 Extension of Cooling Zone.

JANUARY 1976

- 9128 APEX SMELTING CO-Long Beach
Repairs to L9 Furnace
- 9129 POWERINE OIL CO-Santa Fe Springs
Nec Repairs to LXH3, LXH4 and the 3PH #1,
#2 and #3 Heaters
- 9130 TEXACO INC - Long Beach
Repairs to #2 Rental Boiler at the Sulfur
Plant.
- 9131 UNION OIL CO-Wilmington
Refractory Repairs, Burners in B-101,
B-102A, B-102B, B-103 & B-201
Heaters at Unit 60
- 9132 US BORAX-Boron
Major Repairs to #3AB Furnace - Plant 5
- 9133 BETHLEHEM SHIPYARD-"SS Texaco New
Term. Is - Nec repairs to Jersey"
Port & Starboard Boiler
- 9134 EARLE M JORGENSEN-Seattle
Reconstruction of #H4 Heat Treat Furnace
- 9135 TEXACO INC - Long Beach
Nec Repairs to F703 Incinerator
- 9136 THATCHER GLASS CO - Saugus
Repair #3 Glass Tank
- 9137 HYDRO MECHANICAL CO - Long Beach
Repair #2 Crane Murray Boiler

- 9138 ALCOA - Vernon
Repairs to #5 Furnace
"A" Repair Stack #5 Furnace
- 9139 STANDARD OIL CO - El Segundo
Nec Repairs to F105 & F108 Furnace
- 9140 TRUESDALE LABORATORY/ G. L. Carbon Co
Drill 3" Hole in North End of Duct
of #3 Kiln
- 9141 MOBIL OIL CORP - Torrance
Furnish & Install Refractory Lining
for Flue Gas Ductwork.
- 9142 NATIONAL METALS & STEEL CO
Terminal Island
Repair Furnace
- 9143 ORANGE COUNTY STEEL SALVAGE -
Anaheim - Design & Supply Flame Safety Panel
- 9144 BETHLEHEM SHIPYARD-USS Monticello
Terminal Is. - Repairs to #1 & #2 Boilers
- 9145 H KRAMER & CO -El Segundo
Install New Lining in New 6'-10" ID x 10'
Long Rotary Furnace
- 9146 MARTIN MARIETTA ALUM - Torrance
Repairs to #2 & #3 Furnaces.
- 9147 SOUTHERN CALIF EDISON CO-Redondo Bch
Repairs to #12 Boiler

- 9148 US BORAX-Boron
Minor Repairs to #6AB, Plant 5
- 9149 SUPERIOR INDUSTRIES-Van Nuys
Design & Reconstruct 20,000# Alum. Melter
- 9150 GRUMMAN ECOSYSTEMS-Honolulu, Hawaii
Furnish & Install Refractory Linings for
Two (2) Waipahu Incinerators
Repairs to Bypass Breeching #1 Incinerator
"A"
- 9151 INDUSTRIAL ENGINEERS-Glendale
Acidproof Lining for Export
- 9152 CONTINENTAL CAN CO-Commerce
Repair Heat Exchanger for Horizontal 12,000
scfm Fume Incinerator.
Adjust of Oven Dampers.
"A "
- 9153 DOCKSIDE MACHINE-SS Elizabeth Maersk
San Pedro-Repairs to Boiler
- 9154 HIGGENS BRICK CO-Chino
Nec Repairs to Swindell Dressler Tunnel Kiln
- 9155 PACIFIC SMELTING-Torrance
Repair Stack & Melter
"A"
"B"
"C"
Repair Vapor
Repair Condenser
Repair Dross
- 9156 DRAVO CORP/CHEMICAL PLANT DIV of
STAUFFER CHEMICAL CO-Henerson, Nev.
Furnish & Install Acidbrick Lining in
Chlorine Plant Expansion.

FEBRUARY 1976

9157 STANDARD OIL CO-El Segundo
Repairs to the F-5431 Plant 45 Isomax

9158 MYERS DRUM CO-LA
Repairs to Barrel Kiln

9159 POWERINE OIL-Santa Fe Springs
Repairs to #1 Heater

9160 RALPH M PARSONS
ARAMCO-Saudi Arabia
Supply Engineering to Design Waste Gas Incr.

9161 FLETCHER OIL-Carson
Repair #3 North Boiler

9162 NORRIS INDUSTRIES-LA
Nec Repairs to the Sunbeam Furnace

9163 US BORAX - Boron
Minor Repairs #6 Boiler

9164 H KRAMER & CO-El Segundo
Reline #2 Rotary

9165 BARRINGTON-MOBAR-Torrance
Repairs to Knapp Furnace

9166 STAUFFER CHEMICAL CO-Henderson, Nev.
Furnish & Install Acidbrick Lining in
New Vessel S-24

FEBRUARY 1976

9167 TOSCO PETRO-Bakersfield
Nec Repairs to Selas Heater
"A" Nec Repairs to Heaters #21-H, 17-H, 19-H,
11-H, 12-H

9168 MOBIL OIL CO-Torrance
Gunitite Repairs to FCC Unit

9169 CALIF STEEL TANK CO/AMOCO OIL CO
Salt Lake City, Utah
Repairs to FCC Unit
"A" Repairs to FCC Unit

9170 ALCOA-Vernon
Remove & Replace Ramp & Seal #1 Alum Reverbs & #3 Furnaces
"A" Gunitite Entrance Arch #1 & #3 Furnaces.

9171 BETHLEHEM SHIPYARD-USS Paul Revere
Term. Is. - Repair Boilers 1 & 2.

9172 US BORAX - Boron
Minor Repairs to #6 Boiler

9173 PROCTOR GAMBLE-Long Beach
Repair Reformer

9174 PROCTOR & GAMBLE-Long Beach
Repairs to #3 Boiler

9175 MARTIN MARIETTA CARBON-Carson
Repair Bullnose of Kiln

9176 US BORAX-Boron
Minor Repairs to #4AB Furnace - Plant 5

FEBRUARY 1976

- 9177 ITE IMPERIAL CORP
POWER CIRCUIT BREAKER DIV-Downey
Repair Bell Furnace
- 9178 H KRAMER-El Segundo
Repair #1 Reverb
"A" Free Door on Top of Arch
- 9179 KAYNAR CO-Fullerton
Nec Repairs to Ipsen Furnace
- 9180 US LIME/FLINTKOTE DIV-Nelson, Ariz
Repair to Lime Kiln
- 9181 STANDARD OIL CO-El Segundo
Repair to E301 Sulfur Acid Plant.

MARCH 1976

- 9182 TEXACO-Wilmington - Repairs to "B" Generator.
"A" Repairs to "A" Generator.
- 9183 MARTIN MARIETTA CARBON-Carson
Repairs to Nose Ring in Kiln
- 9184 TEXACO-Wilmington
Repairs to the HCU-HS302 Heater
- 9185 SECHRIST & KELLY CONSTR° CO
STAUFFER CHEMICAL-Dominguez
Furnish & Install Acidbrick Lining on
Deionizer Foundation.
"A" Add additional piers

MARCH

- 9186 GOODYEAR TIRE & RUBBER CO-LA
Repairs to #2 Boiler
- 9187 US BORAX & CHEMICAL-Boron
Repairs to #5AB Furnace, Plant 5
- 9188 US BORAX & CHEMICAL-Boron
Two 3" Forehearths
- 9189 STANDARD OIL CO-El Segundo
Nec Repairs to Plant 4 Cat Reformer,
F410, F420, F430
"A" Repair F440
- 9190 MARTIN MARIETTA CARBON-Carson
Repairs to Duct Leading to Stack
- 9191 GREAT LAKES CARBON-Wilm
Nec Repairs to #2 Kiln Duct
- 9192 NISSIN FOODS-Gardena
Nec Repairs to #3 Noodle Cooker
- 9193 TEXACO INC-Wilm
Replace Four Burner Arches #7 Boiler
- 9194 COLLIER CARBON & CHEMICAL-Brea
Furnish & Install Refractory Lining for
Decomposer & Waste Heat Boiler.

MARCH 1976

9195 UNION OIL CO-Wilm
 Nec Repairs to the #401 Boiler

9196 STANDARD OIL CO-El Segundo
 Fireproof Skirt on C9 Column - Alky Plant

9197 N L INDUSTRIES-Vernon
 Install Refractory Lining in New Settling
 Chamber

9198 CELOTEX-LA
 Repairs to Kettles and Stills

9199 STANDARD OIL CO-El Segundo
 Repairs to #35 Boiler

9200 ATLANTIC RICHFIELD-Wilm
 Replace Refractory Walls & Roof & Burner
 Cone on Petro-Chem Vacuum Feed
 Preheater using IFB Type Walls.
"A" Additional Repairs to Furnace

9201 TAMCO (Ameron)-Etiwanda
 Ladle Dryout Lid

9200 PACIFIC FAR EAST LINES
 "SS Pacific Bear"-San Pedro
 Nec Repairs to Starboard Boiler.

9203 UNION OIL CO-Wilm
 Repair Unit #60 Heaters #102A & 102B

MARCH 1976

- 9204 CYPRUS - Torrance
Nec Repairs to Boiler
- 9205 US BORAX & CHEM-Boron
Minor Repairs to #2AB Furnace-Plant 5
- 9206 AMERICAN PRESIDENT LINES
"SS Pres. Kennedy" - San Pedro
Repairs to Port Boiler
- 9207 NORRIS INDUSTRIES-Vernon
Nec Repairs to Combustion Chambers
#11 Annealing Furnace
"A" Supply Extra Material.
- 9208 SHELL OIL
Patch Refractory in Cat Cracker Slide Valves
- 9209 JORGENSEN STEEL-Los Angeles
Nec Repairs to #7 Hammer Furnace
- 9210 W R GRACE-South Gate
Refractory Repairs to Peabody Heater on
"A" #3 Spray Dryer

APRIL 1976

- 9211 U S BORAX & CHEMICAL-Boron
Repairs to #1Air Heater Plant 3
- 9212 COLLIER CARBON & CHEM-Santa Maria
Install Brick in Top of Stack
"A" Additional Repairs
- 9213 DOUGLAS OIL-Paramount
Refractory Installation D-101 & D-1-2 Converters.

APRIL 1976

9214	INTERPACE-Glendale Misc. Repairs
9215	BETHLEHEM SHIPYARDS-Term. Is. "SS Michigan" - Repairs to Port & Starboard Boilers.
9216	OWENS-ILLINOIS - San Juan Capistrano Repair to Shadow Wall
9217	MOBIL OIL CO-Torrance Design & Construct Dampers for the Flue Gas Line between Regenerator & CO Boiler. "A" Design & Construct Four 4 new Insulated Dampers for the Ductwork Between the CO Boiler and the Precipitator.
9218	US BORAX & CHEM-Boron Repair #1 Air Heater, Plant #3
9219	GREAT LAKES CARBON-Wilm Repairs to #3 & #4 Kilns
9220	FIBERBOARD PAPER PRODUCTS-Vernon Repairs to #4 Boiler
9221	UNION OIL CO-Wilm Install external Insulation on Tank #380
9222	AMERON STEEL-TAMCO DIV° Design & Supply Laddle Preheat Station "A" Design & Supply Tundage Preheater "B" Design & Supply Dryer Station

APRIL

- 9223 CONTINENTAL CAN CO-Hayward
Insulation in Ceiling of Hot Tubesheet
- 9224 PACIFIC SMELTING - Torrance
Repairs to Catenary Arch
- 9225 STAUFFER CHEMICAL - Dominguez
Repairs to the Bigelow Tube Return Boiler
- 9226 GREAT LAKES CARBON-Wilmington
Repairs to #4 Kiln
- 9227 UNION OIL CO - Wilmington
Necessary Repairs to the B101 - Unit 89
- 9228 GREAT LAKES CARBON - Wilm
Repairs to #2 Kiln
- 9229 FOSTER WHEELER/UNITED FABRICATORS
Santa Fe Springs
Refractory Linings in Convection Section
Ducts for Shipment to Augusta, Kansas
- 9230 STANDARD OIL - El Segundo-Carson
Necessary Repairs to F-301-B Heater at
#2 Crude Unit.
- 9231 STANDARD OIL - El Segundo
Nec Repairs to F-302 Hydrofiner Heater
- 9232 US BORAX - Boron
Minor Repairs to #1 ABA Furn - Plant 5

APRIL

- 9233 AMERICAN PRESIDENT LINES
SS Pres. Roosevelt - Repairs to
Port Boilers
- 9234 STAUFFER CHEMICAL - Dominguez
Repairs to Tank 31 Pump Base Tank
#200 Pump Base
- 9235 US BORAX - Wilmington
Repairs to #3 Boiler
- 9236 STANDARD OIL - El Segundo
Nec Repairs to Boiler #36
- 9237 KERR GLASS - Santa Ana
Nec Repairs to Glass Furnace
- 9238 THATCHER GLASS - Saugus
Insulate Walls of Regenerator of #3 Furnace.
"A" Insulate Walls of Regenerator #1 Furnace.
- 9239 CAL STATE - Northridge
Nec Repairs to #1 Boiler.
- 9240 HALL HEAT TREATING - Paramount
Remove & Replace Steel Portion of
South Jamb & Support Column
- 9241 UNION OIL CO - Wilm
Install AA22 in Regenerator Flue Gas Line
Dryout
"A"

APRIL

9242

DOUGLAS OIL - Paramount
Repair around Access Door Transition to
Stack of Incinerator.

"A"

Nec Repairs to Install New Burner in
Incinerator.

"B"

H-304 Heater

"C"

H-302 Heater

9243

INTERPACE - LA
Repairs to Tile Kiln #12 Extension of
Cooling Zone.

9244

US BORAX - Boron
Minor Repairs on #6 Furnace - Plant 5

9245

INTERPACE - LA
Nec Repairs to #4 Pottery Kiln

9246

NORRIS INDUSTRIES - Vernon
Repair #9 Annealing Furnace

9247

POWERINE OIL COMPANY-Santa Fe Springs
Repair Cat Cracker

9248

SHELL OIL COMPANY - Dominguez
Repair #20 A Furnace.

9249

INTERPACE - LA
Repair Tile Kiln #9

9250

CHAMPLIN OIL - Wilmington
Nec Repairs to Sulfur Boiler.

APRIL

9251 STANDARD OIL CO - El Segundo
Repairs to Heater #47 Unit.

9252 INTERPACE - LA
Repairs to Tile Kiln #13.

9253 AIRIZONA PORTLAND CEMENT
"A" Additional Material
"B" Furnish 6 rings of brick for #4 Kiln Burner or
"C" Furnish 6 rings of brick for #1 Kiln Burner

9254 INTERPACE - LA
Tile Kiln #16 Extension of Cooling Zone.

9255 STANDARD OIL CO - El Segundo
Nec Repairs to the E-308 at Sulfur Unit

9256 STANDARD OIL CO. - El Segundo
Nec Repairs to the F-305 at Sulfur Unit

9257 EMERY INDUSTRIES - LA
Repairs to #2 Pot Still

9258 SHELL OIL CO-Dominguez
Install 48 lin ft section pipe of reactor
chamber line.

9259 J T THORPE & SON/CHEVRON CHEMICAL
Richmond, Ca. - Provide Engineering only
for Thermal Oxidizer System.

9260 POWERINE OIL CO-Santa Fe Springs
Repairs to the Orifice of the Cat Cracker.

MAY 1976

- 9261 STANDARD OIL CO-El Segundo
Repair #33 Boiler
- 9262 NORRIS INDUSTRIES-Vernon
Repairs to #13 Annealing Furnace
- 9263 TEXACO-Wilmington
Remove & Replace Burner Tile #8 Boiler
- 9264 GREAT LAKES CARBON-Wilm
Repair #2 Kiln
- 9265 INDUSTRIAL ENGINEERS/HIRT COMBUSTION
Montebello - Install Lining in Air Heater.
- 9266 STAUFFER CHEMICAL-Dominguez
Install Brick in One Sump & One Pump Base.
- 9267 DOUGLAS OIL-Paramount
Repairs to #7 Boiler.
- 9268 W R GRACE CO - South Gate
Furnish & Install Acid Brick Lining for Alum.
Cooker.
"A" Patch leak in wall & rebuild steam sparge holder.
- 9269 NORRIS INDUSTRIES-Vernon
Repairs to Spherodizing Unit
- 9270 TEXACO-Carson
Repair #600 Incinerator

MAY 1976

- 9271 MOLYCORP INC
Mountain Pass, Calif. - Refractory
Repairs 10' ID x 6 Hearth Skinner Roaster.
- 9272 SOUTHERN CALIF EDISON-Long Beach
Repairs to #5 Boiler
- 9273 TEXACO INC-Wilm
Repairs to #601 Waste Heat Boiler, Sulfur Plant.
- 9274 POST TRANSPORTATION CO-Carson
Acid Brick Lining for Chemical Sump
"A" Repairs to Concrete.
- 9275 U S BORAX & CHEMICAL-Boron
Minor Repairs to #2AB Furnace - Plant 5
- 9276 U S BORAX & CHEMICAL - Boron
Minor Repairs to #4AB Furnace - Plant 5
- 9277 UNION OIL CO-Wilm
Regenerator & Regenerator Cyclone
Heater #B202 & Stack
"A" Riser Line "C" Peabody Heater
"B" Peabody Heater
"C" Spent Cat Line
"D"
- 9278 MONSANTO CHEMICAL-Long Beach
Repairs to #3 Acid Burner Crossover
"A" Repairs to Calciner
- 9279 APEX INTERNATIONAL-Long Beach
Repairs to #3 Reverb

MAY 1976

9280 STAUFFER CHEMICAL-Dominguez
Refractory Repairs to Plant #1
Combustion Chamber.
"A" Repairs to Quench Tower.

9281 STAUFFER CHEMICAL-Dominguez
Packing Support Replacement in #3 & #4
Absorbing Towers & H101 & H102 Towers
in Plant #1.
"A" Packing Support Replacement in Towers H201 in
Plant #2.

9282 N L INDUSTRIES-Los Angeles
Refractory Repairs Tilting Lead Furnace

9283 STANDARD OIL CO-EI Segundo
Sulfur Acid Plant Repairs to F500 Furnace

9284 STANDARD OIL CO-EI Segundo
Repairs to C520 Drying Tower
Sulfur Acid Plant

9285 STANDARD OIL CO-EI Segundo
Repairs to K510 Furnace Sulfur Acid Plant

9286 MOBIL OIL CO-Torrance
Stack Extension Vacuum Heater 1F2

JUNE 1976

9287	TEXACO INC - Carson Nec Repairs to Shipley Boiler
9288	STAUFFER CHEMICAL - Oxnard Nec Repairs to the Kelp Dryer
9289	MARTIN MARIETTA - Carson Nec Repairs to Kiln
9290	NORRIS INDUSTRIES - Vernon Nec Repairs to #1 Stress Oven
9291	COMMERCIAL ENAMELING - Los Angeles Nec Repairs to Enameling Furnace
9292	APEX INTERNATIONAL - Long Beach Repairs to #3 Furnace
9293	COLLIER CARBON - Wilm Nec Repairs to Converter
9294	STANDARD OIL CO - El Segundo Repair Pump Base B400
9295	Celotex - Los Angeles Nec Repairs to #3 Retort.
9296	STANDARD OIL - El Segundo Nec Repairs to #34 Boiler
9297	STANDARD OIL CO - El Segundo Repairs to #F110 Furnace

JUNE 1976

9298 COSTAL MARINE - Wilm
SS Austin - Repairs to Starboard Boiler

9299 SELAS CORP/STANDARD OIL - El Segundo
Repairs to Selas Furnace

9300 UNION OIL - Wilm
Fireproof on the D1,2,3,4 & 5 Skirts

9301 GREAT LAKES CARBON - Wilm
Repairs to #2 Kiln

9302 REDLAND CO - Torrance
Repairs to Preheater

9303 PHILADELPHIA QUARTZ - South Gate
Repairs to Silicate Furnace

9304 UNION OIL CO - Wilm
Repairs to Thermal Oxidizer

9305 COLLIER CARBON & CHEM - Wilm
Repairs to the Combustion Chamber

9306 N L INDUSTRIES - Los Angeles
Install Two Burners in Lower South Wall.
Patch Misc. Holes.

9307 BETHLEHEM SHIPYARDS - Term. Is.
USS Bronstein - Repairs to Boilers 1 & 2

9308 PHELPS DODGE - Morenci, Arizona
Acid Brick Repairs Humidifying & Cooling Towers
"A" Install Top Floor Course in 2 98% Pump Tanks.

9309 H KRAMER CO - El Segundo
Nec Repairs to #3 Furnace

JUNE 1976

- 9310 TEXACO INC-Wilm
Repairs to #2 Crude Fresh Feed Heater
- 9311 COMBUSTION ENGINEERING/
STANDARD OIL CO - El Segundo
Install Castable Refractory in Lower Mud
Drum on the S1300 & S1310 Boilers
- 9312 BETHLEHEM STEEL - Vernon
Acid Brick Reline North Pickling Tank
Wire Mill Department
"A" Repairs to Trench
- 9313 U S BORAX & CHEM-Boron
Major Repairs to #5AB Plant 5.
- 9314 PHELPS DODGE TUBING - LA
Repairs to Rotary Hearth Furnace
"A" Repairs to Burners on #680 Furnace
- 9315 PACIFIC SMELTING-Torrance
Repairs to the Rotary Kiln
- 9316 SNELSON INC/TEXACO INC
Anacortes, Washington
Refractory Repairs During FCC Turnaround
"A" Extra Work
- 9317 PACIFIC SINTERED METALS CO-Gardena
Furnish Combustion & Flame Safety for
Sintered Metal Furnace.
- 9318 ESB INC - LA
Repairs to Acid Proof Flooring
- 9319 STANDARD OIL-El Segundo
Repairs to #530A & B Furnace,
540 A & B, 620 A & B Isomax Plant

JUNE 1976

9320 AMETEK ALUMINUM EXTRUSION-LA
Refractory Lining for 28,000# Holding Furnace
"A" Repairs to Melting Furnace 1/77

9321 PLESSEY PRECISION METALS-LA
Repairs to Hydrofluoric Pickling Tank

9322 N L INDUSTRIES - LA
Repairs to Roof of South Blast Furnace

9323 SUPERIOR INDUSTRIES - Van Nuys
Refractory Repairs to 8000# McGowan
Aluminum Melting Furnace

9324 SOUTHERN CALIF EDISON - Palmdale
Repairs to West Boiler

9325 APEX SMELTING - Long Beach
Clean Out #2 Furnace

9326 SUPERIOR INDUSTRIES - Van Nuys
Install Two Tapout Blocks McGowan
20,000 Furnace

9327 GAFFERS & SATTTLERS - LA
Install Burner Block

9328 GREAT LAKES CARBON-Wilm
Repairs to #3 Kiln

9329 STANDARD OIL CO-EI Segundo
Nec Repairs for Pump Bases #P450
& MP450

JULY 1976

- 9330 STANDARD OIL CO - El Segundo
Repairs for Pump Bases P458 & P458-A

- 9331 W R GRACE - South Gate
Test Installation of Wet Felt

- 9332 MOBILE OIL CO - Torrance
Install Refractory Fill in FCC
Regenerator Bottom Cone

- 9333 ACE FOUNDRY - Huntington Park
Nec Repairs to Quench Towers

- 9334 CMI SHIPYARD - San Pedro
President Jefferson - Nec Repairs to
Starboard Boiler

- 9335 U S BORAX & CHEMICAL - Boron
Repairs to #3 Air Heater - Plant #4

- 9336 CELOTEX CORP - LA
Flame Supervisory Panel #3 Tube Still

- 9337 STANDARD OIL CO - El Segund
Nec Repairs to #301 Isomax Plant

- 9338 GREAT LAKES CARBON - Wilmington
Nec Repairs to #2 Kiln

- 9339 STANDARD OIL CO - El Segundo
Repairs to Coker Furnace

JULY 1976

- 9340 RB & W - Los Angeles
Replace Loose Quarry Tile
- 9341 CELOTEX - LA
Repairs to Stills, Kettles & Boilers
- 9342 PRECISION HEAT TREATING-Montebello
Reline Two Ipsen Draw Furnaces
- 9343 LEFORT CO/NORRIS INDUSTRY
City of Industry - Repair Pickling Tank
- 9344 ~~CASCADE STEEL/SOUTHWEST ROLLING MILLS~~
~~Make necessary repairs to floor & skid rails~~
~~install 24x 30" opening in east wall~~ *cancelled 7/28/76*
- 9345 J T THORPE & SON/KAISER STEEL
Napa, Calif - Design & Supply Relieve
Furnace Door Lifting System
- 9346 STANDARD OIL CO - El Segundo
Nec Repairs to Pump Base #P457
- 9347 STANDARD OIL CO - El Segundo
Nec Repairs to #F501 C Furnace Coker Plant
- 9348 NORMAN PITT CONSULTING ENGRS-LA
Furnish & Install Lining in 2-Ton Incinerator
Furnace & Heat Exchanger
- 9349 US BORAX - Boron
Minor Repairs to #6AB Furnace - Plant 5

JULY - 1976

- 9350 US NAVY - Long Beach
USS HENDERSON - Nec Repairs to
Boilers #1 & #4
- 9351 UNION OIL CO - Wilmington
Repairs to Heater E-102 in Unit 138
Sulfur Acid Plant
- 9352 GULF OIL CO - Santa Fe Springs
18' Diameter Box
- 9353 CALIFORNIA PORTLAND CEMENT-Mojave
Repairs to Cooler #3
- 9354 STAUFFER CHEMICAL - South Gate
Repairs to the Furnace Tower
- 9355 HITCO - Gardena
Nec repairs to heat treat furnace
- 9356 STAUFFER CHEMICAL - Dominguez
Repairs to Sulfur Recovery Unit
- ~~9357 TEXAS STEEL & WIRE CORP - Fontana~~
~~Design & Construct Galvanizing Kettle~~
- 9358 US BORAX & CHEMICAL - Boron
Minor Repairs to #1AB Furnace - Plant 5
- 9359 US BORAX & CHEMICAL - Boron
Minor Repairs to #2AB Furnace - Plant 5

*cancelled
6/77*

see 10465

JULY 1976

9360 STANDARD OIL CO - El Segundo
Nec Repairs to #38 Boiler

9361 NICHOLS ENGINEERING & RESEARCH CORP
Pomona - Labor to install Refractory Lining
in one 4'6" ID x 6 hearth Sludge Incinerator
"A" Extra Labor & Material

9362 GENERAL ELECTRIC - Ontario
1976 Annual Repairs A & M Furnace.

"A" Die Cast Furnace

"B" Sweat Furnace

"C" Annealing Furnace

"D" Furnish Door for Die Cast Furnace

9363 TEXACO INC - Wilmington
Nec Repairs to "B Generator

9364 STAUFFER CHEMICAL - Dominguez
Refractory Repairs to Plant #2 Combustion
Chamber.

"A" Repairs to Quench Tower.

9365 AIR RESEARCH MFG - LA
Repairs to Cyanide Hot Furnace

9366 TAMCO/AMERON ALLIATE DIVN - Etiwanda
Furnish Tundish Preheat Exhaust System

9367 THATCHER GLASS - Saugus
Dismantling & Repair #2 Furnace

"A" Fireproofing to #2 Furnace

9368 PACIFIC SMELTING - Torrance
Labor & Equipment only to install Lining
Vaporizing Section #5 Muffle Furnace

"A" Install Refractory in Riser Section.

"B" Labor only to Repair Melter.